

REF: CS3/MSG18015452/GHD3-⁰²

ASSIGNMENT (Office)

Pauline Thom MSIG 21/5/2019

Bill to

WS/TP RES / OD RES / EVA / INV / MV / CS

Vehicle No: SLK 7700S Insured: SLC 7886G

Make/Model: Precise Auto Tel: 67457357

No. 1 Kaki St Ave 6 # 02-34 / 36

128986953 AVW Claim No: 567980

Excess:

DDA 19/08/2018

REP. / REV. / HRS Cup

9:34am 21/5/18 Person Contacted: Yan Hong Vehicle IN OUT

Action/Instruction	(X) Estimate	
SLK 7700S - NA / TME18015125 / h4		DDA 19/8/18
SLC 7886G - NA / TME18015125 / h4		DDA 19/8/18
DUM and rest.		

\$4600, 4 Days.
(Red. 1700, 26%)

[Signature]
14/6/2019

Do Not Finalise

RECEIVED 14 JUN 2019

MS
XLR


REF: msk

9434A /

ASSIGNMENT

From: _____ Date: _____
 Estimated cost: _____
 OD: TP RES / OD RES / P/A / INV / MV
 To: _____
 at: _____
 of: _____
 Int: _____
 Po: _____
 Cl: _____
 Su: _____ Excess: _____
 (Record)

Veh No: SUK 7700 S Yr Regn: 16 Jul 2011
 Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Bmw 523i c.c. 2497
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 1482316 T/Radio: Insured / Std / NI / NA
 Engine No: _____
 C/No: WBA FP32010C 864006
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 245/40R19
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or



Re: a veh had commenced its pair at the time of inspection.
 E: \$62k
 ID: Front Consistent?: Yes or No
 C: Front Consistent?: Yes or No
 E: 3 days Res: Yes or No
 L: 20 Val: Yes or No
 C: REP. / 24 HR
 D: _____
 Person Contacted: _____
 Vehicle: IN / OUT

Front Rear
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: _____ D.O.I: 27-08-18
 Survey held at: W/S 3:45pm
 Des. of Damages: Front / Rear / O/S / N/S / U/C / Roof top or
 The U/C / Chassis frame / Body Structure affected due to collision.

Section / Inst: \$2000 - \$3000
 Unit / P: 2254

Report Report
 Report Report
 Add Fee: Site Insp (\$)
 Interview (\$)
 Tech Invs (\$)
 Weekend (\$)

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Survey Fee: 120
 Transportation: _____
 S + RS: _____
 Photos: _____
 Other: 10
 TOTAL: 130

Nivitha (LKK Auto)

From: Accounts (LKKAuto) <account@lkkauto.com>
Sent: Thursday, 23 May 2019 2:03 PM
To: Admin-D (LKKAuto)
Cc: assignments; Accounts (LKKAuto)
Subject: Report Send Back Alerts - SLK7700S (TP)

Dear Nivitha,

FYNA Please...

Pending for Survey Report-CS3/MSG18015452/GZ4D3E2

21 May 2019 12:52	Ins Send Back Adj Rpt please conduct paper survey. Thanks.	[1] Pauline Tham
21 May 2019 12:52	Adj Next Rpt Changed Next Rpt:Final Rpt.Due Date:2019/05/23	[1] Merimen Administrator
21 May 2019 12:52	Adj Mandate Set Maintained.	[1] Merimen Administrator

Thank You

Best Regards,



SuthaShelia (Shelia) | Accounts Dept.

LKK Auto Consultants Pte Ltd

Phone: 6841 1891 | email: account@lkkauto.com | fax: 6844-8805

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Do-Not-Reply [mailto:do-not-reply@merimen.com]

Sent: Tuesday, 21 May 2019 1:00 PM

To: account@lkkauto.com

Subject: Report Send Back Alerts - SLK7700S (TP)

Dear Sir / Madam,

Please login to Merimen Online at www.merimen.com.sg for more information.

Thanks,
The Merimen Team



This email has been checked for viruses by AVG antivirus software.
www.avg.com

MIC SURVEY & ASSESSMENT SERVICE

BLK 355A, SEMBAWANG WAY #08-104 SINGAPORE 751355

TEL/FAX: 6299 9888 HP: 9674 5457

(LICENSED APPRAISERS & ADJUSTERS)

Chia Jun Hao

INVOICE NO. 2018/027

Blk.85 Whampoa Drive

#02-256

Singapore 320085

Date 10 September, 2018

Description	Amount
To: Services rendered including photographs and transport charges.	\$ 600.00 <u> </u>
Our reference: M/T/23307/2018	
Insured:	
Policy/Cert. No:	
Your Claim No:	
Vehicle: BMW 523i - SLK 7700 S	

For Cash payment, only our official receipt will be recognised.

E. & O.E.



MIC SURVEY & ASSESSMENT SERVICE

MIC SURVEY & ASSESSMENT SERVICE

BLK 355A, SEMBAWANG WAY #08-104
SINGAPORE 751355
TEL/FAX: 6299 9888 HP: 9674 5457

RECEIPT NO. 12063

Date, 10 Sept. 2018

Received with thanks from Chia Jun Jao

Sum of dollars Six hundred Only.

In payment of JNV #2018/027

\$ 600/-
CASH/CHEQUE No.

Jay
MIC SURVEY & ASSESSMENT SERVICE

MIC SURVEY & ASSESSMENT SERVICE
BLK 355A, SEMBAWANG WAY #06-104, SINGAPORE 751355 TEL/FAX: 6299 9888 HP: 9574 5457
(LICENSED APPRAISERS & ADJUSTERS)

VEHICLE INSPECTION REPORT

TO: Chia Jun Hao
Blk. 85 Whampoa Drive
#02-256
Singapore 520085

REFERENCE

Requested by: Chia Jun Hao
Date of Request: 27 August, 2018
Date of Inspection: 27 August, 2018

Our Ref: M/T/23307/2018
Policy No.:
Claim No.:

DETAILS OF VEHICLE

Reg No: SLA 7700 B
Year: 2011
Make & Model: BMW 523i
Colour: White

Engine No: 07597679452B25AF
Chassis No: WBAFP52010C864006
Speedo Reading: 142516
Carry Capacity: 4

Air-Conditioners: Yes
Radio/Cassette: Yes
Seat Belt: Yes
Others: Nil

PRE-ACCIDENT CONDITION (STATIC TESTS)

General: Good
Handbrake: servicable
Footbrake: servicable
Steering: servicable

TYRES


70% ————— 70%

Michelin

70% ————— 70%

Rim: Sports
Size: 245/45 R 19

IMPACT: ARROW INDICATES
DIRECTION OF IMPACT.



GENERAL DESCRIPTION OF DAMAGE

The impact was confined to the front portion of the vehicle.

The above vehicle sustained damaged were front o/s & n/s chassis frame - buckled,
front o/s & n/s chassis frame cracked - bent.

APPRAISEMENT

Original Quotation: S 7,855.50 Revised Quotation: S 7,445.50 Less Excess: Nil

SPECIAL REMARKS

The estimated period of repairs will take 10 days to complete. Pursuant to your instructions, we have not authorised s/s. Precise Auto Service to repair on your behalf. A trade discount of 5% was noted and the survey was conducted strictly without prejudice basis.

.....
This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.

MIC SURVEY & ASSESSMENT SERVICE

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

NAME OF REPAIRERS: Precise Auto Service

ADDRESS: 1, Aki Bukit Ave. 6
#02-35/34/36 Autobay
Singapore 417883

Replaces of Parts	Conditions	Repairs Est.	Our Recommendation
<u>To Supply :-</u>			
1 pc Front Bumper	Buckled/Cracked	\$ 1,200.00	\$ 1,200.00
10 pcs Front Bumper Clips	Necessary	60.00	60.00
1 pc Front Bumper Reinforcement	Bent	708.00	708.00 X
1 pc Front Bumper Insulator	Cracked	160.00	160.00
1 pc Front Bumper Tow Cover	Cracked	29.00	29.00 X
1 pc Front Bumper o/s Parking Sensor	Cracked	380.00	380.00
4 pcs Front Bumper o/s Parking Sensor holder	Cracked	112.00	112.00
1 pc Front Bumper o/s Parking Sensor Wire	Torn	185.00	185.00
2 pcs Front Grille	Cracked	176.00	176.00
2 pcs Front Grille Garnish	Cracked	66.00	66.00
1 pc Front Support Panel Grille Garnish (Centre)	Cracked	125.00	125.00
1 pc Front o/s Head-Lamp	Cracked	2,302.00	2,302.00
1 pc Front o/s Head-Lamp Bracket (Lower)	Cracked	200.00	200.00
1 pc Front Air Baffle (Upper)	Cracked	105.00	105.00
1 pc Front Air Baffle (Lower)	Cracked	146.00	146.00
		\$ 3,954.00	\$ 3,954.00
Less 3% discount :-	5217	(\$ 297.70)	(\$ 297.70)
	5%: 4056.15	\$ 3,656.30	\$ 3,656.30
<u>Optional Reft Items :-</u>			
1 pc Front Magn. no. plate	Cracked	\$ 90.00	\$ 50 90.00
1 pc Front Magn. no. plate Bracket	Cracked	29.00	29.00
		\$ 119.00	\$ 119.00
<u>Labour Charges & Miscellaneous :-</u>			
To dismantle front portion damaged parts, straighten front o/s & n/s chassis frame, front o/s & n/s chassis frame bracket and reft above parts.		\$ 800.00	\$ 700.00 300
To juty and spray painting.		\$ 650.00	\$ 600.00 250
To re-set electrical system.		\$ 350.00	\$ 300.00 150
To check wiring and re-align front head-lamp.		\$ 80.00	\$ 70.00 30
		\$ 1,655.30	\$ 1,445.30 730
<u>SPECIAL Remark</u>			
The repairers verbally agreed to repair the vehicle at a global sum of \$6,300.00 corresponding to labour charges, spray painting and replacement of parts. Your liability is \$6,300.00.			

3765.15
20%: 4600

MIC SURVEY & ASSESSMENT SERVICE

AMU
ONG HOCK I ENG

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2018 17:43
Date Of Accident	19/08/2018 12:20
Exact Location Of Accident	ORCHARD GATEWAY LVL 5 CARPARK AREA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK7700S
Insured/Policyholder	
Name Of Registered Owner	MR CHIA JUN HAO
NRIC No	S9049434A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96993335
Alternative Phone No	Office-96993335

Vehicle Particulars

Manufacturer	BMW
Model	523I A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	18-MI001152-R01
Cover Note Number	-

Driver

Name of Driver	MR CHIA JUN HAO
NRIC No	S9049434A
Date Of Birth	31/12/1990
Occupation	INDOOR
Date Of Driving Pass	10/12/2010
Driving Experience	7 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96993335

Fax Number	
Contact Number	OFFICE-96993335
EMail Address	NOEMAIL
Address	BLK 85 WHAMPOA DR #02-256
Postcode	320085
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC7886G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	S8202966D
Contact Number	81335725
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time



Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name:
NIC/FIN No.

SKETCH PLAN



Veh. A: SLK 77005

Veh. B: SLK 78866

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the said date & time of accident, I was driving my vehicle (A) (SLK 77005) along Orchard Gateway Level 5 Carpark Area. Vehicle (B) (SLK 78866) in front of me slow down and stopped and I follow to stopped. Suddenly vehicle (B) reverse and collided into my vehicle front portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time: 20/8/18
4:45pm


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2018 15:37
Date Of Accident	19/08/2018 12:15
Exact Location Of Accident	AT ORCHARD GATEWAY LEVEL 5 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC7886G
Insured/Policyholder	
Name Of Registered Owner	HAN JIANGUANG
NRIC No	S8202966D
Email Address	JIANGUANG1251@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81335725
Alternative Phone No	Office-81335725
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	TOURAN 7 1.4 TSI CL EQP
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28986953 AVW
Cover Note Number	
Driver	
Name of Driver	HAN JIANGUANG
NRIC No	S8202966D
Date Of Birth	20/01/1982
Occupation	INDOOR
Date Of Driving Pass	26/06/2008
Driving Experience	10 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81335725

Fax Number	
Contact Number	OFFICE-81335725
Email Address	JIANGUANG1251@GMAIL.COM
Address	524A TAMPINES CENTRAL 7 #08-41
Postcode	521524
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : ELVIRA MAHARA Gender: : Female

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MORE DETAILS PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK7700S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

i understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Orchard Gateway level 5 carpark.



 Me

 SLK7700S

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


At Orchard Gateway level 5 carpark, I ~~was~~ reversed to make a left turn as I have missed the turn, I bumped into SLK7700S ~~bumper~~ front bumper. It happened on 19 August 2018, 12.15 pm.

DECLARATION


I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:

20 Aug 18,
3.26pm


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

20 Aug 2018


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Driving License

IDENTITY CARD NO. S8202966D



SIC 7886G.

A 2986953 Au

\$ 1K.

MOB: 4070.



jianguang1251@gmail.com

81335725

Identification Card

 ✓

 NRIC No. **S8202966D**

Date of issue
27-01-2012

APT BLK 534A TAMPINES CENTRAL 7 #05-41
SINGAPORE 571524

NRIC No. **S8202966D** Date: **18/08/2014**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 2 Motor Cars -> 3500kg with <=7 passengers, exclusive of the driver, and other motor vehicles -> 2500kg

ISSUE DATE 26 Jun 2008

License No. S8202966D

NP 4254

Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Aug 2018		24 Aug 2018 09:22 Edit Adj Rpt	S\$4,600.00 Edit Estimates	S\$4,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HAN JIANGUANG , ID: S8202966D, Tel: +6581335725, Email: JIANGUANG1251@GMAIL.COM								
Main Claimant:	CHIA JUN HAO , ID: S9049434A								
Vehicle Reg. No.:	SLK7700S	Date of Loss:	19/08/2018 12:00 - :59 [85 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 567980	Policy/Cover Note No.:	A28986953AVW (Comprehensive) Coverage: 30/06/2018 - 29/06/2019						
Vehicle Reg. No. (Insured):	SLC7886G	Policy No. (Claimant):							
		Excess:							
Repairer:	Precise Auto Services (HQ) NO.1 KAKI BUKIT AVE 6 #02-34/36, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 23/05/2019]								
Driver/Custodian (Insured):	HAN JIANGUANG (36 / Male), NRIC: S8202966D, Tel: +6581335725 Email: JIANGUANG1251@GMAIL.COM								
Adj Asg. Remarks:	LIABILITY CLEAR, TP REJECT SJE - ASSIGN LKK AUTO CONSULTANTS PTE LTD CONTACT: 6745 7357								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
• MSIG_SG (21/05/2019): Report Send Back Alerts - SLK7700S (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK7700S (567980)
[SLC7886G]

TP
CHIA JUN HAO
Aug 19 2018 12:00PM
[HAN JIANGUANG]
Precise Auto Services

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Assessment Reports									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print		
1	23/08/18 09:13	Accident Statement <small>From: SC - Reg. No: SLC7886G, Claimant: HAN JIANGUANG</small>					 Load HTM			
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print		
1	29/08/18 10:07	General View					 Load JPG	<input checked="" type="checkbox"/>		
2	29/08/18 10:07	General View					 Load JPG	<input checked="" type="checkbox"/>		
3	29/08/18 10:07	General View					 Load JPG	<input checked="" type="checkbox"/>		
4	29/08/18 10:07	General View					 Load JPG	<input checked="" type="checkbox"/>		
5	29/08/18 10:07	General View					 Load JPG	<input checked="" type="checkbox"/>		
6	29/08/18 10:07	General View					 Load JPG	<input checked="" type="checkbox"/>		
7	29/08/18 10:07	General View					 Load JPG	<input checked="" type="checkbox"/>		
8	29/08/18 10:07	General View					 Load JPG	<input checked="" type="checkbox"/>		
9	29/08/18 10:07	General View					 Load JPG	<input checked="" type="checkbox"/>		
10	29/08/18 10:07	General View					 Load JPG	<input checked="" type="checkbox"/>		
11	29/08/18 10:07	General View					 Load JPG	<input checked="" type="checkbox"/>		
12	29/08/18 10:07	General View					 Load JPG	<input checked="" type="checkbox"/>		
13	29/08/18 10:07	General View					 Load JPG	<input checked="" type="checkbox"/>		
14	29/08/18 10:07	General View					 Load JPG	<input checked="" type="checkbox"/>		
15	29/08/18 10:07	General View					 Load JPG	<input checked="" type="checkbox"/>		
16	29/08/18 10:07	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>		
17	29/08/18 10:07	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>		
18	29/08/18 10:07	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>		
19	29/08/18 10:07	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>		
20	29/08/18 10:07	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>		
21	29/08/18 10:07	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>		
22	29/08/18 10:07	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>		
23	29/08/18 10:07	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>		
24	29/08/18 10:07	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>		
25	29/08/18 10:07	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>		
26	29/08/18 10:07	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>		
27	29/08/18 10:07	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>		
28	29/08/18 10:07	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>		
29	29/08/18 10:07	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>		
30	29/08/18 10:07	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>		
31	29/08/18 10:07	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>		
32	29/08/18 10:07	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>		
33	29/08/18 10:07	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	29/08/18 10:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	29/08/18 10:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	29/08/18 10:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	29/08/18 10:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
38	29/08/18 10:07	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/08/18 09:13	SLK7700S E-FIEL REPORT <small>From: SC - Reg. No: 5LC7885G, Claimant: HAN JIANGUANG</small>	 Load PDF	
2	23/08/18 09:19	TP PRI NOTICE	 Load PDF	
3	23/08/18 11:19	TP REJECT SJE - ASSIGN LKK	 Load PDF	
4	27/03/19 14:27	survey report	 Load PDF	
5	27/03/19 14:28	survey photos	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/06/19 15:27	Colour Photo	 Load PDF	
2	14/06/19 15:27	PRS Invoice	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015452/GTD3E2-1

Date: 14/06/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A28986953AVW
 Claimant Vehicle No: SLK7700S Insured Vehicle No: SLC7886G
 Date of Loss: 19/08/2018 Nature of Claim: TP Claim No: 567980

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK7700S Engine No: 07397679N52B25AF
 Make & Model: BMW 523i, 2.5 (A) Chassis No: WBAFP32010C864006
 Reg. Date: 16/07/2011 (Man. Year: 2011) Odometer: 142316 km
 Colour: White
 Engine Capacity: 2497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R19 Rear Tyre Size: 245/40 R19
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	5,775.30	5,006.15	769.15	13.32	
Miscellaneous Items	0.00	0.00	0.00		
Labour	1,880.00	730.00	1,150.00	61.17	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	7,655.30	5,736.15	1,919.15	25.07	
Approved Total (Overridden) (S\$)		4,600.00			
	(S\$)	7,655.30	4,600.00	3,055.30	39.91
+ GST 7.00/7.00% (S\$)		535.87	322.00	213.87	39.91
Nett Amount (S\$)	8,191.17	4,922.00	3,269.17	39.91	

INSPECTION

Date of Assignment: 24/08/2018
 Date Inspected: 27/08/2018 Inspected At: Precise Auto Services (HQ)
 NO.1 KAKI BUKIT AVE 6 #02-34/36
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Jun 2019)
Parts: 143	BMW 523I 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLK7700S)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Cracked	1,200.00 FL	*1,200.00 FL
2	10		*FRONT BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	708.00 FL	*- FL
4	1		*FRONT BUMPER INSULATOR	Cracked	160.00 FL	*160.00 FL
5	1		*FRONT BUMPER TOW COVER	Not Necessary	29.00 FL	*- FL
6	1		*FRONT BUMPER O/S PARKING SENSOR	Cracked	380.00 FL	*380.00 FL
7	4		*FRONT BUMPER O/S PARKING SENSOR HOLDER	Cracked	112.00 FL	*112.00 FL
8	1		*FRONT BUMPER O/S PARKING SENSOR WIRE	Torn	185.00 FL	*185.00 FL
9	2		*FRONT GRILLE	Cracked	178.00 FL	*178.00 FL
10	2		*FRONT GRILLE GARNISH	Cracked	66.00 FL	*66.00 FL
11	1		*FRONT SUPPORT PANEL GRILLE GARNISH (CENTRE)	Cracked	125.00 FL	*125.00 FL
12	1		*FRONT O/S HEAD-LAMP	Cracked	2,302.00 FL	*2,302.00 FL
13	1		*FRONT O/S HEAD-LAMP BRACKET (LOWER)	Cracked	200.00 FL	*200.00 FL
14	1		*FRONT AIR BAFFLE (UPPER)	Cracked	105.00 FL	*105.00 FL
15	1		*FRONT AIR BAFFLE (LOWER)	Cracked	146.00 FL	*146.00 FL
16	1		*FRONT REGN.NO.PLATE }	Cracked	90.00 FS	*50.00 FS
17	1		*FRONT REGN.NO.PLATE BRACKET)		29.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,073.00	5,267.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	297.70	260.85
Total Parts (\$\$)	5,775.30	5,006.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE FRONT PORTION DAMAGED PARTS, STRAIGHTEN FRONT O/S & N/S CHASSIS FRAME, FRONT O/S & N/S CHASSIS FRAME BRACKET AND REFIT ABOVE PARTS	New	800.00	300.00
2	TO RE-SET ELECTRICAL SYSTEM	New	350.00	150.00
3	TO CHECK WIRING AND RE-ALIGN FRONT HEAD-LAMP	New	80.00	30.00
4	TO PUTTY AND SPRAY PAINTING	New	650.00	250.00
Gross Labour Cost (\$\$)			1,880.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >