

REF: CSI/LAW19068843/AtD302

Special Instructions

L/S: \$5280.00

ASSIGNMENT (Office)

From (Person): Desiree Ooi of JUSEQUITY Date/Time: 18/4/2019

Estimated Cost: _____ Bill to: _____

Third Parties

Claimant:

Surveyor: pro-Option Surveyors

Workshop: tiap Hong Motor

OD/TP Re-inspection / Evaluation /

To inspect Vehicle No. SGT 8921B Insured: GY 9065P

at Workshop m/s Hiap Hong Motor Tel: 9633 8888

of 2 Kaki Bukit Ave 2 # 02-13

Policy No: _____ Claim No: RT/206/2018/bf

Sum Insured: _____

Make of Velt: _____ D.O.A. 14/11/2016

(Client's Record)

M.O.D. Enrichment/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 20/4/2019 Confirmed with _____ Final Fig _____, _____ days (Red S _____ / _____ %; Original 5 days)

Date/Time: 04/07/19 Submit Final Fig 3.91c, 05 days (Red \$1300 / 25%; Original 5 days).

Date/Time	Action/Instruction
	SGT 8921B - X
	CIY 9065P - X

Do Not Finalise

net = (\$1300) 25%

Do Not Finalise

Net = (\$1300) 25%

Para(1) : Parts found not replaced	(To highlight <i>R or UB, LR, Etc</i>)
------------------------------------	---

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)
--

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Date: _____

Basic & Add	
Transport	
Photos	
Others	
Total	

50%

1) Date/Time 5/7/2019 File Pass to Typist

3) Date/Time _____ File Pass to _____

5) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

4) Date/Time: _____ File Return to: _____

6) Date/Time _____ File Return to _____

Nivitha (LKK Auto)

From: Desiree Ooi <desireeooi@juseq.com.sg>
Sent: Thursday, 18 April 2019 10:57 AM
To: assignments@lkkauto.com
Cc: 'Catherine Chong (LKK Auto)'; celinefong@lkkauto.com; 'Caleb';
phien@tanchinhoe.com.sg; ellice@tanchinhoe.com.sg
Subject: RE: (ADRIAN LING APPOINTED AS SJE) MC SUIT NO. 6489/2018 I JEQ's Ref:
JEQ/161115/1116/HH(do) I TCH's Ref: RT/206/2018/bf
Attachments: 4. Defendant's GIA Report.pdf; 5. Plaintiff's GIA Report.pdf

Dear Mr Ling,

I attach the Plaintiff and Defendant's GIA Reports in this email.

Kindly acknowledge receipt of this email.

Thank you.

Warmest Regards,

Desiree Nicole Ooi
Paralegal to Mr Caleb Tan
171 Chin Swee Road
#02-06
Singapore 169877

T : [6536 9339](tel:65369339) (ext 128)
F : [6533 2449](tel:65332449)
Website: www.juseq.com.sg

From: Desiree Ooi <desireeooi@juseq.com.sg>
Sent: Thursday, April 18, 2019 10:56 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: 'Catherine Chong (LKK Auto)' <admin-d@lkkauto.com>; 'celinefong@lkkauto.com' <celinefong@lkkauto.com>;
'Caleb' <caleb@juseq.com.sg>; 'phien@tanchinhoe.com.sg' <phien@tanchinhoe.com.sg>;
'ellice@tanchinhoe.com.sg' <ellice@tanchinhoe.com.sg>
Subject: (ADRIAN LING APPOINTED AS SJE) MC SUIT NO. 6489/2018 I JEQ's Ref: JEQ/161115/1116/HH(do) I TCH's
Ref: RT/206/2018/bf

Dear Mr Ling,

I'm Desiree the paralegal that is assisting Mr Caleb Tan on the abovementioned matter.

We act for the Plaintiff and the Defendant is being represented by Tan Chin Hoe & Co.

Please be informed that by consent and appointment of the Court, you have been appointed as the Single Joint Expert in respect of our client's property damage claim.

I have attached the documents in this email for your perusal.

- 1) Automobile Assessment Report by Pro-Option Services (Pltf)
- 2) Photographs by Pro-Option Services (Pltf)
- 3) Automobile Assessment Report by FormTeam Consultancy Pte Ltd (Deft)
- 4) Defendant's GIA Report (attachment will be sent in next email)
- 5) Plaintiff's GIA Report (attachment will be sent in next email)
- 6) Scene Photographs

Please let us have your available dates and timings so that we can arrange for a reinspection of the plaintiff's vehicle.

✓ Please note as the SJE appointed by the Court, your primary duty is to the Court and that you are required to give a fair and reasonable assessment of the cost of repairs of SGT8921B. In this regard, your attention is drawn to Order 40 of the Rules of Court.

Kindly let us have a copy of the SJE report by 15 May 2019 as per the Court's directions.

For further clarifications, please feel free to contact me.

Kindly acknowledge receipt of this email.

Thank you.

Warmest Regards,

Desiree Nicole Ooi
Paralegal to Mr Caleb Tan
171 Chin Swee Road
#02-06
Singapore 169877

T : 6536 9339 (ext 128)
F : 6533 2449
Website: www.juseq.com.sg

Nivitha (LKK Auto)

From: Richard Tan <richard@tanchinhoe.com.sg>
Sent: Monday, 13 May 2019 10:03 AM
To: Desiree Ooi; 'Admin-D (LKKAuto)'; 'assignments'
Cc: 'Celine Fong (LKKAuto)'; 'Caleb'; ellice@tanchinhoe.com.sg;
emily@tanchinhoe.com.sg
Subject: Re: (ADRIAN LING APPOINTED AS SJE) MC SUIT NO. 6489/2018 I JEQ's Ref: JEQ/161115/1116/HH(do) I TCH's Ref: RT/206/2018/bf

Dear Sirs

Please let us know why is the vehicle not available for physical re-inspection.

Richard Tan
Tan Chin Hoe & Co

From: Desiree Ooi
Sent: Friday, May 10, 2019 3:41 PM
To: 'Admin-D (LKKAuto)'; 'assignments'
Cc: 'Celine Fong (LKKAuto)'; 'Caleb'; phien@tanchinhoe.com.sg; ellice@tanchinhoe.com.sg
Subject: RE: (ADRIAN LING APPOINTED AS SJE) MC SUIT NO. 6489/2018 I JEQ's Ref: JEQ/161115/1116/HH(do) I TCH's Ref: RT/206/2018/bf

Dear Sirs,

Please be informed that the vehicle is not available for a physical reinspection.

Kindly proceed with a paper re-inspection.

May I know when can the Single Joint Expert report be ready?

Thank you.

Warmest Regards,

Desiree Nicole Ooi
Paralegal to Mr Caleb Tan
171 Chin Swee Road
#02-06
Singapore 169877

T : 6536 9339 (ext 128)
F : 6533 2449
Website: www.juseq.com.sg

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, May 9, 2019 12:27 PM
To: 'Desiree Ooi' <desireeooi@juseq.com.sg>; assignments <assignments@lkkauto.com>
Cc: Celine Fong (LKKAuto) <celinefong@lkkauto.com>; 'Caleb' <caleb@juseq.com.sg>; phien@tanchinhoe.com.sg; ellice@tanchinhoe.com.sg
Subject: RE: (ADRIAN LING APPOINTED AS SJE) MC SUIT NO. 6489/2018 I JEQ's Ref: JEQ/161115/1116/HH(do) I TCH's Ref: RT/206/2018/bf

Dear Sir/Mdm,

Nivitha (LKK Auto)

From: Desiree Ooi <desireeooi@juseq.com.sg>
Sent: Friday, 10 May 2019 3:42 PM
To: 'Admin-D (LKKAuto)'; 'assignments'
Cc: 'Celine Fong (LKKAuto)'; 'Caleb'; phien@tanchinhoe.com.sg;
ellice@tanchinhoe.com.sg
Subject: RE: (ADRIAN LING APPOINTED AS SJE) MC SUIT NO. 6489/2018 | JEQ's Ref: JEQ/161115/1116/HH(do) | TCH's Ref: RT/206/2018/bf

Dear Sirs,

Please be informed that the vehicle is not available for a physical reinspection.

Kindly proceed with a paper re-inspection.

May I know when can the Single Joint Expert report be ready?

Thank you.

Warmest Regards,

Desiree Nicole Ooi
Paralegal to Mr Caleb Tan
171 Chin Swee Road
#02-06
Singapore 169877

T : [6536 9339](tel:65369339) (ext 128)
F : [6533 2449](tel:65332449)
Website: www.juseq.com.sg

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, May 9, 2019 12:27 PM
To: 'Desiree Ooi' <desireeooi@juseq.com.sg>; assignments <assignments@lkkauto.com>
Cc: Celine Fong (LKKAuto) <celinefong@lkkauto.com>; 'Caleb' <caleb@juseq.com.sg>; phien@tanchinhoe.com.sg;
ellice@tanchinhoe.com.sg
Subject: RE: (ADRIAN LING APPOINTED AS SJE) MC SUIT NO. 6489/2018 | JEQ's Ref: JEQ/161115/1116/HH(do) | TCH's Ref: RT/206/2018/bf

Dear Sir/Mdm,

Thank you for the assignment.

Please assist to arrange the Re-inspection between MON-FRI (9AM-5PM)

And let us know one day in advance.

Apologize for the late reply.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Nivitha (LKK Auto)

From: Desiree Ooi <desireeooi@juseq.com.sg>
Sent: Monday, 13 May 2019 10:14 AM
To: 'Richard Tan'; 'Admin-D (LKKAuto)'; 'assignments'
Cc: 'Celine Fong (LKKAuto)'; 'Caleb'; ellice@tanchinhoe.com.sg; emily@tanchinhoe.com.sg
Subject: RE: (ADRIAN LING APPOINTED AS SJE) MC SUIT NO. 6489/2018 I JEQ's Ref: JEQ/161115/1116/HH(do) I TCH's Ref: RT/206/2018/bf

Dear Sirs,

I have been informed by my client that the vehicle has been scrapped.

We will be writing to LTA to get the confirmation and will provide you with proof when LTA responds to us.

Thank you.

Warmest Regards,

Desiree Nicole Ooi
Paralegal to Mr Caleb Tan
171 Chin Swee Road
#02-06
Singapore 169877

T : 6536 9339 (ext 128)
F : 6533 2449
Website: www.juseq.com.sg

From: Richard Tan <richard@tanchinhoe.com.sg>
Sent: Monday, May 13, 2019 10:03 AM
To: Desiree Ooi <desireeooi@juseq.com.sg>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; 'assignments' <assignments@lkkauto.com>
Cc: 'Celine Fong (LKKAuto)' <celinefong@lkkauto.com>; 'Caleb' <caleb@juseq.com.sg>; ellice@tanchinhoe.com.sg; emily@tanchinhoe.com.sg
Subject: Re: (ADRIAN LING APPOINTED AS SJE) MC SUIT NO. 6489/2018 I JEQ's Ref: JEQ/161115/1116/HH(do) I TCH's Ref: RT/206/2018/bf

Dear Sirs

Please let us know why is the vehicle not available for physical re-inspection.

Richard Tan
Tan Chin Hoe & Co

From: Desiree Ooi
Sent: Friday, May 10, 2019 3:41 PM
To: 'Admin-D (LKKAuto)'; 'assignments'
Cc: 'Celine Fong (LKKAuto)'; 'Caleb'; phien@tanchinhoe.com.sg; ellice@tanchinhoe.com.sg
Subject: RE: (ADRIAN LING APPOINTED AS SJE) MC SUIT NO. 6489/2018 I JEQ's Ref: JEQ/161115/1116/HH(do) I TCH's Ref: RT/206/2018/bf

Dear Sirs,

Please be informed that the vehicle is not available for a physical reinspection.

Nivitha (LKK Auto)

From: Desiree Ooi <desireeooi@juseq.com.sg>
Sent: Tuesday, 21 May 2019 11:23 AM
To: 'Richard Tan'; 'Admin-D (LKKAuto)'; 'assignments'
Cc: 'Celine Fong (LKKAuto)'; 'Caleb'; ellice@tanchinhoe.com.sg;
emily@tanchinhoe.com.sg
Subject: RE: (ADRIAN LING APPOINTED AS SJE) MC SUIT NO. 6489/2018 | JEQ's Ref: JEQ/161115/1116/HH(do) | TCH's Ref: RT/206/2018/bf
Attachments: 20190517_Fax from LTA (transfer of ownership).pdf

Dear Mr Tan,

Please find attached a self-explanatory letter from LTA.

Dear Nivitha,

As requested on 10 May 2019, kindly let us know when will the Single Joint Expert report be ready.

Thank you.

Warmest Regards,

Desiree Nicole Ooi
Paralegal to Mr Caleb Tan
171 Chin Swee Road
#02-06
Singapore 169877

T : [6536 9339](tel:65369339) (ext 128)
F : [6533 2449](tel:65332449)
Website: www.juseq.com.sg

From: Desiree Ooi <desireeooi@juseq.com.sg>
Sent: Monday, May 13, 2019 10:14 AM
To: 'Richard Tan' <richard@tanchinhoe.com.sg>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; 'assignments' <assignments@lkkauto.com>
Cc: 'Celine Fong (LKKAuto)' <celinefong@lkkauto.com>; 'Caleb' <caleb@juseq.com.sg>; 'ellice@tanchinhoe.com.sg' <ellice@tanchinhoe.com.sg>; 'emily@tanchinhoe.com.sg' <emily@tanchinhoe.com.sg>
Subject: RE: (ADRIAN LING APPOINTED AS SJE) MC SUIT NO. 6489/2018 | JEQ's Ref: JEQ/161115/1116/HH(do) | TCH's Ref: RT/206/2018/bf

Dear Sirs,

I have been informed by my client that the vehicle has been scrapped.

We will be writing to LTA to get the confirmation and will provide you with proof when LTA responds to us.

Thank you.

Warmest Regards,

Desiree Nicole Ooi
Paralegal to Mr Caleb Tan
171 Chin Swee Road
#02-06
Singapore 169877

T : [6536 9339](tel:65369339) (ext 128)

64571639

Land Transport Authority

10 Sin Ming Drive Singapore 575701
Tel: 1800 - CALL LTA (1800 - 2255 582) Fax: (65) 8653 5320/5329

17 May 2019

JusEquity Law Corporation
Advocates & Solicitors
171 Chin Swee Road
#02-06 CES Centre
Singapore 169877

Our ref VR&I/V43.009.002/SGT8921B
Your ref JEQ/161115/1116/HH(do)
DID 65535210 Fax 65535329

Fax: 6536 5368 & POST

Dear Sir/Madam

Confirm Transfer Date for Vehicle SGT8921B


We received your letter of 14 May 2019 and OCBC cheque of \$19.26.

Our records show that the vehicle, SGT8921B was transferred from Chia Sok Ling, NRIC No.: S7633771C to the next owner on 6 March 2017.

We attached the receipt of \$19.26 being payment for the above information.

You may call me on DID: 6553 5210 or Mr Peh Cheng Jic on DID: 6553 5483, if you have any questions.

Yours sincerely


Hamidah Bte Hassan (Ms)
Senior Executive, Operations
Vehicle Licensing Division

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Tel: 6 3151239 Fax: 6 3153298 Mobile: 9 0610543

Report No. : 495M1116.HH
Vehicle No. : SGT8921B

ACCIDENT VEHICLE SURVEY REPORT

1 REFERENCE

Date of Inspection : 15 November 2016
Requested by : Chia Sok Ling (Xie Shuling)
c/o Blk 2 Kaki Bukit Ave 2
#02-13
Singapore 417921
Type of Survey : Independent
Repairer : Hlap Hong Motor Repair
Blk 2 Kaki Bukit Ave 2, #02-13 Kaki Bukit Autohub Singapore 417921
Date of Accident : 14 November 2016

2 VEHICLE DATA

Make/Model : Peugeot 307
Year of registration : 2007
Chassis No. : VF33BRFJ84940237
Engine No. : 10LH5D1578312
Odometer Reading : 157775 km
Colour : Black

3 STATIC CHECK

Steering	: Serviceable	Paintwork	: Good
Foot Brake	: Serviceable	General Condition	: Good
Hand Brake	: Serviceable		

4 TIRE CONDITION

	<u>RH/Make</u>	<u>LH/Make</u>	<u>Size</u>
Front Tread	: 5 mm/Bridgestone	5 mm/Bridgestone	215/45R17
Rear Tread	: 5 mm/Bridgestone	5 mm/Bridgestone	215/45R17

5 GENERAL DESCRIPTION OF DAMAGE

Front bumper scraped/deformed, front fender scraped/bent, front door scraped/dented, LHS side skirt dented/deformed, etc. Please see para. 8 of this report for more details.

6 REMARK

This inspection is carried out on a "WITHOUT PREJUDICE" basis and we have not authorized any repairs.

7 RECOMMENDATION

Recommended cost of repairs = \$5,200.00 (lump sum)
Estimated no. of days for repairs = Five (5).

8 DAMAGE AND REPAIR COSTS ASSESSMENT

Report No. : 495M1116.HH

Vehicle No. : SGT8921B

<u>Description</u>	<u>Qty</u>	<u>Assessed Condition</u>	<u>Repairer's Estimate (\$)</u>	<u>Revised Amount (\$)</u>
A <u>SPARE PARTS</u>				
Front bumper	1	scraped/deformed	1,192.00	1,192.00 ✓
Front bumper side retainer LH/RH	2	necessary	170.00	170.00 ✓
Front bumper clip	8	necessary	48.00	48.00 ✓
Front fender LHS	1	scraped/bent	380.00	380.00 ✓
Front fender splash shield	1	to reuse	100.00	0.00 ✓
Front fender splash shield clip	8	to reuse	40.00	0.00 ✓
Front fender indicator lamp assy	1	to reuse	65.00	0.00 ✓
Front door assy LHS	1	dented/scraped	1,950.00	1,950.00 ✓
Front door weatherstrip	1	to reuse	86.00	86.00 ✓
Front door protector	1	scraped/bent	90.00	90.00 ✓
Front door hinge	2	to repair	190.00	0.00 ✓
Front door glass regulator cum motor	1	bent	342.00	342.00 ✓
Front door trim board	1	to reuse	880.00	0.00 ✓
Front door trim board clip	10	necessary	50.00	50.00 ✓
Front door inner lock assy	1	distorted/jaws shaky	190.00	190.00 ✓
Front door check	1	to repair	69.00	0.00 ✓
Front door outer handle	1	to repair	98.00	0.00 ✓
LHS side skirt	1	dented/deformed	422.00	422.00 ✓
Front door /4 glass moulding	1	bent	205.00	205.00 ✓
Subtotal of the above			6,567.00	5,125.00
Discount 10%			656.70	512.50
Total cost of parts			5,910.30	4,612.50

B LABOUR

To check wirings.	40.00	30.00 ✓
To remove and refix front door glass and serviceable parts.	90.00	60.00 ✓
To apply anti-rust undercoating.	150.00	90.00 ✓
Labour charges to remove and replace, to cut and weld, to knock and reshape affected parts/areas.	1,000.00	600.00 ✓
Spray painting charges to putty and spray all affected parts/areas.	1,200.00	1,000.00 ✓

Total labour cost	2,480.00	1,780.00
TOTAL COST OF REPAIRS	8,390.30	6,392.50

Report No. : 495M1116.HH

Vehicle No. : SGT8921B

9 CONCLUSION

The actual damage on the vehicle was carefully inspected and assessed during the inspection and the assessment is in para. 8 of the report. The degree of the damage sustained by each individual part was carefully assessed before the part was recommended to be replaced or repaired.

The adjusted/revised total cost of repairs to the vehicle is \$6,392.50 .

However, the recommended cost of repair based on lump sum basis would be \$5,200.00 and the estimated number of days for the repairs would be Five (5) working days.

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

The above recommendation in my view is fair and reasonable for the restoration of the damaged vehicle to its pre-accident condition.

I thank you for the opportunity to serve you and assure you of my best at all time.

Yours faithfully



.....
Liaw Leong San
Licensed Automotive Appraiser

total 4888.70 .
h/s: 3.91C
05Days

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident scene



Accident scene



Accident scene



Accident scene



Accident scene



Accident scene



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/11/2016 17:54
Date Of Accident	14/11/2016 13:40
Exact Location Of Accident	SIN MING ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGT8921B
Insured/Policyholder	
Name Of Registered Owner	HIAP HONG MOTOR REPAIR
Co Reg No	42051700J
Email Address	hiap.hong.motor@gmail.com
Mobile Phone No	(LOCAL) +65-82896889
Alternative Phone No	Office-82896889

Vehicle Particulars

Manufacturer	PEUGEOT
Model	307

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? No

If No, Please state action to be taken Third Party

Vehicle Category Private Car

Insurance Company

Name of Insurance Company	Etika Insurance Pte Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DQAL16S015027
Cover Note Number	01/05/2016 TO 30/04/2017

Driver

Name of Driver	CHUA MENG TONG
NRIC No	S1331978B
Date Of Birth	09/08/1958
Occupation	Indoor
Date Of Driving Pass	31/08/1977
Driving Experience	39 Years And 2 Months
Gender	Male
Mobile Number	(Local) +65-82896889
Fax Number	
Contact Number	
Email Address	hiap.hong.motor@gmail.com

Address APT BLK 322 TAMPINES STREET 33 #09-146 S520322
Postcode
Was driver an employee of the Insured's Company Yes
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident Unknown --
Weather Conditions Clear
Road Surface Wet

Other Information

Was any foreign vehicle involved in this accident? No
Was any body injured in the Accident? No
Was any other material or property damaged? Yes
I have been approached by unknown person(s) soliciting/offering accident claims assistance. No
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? Yes
If Yes, Please state which Police Station
Police Station Name Eunos Neighbourhood Police Post
Police Station Address ROAD: Blk 629 Bedok Reservoir Road #01-1620 . POSTCODE: 470629 ,
COUNTRY: Singapore
Police Station Contact TEL NO: 1800-4439999 - FAX NO: 62444376
Was notice of intended Prosecution given? No
If Yes, against whom?

Circumstances of Accident

REFER WITH POLICE REPORT T/20161114/2100

Attachment(s)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GY9065P
Vehicle Make/Model/Colour PREGIO 2.7 M
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

REFER WITH POLICE REPORT.

Insurance Co. ETICA INSURANCE
 Vehicle No. SIT 3921 Date of Accident 14/1/2016
☐ Reporting Only
☐ Own Damage Claim
☒ Third Party Claim
☐ Other Workshop

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

eTiQa

Insurance

INTERVIEW FORM

Name (Driver) : CHUA MENT TONG
 Policy No : DAALIGSS015022
 Vehicle No : SETB921B
 Place of Accident : SIN HIGH ROAD
 Insured Driver's relationship with Insured : CUSTOMER
 Drink Driving of Insured and/or Insured Driver : NO
 No of passenger(s) in Insured vehicle : NIL
 Injury to Insured and/or Insured driver, please indicate which hospital:

NO

Third Party Vehicle No (if any) : 4Y9065P
 No of passenger(s) in Third Party Vehicle : NIL

Injury to Third Party driver and/or passenger(s), please indicate which hospital:

NO

Type of collision and the extensiveness of the damages to all vehicles/Third Party property involved:

Any witness to the accident (if yes, please indicate Name, Contact No and a copy of the statement):

NO

Traffic Police report (enclosed) : Yes / No

Please obtain a copy of the driving licence of Insured driver and/or work permit (where foreign worker is involved)

Driver (Name & Signature) / Date

I, affirmed the above information is given to my best knowledge



Attended by (Name & Signature) / Date

Workshop Name:



Etiqa Insurance Pte Ltd
 One Raffles Quay
 #22-01 North Tower
 Singapore 048583

T +65 63360477
 F +65 63392109

www.etiqa.com.sg
 #empowering the journey

A Member of Maybank Group



**SINGAPORE
POLICE FORCE**



T/20161114/2100

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

1 of 3

Report No. T/20161114/2100

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/11/2016 15:32		Vide Report No.:		Station Diary No.: 18
Informant's Particulars				
Name of Informant: CHUA MENG TONG		Address: APT BLK 322 TAMPINES STREET 33 #09-146 SINGAPORE 520322		
ID Type / ID No.: NRIC NO / S1331978B		Contact No.: Home/Office: Mobile: 82896889		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 58	Date of Birth: 09/08/1958	Type of Informant: Driver	
Race: Chinese		Language:	Institution / School Name:	
Occupation: CAR ENGINEER		Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 14/11/2016 13:40	Type of Location: Straight Road
Location: Along Road 1 SIN MING ROAD SIN MING ROAD IND ESTATE IN FRONT OF RICARDO AUTO CENTRE #01-30				
Weather: Clear	Road Surface: Wet	Road Speed Limit:		
Traffic Flow: Two Way	Traffic Control: Not Controlled	Traffic Volume: Light		
Type of Collision: HIT BY DRAIN COVER			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of
GY9065P	Bus/Coach/Minibus	KIA	PREGIO 2.7 M	White	No Damage	0
SGT8921B	Car	PEUGEOT	307CC2.0 AT	Black	Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20161114/2100

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

2 of 3

Report No. T/20161114/2100

CONTINUATION OF REPORT

Driver			
Name	CHUA MENG TONG	ID No.	S1331978B
Related Vehicle	SGT8921B (Car)	Contact No.	82896889
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 14/11/2016 at around 1343hrs, I was driving along sin ming road when I heard a screeching sound on the left side of my vehicle. As such, I went out of my vehicle to see what happened and I saw that one minibus(GY9065P) had hit an drain cover and cause it to slant upwards. The drain cover then scratched my vehicle as I was driving pass. The driver then denied that it was his fault. I wish to state that I have photo evidence of the accident. I am lodging this report for insurance claims.



**SINGAPORE
POLICE FORCE**



T/20161114/2100

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

3 of 3

Report No. T/20161114/2100

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt LIEW CHONG XIANG, VINCENT

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

14/11/2016 15:32

Officer In Charge Of Case:

TP / GIA /

Sr Staff Sgt ESTHER CHONG

Contact No: 65476368

Classification Of Case:

Authentication Stamp


NR156

Singapore Police Force

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident scene



Accident scene



Accident scene



Accident scene



Accident scene



Accident scene



GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : _____ Vehicle Registration No : DQA 11650/5027
Name(as shown in NRIC): Hiap Hong tota repair
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
NRIC/Passport No : _____
Address : _____
Contact (Tel) : _____ (H/P) : 82896889
(Email) : _____
Date of Accident : 14/11/2016 Time of Accident : 1340hrs
Place of Accident : Sin Ming Road
Insurance Company : Estia Insurance pte ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

I was driving my customer vehicle SGT 89218
and involved in an accident with reference to
our company motor trade policy no: DQA 11650/5027

Signature of Vehicle Owner / Driver: _____

Date: 26/11/2017


Describe Circumstances of the Accident

12
On ~~11~~ 11/11/2016 I send my veh to Liap Hong motor
repair to repair my veh. On 14/11/2016 Mr Chua Meng
Tong inform me said my veh involved accident at
sin ming Rd.

attach Chua meng Tong police report & GIA report

Declaration

I/We declare the foregoing particulars are true in every respect.

 26/04/17
Policyholder's Signature / Date &
Time

Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personal

Insurance Co. _____

Vehicle No. _____

Date of accident _____

☐ Reporting Only

☐ Own Damage Claim

☐ Third Party Claim

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	16/11/2016 15:24
Date Of Accident	14/11/2016 14:30
Exact Location Of Accident	BLK 20 SIN MING IND EST SEC A #01-30 S575678
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GY9065P
Insured/Policyholder	
Name Of Registered Owner	MINSHENG AGENCIES
Email Address	nkhoos@live.jp
Mobile Phone No	
Alternative Phone No	Office-63589754
Vehicle Particulars	
Manufacturer	KIA
Model	PREGIO-2.7 D (M)
Vehicle Category	Motor Trade
Insurance Company	
Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type Of Coverage	Third Party
Fleet Policy	No
Policy Number	5027535052-07
Cover Note Number	
Driver	
Name of Driver	KHOO MENG SEI (QIU MINSHENG)
NRIC No	S0811812D
Address	279B MACPHERSON ROAD SINGAPORE
General Information of the Accident	
Type Of Accident	Unknown - REFER POLICE REPORT
Weather Conditions	Raining
Other Information	
Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Circumstances of Accident	
REFER ATTACHED	
Attachment(s)	
Are accident photos available for attachment?	Yes

Was there any video captured by Car Camera? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGT8921B
Vehicle Make/Model/Colour	PEUGEOT
Name of Driver	
Insurance Company Name	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



[Signature]


[Signature]

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

Without Insurance

On 14 December 2011, at about 2.30pm, our van bearing vehicle registration number GY 9065P, fell into a trench drain when a passenger car, a Peugeot (Registration number: SGT 89218) hit a trench drain cover plate covering the drain.

There was no damage to our van ~~and~~ nor did the van hit, collide or damage any cars there.

This statement is for reporting purposes to the Police, IWA / NHC only.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



SINGAPORE
POLICE FORCE



T/20161115/2171

1 of 3

Report No. T/20161115/2171

Police Station Of Origin:
Thomson NPH
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/11/2016 18:44	Video Report No.:	Station Diary No.: 40
--	-------------------	--------------------------

Informant's Particulars

Informant's Particulars

Name of Informant: KHOO MENG SEI			Address: 5 NIM GREEN SINGAPORE 807605	
ID Type / ID No.: NRIC NO / S0811812D			Contact No.: Home/Office: Mobile: 96609335	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 69	Date of Birth: 20/02/1947	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: SELF EMPLOYED			Driving Licence Information: Class: 3	
			Date of Expiry:	

General Information of the Accident

General Information of the Accident				
Type of Accident:	Non-Injury Government Property	Drink Drive: No	Date/Time of Accident: 14/11/2016 14:30	Type of Location: Car Park
Location: Along Road 1 SECTOR A SIN MING INDUSTRIAL ESTATE				
BLK 20 SECTOR A SIN MING INDUSTRIAL ESTATE				
Weather: Raining		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Moving vehicle against drain cover			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of
GY9065P	Van	KIA	Pregio	Grey	No Damage	0
SGT8921B	Car	PEUGEOT	307cc	Black	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



SINGAPORE
POLICE FORCE



T/20161115/2171

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

2 of 3

Report No. T/20161115/2171

CONTINUATION OF REPORT

Driver			
Name	KHOO MENG SEI		ID No. S0811812D
Related Vehicle	GY9065P (Van)		Contact No. 96609335
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 14/11/2016 at about 2.30pm, I was driving my vehicle GY9065P (KIA/Grey) within a workshop located at Blk 20 Sin Ming Ind Est Sect A. When my vehicle when over a improper drain cover, it could not support the weigh and was lifted. Thereafter, a vehicle SGT8921B (Peugeot/Black) did not keep a proper look out and hit onto the cover. I made a check on my vehicle and there was no damage. To my best understanding, there was no one injured as well. I am lodging this report for record purpose. I wish to state that the cover was just a metal plate and it was in sufficient to support vehicle.



POLICE FORCE

Police Station Of Origin:

Tombon NPP

75 Sin Ming Road #01-180 SINGAPORE

570025

Tel No: 1800-4528999

T/20161115/2171

3 of 3

Report No. T/20161115/217

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /
Staff Sgt ONG KIAN KENGSignature Of Interpreter:
Not applicable.

Officer In Charge Of Case:

TP / AEIT /
Sr Staff Sgt ANG YI TING, STEPHANIE
Contact No.: 65476180

Signature Of Informant:

Date/Time:
15/11/2016 18:44

Classification Of Case:

Authentication Stamp
NP168

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: JEQ/161115/1116/HH

Date: 09th July 2019

Our Ref: CS1/LAW19008893/Atd3e2

M/s Jusequity Law Corporation

171 Chin Swee Road

#02-06 Ces Centre

Singapore 169877

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SGT 8921R

INSURED VEHICLE: GY 9065P

ACCIDENT DATE: 14/11/2016

We thank you for your instruction on 18/04/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SGT 8921B from M/s Por-option Services.
- b) Survey report by FormTeam Consultancy Pte Ltd with colour photographs.
- c) Singapore Accident Statement and Police Report of Vehicles SGT 8921B and GY 9065P.
- d) Colour damaged vehicle photographs of SGT 8921B.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SGT 8921B
Make & Model	: Peugeot 307
Chassis Number	: VF33BRFJ84940237
Year of Registration	: 2007

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



Your Ref: RT/206/2018/BF

Date: 09th July 2019

Our Ref: CS1/LAW19008893/Atd3e2

M/s Tan Chin Hoe & Co
24 Raffles Place
#24-01 Clifford Centre
Singapore 048621

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SGT 8921R
INSURED VEHICLE: GY 9065P
ACCIDENT DATE: 14/11/2016

We thank you for your instruction on 18/04/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SGT 8921B from M/s Por-option Services.
- b) Survey report by FormTeam Consultancy Pte Ltd with colour photographs.
- c) Singapore Accident Statement and Police Report of Vehicles SGT 8921B and GY 9065P.
- d) Colour damaged vehicle photographs of SGT 8921B.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SGT 8921B
Make & Model	: Peugeot 307
Chassis Number	: VF33BRFJ84940237
Year of Registration	: 2007
2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGT 8921B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,192.00	-
2	FRONT BUMPER SIDE RETAINER LH/RH	NOT NECESSARY	170.00	-
8	FRONT BUMPER CLIP	NECESSARY	48.00	48.00
1	FRONT FENDER LHS	SCRAPED / BENT	380.00	380.00
1	FRONT FENDER SPLASH SHIELD	REUSE	100.00	-
8	FRONT FENDER SPLASH SHIELD CLIP	REUSE	40.00	-
1	FRONT FENDER INDICATOR LAMP ASSY	REUSE	65.00	-
1	FRONT DOOR ASSY LHS	DENTED / SCRAPED	1,950.00	1,950.00
1	FRONT DOOR WEATHERSTRIP	NECESSARY	86.00	86.00
1	FRONT DOOR PROTECTOR	SCRAPED / BENT	90.00	90.00
2	FRONT DOOR HINGE	TO REPAIR SEE LABOUR	190.00	-
1	FRONT DOOR GLASS REGULATOR CUM MOTOR	BENT	342.00	342.00
1	FRONT DOOR TRIM BOARD	REUSE	880.00	-
10	FRONT DOOR TRIM BOARD CLIP	NECESSARY	50.00	30.00
1	FRONT DOOR INNER LOCK ASSY	DISTORTED / JAWS SHAKY	190.00	190.00
1	FRONT DOOR CHECK	TO REPAIR SEE LABOUR	69.00	-
1	FRONT DOOR OUTER HANDLE	TO REPAIR SEE LABOUR	98.00	-
1	LHS SIDE SKIRT	DENTED / DEFORMED	422.00	422.00
1	FRONT DOOR / 4 GLASS MOULDING	BENT	205.00	205.00
	LESS 10% DISCOUNT		-656.70	-374.30
			5,910.30	3,368.70
LABOUR				
	TO CHECK WIRINGS.		40.00	30.00
	TO REMOVE AND REFIX FRONT DOOR GLASS AND SERVICEABLE PARTS.		90.00	60.00
	TO APPLY ANTI-RUST UNDERCOATING.		150.00	30.00
	LABOUR CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE AFFECTED PARTS / AREAS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, FRONT DOOR HINGE, FRONT DOOR CHECK AND FRONT DOOR OUTER HANDLE.		1,000.00	600.00

Report Ref No. CS1/LAW19008893/Atd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING CHARGES TO PUTTY AND SPRAY ALL AFFECTED PARTS / AREAS.		1,200.00	800.00
			2,480.00	1,520.00
GRAND TOTAL			8,390.30	4,888.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,900.00

Report Ref No. CS1/LAW19008893/Atd3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.