

22/03/2019

ASS. REC. BY:

REF:

CS/AIG19008904/Ecd3²⁴

Special Instruction:

Summar: Steve

ASSIGNMENT (Office)

From (Person):

chin lee ying

of

AK

Date/Time:

21/5/19 @ 2:28pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKM 9206R

Insured:

SLP 7834M

at Workshop m/s

Green Star Spray

Tel:

8482-2655

of

Blk 3011 Bedok North Ave 4 #01-2004/2006

Policy No:

0999994855

Claim No:

87923562018G

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/5/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:34pm @ 21/5/19

Person Contacted:

JaneVehicle IN/OUT

Date/Time	Action/Instruction	Estimate (x)
	SKM 9206R-CS/MSG/7023085/Ktbn 2	20A: 26/1/17
	SLP 7834M-x	
	Dismantle: 22/5/2019	
	After repair: 24/5/2019	

Steve

REF:

AIG

ASSIGNMENT

From
Estimated Cost
QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No

Claims No

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time : Action / Instruction

MV-49K

Veh No: SKM 9206R
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Volkswagen Jetta

Colour: Black

Sp. Reading: 103722

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

F:

R:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to?

☐

Proll. Report

4)

☐

Final Report

Date/Time: File Return to?

2)

Report Format:

DAR

Lump Sum / I.B. /

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Week-end (\$

Survey Fee:

Transportation

) 3 + R's 2

) Photos

) 1 day


) 1

1014

RECEIVED 07 JUN 2019

180
11
1014

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 5/21/2019 2:28:59 PM
Attachments:  tmp800D.TIF

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**Daniel Poon & Co.**Advocates & Solicitors
Commissioners for OathsDaniel Poon Choon Kow
LL.B. (Hons), LL.M133 New Bridge Road
#11-02 Chinatown Point
Singapore 059413
Tel: +65 6227-2469
Fax: +65 6225-2579
Email: law@dpco.com.sg
(UEN: S3130838C)

Our Ref: DP.sl.isk.10965.19.GSSP
Your Ref: -----
Please quote our reference number when replying

Date: 21 MAY 2019

M/S AIG ASIA PACIFIC INSURANCE PTE. LTD.
AIG BUILDING
78 SHENTON WAY
#08-16
SINGAPORE 079120
ATTN: MOTOR CLAIMS DEPARTMENT

FAX (6835-7416) ONLY

DEAR SIRs,

**PRE-REPAIR INSPECTION
YOUR INSURED VEHICLE REGISTRATION NO: SLP 7834M
ACCIDENT ON 21 MAY 2019 INVOLVING SKM 9206R AND SLP 7834M
ALONG TPE (PUNGGOL) EXIT LOYANG AVENUE**

We are instructed by Kok Miew Chei to notify you of a road traffic accident on 21st May 2019 at about 08:00 along TPE (Punggol) exit Loyang Avenue involving our client's vehicle registration number SKM 9206R and vehicle registration number SLP 7834M driven by your insured at the material time. A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair inspection of the vehicle, by the attached list of ten (10) surveyor which our client deemed suitable to be appointed.

If the aforesaid is not agreeable, kindly therefore instruct your appointed surveyor for a pre-repair inspection of our client's vehicle at by making a prior appointment with the repairer stated below:-

M/S GREEN STAR SPRAY PAINTING
BLK 3011 BEDOK NORTH AVENUE 4
#01-2004 / 2006,
BEDOK INDUSTRIAL PARK E
SINGAPORE 489977
ATTN: MS JANE (8482-2655 / 6546-3092)

... 2/-

Page 2

Date: 21st May 2019

Messrs Daniel Poon & Co.

Our Ref: DP.sl.isk.10965.19.GSSP

If we do not receive any agreement from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

J. DP & Co.

c.c. M/S GREEN STAR SPRAY PAINTING

BY E-MAIL ONLY

SINGAPORE AUTOMOBILE APPRAISERS ASSOCIATION**QUALIFIED MOTOR SURVEYORS**

- 01) ONG AH KENG, KENT
- 02) PHILLIP FOO
- 03) LEE KOK WENG
- 04) WINSTON GOH
- 05) ALAN CHEONG
- 06) AMAS ONG POH MENG
- 07) SEBASTIAN LIM YONG TIAN
- 08) ANDREW HOW
- 09) DAVID PHOR
- 10) DAVE CHANG FUH KEONG

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/05/2019 08:42
Date Of Accident	21/05/2019 08:00
Exact Location Of Accident	TPE (PUNGGOL) EXIT LOYANG AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKM9206R
Insured/Policyholder	
Name Of Registered Owner	KOK MIEW CHEI
NRIC No	S1385120D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96538681
Alternative Phone No	OTHERS-96538681

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA-1.4 TSI (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5108296354
Cover Note Number	24/04/2019 - 23/04/2020

Driver

Name of Driver	KOK MIEW CHEI
NRIC No	S1385120D
Date Of Birth	11/12/1959
Occupation	INDOOR
Date Of Driving Pass	05/06/1984
Driving Experience	34 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96538681
Fax Number	
Contact Number	OTHERS-96538681
Email Address	NOEMAIL

Address	8 ANG MO KIO AVENUE 2 #04-05
Postcode	567695
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE STATED DATE & TIME, I TRAVELING STRAIGHT ALONG THE SAID LOCATION, OUT OF SUDDEN, I FELT AN IMPACT FROM BEHIND AND NOTICED THAT VEHICLE B (SLP7834M) WAS COLLIDED ONTO MY REAR RIGHT PORTION OF VEHICLE. THERE WERE NO INJURIES.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP7834M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this Report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore; for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRC/FIN No.:



SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER VIA APT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No: _____



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5120D
Vehicle Details	
Vehicle No.:	SKM9206R
Vehicle to be Exported:	No
Intended Deregistration Date:	21 May 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 1.4 TSI AT 1623G5
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	CAXD15246
Chassis No.:	WVWZZZ16ZDM066938
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$20,842.00
Original Registration Date:	24 Apr 2014
First Registration Date:	24 Apr 2014
Transfer Count:	0
Actual ARF Paid:	\$11,179.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Apr 2024
PARF Rebate Amount:	\$7,825.00
Intended COE Rebate Details	
COE Expiry Date:	23 Apr 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$77,400.00
COE Rebate Amount:	\$38,098.00
Total Rebate Amount:	\$45,923.00

The information contained herein is correct as at 21 May 2019

OK

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 10 Years Coe Renewal Toyota Wish 1.8A



2.98%P/A \$0 Admin Fees@Gv
Finance.2 Years Warranty.\$2500
Down Monthly From \$638
GV Credit Pte Ltd StarAd

Lake View Credit Pte Ltd

view our cars

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

Sort by Date Posted

20 results/page

4 vehicles

Volkswagen Jetta

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Volkswagen Jetta	Any	Any	2014	Any	Any	Any	Availabl
	Volkswagen Jetta 1.4A TSI	\$51,800	\$9,200 /yr	17-Jul-2014	1,390 cc	67,866 km	Sedan	Availabl
High Coe Of \$62k, High Paper Value, 1 Owner, Low Mileage, Well Maintained, Original Condition, Bank/In House Loan Available. Subject To Approval Buy With A Peace Of Mind. Trade In Welcome, Come View ...								
AL Autocar Pte Ltd								
Posted: 12-May-2019 Tags: 2014 Volkswagen Jetta, 2014 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen, Jetta, jetta, Used Volkswagen								
	Volkswagen Jetta 1.4A TSI	\$51,800	\$9,060 /yr	14-Aug-2014	1,390 cc	45,374 km	Sedan	Availabl
1 Owner Only! Well Maintained, Excellent Condition! Bank Or In House Loan Available. Call For More Enquiries!								
Posted: 18-May-2019 Tags: 2014 Volkswagen Jetta, 2014 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen, Jetta, jetta, Used Volkswagen								
	Volkswagen Jetta 1.4A TSI	\$49,800	\$8,460 /yr	23-Sep-2014	1,390 cc	51,500 km	Sedan	Availabl
Low Mileage Done, Selling With Extended Warranty, 100% Accident-Free, Superb Condition, High Paper Value, Value For Money, Easy Loan/Trade In Available.								
Posted: 21-May-2019 Tags: 2014 Volkswagen Jetta, 2014 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen, Jetta, jetta, Used Volkswagen								
	Volkswagen Jetta GP 1.4A TSI Highline	\$53,800	\$9,100 /yr	17-Oct-2014	1,390 cc	86,000 km	Sedan	Availabl
Low Interest Rate From 2.28% And In House Available! One Year Warranty On Engine, Gearbox And Aircon!, High Trade In, Buy With A Peace Of Mind From An ISO Certified Company For More Than 34 Years Of E...								
Hua Yang Credit Pte Ltd								
Posted: 11-May-2019 Tags: 2014 Volkswagen Jetta, 2014 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen, Jetta, jetta, Used Volkswagen								

Save this search criteria, to get email alerts whenever a match is found.

Make: Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/pag

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rate: used Volkswagen Jetta, Volkswagen Jetta Singapore, used Volkswagen Jetta Singapore, used Volkswagen Jetta, used vehicles Singapore or even buy used Volkswagen Jetta, new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promo

https://www.sgcarmart.com/used_cars/listing.php?ORD=RGD_ASC&MOD=Volkswagen Jetta&RPG=20&VEH=0&RGD=2014&AVL=2

(01)Best (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Turn (14)Unconfirmed (15)Not Working

MOTOR CAR (UC)

ACTION (AC)

(1)Replace (✓) (2)Repair (X) (3)Check (7)
(4)Not Consistent (NC)

Aug 2005

Undercarriage

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber			
1373	991944	Frt LH Shock Absorber Mounting			
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm			
1376	995199	Frt LH Knuckle Arm Bearing			
1377	995178	Frt LH Lower Arm			
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod			
1380	995143	Frt LH Drive Shaft			
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage			
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1410	990534	Centre Exhaust Pipe Assy			
1411	990532	Centre Exhaust Mounting			
1404	991134	Floor Panel			
1405	993719	Rear LH Shock Absorber			
1406	993723	Rear LH Shock Absorber Mounting			
1407	993170	Rear LH Coil Spring			
1408	993550	Rear LH Knuckle Arm			
1409	993551	Rear LH Knuckle Arm Bearing			
1410	993597	Rear LH Lower Arm			
1411	993884	Rear LH Upper Arm			
1412	995161	Rear LH Drive Shaft			
1413	995216	Rear LH Control Arm			
1414	993881	Rear LH Trailing Arm			
1415	993573	Rear LH Leaf Spring			
1416	992941	Rear LH Brake Disc Rotor			
1417	992937	Rear LH Brake Caliper Assy			
1418	990434	Rear LH Brake Pipe			
1419	992946	Rear LH Brake Hose			
1420	993819	Rear Sub Frame			
1421	993820	Rear Sub Frame Mounting			
1422	992813	Rear Anti Roll Bar			
1423	990168	Rear Anti Roll Bar Linkage			
1424	990202	Axle Beam			
1425	990170	Rear Axle Panhard Rod			
1426	990810	Differential Assy			
1427	992706	Propeller Shaft			

No of Items: _____ Assessor: _____

4 days repair

Vehicle No:

SXM 9206 R

NAC	INC	Item	CON	AC	Qty
1428	991935	Frt RH Shock Absorber			
1429	991944	Frt RH Shock Absorber Mounting			
1430	990632	Frt RH Coil Spring			
1431	991844	Frt RH Knuckle Arm			
1432	991845	Frt RH Knuckle Arm Bearing			
1433	991851	Frt RH Lower Arm			
1434	992064	Frt RH Upper Arm			
1435	992040	Frt RH Tie Rod			
1436	991692	Frt RH Drive Shaft			
1437	990661	Frt RH Control Arm			
1438	992062	Frt RH Trailing Arm			
1439	991848	Frt RH Leaf Spring			
1440	991293	Frt RH Brake Disc Rotor			
1441	991281	Frt RH Brake Caliper			
1442	991292	Frt RH Brake Pipe			
1443	991287	Frt RH Brake Hose			
1444	991295	Frt RH Brake Sensor Wire			
1445	993720	Rear RH Shock Absorber			
1446	993723	Rear RH Shock Absorber Mounting			
1447	993173	Rear RH Coil Spring			
1448	993550	Rear RH Knuckle Arm			
1449	993551	Rear RH Knuckle Arm Bearing			
1450	993601	Rear RH Lower Arm			
1451	993885	Rear RH Upper Arm			
1452	993322	Rear RH Drive Shaft			
1453	993178	Rear RH Control Arm			
1454	995117	Rear RH Trailing Arm			
1455	995110	Rear RH Leaf Spring			
1456	992942	Rear RH Brake Disc Rotor			
1457	992938	Rear RH Brake Caliper Assy			
1458	990434	Rear RH Brake Pipe			
1459	992947	Rear RH Brake Hose			

Signature
22/5/2019

* Rear bumper

* " " Bracket

* " " lower spool

CUT ✓

BR ✓ 2

R

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 May 2019 Edit Reg		21 May 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	BKW RENT A CAR PTE LTD, Co. Reg. No.: 200106276D		
Main Claimant:	KOK MIEW CHEI, ID: S1385120D		
Vehicle Reg. No.:	SKM9206R	Date of Loss:	21/05/2019 07:00 - :59 [60 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8792356201SG	Policy/Cover Note No.:	0999994355 (Comprehensive)
Vehicle Reg. No. (Insured):	SLP7834M	Policy No. (Claimant):	
		Excess:	
Repairer:	GREEN STAR SPRAY PAINTING (HQ) BLK 3011 BEDOK NORTH AVENUE 4 #01-2004 BEDOK INDUSTRIAL PARK E, 489977 Bedok - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 30/05/2019]		
Claimant's Solicitor:	DANIEL POON & CO - Tel: 62272469		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (22/05/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKM9206R (8792356201SG)
[SLP7834M]**

TP

KOK MIEW CHEI





























May 21 2019 7:00AM








[BKW RENT A CAR PTE LTD]


GREEN STAR SPRAY PAINTING

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
2	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
3	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
4	21/05/19 18:24	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
5	21/05/19 18:24	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
6	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
7	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
8	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
9	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
10	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
11	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
12	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
13	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
14	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
15	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
16	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
17	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
18	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
19	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
20	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
21	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
22	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
23	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
24	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
25	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
26	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
27	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
28	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
29	21/05/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
30	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
37	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
38	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
39	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
40	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
41	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
42	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
43	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
44	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
45	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
46	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
47	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
48	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
49	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
50	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
51	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
52	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
53	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
54	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
55	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
56	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
57	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
58	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
59	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
60	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
61	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
62	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
63	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
64	06/06/19 15:46	Photographs of Damaged Parts	 Load JPG	✓
65	06/06/19 15:46	Photo After Spray	 Load JPG	✓
66	06/06/19 15:46	Photo After Spray	 Load JPG	✓
67	06/06/19 15:46	Photo After Spray	 Load JPG	✓
68	06/06/19 15:46	Photo After Spray	 Load JPG	✓
69	06/06/19 15:46	Photo After Spray	 Load JPG	✓
70	06/06/19 15:46	Photo After Spray	 Load JPG	✓
71	06/06/19 15:46	Photo After Spray	 Load JPG	✓
72	06/06/19 15:46	Photo After Spray	 Load JPG	✓
73	06/06/19 15:46	Photo After Spray	 Load JPG	✓
74	06/06/19 15:46	Photo After Spray	 Load JPG	✓
75	06/06/19 15:46	Photo After Spray	 Load JPG	✓
76	06/06/19 15:46	Photo After Spray	 Load JPG	✓
77	06/06/19 15:46	Photo After Spray	 Load JPG	✓
78	06/06/19 15:46	Photo After Spray	 Load JPG	✓
79	06/06/19 15:46	Photo After Spray	 Load JPG	✓
80	06/06/19 15:46	Photo After Spray	 Load JPG	✓
81	06/06/19 15:46	Photo After Spray	 Load JPG	✓
82	06/06/19 15:46	Photo After Spray	 Load JPG	✓

Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	22/05/19 11:34	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19008904/ECD3S2
Date: 13/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994355
Claimant Vehicle No: SKM9206R Insured Vehicle No: SLP7834M
Date of Loss: 21/05/2019 Nature of Claim: TP Claim No: 8792356201SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKM9206R
Make & Model: VOLKSWAGEN JETTA, 1.4 TSI (A) Engine No: CAXD15246
Reg. Date: 24/04/2014 (Man. Year: 2013) Chassis No: WVVZZZ16ZDM066938
Colour: Black Odometer: 103722 km
Engine Capacity: 1390 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18 Rear Tyre Size: 225/40R18
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/05/2019
Date Inspected: 21/05/2019 Inspected At: GREEN STAR SPRAY PAINTING (HQ)
BLK 3011 BEDOK NORTH AVENUE 4 #01-2004
BEDOK INDUSTRIAL PARK E
Singapore 489977
Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH KNUCKLE ARM	Bent	0.00 F	*- F
2	1		*REAR RH KNUCKLE ARM BEARING	Necessary	0.00 F	*- F
3	1		*REAR RH LOWER ARM	Bent	0.00 F	*- F
4	1		*REAR RH TRAILING ARM	Bent	0.00 F	*- F
5	1		*REAR BUMPER	Cut	0.00 F	*- F
6	2		*REAR BUMPER BRACKET	Broken	0.00 F	*- F
7	1		*REAR BUMPER LOWER SPOILER	Repair	0.00 F	*- F
				Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >