

ASS. REC. BY:

REF: CS/MSG19008906/TIVd3

Special Instruction:

Surveyor: Taufek

ASSIGNMENT (Office)

From (Person): Elaine Ngan Sian Mei

of MSIG

Date/Time: 21.5.19 9.00am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SNE 3559E

Insured:

SLV 9400M

at Workshop m/s Borneo Motors

Tel:

98476171

of Toyota Bodycare Centre, No 2 Pandan Crescent

Policy No: 29070041

Claim No:

589476

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 31.3.2019

CA / REV / REP. / REV 24 HRS

rup

H.O.D. Endorsement:

Date/Time: 21.5.19 01.51pm

Person Contacted:

Thomas

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SNE 3559E - NA/MSG19006528/r3
	D.O.A - 31/03/2019
23/5/19	Send preli revised via merimen
27/5/19	Final fig \$ 2644.02 confirmed by email (Ref 2336.34, 4713)

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

rup

Vehicle: IN / OUT

Date: Person Contacted:

D.O.A.

D.O.I. 22/5/19 21030

Survey held at

Borneo Pandan

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 27 MAY 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 27/5- typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

150

10

160

Report Format:

merimen

Lump Sum / I.B.I. (\$) 2644.02