

ASS. REC. BY:

REF: CS/PWD 19003913.1 Aq ds

n2

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Clara Li

of PWD

Date/Time: 21.5.19 4.19p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKP 146E

Insured:

SKV 590S

at Workshop m/s Reliable Carz

Tel: 81669797

of 8 Kaki Bukit Avenue 4 #05-50

Policy No: PNCV2018-0000289

Claim No:

1201900013677

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 18.5.2019

CA / REV / REP. / REV 24 HRS

"wp"

Date/Time: 21.5.19 4.57p.m

Person Contacted:

Jason Lee

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	SKP 146E - NAI INC 19008852/14	D.O.A. - 13/05/2019
	SKV 590S - NAI INC 19008852/14	D.O.A. - 18/05/2019
31/5/19 @ 3.29pm	Informed Clara Li, we are pending estimate from repairer.	
18/6/19 @ 3.05pm	Revised to Clara Li via Marina.	
	Vg. to 3700, 4 days Cred to 2870.12, 44%.	

ASS. REQ. BY:

REF: FWD

ASSIGNMENT

From: Date: 31/5/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKP 1176E

at Workshop n/s Reliabe Carz

of 81caki Bukit Ave 4 # 05-50

Insured: Premier

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 1up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKP 1176E

Yr Regn:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW

C.C.

Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 134335

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA3B16020NS - 51509.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/35R19.

R: 235/35R19.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 31/05/19.

Survey held at

Reliabe

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front d/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PP FWD

RECEIVED 19 JUN 2019

Date/Time, File Pass to?

: Preli. Report

11/6/19

: Final Report

Date/Time, File Return to?

2)

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Wheel and (\$)

Report Format:

WEEK-7P

Lump Sum / L.E. (\$)

3700

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Other:

TOTAL

200

50

50

11

311

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 18 Jun 2019

Preliminary Advice

Insured Vehicle No	: SKV590S	Accident Date	: 18/05/2019
TP Vehicle No	: SKP1176E	Assignment Date	: 21/05/2019
Make	: BMW 320I	Est. Duration of Repair	: 4.00
Date of Inspection	: 31/05/2019		
Inspection At	: RELIABLE CARZ PTE LTD (HQ) 8 KAKI BUKIT AVE 4, #05-50 SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,570.12
Revised Amount	:S\$	4,631.89
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,631.89
Lump Sum Repair	:S\$	3,700.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Nivitha (LKK Auto)

From: clara.li@fwd.com
Sent: Tuesday, 21 May 2019 4:19 PM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: Our client's vehicle no. SKP1176E (RC); Your insured's vehicle no. SKV590S - PRI Our Ref: PNCV2018-00000289/CL
Attachments: Reliable Carz - Pre-Repair Notice (FWD)(SKP1176E).pdf

Hi LKK team,

Please assist with the TPPRS.

Thanks.

Regards,
Clara

From: Hui Ting [mailto:huiting@crossbordersllc.com]
Sent: Tuesday, 21 May, 2019 4:16 PM
To: Clara Li Zirong - SGUser; Corene
Cc: Motor Claims SG - SG Common
Subject: RE: Our client's vehicle no. SKP1176E (RC); Your insured's vehicle no. SKV590S - PRI Our Ref: PNCV2018-00000289/CL

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Clara

1. We refer to your email dated 21 May 2019.
2. We are instructed that our client has confirmed LKK AUTO CONSULTANTS PTE LTD as a single joint expert.
3. Please be informed that the said vehicle can be inspected at:

Venue:	Reliable Carz Pte Ltd
Address:	8 Kaki Bukit Avenue 4
	#05-50
	Singapore 4157875
Contact:	Jason Lee (8166 9797)
4. Please liaise with the above workshop.

Thank You.

Regards
Huiting
TEL: 6438 1323 ext 2006

CrossBorders LLC
133 New Bridge Road

#23-03/04/05 Chinatown Point
Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

From: clara.li@fwd.com <clara.li@fwd.com>
Sent: Tuesday, 21 May 2019 12:06 PM
To: Corene <corene@crossborderllc.com>; Hui Ting <huiting@crossborderllc.com>
Cc: motorclaims.sg@fwd.com
Subject: RE: Our client's vehicle no. SKP1176E (RC); Your insured's vehicle no. SKV590S - PRI Our Ref: PNCV2018-00000289/CL

WITHOUT PREJUDICE

Dear Sir/ Madam,

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

**Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.*

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.*

Kind Regards,
Clara Li




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg



From: Hui Ting [<mailto:huiting@crossbordersllc.com>]

Sent: Tuesday, May 21, 2019 11:59 AM

To: Motor Claims SG - SG Common

Cc: Corene

Subject: Our client's vehicle no. SKP1176E (RC); Your insured's vehicle no. SKV590S - PRI

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Sirs

1. Please find attached our PRI notice dated 21 May 2019 for your kind attention.
2. Please reply email to corene@crossbordersllc.com & huiting@crossbordersllc.com

Thank You.

Regards

Huiting

TEL: 6438 1323 ext 2006

CrossBorders LLC
133 New Bridge Road
#23-03/04/05 Chinatown Point
Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

CrossBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk.RC (SKP1176E)
Your Ref: SKV590S

21 May 2019

✓ FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower Four
Singapore 038986
Attn: Motor Claims Department

BY EMAIL ONLY

URGENT

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
CLAIMANT: SONG WEICHENG
TRAFFIC ACCIDENT ON 18 MAY 2019 AT 18:45 HRS ALONG LOR TELOK PARALLEL
CARPARK INVOLVING VEHICLES NO. SKP1176E & SKV590S

We are instructed by Song Weicheng to notify you of a road accident on 18 May 2019 at about 18:45 hrs along Lor Telok Parallel Carpark involving our clients' vehicle registration number SKP1176E and vehicle registration number SKV590S driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our clients' vehicle has been damaged. Before our clients proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our clients shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: Reliable Carz Pte Ltd ✓
Address: 8 Kaki Bukit Avenue 4
#05-50
Singapore 4157875
Contact: Jason Lee (8166 9797)

Please liaise with the above workshop directly.

Yours faithfully

CrossBorders LLC
CrossBorders LLC

Email: corene@crossbordersllc.com /
huiting@crossbordersllc.com
encs

PLEASE LET US KNOW THE DATE
OF THE PRE-REPAIR INSPECTION

.....

CONFIDENTIALITY CAUTION
THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE
SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

CrossBORDERS LLC

A LIMITED LIABILITY CORPORATION, REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413
TEL: 6438 1323
FAX: 6438 2313

BRANCH OFFICE
1 JALAN BERSEH
#03-12 NEW WORLD CENTRE
SINGAPORE 209037

PLEASE SEND ALL
CORRESPONDENCES TO
THE MAIN OFFICE

WE DO NOT ACCEPT
SERVICE BY FAX

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 31 May 2019 3:29 PM
To: clara.li@fwd.com; assignments
Cc: motorclaims.sg@fwd.com; SUR
Subject: RE: Our client's vehicle no. SKP1176E (RC); Your insured's vehicle no. SKV590S - PRI
Our Ref: PNCV2018-00000289/CL

Dear Clara,

Please be informed that we have inspected the vehicle SKP 1176E.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 21 May 2019 5:18 PM
To: clara.li@fwd.com; assignments <assignments@lkkauto.com>
Cc: motorclaims.sg@fwd.com; SUR <sur@lkkauto.com>
Subject: RE: Our client's vehicle no. SKP1176E (RC); Your insured's vehicle no. SKV590S - PRI Our Ref: PNCV2018-00000289/CL

Dear Clara,

Thank you for the email.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: clara.li@fwd.com [<mailto:clara.li@fwd.com>]
Sent: Tuesday, 21 May 2019 4:19 PM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: Our client's vehicle no. SKP1176E (RC); Your insured's vehicle no. SKV590S - PRI Our Ref: PNCV2018-00000289/CL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4993G
Vehicle Details	
Vehicle No.:	SKP1176E
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Jun 2019
Vehicle Make:	B.M.W.
Vehicle Model:	320I SEDAN AT D/AB 4DR ABS HID
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	A3550620N20B20B
Chassis No.:	WBA3B16020NS51509
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$35,862.00
Original Registration Date:	25 Feb 2014
First Registration Date:	25 Feb 2014
Transfer Count:	1
Actual ARF Paid:	\$32,207.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Feb 2024
PARF Rebate Amount:	\$22,544.00
Intended COE Rebate Details	
COE Expiry Date:	24 Feb 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$78,604.00
COE Rebate Amount:	\$36,817.00
Total Rebate Amount:	\$59,361.00

The information contained herein is correct as at 18 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/05/2019 10:48
Date Of Accident	18/05/2019 18:45
Exact Location Of Accident	LOR TELOK PARALLEL CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP1176E
Insured/Policyholder	
Name Of Registered Owner	SONG WEICHENG
NRIC No	S8214993G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81982228
Alternative Phone No	OFFICE-81982228

Vehicle Particulars

Manufacturer	BMW
Model	320I
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5087806223-02
Cover Note Number	-

Driver

Name of Driver	SONG WEICHENG
NRIC No	S8214993G
Date Of Birth	26/05/1982
Occupation	INDOOR
Date Of Driving Pass	01/12/2005
Driving Experience	13 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81982228
Fax Number	
Contact Number	OFFICE-81982228
Email Address	NOEMAIL

Address	28 JLN LEMPENG #10-05
Postcode	128807
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV590S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



A = SKP 1175 €

B = 5KV 570S

For $\pi \leq 10\%$

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to Police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

RELIABLE CARZ PTE LTD

8 Kaki Bukit Avenue 4 #05-50 Premier @ Kaki Bukit Singapore 415875
Contact No.: +65 8166 9797 Fax No.: +65 6385 1751

WBA3816020NS51509.

Vehicle No.: SKP1176E

Model: BMW F30

TAFWD
xiaochan.

REF: RC3179

QTY DESCRIPTION

List Items:

- 1 Front bumper *ton*
- 1 Front bumper retainer RH *new*
- 1 Head lamp RH *let*
- 1 Front fender RH *Rebed*
- 1 Front fender liner RH *new*
- 1 Head lamp panel RH *repair*

2857.65
2571.88
S.N. 1200

AMOUNT (S\$)

	1938.40	1200(SN)
	38.40	✓
	2119.70	✓
	699.55	✓
	233.10	✗
	493.20	✗
	5522.35	
Less 20 %	(1104.47)	
Subtotal	4417.88	

Special Nett Items:

- Front bumper clip (set) *new*
- Front fender liner clip (set) *new*

30

	50.00	30
	50.00	✗
Subtotal	100.00	

Labour Charges:

- To check wiring system
- To remove and replace above part
- To spray painting on affected area

830

	100.00	30
	600.00	400
	800.00	400
Subtotal	1500.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL S\$

6,017.88 6570.11

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
4/5 31/05/19.
042mg

total: 4638.88
4/5: 371c

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD19008913/AQD3N2
Date: 20/06/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNCV2018-00000289
 Claimant Vehicle No: SKP1176E Insured Vehicle No: SKV590S
 Date of Loss: 18/05/2019 Nature of Claim: TP Claim No: 1201900013677

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKP1176E Engine No: A3550620N20B20B
 Make & Model: BMW 320i, 2.0 (A) Chassis No: WBA3B16020NS51509
 Reg. Date: 25/02/2014 (Man. Year: 2013) Odometer: 134335 km
 Colour: White
 Engine Capacity: 1997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35 R19 Rear Tyre Size: 235/35 R19
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,070.11	3,801.88	1,268.23	25.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	830.00	670.00	44.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,570.11	4,631.88	1,938.23	29.50
Approved Total (Overridden) (S\$)		3,700.00		
Nett Amount (S\$)	6,570.11	3,700.00	2,870.11	43.68

INSPECTION

Date of Assignment: 21/05/2019
 Date Inspected: 31/05/2019 Inspected At: Reliable Carz Pte Ltd (HQ)
 8 Kaki Bukit Ave 4, #05-50
 Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 20 Jun 2019)	
Parts:	N/A	BMW 320i 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKP1176E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER RETAINER RH	Necessary	38.40 FL	*38.40 FL
2	1		*HEAD LAMP RH	Cut	2,119.70 FL	*2,119.70 FL
3	1		*FRONT FENDER RH	Dented	699.55 FL	*699.55 FL
4	1		*FRONT FENDER LINER RH	Not Necessary	233.10 FL	*- FL
5	1		*HEAD LAMP PANEL RH	Repair	493.20 FL	*- FL
6	1		*FRONT BUMPER	Torn	1,744.56 FS	*1,200.00 FS
7	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
8	1		*SET FRONT FENDER LINER CLIP	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,428.51	4,087.65
- List Item Discount on L Items 10.00/10.00% (\$\$)	358.40	285.77
Total Parts (\$\$)	5,070.11	3,801.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING SYSTEM.	New	100.00	30.00
2	TO REMOVE AND REPLACE ABOVE PART.	New	600.00	400.00
3	TO SPRAY PAINTING ON AFFECTED AREA.	New	800.00	400.00
Gross Labour Cost (S\$)			1,500.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >