

INS. CASE OWNER

CC 6/LPC1900 8915, A16302 LKK
IDAC:Surveyor: AdrianDOI: 8/5/19Date / Time: 17/5/19Registered in Merimen: -

Pre-assign / CCU / FTE

Insured Vehicle No. : GBB 3746CClaim No. : 191/1/191405/01/333Name of Insured : SAW HING FOOD MANUFACTURINGPolicy No. : 31900501466Insured Tel No. : HP: 8/5/19Make / Model : NISSANExcess Sec II :SS D.O.A: 8/5/19Place of Accident : PIE TMS TMS

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : MR PANG HENG (Huang Bangxing) OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No. : (V/L: YES / NO) Insured Liability : % Final ? Yes / No

GBB 3746CINSRS: NHT
WSP: WSP
Tel : WSP
Liability : WSP
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time

4/6/2019 7:45 AM 191405/01/333
GBB 3746C 31900501466- GOT AUDIO CLIP FROM OI.
- MANUFACTURED
- ORIGINAL TP LOD IN07/08/19- MR KUTUBUDD. CONSULTING URGENTLY.
- CUTTING CLAIM
- EMAIL TO OI TO CHECK CLAIM UPDATE
- TYPE REPORT FOR WANDATE
- REPORT DONE21/08/19
22/08/19- SEEK WANDATE APPROVAL TO LPC
- LPC APPROVED WANDATE.
- SEND 1st OFFER TO TP.
- TP ACCEPTED OFFER
- ALL DONE IN ORDER.
- TO CLOSE.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time: 07/08/19Sent By: VIC

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: LGSS 2,100.00(4 days)Reduction: GA

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 22/08/19Confirm with: SUREYEmail ☒ Call ☐

Final Liability:

SS 50

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28. Ass. Lia:

Repair Cost: 2,247.00SS 1,123.50

Loss of Rental (LOR):

SS -(- days)Loss of Use (LOU): 240SS 120.00(60 x 4 days)

Loss of Income (LOI):

SS -(S x days)LOR only ☐LOU only ☒LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search: 27.45SS 7.45

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost:

SS -1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

450.00Total: 2,414.45SS 1,250.95

Global Sum SS:

1,250.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS 1,250.00

Name 1:

NEW HOCK TACK MOTOR PTE LTD

Payee 2: (Strike if N.A.)

SS -

Name 2:

Payee 3: (Strike if N.A.)

SS -

Name 3:

ASS. REC BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: G B 6 7 3 4 1 J Yr Regn: 2017 Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV200 C.C. 1461

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 35885 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VSKYBAM2020148311

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/70R14C

R: 175/70R14C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 17/05/19

Survey held at Chew n's

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

TP Con Pac.

Lig \$2,100.00

(Roo: \$3,749.00 (G+H))

MV:

PV:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

Survey Fee:

Date:

1)

2)

IN

OUT

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Preli. Report:

Final Report:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 19/19/19/VC05/021773
Our ref: CC6/LPC19008915/Ahb3

Date: 07.08.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBG 7341J


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17.05.2019 at the premises of M/s NEW HOCK TECK MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	5,849.60
Revised Estimate Amount	: S\$	2,731.47
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

ADRIAN LING
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 4540N

Vehicle Details

Vehicle No.: GBG7341J
Vehicle to be Exported: Yes
Intended Deregistration Date: 08 May 2019
Vehicle Make: NISSAN
Vehicle Model: NV200 1.5 MT ABS AIRBAG
2WD 6DR E5 W/RC

Primary Colour: Silver
Manufacturing Year: 2017
Engine No.: K9KC400D057494
Chassis No.: VSKYBAM20Z0148311
Maximum Power Output: -
Open Market Value: \$20,119.00
Original Registration Date: 12 Oct 2017
First Registration Date: 12 Oct 2017
Transfer Count: 1
Actual ARF Paid: \$1,006.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 11 Oct 2027
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
QP Paid: \$42,801.00
COE Rebate Amount: \$34,240.00
Total Rebate Amount: \$34,240.00

The information contained herein is correct as at 08 May 2019

OK

Sketch Plan #3

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7134469Z



Name
NG PANG HENG
(HUANG BANGXING)
黄邦兴

Race
CHINESE

Date of birth
02-10-1971

Sex
M

Country of birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number S7134469Z

Name
NG PANG HENG (HUANG BANGXING)

Birth Date 02 Oct 1971


Valid Until 16 Dec 2002



4756788



NRIC No. S7134469Z




Date of issue
08-08-2011

Address
APT. DLK 677B JURONG WEST STREET #4
#14-299
SINGAPORE 642677

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

PASS DATE
21/07/1997

Class 3	Motor Cars and Motor
	which unladen does not
Class 4	Heavy Motor Cars and
	weight of which unladen



NP 425A

Sketch Plan #4

TP



Aden Leo
Sales Executive

Forem Electric Pte Ltd

1, Ecotech Park III Sunview Road
#01-04 Singapore 627615

T : +65 6255 4932

F : +65 6255 4942

M : +65 9759 8700

E : sales@forem.com.sg

Web : www.forem.com.sg



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

LONPAC

LKK

EZ SWIFT CAR RENTAL & LEASING PTE LTD

16/05/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP CarPac
Joy.

Accident date: 08/05/2019

Estimated repair cost for vehicle no: GBG7341J NISSAN NV200 1.5 M '17

CHASSIS: VSKYBAM20Z0148311

S/n	Qty	Items / Nett	U/price	Amount
1	1	Front L/H Head Lamp <i>wt</i>		\$486.40
2	1	Front L/H Head Lamp Bracket <i>Not new</i>		\$248.60
3	1	Front Bumper <i>torn</i>		\$589.70
4	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 <i>30</i>
5	1	Front L/H Bumper Side Retainer <i>new</i>		\$35.20
6	1	Front L/H Bumper Top Side Cover <i>del</i>		\$362.20
7	1	Front L/H Fender <i>dented</i>		\$564.80
8	1	Front L/H Fender Cowling <i>3 x 1/2</i>		\$122.00
9	6	Front L/H Fender Cowling Clip <i>new</i>	\$6.50	\$39.00

2068.30
1861.47

Subtotal :- \$2,512.90

S/n	Qty	Items / Special Nett	U/price	Amount
10	1	Front L/H Hub Cap <i>wt</i>		\$186.70 <i>60</i>
11	1	Front L/H Tyre <i>Not new</i>		\$350.00

Subtotal :- \$536.70

60.

Labour charges

To check wheel alignment

\$150.00

To check wiring

\$100.00

Tuff kote

\$150.00

Panel beating

\$1,200.00

Spray painting

\$1,200.00

Subtotal :- \$2,800.00

Total:- \$5,849.60

total: 2731.47.

h/s. 2.1K ✓

04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Shu Pei (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 22 May 2019 10:42 AM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG; Joy Irene (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GBB3746C (OI : LPC - TBA) AND GBG7341J (TP : LKK REF - CC6/LPC19008915/Ajb3) on 08.05.2019 [External Confidential]
Attachments: 22052019103658.pdf


Lonpac External - Confidential
Our Ref : 19/19/19/VC05/021773

Dear Shu Pei,

Attached copy of insured's GIA report for your attention.

Aside to Joy Irene – Please assess liability before proceeding with
Direct Settlement as our insured is claiming against the third party.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 22 May, 2019 9:35 AM
To: GERALD POH WEE BIN; ONG LI LI
Cc: MT_Claim_SG; Admin A; Joy Irene (LKKAUTO)
Subject: Direct Settlement - Accident Involving GBB3746C (OI : LPC - TBA) AND GBG7341J (TP : LKK REF - CC6/LPC19008915/Ajb3) on 08.05.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle GBG 7341J at M/s Chew Motor Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Our case handler in-charge is Joy and she can be contacted at DID: 6841 2409 .

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC6/LPC19008915/Ahb3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 27-08-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 3746C	Veh. Inspected	GBG 7341J	
Policy No.	Z19VC05001466	Coverage (\$)	0.00	
Claim No.	19/19/19/VC05/021773	Excess (\$)	0.00	
Assign From		Assign Date	17/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VSKYBAM20Z0148311	Colour	SILVER	
Odometer	35985	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14C	GOODYEAR	6 mm	
L/H Front Tyre	175/70 R14C	GOODYEAR	6 mm	
R/H Rear Tyre	175/70 R14C	GOODYEAR	6 mm	
L/H Rear Tyre	175/70 R14C	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/05/2019	Inspection Date	17/05/2019	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 7341J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT L/H HEAD LAMP	CUT	486.40	486.40
1	FRONT L/H HEAD LAMP BRACKET	NOT NECESSARY	248.60	-
1	FRONT BUMPER	TORN	589.70	589.70
10	FRONT BUMPER CLIP @\$6.50	NECESSARY	65.00	30.00
1	FRONT L/H BUMPER SIDE RETAINER	NECESSARY	35.20	35.20
1	FRONT L/H BUMPER TOP SIDE COVER	DEFORMED	362.20	362.20
1	FRONT L/H FENDER	DENTED	564.80	564.80
1	FRONT L/H FENDER COWLING	NOT NECESSARY	122.00	-
6	FRONT L/H FENDER COWLING CLIP @\$6.50	NOT NECESSARY	39.00	-
	LESS 10% DISCOUNT		-	-206.83
			2,512.90	1,861.47
<u>SPECIAL NETT ITEMS</u>				
1	FRONT L/H HUB CAP (SN)	CUT	186.70	60.00
1	FRONT L/H TYRE (SN)	NOT NECESSARY	350.00	-
			536.70	60.00
<u>LABOUR</u>				
	TO CHECK WHEEL ALIGNMENT.		150.00	80.00
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.	NOT NECESSARY	150.00	-
	PANEL BEATING.		1,200.00	400.00
	SPRAY PAINTING.		1,200.00	300.00
			2,800.00	810.00
GRAND TOTAL			5,849.60	2,731.47
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,100.00

Report Ref No. CC6/LPC19008915/Ahb3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.