

22/05/2019

ASS. REC. BY:

REF: CS/CT1 19008967/NCD 382

Special Instruction:

Surveyor: NAZ

ASSIGNMENT (Office)

From (Person): Elaine (huong)

of CTI

Date/Time: 22.5.19 11:59am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMC 7304H

Insured: SKH 6881

at Workshop m/s Hundo Automotive

Tel: 94592825

of 280 Woodland Industrial Park E 5 #01-19

Policy No: DMPCSN 30157619000

Claim No: SNM19D 20216602

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 15.5.2019

CA / REV / REP. / REV 24 HRS

rup

H.O.D. Endorsement:

Date/Time: 22.5.19 1:23pm

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time	Action/Instruction
	Estimate (X)
	SMC 7304H - X
	SKH 6881 - X

REF:

GT

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bol. or Market Value: _____

WAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Secs: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % J Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S.MC 7304 H

Yr Regn: 5 AUG 2010

Type: M.Car / M.Cycle / BUS / Van / Lorry / Taxi / Prime Mover /

Truck / Tractor or

Make: VOLKSWAGEN JETTA

c.o. 1390

Colour: BLACK

A/C: Insured / Std / NI / NA

Sp. Reading: 153,404

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WUW2221KZAM.133130

Gon. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modl: NI / SIRIm / STD A/RIm or

Tyre Size: F: 205 / 55 R 16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bol. 6

mm

Rear

R/Bol. 6

mm

L/Bol. 6

mm

L/Bol. 6

mm

D.O.A. 1515 / 19

U.O.I. 22 / 5 / 19

Survey held at _____

Des. of Damages: Frl / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Range + Day Repair Range \$5K - \$6K

RECEIVED 07 JUN 2019

28/5/2019

Date/Time, File Pass to?

☐ : Prelim Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format: PRO

Lump Sum / I.B.I. (\$) _____

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Foot:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invo (\$ _____)

☐ : Weekend (\$ _____)

\$ + RS. \$1

Photos

Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2019		22 May 2019 11:59 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	ZHANG NAN, ID: S8262734J	
Main Claimant:	TAN MEI LING (CHEN MEILING), ID: S8312007Z	
Vehicle Reg. No.:	SMC7304H	Date of Loss: 15/05/2019 13:00 - :59 [105 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D202166C02	Policy/Cover Note No.: DMPCSN30157619000 (Comprehensive)
Vehicle Reg. No. (Insured):	SKH688T	Policy No. (Claimant): 5102921741 Excess: S\$0.00
Repairer:	Hendon Automotive Pte Ltd (HQ) 280 Woodlands Industrial Park E5, #01-19 Harvest @ Woodlands, 757322 Woodlands - Tel:	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]	
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/05/2019]	
Driver/Custodian (Insured):	LEE KEOW CHIN (/ Female) , NRIC: S1201750B Email:	
Adj Asg. Remarks:	to contact Ms Lynn at 9459 2885 to arrange for pre repair inspection. No SJE. thank you.	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/05/2019 10:23
Date Of Accident	15/05/2019 13:50
Exact Location Of Accident	SERANGOON ROAD TOWARDS MACPHERSON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC7304H
Insured/Policyholder	
Name Of Registered Owner	TAN MEI LING (CHEN MEILING)
NRIC No	S8312007Z
Email Address	KRISCIA83@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-84448817
Alternative Phone No	OTHERS-84448817

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA-1.4 TSI 1623Q5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102921741
Cover Note Number	

Driver

Name of Driver	TONG WAI SENG JAVIER
NRIC No	S7925220D
Date Of Birth	21/08/1979
Occupation	OUTDOOR
Date Of Driving Pass	17/09/2008
Driving Experience	10 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-87827837
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	APT BLK 8 LORONG 7 TOA PAYOH #03-295
Postcode	310008
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : TAN MEI LING GENDER: : FEMALE
Passenger 2	NAME: : TONG XIN CI GERMAINE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TOA PAYOH CENTRAL
Police Station Address	ROAD: 93 TOA PAYOH CENTRAL , POSTCODE: 319194 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKH688T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE KEOW CHIN

NRIC/Passport Number	S1201750B
Contact Number	91188818
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TAN MEI LING
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SMC7304H
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	APT BLK 8 LORONG 7 TOA PAYOH #03-295
Postcode	310008

DETAILS OF INJURED PERSON 2

Name	TONG WAI SENG ZAVIER
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SMC7304H
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	APT BLK 8 LORONG 7 TOA PAYOH #03-295
Postcode	310008

DETAILS OF INJURED PERSON 3


Name	TONG XIN CI GERMAINE
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SMC7304H
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	APT BLK 8 LORONG 7 TOA PAYOH #03-295
Postcode	310008

Accident Sketch Plan

SKETCH PLAN

Veh A: SML 7304H

B: SKH 688T




Serangoon Rd


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was driving along Serangoon Rd toward Upper Serangoon Rd in front vehicle had stop so I also stop but suddenly Veh B, (SKH 688T) hit my car rear portion. My family suffer pain. we will go to see doctor.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:



Scanned with
CamScanner

Police Report



**SINGAPORE
POLICE FORCE**



Police Station Of Origin
Toa Payoh N.P.C.
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

Report No: T201905150227

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/05/2019 23:11
Video Report No:
Station Diary No: 198

Informant's Particulars

Name of Informant TONG WAI SENG ZAVIER		Address APT BLK 8 LORONG 7 TOA PAYOH #03-295 SINGAPORE 310008	
ID Type / ID No NRIC NO / S7925220D		Contact No. Home/Office Mobile: 87827837	
Nationality SINGAPORE CITIZEN		Email	
Sex Male	Age 39	Date of Birth 21/08/1979	Type of Informant Driver
Race Chinese		Language	Institution / School Name
Occupation HOME APPLIANCES SALESMAN		Driving Licence Information Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident	Injury Others	Drink Drive No	Date/Time of Accident 15/05/2019 13:50	Type of Location Straight Road
Location: Along Road 1 SERANGOON ROAD				
SERANGOON ROAD TOWARDS MACPHERSON ROAD				
Weather: Clear		Road Surface Dry	Road Speed Limit	
Traffic Flow One Way		Traffic Control Traffic Light - Working	Traffic Volume Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance No


Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKH688T	Car	BMW	X5 XDRIVE35i 3.0 AT 4WD 5DR GAS/D NAV SR		Slightly Damaged	0
SMC7304H	Car	VOLKSWAGO N	JETTA 1.4 TSI AT 1K23Q5 MX	Black	Seriously Damaged	2

Police Report



**SINGAPORE
POLICE FORCE**



120100615/2227

2 of 4

Police Station Of Origin
Toa Payoh N.P.C.
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

Report No: 120100615/2227

CONTINUATION OF REPORT

Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: Nil

Use of Pedestrian Crossing: NA

Driver

Name: LEE KEOW CHIN

ID No: S1201750B

Related Vehicle: SKH588T (Car)

Contact No: 91188818

Hospital/Clinic: NIL

Class of Driving Licence & Expiry Date: Class: NIL
Date of Expiry: NIL

Date Treatment: NIL

Date Discharge: NIL

No. of Days granted Medical Leave: NIL

Degree of Injury: NIL

Driver

Name: TONG WAI SENG ZAVIER

ID No: S7925220D

Related Vehicle: SMC7304H (Car)

Contact No: 87827837

Hospital/Clinic: ACCESS MEDICAL KIM KEAT

Class of Driving Licence & Expiry Date: Class: 3
Date of Expiry: NIL

Date Treatment: NIL

Date Discharge: NIL

No. of Days granted Medical Leave: 03

Degree of Injury: Slight

Passenger

Name: TAN MEI LING

ID No: S8312007Z

Related Vehicle: SMC7304H (Car)

Contact No: 84448817

Hospital/Clinic: ACCESS MEDICAL KIM KEAT

Class of Driving Licence & Expiry Date: Class: NIL
Date of Expiry: NIL

Date Treatment: NIL

Date Discharge: NIL

No. of Days granted Medical Leave: 03

Degree of Injury: Slight

Brief Details:

On 15/05/2019 at about 1350hrs, I was driving my vehicle (SMC7304H) along Serangoon Road with my wife and daughter as my passengers. Traffic was slow moving at that point of time and I had stopped behind a van.

Out of a sudden, I felt an impact from the rear of my car. I then alighted my vehicle and made a check and discovered that another car (SKH588T) had hit onto my vehicle. I wish to state that there were no visible injuries to me and my wife at this point of time. However, I made a check on my daughter and discovered that she had slight redness on her right rib area.

Police Report



SINGAPORE
POLICE FORCE



T/20190515/2227

3 of 4

Report No. T/20190515/2227

Police Station Of Origin:

Toa Payoh N.P.C.

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No. 1800-2519999

CONTINUATION OF REPORT

I then talked to the other party and we exchanged particulars with each other. Subsequently, we agreed to settle the matter with our respective insurance companies and left the scene. I do not have any camera footage of the incident.

On 15/05/2019 at about 1900hrs, my wife and myself went to the clinic and received 3 days of medical leave.

I am lodging this report for insurance claiming purposes.

Police Report



SINGAPORE
POLICE FORCE



Police Station Of Origin
Tua Payoh N.P.C.
23 Tua Payoh Central #01-02 Tua Payoh
Community Building SINGAPORE 319154
Tel No. 1800-2519999

Report No. T050625000000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474865 using the report number as reference.

Signature Of Officer Recording The Report

Sgt 2 MUHAMMAD NOOR HAKAL BIN U
MUHAMMAD

Signature Of Informant

[Signature]

Signature Of Interpreter

Not applicable

Date/Time

15/05/2019 23:15

Officer In Charge Of Case

SP / ASST /
Sr Staff Sgt MUHAMMAD ZULFAZRI BIN
ABDULLAH

Contact No. 65475204

Authentication Stamp
SP/AS

Classification Of Case

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2007Z
Vehicle Details	
Vehicle No.:	SMC7304H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	16 May 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 1.4 TSI AT 1K23Q5 MX
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	CAV180027
Chassis No.:	WVWZZZ1KZAM133130
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$22,085.00
Original Registration Date:	05 Aug 2010
First Registration Date:	05 Aug 2010
Transfer Count:	2
Actual ARF Paid:	\$22,085.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Aug 2020
PARF Rebate Amount:	\$12,146.00
Intended COE Rebate Details	
COE Expiry Date:	04 Aug 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$36,162.00
COE Rebate Amount:	\$4,403.00
Total Rebate Amount:	\$16,549.00

The information contained herein is correct as at 16 May 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd
Main	22 May 2019		22 May 2019 11:59 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt	
						Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	ZHANG NAN, ID: S8262734J		
Main Claimant:	TAN MEI LING (CHEN MEILING), ID: S8312007Z		
Vehicle Reg. No.:	SMC7304H	Date of Loss:	15/05/2019 13:00 - :59 [105 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D202178C02	Policy/Cover Note No.:	DMPCSN30157619000 (Comprehensive)
Vehicle Reg. No. (Insured):	SKH688T	Policy No. (Claimant):	S102921741
		Excess:	S\$0.00
Repairer:	Hendon Automotive Pte Ltd (HQ) 280 Woodlands Industrial Park E5, #01-19 Harvest @ Woodlands, 757322 Woodlands - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 31/05/2019]		
Driver/Custodian (Insured):	LEE KEOW CHIN (/ Female) , NRIC: S1201750B Email:		
Adj Asg. Remarks:	to contact Ms Lynn at 9459 2885 to arrange for pre repair inspection. No SJE. thank you.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents




***SMC7304H (SNM19D202178C02)**
[SKH688T]
TP
TAN MEI LING (CHEN MEILING)
May 15 2019 1:00PM
[ZHANG NAN]
Hendon Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser































Assessment Reports




































1 per page

No	Finalized On	Insmart Auto Care Pte Ltd (HQ)	Thumbnail	Print
1	16/05/19 11:48	Accident Statement	 Load HTM	
2	17/05/19 10:42	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>
3	17/05/19 10:47	Accident Statement Addm. #1	 Load HTM	




Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
2	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
3	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
4	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
5	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
6	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
7	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
8	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
9	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
10	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
11	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
12	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
13	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
14	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
15	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
16	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
17	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
18	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
19	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
20	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
21	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
22	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
23	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
24	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Insmart Auto Care Pte Ltd (HQ)	Thumbnail	Print
31	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	06/06/19 16:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
45	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
46	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
47	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
48	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
49	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
50	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
51	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
52	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
53	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
54	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
55	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
56	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
57	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
58	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
59	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
60	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
61	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
62	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
63	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
64	06/06/19 17:15	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/05/19 11:58	INSK SKH688T GIA REPORT	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Insmart Auto Care Pte Ltd (HQ)	Thumbnail	Print
1	16/05/19 11:48	Accident Statement	 Load HTM	
2	17/05/19 10:42	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>
3	17/05/19 10:47	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>

Documents Checklist

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_docview&domainid=1&corole=4&objid=825192&extid=304484&... 3/3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119008967/NCD3S2

Date: 25/06/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30157619000
Claimant Vehicle No :	SMC7304H	Insured Vehicle No :	SKH688T
Date of Loss:	15/05/2019	Nature of Claim:	TP
		Claim No:	SNM19D202178C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC7304H	Engine No:	CAV180027
Make & Model:	VOLKSWAGEN JETTA, 1.4 TSI 1623Q5 (A)	Chassis No:	WVWZZZ1KZAM133130
Reg. Date:	05/08/2010 (Man. Year: 2010)	Odometer:	153404 km
Colour:	Black		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	22/05/2019	
Date Inspected:	22/05/2019 Inspected At:	Hendon Automotive Pte Ltd (HQ) 280 Woodlands Industrial Park E5, #01-19 Harvest @ Woodlands Singapore 757322
Estimated Period of Repair:	6.0 days	

Adjuster: Muhammad Nazril Bin Abdullah

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Jun 2019)

Parts: 143 VOLKSWAGEN JETTA 1.4 TSI 1623Q5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMC7304H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the
END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >