V 0 -	Irm Tan His Ping CTI	NT (Office)
	01	Dete/Time: 22-5-19 10 460.14
Estimated Co		Bill to:
To Inspect V	TTP RESIDD RESIEVAINVIMVICS	Insured: SJ 1 6557 Y
at Workshop	als hi Sheng hutomobile	Tel: 91474552
of NO 18	londan Loop # 01-18 BIK K	
Policy No:	MPCSN30174119000	Claim No: SNM 1910 2021 35(0) I
Sum Insured:		Excess:
Make of Veh (Client's Recor		D.O.A 18.5.19
CA / REV	REP. / REV 24 HRS	H.O.D. Endorsement:
	Action/Instruction Estimate ()	
Date/Time		
Date/Time	SAK 70945- CE41 ASMIBO1821	15/21) b3 b:04-13/10/2018
Date/Time	STT 65574 - x	15/21)63 0:04-13/10/2018

REF:

2360A

...CLAIM SUBFOLDER...(New Assignment)

AIM SU	BFOLDER TRAC	KING					
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 May 2019		22 May 2019 10:46 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Doc	cuments	Show All
CLAIM SUBFOLDER DETAILS	THE RESERVE OF THE PERSON NAMED IN COLUMN	David or to his support to the support of the suppo		[Created b	y insurer]
Insured:	JUBILICIOUS PTE LTD, Co.	Reg. No.: 201509772C			
Main Claimant:	QUEK WEI KIAT, ID: S8532	360A			
Vehicle Reg. No.:	SGK7094S	Date of Loss:			13:00 - :59 s and 26 Days From te (Man Yr)]
Claim Type:	TP / SNM19D202233C02	Policy/Cover Note	No.:	(Compreher	
Vehicle Reg. No. (Insured):	SJT6557Y	Policy No. (Claima	nt):		
		Excess:	30	S\$0.00	
Repairer:	Li Sheng Automobile Trading 91474552				
Repairer: Handling Insurer:	91474552 China Taiping Insurance (Sir Ping - 638986192]	ngapore) Pte. Ltd. (H	Q) - Tel: 6389 61	11 [Handle	ed by Irene Tay Hu
100 C VII -	91474552 China Taiping Insurance (Si	ngapore) Pte. Ltd. (H	Q) - Tel: 6389 61	11 [Handle	ed by Irene Tay Hui
Handling Insurer:	91474552 China Taiping Insurance (Sir Ping - 638986192] LKK Auto Consultants Pte Lt	ngapore) Pte. Ltd. (H	Q) - Tel: 6389 61 i1 [Final Rpt	11 [Handle	ed by Irene Tay Hui
Handling Insurer: Adjuster:	91474552 China Taiping Insurance (Sir Ping - 638986192] LKK Auto Consultants Pte Lt	ngapore) Pte. Ltd. (H	Q) - Tel: 6389 61 i1 [Final Rpt	11 [Handlet due 31/0]	ed by Irene Tay Hui 5/2019]
Handling Insurer: Adjuster: ASSOCIATED MAIL RECEIVED There are no mail for this case.	91474552 China Taiping Insurance (Sir Ping - 638986192] LKK Auto Consultants Pte Lt	ngapore) Pte. Ltd. (H	Q) - Tel: 6389 61 51 [Final Rpt	11 [Handle t due 31/0! lew All	ed by Irene Tay Hui 5/2019] Compose Case Mail
Handling Insurer: Adjuster: ASSOCIATED MAIL RECEIVED There are no mail for this case.	91474552 China Taiping Insurance (Sir Ping - 638986192) LKK Auto Consultants Pte Lt	ngapore) Pte. Ltd. (H d (HQ) - Tel: 6256-356	Q) - Tel: 6389 61 51 [Final Rpt Vi	11 [Handlet due 31/0]	ed by Irene Tay Hu i 5/2019] Compose Case Mail
Handling Insurer: Adjuster: ASSOCIATED MAIL RECEIVED There are no mail for this case.	91474552 China Taiping Insurance (Sir Ping - 638986192) LKK Auto Consultants Pte Lt	ngapore) Pte. Ltd. (H	Q) - Tel: 6389 61 51 [Final Rpt Vi	11 [Handlet due 31/0]	ed by Irene Tay Hui 5/2019] Compose Case Mail

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Thursday, 30 May 2019 6:00 PM

To:

Khar Kian Toh; SUR; Rasul (LKKAuto) 'lishengauto@yahoo.com.sg'

Cc: Subject:

RE: FINALIZE SGK7094S-Accident involved with vehicle SGK7094S (OUR INSURED) and SJT6557Y(TP) on 18/05/2019 along PIE TOWARDS RUAS BEFORE CTE EXIT

Dear Sir,

Noted with thanks.

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Khar Kian Toh <tohkk_90@hotmail.com>

Sent: Thursday, 30 May 2019 5:45 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Rasul (LKKAuto)

<Rasul@lkkauto.com>

Cc: 'lishengauto@yahoo.com.sg' <lishengauto@yahoo.com.sg>

Subject: RE: FINALIZE SGK7094S-Accident involved with vehicle SGK7094S (OUR INSURED) and SJT6557Y(TP) on

18/05/2019 along PIE TOWARDS RUAS BEFORE CTE EXIT

Hi All,

Confirm Lump Sum as \$1200 @3 working day.

Thanks.

Best Regards, Toh Khar Kian

Li Sheng Automobile Trading

18 Pandan Loop #01-18 Singapore 128236 (Blk K)

Mobile: (65) 83987469 | Fax: 67744885

Email: tohkk 90@hotmail.com

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Thursday, 30 May, 2019 4:37 PM

To: Khar Kian Toh < tohkk 90@hotmail.com >; SUR < sur@lkkauto.com >; Rasul (LKKAuto) < Rasul@lkkauto.com >

Cc: 'lishengauto@yahoo.com.sg' < lishengauto@yahoo.com.sg >

Subject: RE: FINALIZE SGK7094S-Accident involved with vehicle SGK7094S (OUR INSURED) and SJT6557Y(TP) on

18/05/2019 along PIE TOWARDS RUAS BEFORE CTE EXIT

Dear Sir,

WITHOUT PREJUDICE

Offer Lump Sum \$1200/- @ 3 working days.

Please check and confirm

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Khar Kian Toh < tohkk 90@hotmail.com > Sent: Wednesday, 29 May 2019 12:38 PM

To: SUR < sur@lkkauto.com >; Rasul (LKKAuto) < Rasul@lkkauto.com >

Cc: 'lishengauto@yahoo.com.sg' < lishengauto@yahoo.com.sg>

Subject: FINALIZE SGK7094S-Accident involved with vehicle SGK7094S (OUR INSURED) and SJT6557Y(TP) on

18/05/2019 along PIE TOWARDS RUAS BEFORE CTE EXIT

Dear All,

The above attachment is the after paint photo, and finalize estimate.

Kindly Assist to Finalize for vehicle SGK7094S lump sum \$1217.00 with 3 repair days.

Please check and revert.

Thanks.

Best Regards, Toh Khar Kian

Li Sheng Automobile Trading

18 Pandan Loop #01-18 Singapore 128236 (Blk K)

Mobile: (65) 83987469 | Fax: 67744885

Email: tohkk 90@hotmail.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	2360A
Vehicle No.:	SGK7094S
Vehicle to be Exported:	No
Intended Deregistration Date:	23 May 2019
Vehicle Make:	HONDA
Vehicle Model:	ACCORD 2.0 A
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	K20A6043736
Chassis No.:	CL73203223
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$23,375.00
Original Registration Date:	22 Aug 2006
First Registration Date:	22 Aug 2006
Transfer Count:	2
Actual ARF Paid: Intended PARF Rebate Details	\$25,713.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	1
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	31 May 2021
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$23,024.00
COE Rebate Amount:	\$9,308.00
Total Rebate Amount: Message	\$9,308.00

The information contained herein is correct as at 23 May 2019

reaches its statutory lifespan (if applicable), whichever is earlier.

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.		
	ACCIDENT STATEMENT	
Date Of Report	21/05/2019 10:51	
Date Of Accident	18/05/2019 13:20	
Exact Location Of Accident	ALONG PIE TOWARDS TUAS BEFORE CTE EXIT	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGK7094S	
Insured/Policyholder		
Name Of Registered Owner	QUEK WEI KIAT	
NRIC No	S8532360A	
Email Address	ARISTOGAVINQUEK@GMAIL.COM	

Mobile Phone No (LOCAL) +65-82455944

Alternative Phone No OFFICE-NOPHONE

Vehicle Particulars

Manufacturer HONDA

Model ACCORD-2.0 I-VTEC (A)

Exact Purpose for which vehicle was being used at

time of accident

TRAVEL TO WORKING

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY PRIVATE CAR

Vehicle Category

Insurance Company

Name of Insurance Company

AXA INSURANCE PTE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

GA394057

Cover Note Number

Driver

 Name of Driver
 QUEK WEI KIAT

 NRIC No
 \$8532360A

 Date Of Birth
 27/09/1985

 Occupation
 INDOOR

 Date Of Driving Pass
 20/02/2014

Driving Experience 5 YEARS AND 2 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-82455944

Fax Number

Contact Number OFFICE-NOPHONE

EMail Address ARISTOGAVINQUEK@GMAIL.COM

Address

BLK 38C BENDEMEER ROAD

#12-850

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

.

-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

KOLAM AYER NEIGHBOURHOOD POLICE POST

Police Station Address

ROAD: BLK 72 GEYLANG BAHRU #01-3038, POSTCODE: 330072,

COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-2969999 - FAX NO: 62937659

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJT6557Y

Vehicle Make/Model/Colour

HYUNDAI/AVANTE/SILVER

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

JAMSHEED MAJEED

NRIC/Passport Number

G6413229L

Contact Number

96259059

Address

Postcode

Insurance Company Name

Page 2 of 16

Nature Of Damage

No. Of Passenger (Including Driver)

Name QUEK WEI KIAT Approximate Age Injuries Sustain Injured person in which vehicle? SGK7094S Were seat belts worn? YES Was this injured conveyed to hospital by ambulance? Address Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the socident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorized Orlyer.
- Information provided must be as <u>invitiful</u> and <u>noturate as possible</u>. Any wifful misrepresentation or withholding of material facts may allow insurance companies in <u>repudiate policy liability</u>.
- The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reportlysumay be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers to the GIA Records Mangement Centre establised by the General Insurance Association of Singapore (GIA) for erchiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforecald.
- 8 Consent under the Personal Data Protection Act (PDPA) | understand, acknowledge, agree and consent that
- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers iswyses/law times, the Monetary Authority of Singapore and any relevant government agancy/suthority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
 - (ii) Investigating the accident and/or my claims,
 - (6) carrying out and/or dealing with my instructions or responding to any enquiries by me.
 - (iv) administrating my claims (including the matting of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(a) who have insured vehicle(a) involved in this socident and the Insurera' lawyers/law firms, maylare permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (Including their Iswyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detention, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insureres and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as researchly required for the purposes stated, or
 - (ii) for complying with requirments under any regulations, laws or court orders.

Policyholder's Signature

Dog & Time

MAJULA

Driver's Signature (if driver is not the policyholosi)

Date & Time

CONFORTURE CAS ENGINEERING PTE LTD EXTERNAL BIGGRESS OR, PANCAR SHANCH NAME & EGRACIAN

DESIGNATION:___

Peporting Centre Personpel's Signatura Name: (La Mac F19

HARC / FAT 10: 6) 60 (1 71 10

Page

Sketch Plan #2

		(D)	>		
A-SGK-7094	1-5				
B-SJT-6557	1->			Part II	
		Szemely (A)	117		
SCRIBE CIRCUMSTANC	ES OF THE ACCIDE	NT			
Refer to P	Police Repo	of Report No	- 7/20190	5-18/2160	
					_
PORTANT NOTE					
PORTANT NOTE der General Condition	Conduct of Claim of	the Motor Policy, you have to	o decide within 21 day	rs of occurrence	
der General Condition -	Conduct of Claim of her or not to claim unc	the Motor Policy, you have to der the policy. Please check	o decide within 21 day your policy for more in	s of occurrence	
der General Condition – (discovery of damage wheth	her or not to claim und	der the policy. Please check	your policy for more in	formation.	
der General Condition – (Recovery of damage wheth CLARATION	her or not to claim und	der the policy. Please check	your policy for more in	formation.	
der General Condition – (Siscovery of damage wheti	her or not to claim und	der the policy. Please check	your policy for more in	COMMERCIAL STATE OF THE LESS O	





Certificate number

Chassis number

Engine number

AXA Insurance Pte Ltd

1800 880 4888 (Within Singapore) (65) 6880 4888 (International)

(65) 6880 4740

customer.care@axa.com.sg

www.axa.com.sg

account number 09116

GA394057/1

CL73203223

K20A6043736

Certificate of Insurance

cles (Third Party Rieks and Compensation (4c) (Chapter 189) - Motor Vehicles (Third Party Ricks and Compensation Rules 1960, Poad Transport Act 1997 (Matausia) Motor vehicles (Third Party Risks) Rules 1959 (Malaysia)

Policy details

Policyholder name

Cover Plan name

NCD applicable Vehicle registration number Period of Insurance

Finance loan company

OUEK WEI KIAT Comprehensire Essential 0%

SGK70945

from 29/08/2018 to 28/08/2019 (both dates inclusive) TECK WEI CREDIT PTE LTD

Persons or classes of persons entitled to drive*

ial The Policyholder

(b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

Limitation as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business

The pointy does not cover - use for hire or reward, racing pace-making reliability trial speed testing the carriage of goods other than samples in connection with any triade or business or use for any purpose in connection with motor trade, or when the Motor Car, whether stationary in use or otherwise is in or on a racing track circuit route course or any other roads by whatever name called that are typically used for racing pace-mailing or such similar purposes

Unividuals rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings

EXCESS

Basic Own Damage Ercess Windscreen Ficess

5GD 700 DO SGD 100 00

An Additional Excess is applicable as follows

- 1 S\$500 for unnamed Authorised Driver
- 2 S\$500 for declared Young and Inexperienced Driver
- 3 \$\$5 000 for undeclared Young and Inexperienced Drivers. This additional excess is reduced to \$\$2,500 if You have chosen AXA Premium Workshops

Additional clauses & endorsements to your policy

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act 1987 (Malaysia)

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor valuate they must surrender the Certificate of Insurance and the Policy to the insurance company if the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Fasure to comply with the obligation is an offence under the Motor Vehicle (Tring Perty Richs and Compensation Act (Ceo. 189)

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there adult be no liability under the policy renewal certificate endorsement etc.

1 of 3

POLICE REPORT Pg. 1





Police Station Of Origin:

Kolam Ayer NPP 72 Geylang Bahru #01-3038 SINGAPORE 330072

Tel No: 1800-2969999

REPORT OF A TRAFFIC ACCIDENT

112010001012100
. 1 of 3
Report No. T/20190518/2160

	ate/Time Report Made: 8/05/2019 21:50		Vide Report No.:	Station Diary No.: 34
Informa	nt's Partic	ulars	Constitution of the Constitution	PER SERVICE SERVICES
	f Informant: VEI KIAT		Address: APT BLK 38C BENDEMEER 333038	ROAD #12-850 SINGAPORE
	/ ID No.: O / S853236	60A	Contact No.: Home/Office:	Mobile: 82455944
National SINGAP	ity: ORE CITIZ	EN	Email:	
Sex: Male	Age: 33	Date of Birth: 27/09/1985	Type of Informant: Driver	ay =t=
200 March 200 Ma			Language: English	Institution / School Name:
Occupat RENOV		NTRACTOR	Driving Licence Information: Class: 3A	Date of Expiry:

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 18/05/2019 13:20	Type of Location Straight Road
towards Tuas Weather:	EXPRESSWAY	Road Surface:		Road Speed Limit:
Clear		Dry		80 Km/h
		Traffic Control:		Traffic Volume:
Traffic Flow: Dual Carriage	Way	Not Controlled		Moderate

Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SGK7094S	Car	HONDA	ACCORD 2.0 A	Black	Slightly Damaged	0
SJT6557Y	Car	HYUNDAI	AVANTE 1.6 AT	Silver	Slightly Damaged	0

	ehicle Insurance	the scored activities and attack of		
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SGK7094S	AXA INSURANCE SINGAPORE PTE	GA394057	29/08/2018	28/08/2019

POLICE REPORT Pg. 1





Police Station Of Origin: Kolam Ayer NPP 72 Geylang Bahru #01-3038 SINGAPORE 330072

2 of 3 Report No. T/20190518/2160

Tel No: 1800-2969999

CONTINUATION OF REPORT

Any Pedestrian II	rvolved: No			***************************************		
No. of Pedestriar	Technique of the second		Use of Peo	lestriar	Cross	sina: NA
Driver		REAL SOCIE	F-1965613	1444	BANKSH BANKSH	
Name	QUEK WEI KIAT			ID No.		S8532360A
Related Vehicle	SGK7094S (Car)			Contact No.		82455944
Hospital/Clinic	SIMS DRIVE MEDICAL CLINIC		TO A STATE OF THE PARTY OF THE		Class: 3A Date of Expiry: NIL	
Date Treatment	18/05/2019		Date Disch	narge	18/05	/2019
No. of Days gran	ted Medical Leave 03	3	Degree of	Injury	Slight	
Driver					33.00	Land delication of the second
Name	Jamsheed Majeed	10.00		ID No		G6413229L
Related Vehicle	SJT6557Y (Car)			Contact No.		96259059
Hospital/Clinic	NIL			Class Driving Licent Expiry	g ce &	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Disch	narge	NIL	
No. of Days gran	ted Medical Leave N	IIL I	Degree of	Injury	NIL	

Brief Details.

I was driving my car SGK7094S at along Pan Island Expressway towards Tuas. I then filter to the left most lane as I wanted to exit at CTE exit towards Woodlands. My car was stationery when I heard a loud bang on my rear. I then realized that one car SJT6557Y had banged on the rear of my car. The other driver was not injured. His car was slightly scratched on the front bumper. My rear bumper was slightly dented and scratches. We exchanged particulars.

On the same day, at about 2030hrs I felt pain on my neck and back. I then went to see a doctor at Sims Drive Medical . I was given three (3) days medical leave. When I viewed the rear camera of my In-car camera, I realized that the SJT6557Y had filter to the left of PIE and banged on my rear of my car SGK7094S. That's all.

POLICE REPORT Pg. 1





Police Station Of Origin: Kolam Ayer NPP 72 Geylang Bahru #01-3038 SINGAPORE 330072 Tel No: 1800-2969999

3 of 3

Report No. T/20190518/2160

CONTINUATION OF REPORT

C		5 - L		lan
-	ке	Ю	1 1	ıan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.


Signature Of Officer Recording The Report: A / Sr Staff Sgt MUNAWIR BIN MOHAMMAD TAHIR	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 18/05/2019 21:50
Officer In Charge Of Case: TP / AEIT / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Stamp NP168	de roce.

INSURED IC AND LICENCE Pg. 1



9







Estimate

CHINA TAIPING



Li Sheng Automobile Trading

appl

			List Pric		Remarks
	REAR BUMPER 06		5	950.20	
11	REAR BUMPER RETAINER NEC / RH		5	58.00	
10	REAR BUMPER CLIP 14 /			60.00	
				REPAIR	
130	REAR RHS TAIL LAMP 7 XSUC		5	210.20	
		TOTAL		1,278.40	
		LESS 20%;	5		
			5	1,022.72	

Qty	Description		
	REVERSE SENSOR 7 X50C	\$ 180	

Tala			51	
- A 1/1/AL				

Qty.			Remark
1.00	LABOUR FOR REPAIR ON AFFECTED AREA	S	200
1.00			400
	CHECK WIRING	S	60 30
	LABOUR TO REPALCE REVERSE SENSOR	5	160
	APPLY RUST PROOF ON AFFECTED PANEL		100.00 XAA
		S	50.00 X n A
	TOTAL	· \$	2,250.00

SUBTOTAL: 5

3453.72

Estimate prepared by: TOH KHAR KIAN

- . To remove y botan, after spray painting
- To display damaged part(v) during resurvey.
- Parts prints are in elect to confirmation
 Third party stoney is on a "Worthit Projudge" hasts.
- No illegal modication(s) is allowed.
- . Supplementary item(s) must be resurreyed and

Rasul

Ap 200 100 68

3 days

45

22/05/19 @ 1640

Resy after repair

Estimate



Li	Sheng	Automobile	Trading
----	-------	------------	---------

Please arrange to survey at

Blk K, Pandan I oop #01-16 /18 S(128236)

Date:

21/5/2019

Vehicle No:

SGK7094S

Model:

HONDA ACCORD

Date of loss:

3/4/2019

Your Ref Vehicle No:

CHINA TAIPING

(SJT6557Y-TP)

Our ref:

List Price

LSA290TJS

Remarks

Year:

2006

(1pd)

Otv	Description		List Pric	e de la companya de l	Remarks
1.00	REAR BUMPER 06		5	950.20	
200	REAR BUMPER RETAINER ALL / RA		5	58.00	
10.00	REAR BUMPER CLIP		\$	60.00	
1.00	REAR RHS FENDER			REPAIR	
1.00	REAR RHS TAIL LAMP		\$	210.20	
100000		TOTAL:	S	1,278.40	1034.50
		LESS 20%:	\$	255.68	207.84
		70.77	\$	1,022.72	831.36

SPECIAL NEIT ITEMS

Qty	Description	Wednesday who was	Unit Price	Remarks
-	REVERSE SENSOR	1	s	180,00
2.00	REVERSE SENSOR		8	Carlot Control (Carlot Control

Total

\$180.00

Oty	Description	Unit Price	
1.00	LABOUR FOR REPAIR ON AFFECTED AREA	\$	1,000.00 200 900.00 400
1.00	SPRAY PAINT ON AFFECTED AREA	\$	908:00 400
1.00	CHECK WIRING	\$	8000 6 30
1.00	LABOUR TO REPALCE REVERSE SENSOR	\$	120.00 60
1.00	APPLY RUST PROOF ON AFFECTED PANEL	\$	100.00 🗙
1.00	SUNDARIES	\$	50,00 🗶
		TOTAL: \$	2,250.00 \$690

SUBTOTAL: \$

Estimate prepared by: TOH KHAR KIAN

Telephone: 83987469

tohkk 90@hotmail.com

\$1521.36

-20% (US) 3457.72

Fasul = \$1217.00 pt Hp 20010068 3 days 45 22/05/19 @1640 Reany after rapair

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI19008972/R1VD3N2

Date:

03/06/2019

REFERENCE

Handling Insurer:

China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMPCSN30174119000

Claimant

Vehicle No:

SGK7094S

Insured Vehicle No:

SJT6557Y

Date of Loss:

18/05/2019

Nature of Claim:

TP

Claim No:

SNM19D202233C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Make & Model:

HONDA ACCORD, 2.0 (A)

22/08/2006 (Man. Year: 2006)

Engine No: Chassis No: Odometer:

K20A6043736 CL73203223

154662 km

Reg. Date: Colour:

Black

SGK7094S

Engine Capacity: Market Value/New Car 1998 cc N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

215/45ZR17

Rear Tyre Size:

215/45ZR17

Front Tyre Size: Front Left Side:

Minerva 6 mm

Rear Left Side:

Minerva 6 mm

Front Right Side:

Minerva 6 mm

Rear Right Side:

Minerva 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 1,252.72 0.00	Adjuster's 831.36 0.00	Difference 421.36 0.00	Diff % 33.64
Labour Paintwork Labour	2,200.00	690.00	1,510.00	68.64
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$) Approved Total (Overridden) (S\$)	3,452.72	1,521.36 1,200.00	1,931.36	55.94
Nett Amount (S\$)	3,452.72	1,200.00	2,252.72	65.24

INSPECTION

Date of Assignment:

22/05/2019

Date Inspected:

22/05/2019 Inspected At:

Li Sheng Automobile Trading (HQ) No. 18 Pandan Loop #01-18 Blk K

Singapore 128236

Estimated Period of Repair:

3.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 03 Jun 2019)

Parts:

143

HONDA ACCORD 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGK7094S)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	950.20 FL	*950.20 FL
2	1		*REAR BUMPER RETAINER	O/s Necessary	58.00 FL	*29.00 FL
3	10 1		*REAR BUMPER CLIP *REAR RHS FENDER (NPA)	Necessary Repair	60.00 FL 0.00 FL	*60.00 FL *- FL
5 6	1 2		*REAR RHS TAIL LAMP *REVERSE SENSOR	Serviceable Serviceable	210.20 FL 180.00 FS	*- FL *- FS
7 F=Fra	1 inchise	part. S=SpcNe	*SUNDARIES tt. L=ListItemDisc.	Not Necessary	50.00 FS	*- FS
				Sub Total (S\$)	1,508.40	1,039.20
			- List Item Discount on I	L Items 20.00/20.00% (S\$)	255.68	207.84
				Total Parts (S\$)	1,252.72	831.36
			Report was unsubmitt	ted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR FOR REPAIR ON AFFECTED AREA	New	1,000.00	200.00
2	SPRAY PAINT ON AFFECTED AREA	New	900.00	400.00
3	CHECK WIRING	New	80.00	30.00
4	LABOUR TO REPLACE REVERSE SENSOR	New	120.00	60.00
5	APPLY RUST PROOF ON AFFECTED PANEL	New	100.00	0.00
	Gross I	abour Cost (S\$)	2,200.00	690.00
	Report was unsubmitted	d during this print-out.		

< END OF ESTIMATES >