SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	21/05/2019 13:36
Date Of Accident	17/05/2019 21:15
Exact Location Of Accident	BAYFRONT AVENUE
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHB9875C
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666
Vehicle Particulars	
Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
Driver	
Name of Driver	SIM THIAM HOCK
NRIC No	S7332367C

NAME OF Driver

NRIC No

S7332367C

Date Of Birth

Occupation

OUTDOOR

Date Of Driving Pass

23/09/1993

Driving Experience 25 YEARS AND 7 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-94893729

Fax Number

Contact Number

EMail Address NOEMAIL

BLK 4 TECK WHYE AVENUE Address

#09-220

Postcode 680004

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - RELIEF

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident SIDE SWIPE Weather Conditions **CLEAR** Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

involved in the accident

NO

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

NO

YES

NO

4

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Passenger 1

NAME: : UNKNOWN

GENDER: : FEMALE

Passenger 2 NAME: : UNKNOWN

> GENDER: : FEMALE

Passenger 3 NAME: : UNKNOWN

> GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name BISHAN NEIGHBOURHOOD POLICE CENTRE

ROAD: 20 BISHAN STREET 23, POSTCODE: 579757, COUNTRY: Police Station Address

SINGAPORE

Police Station Contact TEL NO: 1800-5529999 - FAX NO: 65561905

Was notice of intended Prosecution given?

If Yes, against whom?

NO

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT: T/20190518/2022

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHD2707R Vehicle Make/Model/Colour **COMFORT TAXI** **Details Of Properties**

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Page 3 of 15

TAXI

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature Date & Time: Driver's Signature
(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

	5.5 + 2				
	į	٠.			
	DIS	see_	ottach	Poli e	Robert
			. :		
	1		-		
4.004	,				
. 15 A.					
*		.*			
Whose teachers are a second of the second of					
			· · · · · · · · · · · · · · · · · · ·		
			2		

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time:

GIARMC SketchPlanForm_V3

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

POLICE REPORT Pg. 1



Date of Expiry:

Police Station Of Origin: Bishan N.P.C

Occupation: Taxi driver

20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999

1 of 3 Report No. T/20190518/2022

REPORT OF	A TRAFFIC	ACCIDENT	•	•				
Date/Time 18/05/2019		ade:	Vide Report No.:		Station Diary No.: 13			
Informant	s Particul	ars	<u> </u>	941-11-11-11-11-11-11-11-11-11-11-11-11-1	Fall			
Name of In	formant:		Address:	Address:				
SIM THIAN	/I HOCK		APT BLK 4 TECK WHYE AVENUE #09-220 SINGAPORE					
•			680004					
ID Type / II	D No.:		Contact No.:		· · · · · · · · · · · · · · · · · · ·			
NRIC NO / S7332367C			Home/Office:	Mobile: 94	893729			
Nationality			Email:	•	•			
SINGAPO	RE CITIZE	N ·						
Sex:	Age:	Date of Birth:	Type of Informant:					
Male	45	02/09/1973	Driver	,				
Race:			Language:	Institution	/ School Name:			
Chinese			English					

Driving Licence Information:

Class: 3,4,5

General Inform	ation of the Accident		to the in the control of the	11111
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 17/05/2019 21:15	Type of Location: Straight Road
Location: Along Road 1 BAYFRONT AV		** **		4.
Occurred along Weather:	Sheares Link.	Road Surface:		Road Speed Limit:
Clear	•	Dry		Trodu opood Emmi
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume:
Type of Collision Between Movin	on: ng Vehicles - Head To	Side		Anyone conveyed by ambulance: No

Details of V	ehicle İnvolved		4-			ke der e	ladikan
Vehicle No.	Туре	Make	Model	Color	Condition	No of Pa	ssenger
SHB9875C	Car	RENAULT	LATITUDE 2.0L DCI AUTO D/AB 4DR	Red	Slightly Damaged	3	
SHD2707R	Car	ТОУОТА	VELLFIRE HYBRID 7- SEATER 2.5X CVT	White	Slightly Damaged	0	

POLICE REPORT Pg. 1





Police Station Of Origin: Bishan N.P.C

20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999

Report No. T/20190518/2022

CONTINUATION OF REPORT

			C. Lamin		TABLE	品 · (最) 在 市住地 (智) 建筑建筑建筑。
Details of Person		115 - 15 - 15 - 15 - 15 - 15 - 15 - 15		A CONTRACTOR		
Any Pedestrian Involved: No			Use of Pedestrian Crossing; NA			
No. of Pedestrian	s Injured: NIL	Service order	USE OF FED	Collian	U1033	
Driver		Length of Participation		ID No.	\$ 155 SAB	S7332367C
Name	SIM THIAM HOCK			יטו עו.		373323010
	OUD00750 (Cor)			Contac	t No	94593729
Related Vehicle	SHB9875C (Car)			Contac		
Hospital/Clinic	NIL			Class	of	Class: 3,4,5
nospital/Citilic	INIL			Driving		Date of Expiry: NIL
				Licenc	е&	
				Expiry	Date	
Date Treatment	Date Disc		NIL			
No. of Days gran	ted Medical Leave	NIL	Degree of	Injury	NIL	114
Driver	titude til printer end				district (C)	
Name	Unknown Driver			ID No.		NIL
Related Vehicle	SHD2707R (Car)			Conta	ct No.	NIL .
	•			01		Olean NIII
Hospital/Clinic	NIL			Class	-	Class: NIL
				Driving	,	Date of Expiry: NIL
				Licenc		Ì
				Expiry		
Date Treatment	NIL		Date Disc		NIL	
	ted Medical Leave	NIL	Degree of	f injury	NIL_	

Brief Details.

On 17/05/2019 at about 2115hrs, I was turning into Sheares Link in my vehicle(SHB9875C). At this point in time, I observed there to be another vehicle(SHD2707R) which was also turning into Sheares Link on the right side of my vehicle. I observed the other driver to only be looking at the oncoming traffic, and not paying attention to my vehicle, and I thus sounded my car horn. The other driver did not heed my warning, and continued turning into Sheares Link, eventually colliding the right side of his vehicle into the left side of my car. Both of us exited our vehicles to talk, however he refused to provide any personal information, and subsequently drove off. I do not have in car camera. I am lodging this report for police follow up actions.

POLICE REPORT Pg. 1





Police Station Of Origin: Bishan N.P.C 20 Bishan Street 23 SINGAPORE 579757 Tel No: 1800-5529999 3 of 3 Report No. T/20190518/2022

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: E / Sgt 2 LEE QI, THEODORE	Signature Of Informants
Signature Of Interpreter: Not applicable	Date/Time: 18/05/2019 05:01
Officer In Charge Of Case: TP / HRT / SI KALESWARI PALANI Contact No.: 65476902	Classification Of Case:
Authentication Stamp NP168 SINGAPORE POLICE FORCE	SN 061













