(08/11/13)

ASS. REC. BY: Tanfhm | REF LPC

ASSIGNMENT

From: | Date: 27.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMF 243E

at Workshop m/s Cycle & carriage

of 209 Pandan Gardens

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh: 11.00 a.m owner waiting

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S
	X

Bal. or Market Value:

IDAC Accident Rport: | Consistent? : **Yes** or **No**

GIA / PR Seen: | Consistent? : **Yes** or **No**

Est. Repairs: days | Res.: **Yes** or **No**

Lum Sum: % | 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS "rup"

Vehicle: **IN / OUT**

Date: | Person Contacted: Don

Veh No: SMF243E | Yr Regn: 2018, Oct

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer** or

Make: Mitsubishi Attrage | c.c 1193.

Colour: white | A/C: **Insured / Std / NI / NA**

Sp.Reading: 10934 | T/Radio: **Insured / Std / NI / NA**

Eng/No:

C/No: MMBSTA13AJH005787

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or

Brake: **Inorder / Jammed / Leaked / Burnt** or

Modi : **Nil / S/Rim / STD A/Rim** or

Tyre Size: F: 185/55R15

R: 〃

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	27/5/19

Survey held at C&C Pandan Gdns

Des. of Damages : **Frt / Rear / O/S / N/S / U/C / Rooftop** or

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : **Preli. Report**

1) ☐ : **Final Report**

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: ___S + RS, ___SI

Photos

Others

TOTAL