



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 21/05/2019

User ID : BoonChewTay

Section A - Accident Details

Registration Number	SMB1538U
Case Reference Number	BUS/05/19/1025
Registration Date	3/12/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Chang Chuansheng
Type of Accident	Others
Accident Date and Time	10/5/2019 6:00 PM
Accident Reported Date and Time	13/5/2019 11:48 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1538U - RIGHT SIDE TURN SIGNAL DAMAGED FS380G - TP INSURED WITH EQ INSURANCE - LEFT PORTION DAMAGED OUR BUS
Prepared Date and Time	21/5/2019 1:37 PM
Chassis Number	WMAA22ZZXE7002416
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$265.00	\$0.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$133.99	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$398.99	\$0.00
Lump Sum Total	\$400.00	\$0.00
Number of Repair Days	1.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date		
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/05/2019

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$265.00 132.5	
Total Labour	\$265.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Spray Painting & Panel Beating		

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010303	VE	4001B05-LAM141	LAMP,INDICATOR,SIDE: LED (MAN BUS)	1.00	\$186.10	10.00	\$167.49	Replace	✓ CRA
Total					\$186.10		\$167.49		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hwee Jie - LKK

21/5/19

L/S 0.5 days.