



## SMRT Accident Vehicle Repair Estimates

Hsiao fong

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/06/2019


User ID : CatherineLee

### Section A - Accident Details

Registration Number	SMB1538U
Case Reference Number	BUS/05/19/1025
Registration Date	3/12/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Chang Chuansheng
Type of Accident	Others
Accident Date and Time	10/5/2019 6:00 PM
Accident Reported Date and Time	13/5/2019 11:48 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101593
Special Instruction to ARC, if any	SMB1538U - RIGHT SIDE TURN SIGNAL DAMAGED FS380G - TP INSURED WITH EQ INSURANCE - LEFT PORTION DAMAGED OUR BUS
Prepared Date and Time	21/5/2019 1:37 PM
Chassis Number	WMAA22ZZXE7002416
Mileage	
Work Shop	
Repair Completion Date and Time	

L/s \$250/- 0.5 days.

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$265.00	\$132.50
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$133.99	\$133.99
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$398.99	\$266.49
Lump Sum Total	\$400.00	\$250.00
Number of Repair Days	1.0	0.5
Prepared / Adjusted By	Boon Chew Tay	Hwee Jie
ARC / Surveyor Sign Off Date	21/05/2019 1:54 PM	21/05/2019 4:08 PM
Signature		Lkk
Remarks		

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/06/2019

User ID : CatherineLee

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$265.00	\$132.50 ✓
Total Labour	\$265.00	\$132.50

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Spray Painting & Panel Beating		

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010303	VE	4001B05-LAM141	LAMP,INDICATOR,SIDE: LED (MAN BUS)	1.00	\$186.10	10.00	\$167.49	✓ Replace	Replace
Total					\$186.10		\$167.49		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: