

A.S. REC. BY:

REF:

CS/FCI 9009014 / 8sd307

Special Instruction:

Surveyor: Hwee Jie

CWS

ASSIGNMENT (Office)

From (Person):

Joanne Yong

of

FCI

Date/Time:

5.49pm @ 21/5/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 91932

Insured:

SH 8887M

at Workshop m/s

My Car Consultant

Tel:

88668832

of

53 Ubi Ave 1 #01-25

Policy No:

Claim No:

D19C03326MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 17/5/19

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

1.43pm @ 22/5/19

Person Contacted:

Hui Qian

Vehicle: IN/OUT

Date/Time

Action/Instruction

Estimate (✓)

SLE 91932 - NA / INC 191008842 / R3

DOA: 17/5/2019

SH 8887M - NA / INC 191008842 / R3

DOA: 17/5/2019

28/05/19

@ 10:38 am received PA to Joanne Yong via email.

Barrymore Hwa Jia

REF: FCI

ASSIGNMENT

From: Date: 22/5/19
 Estimated Cost:
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SLE 91932
 at Workshop n/s: My Car Consultant
 of 53 ubi Ave 1 # 01-25
 Insured:
 Policy No.:
 Claims No.:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh:



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res.: Yes or No
 Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLE 91932 Yr Regn: 5 Aug 2016
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Hamier CC 1986
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 47149 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: ZSU600083548
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: Nil / ☒ STD / STD A/Rim or
 Tyre Size: F: 225/65 R17
 R: -

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIO / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	17/5/19	D.O.A.	22/5/19
Survey held at <u>My Car</u>			
Des. of Damages: Frt / <input checked="" type="radio"/> Rear / O/S / N/S / U/C / Rooftop or			

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
15/8/19	Finalize confirm \$3500, 4 days (Huiqin) (4 10,607.61 Red - 75%)

RECEIVED 19 AUG 2019

[Signature]
 19/8/2019

Date/Time, File Pass to? 19/08/19
 1) Typist
 Date/Time, File Return to?

2)

Report Format :

Lump Sum / L.B.I: (\$) 3,500/- 45

Days Of Repair: 4
 Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Invs (\$) ☐ Weekend (\$)

Survey Fee:
 Transportation:

☐ S + RES St
☒ Photo
☐ Others

OSD
 TOTAL 20/8/19

4x15=60

60+170
90
90+90
66
446

MOTOR SURVEY ASSIGNMENT

Date	21-05-2019	Our Ref No. D19003326MFSH
Accident Date	17-05-2019	Claim Type. Third Party
Insured Vehicle	SH8887M	Third Party Vehicle. SLE9193Z
Survey Location	53 UBI AVE 1 #01-25 PAYA UBI INDUSTRIAL PARK	
Contact Person.	KAI LING	
Contact No.	0/ 98686000	Fax No. 69255219
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MY CAR CONSULTANT	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4017C
Vehicle Details	
Vehicle No.:	SLE9193Z
Vehicle to be Exported:	No
Intended Deregistration Date:	23 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER 2.0 ELEGANCE AT ABS D/AIRBAG 2WD
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	3ZRB829492
Chassis No.:	ZSU600083548
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$29,292.00
Original Registration Date:	05 Aug 2016
First Registration Date:	05 Aug 2016
Transfer Count:	1
Actual ARF Paid:	\$28,009.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Aug 2026
PARF Rebate Amount:	\$21,006.00
Intended COE Rebate Details	
COE Expiry Date:	04 Aug 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,010.00
COE Rebate Amount:	\$41,041.00
Total Rebate Amount:	\$62,047.00

The information contained herein is correct as at 23 May 2019

OK

Steve Chen (LKK Auto)

From: My Car Consultant <admin@mycar.sg>
Sent: Thursday, August 15, 2019 11:30 AM
To: Steve Chen (LKK Auto)
Subject: re: SLE9193Z

WITHOUT PREJUDICE

Dear Steve,

Pls close at the same.

Best Regards,

Huiqin

Direct line: 88668832 | Fax: 69255219

My Car Consultant Pte Ltd

53 Ubi Avenue 1
Paya Ubi Industrial Park #01-33
Singapore 408934

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

From: "Steve Chen (LKK Auto)" <SteveChen@lkkauto.com>
Sent: Thursday, August 15, 2019 10:29 AM
To: "admin@mycar.sg" <admin@mycar.sg>
Subject: SLE9193Z

Dear HuiQin,

The above vehicle finalize \$3500 (L/S, before GST). 4 repair days.

Kindly confirm.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: My Car Consultant [<mailto:admin@mycar.sg>]
Sent: Wednesday, August 14, 2019 11:01 AM
To: Steve Chen (LKK Auto)
Cc: SUR
Subject: SLE9193Z

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 28 May 2019 10:38 AM
To: 'Joanne Yong Lai fong'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19003326MFSH/1
Attachments: SLE 9193Z - Preli Advise .pdf

Dear Joanne,

Enclosed preliminary revised of vehicle SLE 9193Z.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 22 May 2019 1:44 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <JoanneYong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003326MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 21 May 2019 5:48 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <JoanneYong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003326MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003326MFSH

Date: 28 May 2019

Our Ref: CS/FCI19009014/Jsd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLE 9193Z

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/05/2019 at the premises of M/s My Car Consultant Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 14,107.61 .
Revised Estimate Amount	: S\$ 5,102.20 .
"Check" Items Amount	: S\$ 3,352.13 .
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 4 Days

Yours faithfully,
Ong Hwee Jie
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/05/2019 16:39
Date Of Accident	17/05/2019 22:55
Exact Location Of Accident	PIE(TUAS)AFT ENG NEO L/P 1131
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE9193Z
Insured/Policyholder	
Name Of Registered Owner	FONG SIEW KUAN
NRIC No	S6914017C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-99999999
Alternative Phone No	OFFICE-99999999

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5092249552-01
Cover Note Number	

Driver

Name of Driver	NGOI CHUN KIAT,FRANCIS(WEI JUNJIE)
NRIC No	S8800323C
Date Of Birth	04/01/1988
Occupation	OUTDOOR
Date Of Driving Pass	10/05/2010
Driving Experience	9 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91458324
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 488D CHOA CHU KANG AVENUE 5 #10-173
Postcode	684488
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE POLICE REPORT: T/20190518/7002

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH8887M
Vehicle Make/Model/Colour	HYUNDAI I40
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKC8069D

Vehicle Make/Model/Colour

TOYOTA PREVIA

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

NGOI CHUN KIAT, FRANCIS (WEI JUNJIE)

Approximate Age

Injuries Sustain

SLIGHT

Injured person in which vehicle?

SLE9193Z

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to provoke policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that exist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If Driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

KIAHAC-Summary-Police-Form_V01

Accident Sketch Plan

SKETCH PLAN

Lamp Post
1131
PHE. TUBS
after fence
NEO

১৫৪

A - SLE 9T932
B - 548887M
C - SK 806AD

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Police Report



**SINGAPORE
POLICE FORCE**



T/20190518/7002

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408885
Tel No: 65470000

1 of 3

Report No. T/20190518/7002

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/05/2019 03:14		Vice Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: NGO CHUN KIAT, FRANCIS			Address: APT BLK 488D CHOA CHU KANG AVENUE 5 #10-173 SINGAPORE 684488		
ID Type / ID No.: NRIC NO / S8800323C			Contact No.: Home/Office: Mobile: 91458324		
Nationality: SINGAPORE CITIZEN			Email: admin@mycar.sg		
Sex: Male	Age: 31	Date of Birth: 04/01/1988	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: BANK SALES EXECUTIVE			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 17/05/2019 22:55	Type of Location: Straight Road
Location: PAN ISLAND EXPRESSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 90 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Year	Make	Model	Color	Condition	No. of Passenger
SLE9193Z	Car					0

Details of Pedestrian Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Individual Statement



**SINGAPORE
POLICE FORCE**



T/20190518/7002

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20190518/7002

CONTINUATION OF REPORT

Driver:			
Name	NGOI CHUN KIAT, FRANCIS	ID No.	S8800323C
Related Vehicle	SLE9193Z (Car)	Contact No.	91458324
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 17/5/2019, at about 22:55hrs, I was travelling on lane 4 along PIE (TUAS) after eng neo at lamppost 1131. Suddenly I felt a huge impact from my rear. I stop my vehicle and realise that I had gotten into a chain accident with 2 other vehicle. A vehicle bearing (SKC8069D) had collided into a taxi bearing (SH8887M) causing the taxi to collide onto the rear of my vehicle. We then exchange particulars and decided to proceed with insurance claims. I was given 7 days mc

Police Report



**SINGAPORE
POLICE FORCE**



T/20190518/7002

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408866
Tel No: 85470000

2 of 3

Report No. T/20190518/7002

CONTINUATION OF REPORT

Driver			
Name	NGOI CHUN KIAT, FRANCIS	ID No.	S8800323C
Related Vehicle	SLE9193Z (Car)	Contact No.	91458324
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details:

On 17/5/2019, at about 22:55hrs, I was travelling on lane 4 along PIE (TUAS) after eng neo at lampost 1131. Suddenly i felt a huge impact from my rear. I stop my vehicle and realise that I had gotten into a chain accident with 2 other vehicle. A vehicle bearing (SKC8069D) had collided into a taxi bearing (SH8887M) causing the taxi to collide onto the rear of my vehicle. We then exchange particulars and decided to proceed with insurance claims. I was given 7 days mc

Police Report



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20190518/7002

3 of 3

Report No. T/20190518/7002

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
NOR HIDAYU BINTE ABDUL SAMAD
Contact No.: 65476423

Authentication Stamp
NP155

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
18/05/2019 03:14

Classification Of Case:



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 21 May 19
Vehicle: SLE9193Z
Make / Model: TOYOTA/HARRIER
Chassis:

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	REAR BUMPER DEF ✓	1	\$ 1,343.20	\$ 1,343.20 ✓
2	REAR BUMPER LOWER COVER DEF ✓	1	\$ 365.40	\$ 365.40 ✓
3	REAR BUMPER REFLECTOR ? X NAI	2	\$ 56.90	\$ 113.80 X
4	REAR BUMPER LOWER CLIP rec ✓	8	\$ 3.80	\$ 30.40 15 ✓
5	REAR BUMPER SIDE SUPPORT L/R ? / OR	21	\$ 65.00	\$ 130.00 65 ✓
6	REAR BUMPER RETAINER L/R ? / OR	21	\$ 94.80	\$ 189.60 94.80 ✓
7	REAR BUMPER ABSORBER CRA ✓	1	\$ 96.60	\$ 96.60 ✓
8	REAR BUMPER LOWER GARNISH ? X NAI	1	\$ 481.34	\$ 481.34 X
9	REAR TAILLAMP L/R ? (RH) OR	21	\$ 480.60	\$ 961.20 480.60 ✓
10	REAR TAILLAMP SEALER L/R ? X NAI	2	\$ 20.00	\$ 40.00 X
11	TAILGATE BUC ✓	1	\$ 1,224.80	\$ 1,224.80 ✓
12	TAILGATE NO. PLATE GARNISH ASSY nn x	1	\$ 620.60	\$ 620.60 X
13	TAILGATE INNER TRIM ? X NAI	1	\$ 453.70	\$ 453.70 X
14	TAILGATE INNER TRIM CLIP ? X NAI	12	\$ 2.10	\$ 25.20 X
15	TAILGATE LOCK ASSY ✓ / SHI	1	\$ 954.00	\$ 954.00 418 ✓
16	TAILGATE LOCK COVER SCR ✓	1	\$ 24.60	\$ 24.60 ✓
17	TAILGATE LOCK STRIKER nn x	1	\$ 47.50	\$ 47.50 X
18	TAILGATE WEATHERSTRIP nn x	1	\$ 353.40	\$ 353.40 X
19	REAR FENDER L/R nn x	2	\$ 1,019.45	\$ 2,038.90 X
20	REAR FENDER INNER GARNISH L/R nn x	2	\$ 563.30	\$ 1,126.60 X
21	REAR FENDER INNER GARNISH CLIP L/R nn x	12	\$ 2.10	\$ 25.20 X
22	REAR COMPARTMENT BOX nn x	1	\$ 697.40	\$ 697.40 X
23	REAR SPARE TYRE TRAY nn x	1	\$ 614.00	\$ 614.00 X
24	REAR SPARE TYRE SUPPORT SPONGE nn x	1	\$ 137.60	\$ 137.60 X
25	REAR END PANEL ? X R	1	\$ 715.30	\$ 715.30 X
26	REAR END PANEL GARNISH ? X NAI	1	\$ 343.40	\$ 343.40 X
27	REAR END PANEL GARNISH CLIP ? X NAI	4	\$ 2.10	\$ 8.40 X
28	REAR FLOOR PANEL ? X NAI	1	\$ 780.90	\$ 780.90 X
29	REAR FLOOR PANEL TRIM nn x	1	\$ 278.50	\$ 278.50 X
30	REAR EXHAUST SILENCER nn x	1	\$ 628.60	\$ 628.60 X
				\$14,850.14 4198
			Less 25%	\$ 3,712.54 -25%
			Total	\$11,137.61 3096
	S/Nett items:			

19	REAR REVERSE SENSOR <i>shorted /</i>	1 SET	\$ 250.00	\$ 250.00	200
20	REAR END PANEL SEALANT <i>? N/A</i>	1	\$ 50.00	\$ 50.00	X
				\$ 300.00	200 ✓
	Labour to:				
21	TO CHECK REAR ELECTRICAL WIRING	1	\$ 50.00	\$ 50.00	30
22	TO RESPRAY UNDERCOATING	1	\$ 100.00	\$ 100.00	40
23	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 120.00	\$ 120.00	? 30
24	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,200.00	\$ 1,200.00	500
25	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,200.00	\$ 1,200.00	500
				\$ 2,670.00	1100
			Parts Replacement Amount	\$11,437.61	
			Total Amount for Labour	\$ 2,670.00	
			Total Amount	\$14,107.61	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

[Signature]
28/5/19
Hume Jia - LKK
22/5/19
L/S 4 days.
[Signature]

P- 3096
N- 200
L - 1109
4396
L/S - 3516.89
= 3500




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19009014/Esd3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-09-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8887M	Veh. Inspected	SLE 9193Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003326MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	21/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZSU600083548	Colour	WHITE	
Odometer	47149	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	MICHELIN	6 mm	
L/H Front Tyre	225/65 R17	MICHELIN	6 mm	
R/H Rear Tyre	225/65 R17	MICHELIN	6 mm	
L/H Rear Tyre	225/65 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/05/2019	Inspection Date	22/05/2019	
Survey held at	53 UBI AVENUE 1 #01-25			
Repairer	MY CAR CONSULTANT PTE LTD			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 9193Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	1,343.20	1,343.20
1	REAR BUMPER LOWER COVER	DEFORMED	365.40	365.40
2	REAR BUMPER REFLECTOR @\$56.90	NOT NECESSARY	113.80	-
8	REAR BUMPER LOWER CLIP @\$3.80	NECESSARY	30.40	15.00
2	REAR BUMPER SIDE SUPPORT L/R @\$65.00	BROKEN-1PC ONLY	130.00	65.00
2	REAR BUMPER RETAINER L/R @\$94.80	BROKEN-1PC ONLY	189.60	94.80
1	REAR BUMPER ABSORBER	CRACKED	96.60	96.60
1	REAR BUMPER LOWER GARNISH	NOT NECESSARY	481.34	-
2	REAR TAILLAMP L/R @\$480.60	O/S BROKEN	961.20	480.60
2	REAR TAILLAMP SEALER L/R @\$20.00	NOT NECESSARY	40.00	-
1	TAILGATE	BUCKLED	1,224.80	1,224.80
1	TAILGATE NO. PLATE GARNISH ASSY	NOT NECESSARY	620.60	-
1	TAILGATE INNER TRIM	NOT NECESSARY	453.70	-
12	TAILGATE INNER TRIM CLIP @\$2.10	NOT NECESSARY	25.20	-
1	TAILGATE LOCK ASSY	SHORTED	954.00	418.00
1	TAILGATE LOCK COVER	SCRATCHED	24.60	24.60
1	TAILGATE LOCK STRIKER	NOT NECESSARY	47.50	-
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	353.40	-
2	REAR FENDER L/R @\$1019.45	NOT NECESSARY	2,038.90	-
2	REAR FENDER INNER GARNISH L/R @\$563.30	NOT NECESSARY	1,126.60	-
12	REAR FENDER INNER GARNISH CLIP L/R @\$2.10	NOT NECESSARY	25.20	-
1	REAR COMPARTMENT BOX	NOT NECESSARY	697.40	-
1	REAR SPARE TYRE TRAY	NOT NECESSARY	614.00	-
1	REAR SPARE TYRE SUPPORT SPONGE	NOT NECESSARY	137.60	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	715.30	-
1	REAR END PANEL GARNISH	NOT NECESSARY	343.40	-
4	REAR END PANEL GARNISH CLIP @\$2.10	NOT NECESSARY	8.40	-
1	REAR FLOOR PANEL	NOT NECESSARY	780.90	-
1	REAR FLOOR PANEL TRIM	NOT NECESSARY	278.50	-
1	REAR EXHAUST SILENCER	NOT NECESSARY	628.60	-

Report Ref No. CS/FCI19009014/Esd3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-3,712.54	-1,032.00
			11,137.60	3,096.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR REVERSE SENSOR (SN)	SHORTED	250.00	200.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
			300.00	200.00
	<u>LABOUR</u>			
	TO CHECK REAR ELECTRICAL WIRING.		50.00	30.00
	TO RESPRAY UNDERCOATING.		100.00	40.00
	APPLY ANTI RUST ON AFFECTED AREAS.		120.00	30.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,200.00	500.00
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,200.00	500.00
			2,670.00	1,100.00
GRAND TOTAL			14,107.60	4,396.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,500.00

Report Ref No. CS/FC119009014/Esd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.