

22/05/2019

ASS. REC. BY:

REF

C23/CTI/9009021/71C0362

Special Instruction:

Surveyor: Tau HichASSIGNMENT (Office)From (Person): Chong Soon Sen of CTIDate/Time: 22/5/19 @ 9.12am

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKX 6445DInsured: GBJ 3501Aat Workshop m/s Gold AutoworksTel: 81999149of 48toh Guen Rd East #01-119Policy No: DMCVSN19128619000Claim No: SNM19D20228C02

Sum Insured: _____

Excess: _____

Make of Veh:

(Client's Record)

D.O.A. 15/05/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 11.05am @ 22/5/19Person Contacted: SimonVehicle IN / OUT

Date/Time	Action/Instruction	Estimate
	SKX 6445D - NA / CTI / 9006950 / v3	
	GBJ 3501A - NA / CTI / 9006950 / v3	
	Demantle: 23/5/2019	
	After repair: 28/5/2019	

DVA: 15/5/2019

DVA: 15/5/2019

Tanpuku


REF

CT1

ASSIGNMENT

2015, Dec.

From _____ Date _____
 Estimated Cost _____
 QD / TP / WS / TP RES / OD RES / EVA / RV / MV
 To inspect Vehicle No. _____
 at Workshop no. _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured _____ Excess _____
 (Client's Record)
 Make of Veh. _____



(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Est. or Market Value _____
 IDAC Accident Report _____ Consistent? Yes or No _____
 GIA / IR Seen _____ Consistent? Yes or No _____
 Est. Repairs: 6 days Res: Yes or No _____
 Lump Sum: % 3 Val: Yes or No _____
 CA / REV / REP. / 24 HRS _____
 Date _____ Person Contacted _____

PRS

Vehicle: IN / OUT

Veh No. SKX 6445D in Regn
 Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
 Truck / Trailer or _____
 Make Hyundai Elantra. Yr. 15.91
 Colour white ABS Insured / Std / HI / HA
 Sp Reading 2.0 939 TB Radio Insured / Std / HI / HA
 Eng No. KM HDH 41CM 94642853
 C/Nr _____
 Gen Cond ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt
 Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or _____
 Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or _____
 Mod: ☒ NR / ☐ ARim / ☐ STD ARim or _____
 Tyre Size: F: 195/65R15
 R: 195/65R15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake
 Front 6 mm Rear 6 mm
 L/R Bal 6 mm L/R Bal 6 mm
 D.O.A. 22/5/19 @ 1215
 Survey held at Gold Auto
 Des. of Damages: ☒ Front / ☐ Rear / ☐ O/S / ☐ H/S / ☐ U/C / ☐ Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time _____ Action / Instruction _____

Estimated repair range \$4,000 - \$7,000

5/7/2015

Date/Time, File Pass to? ☐ : Prel. Report
 if ☐ : Final Report
 Date/Time, File Return to? _____

Days Of Repair: 6
 Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech Insp (\$) ☐ Weekend (\$)

Survey Fee:	150
Transportation	
Photos	
Others	
TOTAL	150

Report Format: PRS
 Lump Sum / T.B.I. (\$) _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 May 2019		22 May 2019 16:50 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:				
Main Claimant:	ASIA CARZ AUTO, Co. Reg. No.: 53310402E			
Vehicle Reg. No.:	SKX6445D	Date of Loss:	15/04/2019 22:00 - :59	
Claim Type:	TP / SNM19D202228C02	Policy/Cover Note No.:	DMCVSN19128619000	
Vehicle Reg. No. (Insured):	GBJ3501A	Policy No. (Claimant):	5102880307-01	
		Excess:	S\$0.00	
Repairer:	Gold Auto Works Pte Ltd (HQ) 48 Toh Guan Rd East #01-119, Enterprise Hub, 608586 Jurong East - Tel: 96199144/ 87789382			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 31/05/2019]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Celine Fong (LKKAuto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 22 May 2019 9:12 AM
To: Lee Jia Yun
Cc: 'Max'; assignments
Subject: RE: OUR REF: SNM19D202228-GBJ3501A - & YR DT/mlc/100902/PD SKX6445D, - PRS

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road
#16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Lee Jia Yun [mailto:jiayun.lee@advlawllc.com]
Sent: Wednesday, 22 May, 2019 8:59 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: 'Max' <max@advlawllc.com>
Subject: RE: OUR REF: SNM19D202228-GBJ3501A - & YR DT/mlc/100902/PD SKX6445D, - PRS

Dear Boon Sen

We disagree with your list of surveyors.

Kindly proceed accordingly

Thank you.

Best Regards

Jia Yun



430 Lorong 6 Toa Payoh #11-01 OrangeTee Building Singapore 319402
Tel: (65)6323 5488 | Fax: (65)6258 5521

STRICTLY CONFIDENTIAL
This message, its contents and any files transmitted with it are intended SOLELY for the addressee(s) and may be legally privileged and/or confidential. Access by any other party is unauthorised without the express written permission of the sender. If you have received this message in error, you may not copy or use the contents, attachments or information in any way. Please destroy it and contact us immediately via e-mail return. This message has been prepared using information believed by the author to be reliable and accurate; we make no warranty as to its accuracy or completeness. We do not accept responsibility for changes made to this message after it was sent.

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, May 21, 2019 4:39 PM
To: jiayun.lee@advlawllc.com
Subject: RE: OUR REF: SNM19D202228-GBJ3501A - & YR DT/mlc/100902/PD SKX6445D, - PRS

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road
#16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Lee Jia Yun [<mailto:jiayun.lee@advlawllc.com>]
Sent: Tuesday, May 21, 2019 12:44 PM
To: DL-CLAIMS
Cc: 'Max'; claims@goldautoworks.com.sg
Subject: DT/mlc/100902/PD SKX6445D, YOUR INSURED CAR: GBJ3501A

Dear Sir/ Ms,

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURUSANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES.

We act for who has been instructed with motorcar no. **SKX6445D** with instructions to repair the same.
Accident on : 15/05/2019 @ 23:30 HRS, WITHIN MALAYSIA CUSTOM IMMIGRATION CHECK POINT

Please be informed that the said vehicle can be inspected at:-

Venue : GOLD AUTOWORKS PTE LTD
48 TOH GUAN ROAD EAST
#01-119 ENTERPRISE HUB
SINGAPORE 608586

PIC : SIMON TAN

Contact No : 81999149

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening weekend and public holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Best Regards

Jia Yun

ADVANCE
ADVANCE LAW LLC

STRICTLY CONFIDENTIAL

This message, its contents and any files transmitted with it are intended SOLELY for the addressee(s) and may be legally privileged and/or confidential. Access by any other party is unauthorised without the express written permission of the sender. If you have received this message in error, you may not copy or use the contents, attachments or information in any way. Please destroy it and contact us immediately via e-mail return. This message has been prepared using information believed by the author to be reliable and accurate; we make no warranty as to its accuracy or completeness. We do not accept responsibility for changes made to this message after it was sent.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	0402E
Vehicle Details	
Vehicle No.:	SKX6445D
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Jun 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	G4FGFU039307
Chassis No.:	KMHDH41CMGU642853
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$12,673.00
Original Registration Date:	22 Dec 2015
First Registration Date:	22 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$12,673.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Dec 2025
PARF Rebate Amount:	\$9,504.00
Intended COE Rebate Details	
COE Expiry Date:	21 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,989.00
COE Rebate Amount:	\$37,058.00
Total Rebate Amount:	\$46,562.00

The information contained herein is correct as at 20 Jun 2019

OK

MSI119049828 / STA INSPECTION PTE LTD - Sin Ming
 ENTRY DATE & TIME: 16/04/2019 18:02
 SUBMITTED BY: Wong Lip Yong

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 16/04/2019 18:02
 Date Of Accident 15/04/2019 22:00
 Exact Location Of Accident JALAN MAS PUTEH
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKX6445D
Insured/Policyholder
 Name Of Registered Owner ASIA CARZ AUTO
 Co Reg No 53310402E
 Email Address ASIACARZAUTOGROUP@GMAIL.COM
 Mobile Phone No
 Alternative Phone No Office-91946922

Vehicle Particulars

Manufacturer HYUNDAI
 Model ELANTRA-1.6 (A)
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken REPORTING ONLY
 Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 5102880307-01
 Cover Note Number

Driver

Name of Driver GOH WEE KOK
 NRIC No S7134642J
 Date Of Birth 06/10/1971
 Occupation OUTDOOR
 Date Of Driving Pass 27/05/1992
 Driving Experience 26 YEARS AND 10 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-91946922

Fax Number

Contact Number

EMail Address

GWK322003@HOTMAIL.COM

Address

BLK 62 CIRCUIT ROAD #02-295
SINGAPORE

Postcode

370062

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own
Vehicle-
-
-

Insurance Company of Driver's Own Vehicle

-
-
-**General Information of the Accident**

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved
in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by
ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)
soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBJ3501A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

ZHOU SHENGHUA

NRIC/Passport Number

G5892011N

Contact Number

96698226

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


Sketch Plan

SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:





 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 16/4 1115hrs


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

1204514, 0200040 miform_03

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Both vehicles are in station position.
 Lorry number GBJ 3501 A, upon intend to turn
 out. While reversing, it bang on my car
 (SKX 6445 D).

All Photos taken on the damage of car
 number SKX 6445 D.

Driver driving license was recorded. He
 send me SMS that he was willing to
 pay the cost of repairing the damage
 incur on the car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:



Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 16/4

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

1115 hrs




























...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 May 2019		22 May 2019 16:50 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case



Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	ASIA CARZ AUTO , Co. Reg. No.: 53310402E								
Vehicle Reg. No.:	SKX6445D	Date of Loss:	15/04/2019 22:00 - :59 [39 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202228C02	Policy/Cover Note No.:	DMCVSN19128619000						
Vehicle Reg. No. (Insured):	GBJ3501A	Policy No. (Claimant):	5102880307-01						
		Excess:	S\$0.00						
Repairer:	Gold Auto Works Pte Ltd (HQ) 48 Toh Guan Rd East #01-119, Enterprise Hub, 608586 Jurong East - Tel: 96199144/ 87789382								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 31/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

















*SKX6445D (SNM19D202228C02)
[GBJ3501A]
TP
ASIA CARZ AUTO
Apr 15 2019 10:00PM
[-]
Gold Auto Works Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)							Thumbnail			Print		
1	16/04/19 18:22	Accident Statement										Load HTM		
2	23/04/19 10:42	Addendum Sheet										Load TIF		
3	23/04/19 10:43	Accident Statement Addm. #1										Load HTM		
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)							Thumbnail			Print		
1	16/04/19 18:10	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
2	16/04/19 18:10	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
3	16/04/19 18:10	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
4	16/04/19 18:10	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
5	16/04/19 18:10	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
6	16/04/19 18:10	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
7	16/04/19 18:10	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
8	16/04/19 18:10	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
9	16/04/19 18:10	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
10	16/04/19 18:10	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
11	16/04/19 18:10	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail			Print		
1	20/06/19 17:41	General View										Load JPG <input checked="" type="checkbox"/>		
2	20/06/19 17:41	General View										Load JPG <input checked="" type="checkbox"/>		
3	20/06/19 17:41	General View										Load JPG <input checked="" type="checkbox"/>		
4	20/06/19 17:41	General View										Load JPG <input checked="" type="checkbox"/>		
5	20/06/19 17:41	General View										Load JPG <input checked="" type="checkbox"/>		
6	20/06/19 17:41	General View										Load JPG <input checked="" type="checkbox"/>		
7	20/06/19 17:41	General View										Load JPG <input checked="" type="checkbox"/>		
8	20/06/19 17:41	General View										Load JPG <input checked="" type="checkbox"/>		
9	20/06/19 17:41	General View										Load JPG <input checked="" type="checkbox"/>		
10	20/06/19 17:41	General View										Load JPG <input checked="" type="checkbox"/>		
11	20/06/19 17:41	General View										Load JPG <input checked="" type="checkbox"/>		
12	20/06/19 17:41	General View										Load JPG <input checked="" type="checkbox"/>		
13	20/06/19 17:41	General View										Load JPG <input checked="" type="checkbox"/>		
14	20/06/19 17:41	General View										Load JPG <input checked="" type="checkbox"/>		
15	20/06/19 17:41	General View										Load JPG <input checked="" type="checkbox"/>		
16	20/06/19 17:41	General View										Load JPG <input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail Print
17	20/06/19 17:41	General View		Load JPG <input checked="" type="checkbox"/>
18	20/06/19 17:41	General View		Load JPG <input checked="" type="checkbox"/>
19	20/06/19 17:41	General View		Load JPG <input checked="" type="checkbox"/>
20	20/06/19 17:41	General View		Load JPG <input checked="" type="checkbox"/>
21	20/06/19 17:41	General View		Load JPG <input checked="" type="checkbox"/>
22	20/06/19 17:41	General View		Load JPG <input checked="" type="checkbox"/>
23	20/06/19 17:41	General View		Load JPG <input checked="" type="checkbox"/>
24	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
25	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
26	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
27	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
28	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
29	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
30	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
31	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
32	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
33	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
34	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
35	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
36	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
37	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
38	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
39	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
40	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
41	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
42	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
43	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
44	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
45	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
46	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
47	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
48	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
49	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
50	20/06/19 17:55	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
51	20/06/19 17:56	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
52	20/06/19 17:56	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
53	20/06/19 17:56	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
54	20/06/19 17:56	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
55	20/06/19 17:56	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
56	20/06/19 17:56	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
57	20/06/19 17:56	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
58	20/06/19 17:56	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
59	20/06/19 17:56	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
60	20/06/19 17:56	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
61	20/06/19 17:56	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
62	20/06/19 17:56	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	22/05/19 16:51	pri contact		Load PDF
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail Print

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	16/04/19 18:12	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	16/04/19 18:12	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	16/04/19 18:22	Accident Statement	 Load HTM	
2	23/04/19 10:42	Addendum Sheet	 Load TIF	
3	23/04/19 10:43	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	16/04/19 18:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	16/04/19 18:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	16/04/19 18:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	16/04/19 18:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	16/04/19 18:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	16/04/19 18:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	16/04/19 18:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	16/04/19 18:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	16/04/19 18:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	16/04/19 18:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	16/04/19 18:10	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	16/04/19 18:12	Sketch Plan	 Load TIF	
2	16/04/19 18:12	Sketch Plan #2	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119009021/T1CD3E2

Date: 11/07/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN19128619000

Claimant Vehicle
No: SKX6445DInsured Vehicle
No: GBJ3501A

Date of Loss: 15/04/2019

Nature of Claim: TP

Claim
No: SNM19D202228C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKX6445D

Make & Model: HYUNDAI ELANTRA, 1.6 (A)

Engine No: G4FGFU039307

Reg. Date: 22/12/2015 (Man. Year: 2015)

Chassis No: KMHDH41CMGU642853

Colour: White

Odometer: 202939 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/05/2019

Date Inspected: 22/05/2019 Inspected At:

Gold Auto Works Pte Ltd (HQ)
48 Toh Guan Rd East #01-119, Enterprise
Hub
Singapore 608586

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Jul 2019)

Parts: 143 HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKX6445D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >