

12/03/2009

ASS. REC. BY:

REF:

CS/CTI19009031/Kgd3^{SP}

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Cheng Boon Sen

of

CTI

Date/Time:

22/5/19 @ 2:48pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJ1 1962X

Insured:

GY16 34A

at Workshop m/s

BEG Sin Ming

Tel:

84550600

of

176 Sin Ming Drive # 02-05

Policy No:

PNCUSN 30013079000

Claim No:

SNM19D202259002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/5/2019

CA / REV / REP. / REV 24 HRS

24/5/19

H.O.D. Endorsement:

Date/Time:

3:51pm @ 22/5/19

Person Contacted:

Angela

Vehicle IN ☒ OUT

Date/Time

Action/Instruction

Estimate (✓)

SJ1 1962X - CC6/AG09010566/Kwuh

DOA: 22/7/2009

GY1634A - NJ/INCO9007578/Y1

DOA: 6/4/2009

16/10/19 @

1:48pm

LI Reg 8235ch Remot - The vehicle has not send in for repair.
checked with Angela, due to liability not clear & owner towout all.

ASS. REQ. BY: KennethREF: CTI

ASSIGNMENT

From:

Date:

24/5/19

Estimated Cost:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJ1962X

at Workshop m/s

BFG Sin Mingof 176 Sin Ming Drive # 02-05

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

9/23

(wp)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJ1962X

Yr Regn:

09 ofType: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

707 Camry

C.C.

2362

Colour:

M. P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

283074

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MRO 53BK 4007029747Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

2

mm

L/Bal.

3

mm

L/Bal.

2

mm

D.O.A.

22/5/19

D.O.I.

24/5/19

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S / R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 16 OCT 2019

Date/Time, File Pass to?

1) 16/10 10:15

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.I.:

☒ Preli. Report☐ Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + R \$

Photos

Other

TOTAL

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 22 May 2019 2:48 PM
To: Motor Claims
Cc: 'assignments'
Subject: RE: THIRD PARTY CLAIM OF SJJ1962X & GY1634A ACCIDENT ON 22.05.2019 / our refa: snm19d202259

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Motor Claims [mailto:motorclaims@autocare.com.sg]
Sent: Wednesday, 22 May, 2019 2:46 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: THIRD PARTY CLAIM OF SJJ1962X & GY1634A ACCIDENT ON 22.05.2019 / our refa: snm19d202259

Dear Boon Sen,

Our selection surveyor is **Kenneth Kong**

Thank you

With Regards,
Angela Tan
Claims & Admin Executive



Sin Ming Autocare BFG Pte Ltd
176 SIN MING DRIVE, #02-05 SINGAPORE 575721
Email: motorclaims@autocare.com.sg
Tel : 6455 0600 | Fax : 6455 6192

From: Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]

Sent: Wednesday, 22 May, 2019 2:39 PM

To: motorclaims@autocare.com.sg

Subject: RE: THIRD PARTY CLAIM OF SJJ1962X & GY1634A ACCIDENT ON 22.05.2019 / our refa: snm19d202259

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Wednesday, 22 May, 2019 2:21 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; motorclaims@autocare.com.sg

Cc: Angie Foo <angie.foo@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: FW: THIRD PARTY CLAIM OF SJJ1962X & GY1634A ACCIDENT ON 22.05.2019

Dear Boon Sen,

Please conduct PRS – TP: SJJ1962X (SNM19D202259) soonest possible.
File with OIC – Boon Sen - 63896171

From: Motor Claims [<mailto:motorclaims@autocare.com.sg>]

Sent: Wednesday, 22 May 2019 2:12 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: THIRD PARTY CLAIM OF SJJ1962X & GY1634A ACCIDENT ON 22.05.2019

To: China Taiping Motor Claims Dept. (Arrangement of Surveyor Unit)

**RE: NOTICE TO THIRD PARTY INSURERS TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKINGS DAY
PURSUANT TO**

PARAGRAPH PHOTOCOL FOR NIN-INJURY MOTOR ACCIDENT CLAIMS (NIMA)

**ACCIDENT INVOLVING SJJ1962X & GY1634A ALONG ROBINSON ROAD JUNCTION MCCALLUM STREET ON
22.05.2019**

We are repairer for TAN TENG HENG the owner of vehicle no SJJ1962X.

Please be informed that the said vehicle can inspected at the following venue:

Sin Ming Autocare BFG Pte Ltd

176 Sin Ming Drive #02-05 Singapore 575721

Tel: 6455 0600 Fax: 64556192 Email: motorclaims@autocare.com.sg

Contact Person: Angela Tan

Please also provide us a list of 10 surveyors as your nominated SJE (Single Joint Expert)

**PLEASE ARRANGE OFFICER-IN-CHARGE TO LET US KNOW ASAP IF WE COULD DO DIRECT SETTLEMENT FOR THIS
CASE.**

Thank you

With Regards,

Angela Tan

Claims & Admin Executive



Sin Ming Autocare BFG Pte Ltd

176 SIN MING DRIVE, #02-05 SINGAPORE 575721

Email: motorclaims@autocare.com.sg

Tel : 6455 0600 | Fax : 6455 6192

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/05/2019 12:30
Date Of Accident	22/05/2019 09:05
Exact Location Of Accident	ROBINSON ROAD JUNCTION MCCALLUM STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJJ1962X
Insured/Policyholder	
Name Of Registered Owner	TAN TENG HENG
NRIC No	S7319212I
Email Address	ELSONTTH@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-93375336
Alternative Phone No	OTHERS-93375336

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY-2.4 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE & REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095685176-01
Cover Note Number	DRIVO CLASSIC

Driver

Name of Driver	TAN TENG HENG
NRIC No	S7319212I
Date Of Birth	28/05/1973
Occupation	OUTDOOR
Date Of Driving Pass	06/08/1994
Driving Experience	24 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93375336
Fax Number	
Contact Number	OTHERS-93375336
Email Address	ELSONTTH@YAHOO.COM.SG

Address	8 BOON KENG ROAD #14-148
Postcode	330008
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GY1634A
Vehicle Make/Model/Colour	NISSAN NV350
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHUA PECK BOON
NRIC/Passport Number	S7538993J
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

22/9/19


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Tan Teng Heng

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:



Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This morning around 9.05am I was turning into Macullen Street on extra right lane. My intention is to turn into Robinson Road. the weather at that time was clear.

Vehicle Nissan 350 was on my left, last minutes signal to turn right which I am turning right as well.

Due to some road work on the ~~the~~ first lane and there was a barrage blockage as well I have to turn ~~from~~ second lane to be safer. I am approaching cautiously at the low speed before turning.

The vehicle Nissan 250, last minutes signal and ~~turn~~ turn abruptly straight into second lane which hit my car front part and causes damages. Both parties were not injured at that point of time.

On the Robinson Road there was Five lane and ~~the~~ lane one was partially closed due to construction the turning driver did not check right before turning.

I have attached a video footage for your ~~kind~~ review.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





Sin Ming Autocare BFG Pte Ltd

176, Sin Ming Drive #02-05
Sin Ming Autocare Complex
Singapore 575721
Tel : (65) 6455 0600
Fax : (65) 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET #18-00 / #19-00 / #16-01/02
THE OCTAGON SINGAPORE 069534

Attention : Motor Claim Department
Contact : 6389 6111 Fax No. : 6222 1033

Estimate : E19/2493

Date : 22/05/2019
Vehicle Num. : SJJ1962X
Make/Model : TOYOTA CAMRY-2008
Chassis/Eng# : MR053BK4007029747/2AZE113963
Accident Date : 22/05/2019
Claim No. : BFG
Reference : TP CLAIM
Policy No. : 5095685176-01

*Not Authorized
Call 823501
Resurvey After Paint
4 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|-----|-------------------------------|--------|--|
| 1. | 1PC | LIST ITEMS : | | |
| 2. | 1PC | FRONT BUMPER | 518.70 | |
| 3. | 1PC | RADIATOR GRILLE | | |
| 4. | 1PC | FRONT BUMPER SIDE RETAINER LH | | |
| 5. | 1PC | FRONT FENDER LH | | |
| 6. | 1PC | FRONT FENDER INNER SHIELD LH | | |
| 7. | 1PC | HEADLAMP | | |
| | | FRONT DOOR LH | | |

List Total S\$:
25.00% Discount S\$:

Bumper	617.00	✓
in	570.00	X
dit	145.00	✓
in	640.00	✓
dit	198.00	✓
in	1,209.00	✓
in	1,147.00	X
	4,526.00	
	1,131.50	
	3,394.50	

- | | | | | |
|----|------|------------------------------------|--|--|
| 1. | 6PCS | SPECIAL NETT ITEMS : | | |
| 2. | 3PCS | FRONT BUMPER CLIPS | | |
| 3. | 6PCS | FENDER CLIPS | | |
| | | FRONT FENDER INNER SHIELD CLIPS LH | | |

Special Nett Total S\$:

in	5.00	in	30.00	✓
in	5.00	in	15.00	✗
in	5.00	in	30.00	✓
			75.00	

LABOUR :
TO PANEL BEATING ALL AFFECTED AREAS
TO PUTTY & SPRAY PAINT ALL AFFECTED AREAS
TO APPLY ANTI-RUST

Labour Total S\$:

400l	600.00	
440l	800.00	
	100.00	30l
	1,500.00	

E. & O.E.

Total S\$: 4,969.50
=====

for Sin Ming Autocare BFG Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 May 2019		24 May 2019 17:17 Edit Adj Rpt	S\$2,350.00 Edit Estimates	S\$2,350.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	0, Co. Reg. No.: 0		
Main Claimant:	TAN TENG HENG, ID: S73192121		
Vehicle Reg. No.:	SJJ1962X	Date of Loss:	22/05/2019 09:00 - :59 [128 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D202259C02	Policy/Cover Note No.:	DMCVSN30013019000
Vehicle Reg. No. (Insured):	GY1634A	Policy No. (Claimant):	5095685176-01
		Excess:	S\$0.00
Repairer:	Sin Ming Autocare BFG Pte Ltd (HQ) 176, Sin Ming Drive #02-05, Sin Ming Autocare Complex, 575721 Sin Ming - Tel: 64550600		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Alfred Toh - 6389 6183]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 04/06/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

1/2

Claim Documents

***SJJ1962X (SNM19D202259C02)**
[GY1634A]

TP

TAN TENG HENG

May 22 2019 9:00AM

[0]

Sin Ming Autocare BFG Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	☒
No	Finalized On	Sin Ming Autocare BFG Pte Ltd (HQ)	Thumbnail	Print
1	22/05/19 12:46	Video - Accident [Linked Accident Report Documents]	Load MP4	☒
Assessment Reports			1 per page	☒
No	Finalized On	Sin Ming Autocare BFG Pte Ltd (HQ)	Thumbnail	Print
1	22/05/19 12:50	Accident Statement	Load HTM	☒
Photos/Images			3 per page	☒
No	Finalized On	Sin Ming Autocare BFG Pte Ltd (HQ)	Thumbnail	Print
1	22/05/19 12:37	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	22/05/19 12:37	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	22/05/19 12:37	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	22/05/19 12:37	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	22/05/19 12:37	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
6	22/05/19 12:37	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
7	22/05/19 12:37	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
8	22/05/19 12:37	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
9	22/05/19 12:37	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
10	22/05/19 12:37	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
11	22/05/19 12:37	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
12	22/05/19 12:37	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
13	22/05/19 12:37	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
14	22/05/19 12:37	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
15	22/05/19 12:37	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
16	22/05/19 12:37	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/10/19 15:38	General View	Load JPG	☒
2	16/10/19 15:38	General View	Load JPG	☒
3	16/10/19 15:38	General View	Load JPG	☒
4	16/10/19 15:38	General View	Load JPG	☒
5	16/10/19 15:38	General View	Load JPG	☒
6	16/10/19 15:38	General View	Load JPG	☒
7	16/10/19 15:38	General View	Load JPG	☒
8	16/10/19 15:38	General View	Load JPG	☒
9	16/10/19 15:38	General View	Load JPG	☒
10	16/10/19 15:38	General View	Load JPG	☒
11	16/10/19 15:38	Odometer Reading	Load JPG	☒

Video			1 per page ▼	✓
No	Finalized On	Sin Ming Autocare BFG Pte Ltd (HQ)	Thumbnail	Print
12	16/10/19 15:38	Odometer Reading	1 Load JPG	✓
13	16/10/19 15:38	Chassis Number	1 Load JPG	✓
14	16/10/19 15:38	General View	1 Load JPG	✓
15	16/10/19 15:38	General View	1 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/05/19 17:18	pri contact	1 Load PDF	
No	Finalized On	Sin Ming Autocare BFG Pte Ltd (HQ)	Thumbnail	Print
1	22/05/19 12:41	Sketch Plan [Linked Accident Report Documents]	1 Load TIF	
2	22/05/19 12:41	Sketch Plan #2 [Linked Accident Report Documents]	1 Load TIF	

Linked Accident Report Documents

Video			View	View in Browser	View
No	Finalized On	Sin Ming Autocare BFG Pte Ltd (HQ)	1 per page		
1	22/05/19 12:46	Video - Accident		Thumbnail	Print
				Load MP4	
Assessment Reports			1 per page		
No	Finalized On	Sin Ming Autocare BFG Pte Ltd (HQ)		Thumbnail	Print
1	22/05/19 12:50	Accident Statement		Load HTM	
Photos/Images			3 per page		
No	Finalized On	Sin Ming Autocare BFG Pte Ltd (HQ)		Thumbnail	Print
1	22/05/19 12:37	Accident Photo		Load JPG	
2	22/05/19 12:37	Accident Photo		Load JPG	
3	22/05/19 12:37	Accident Photo		Load JPG	
4	22/05/19 12:37	Accident Photo		Load JPG	
5	22/05/19 12:37	Accident Photo		Load JPG	
6	22/05/19 12:37	Accident Photo		Load JPG	
7	22/05/19 12:37	Accident Photo		Load JPG	
8	22/05/19 12:37	Accident Photo		Load JPG	
9	22/05/19 12:37	Accident Photo		Load JPG	
10	22/05/19 12:37	Accident Photo		Load JPG	
11	22/05/19 12:37	Accident Photo		Load JPG	
12	22/05/19 12:37	Accident Photo		Load JPG	
13	22/05/19 12:37	Accident Photo		Load JPG	
14	22/05/19 12:37	Accident Photo		Load JPG	
15	22/05/19 12:37	Accident Photo		Load JPG	
16	22/05/19 12:37	Accident Photo		Load JPG	
Documentation			1 per page		
No	Finalized On	Sin Ming Autocare BFG Pte Ltd (HQ)		Thumbnail	Print
1	22/05/19 12:41	Sketch Plan		Load TIF	
2	22/05/19 12:41	Sketch Plan #2		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19009031/KQD3S2
Date: 16/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30013019000
Claimant Vehicle No :	SJJ1962X	Insured Vehicle No :	GY1634A
Date of Loss:	22/05/2019	Nature of Claim:	TP
		Claim No:	SNM19D202259C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ1962X	Engine No:	2AZE113963
Make & Model:	TOYOTA CAMRY, 2.4 (A)	Chassis No:	MR053BK4007029747
Reg. Date:	04/09/2008 (Man. Year: 2008)	Odometer:	283074 km
Colour:	Metallic Pearl White		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Michelin 3 mm	Rear Left Side:	Michelin 2 mm
Front Right Side:	Michelin 3 mm	Rear Right Side:	Michelin 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,469.50	2,093.02	1,376.48	39.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	870.00	630.00	42.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,969.50	2,963.02	2,006.48	40.38
Approved Total (Overridden) (S\$)		2,350.00		
(S\$)	4,969.50	2,350.00	2,619.50	52.71
+ GST 7.00/7.00% (S\$)	347.87	164.50	183.37	52.71
Nett Amount (S\$)	5,317.37	2,514.50	2,802.87	52.71

INSPECTION

Date of Assignment:	24/05/2019	
Date Inspected:	24/05/2019 Inspected At:	Sin Ming Autocare BFG Pte Ltd (HQ) 176, Sin Ming Drive #02-05, Sin Ming Autocare Complex Singapore 575721
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

10/16/2019

Adjuster Report

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Oct 2019)
Parts: 143	TOYOTA CAMRY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJJ1962X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled/Cracked	617.00 FL	*518.70 FL
2	1		*RADIATOR GRILLE	Serviceable	570.00 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	145.00 FL	*145.00 FL
4	1		*FRONT FENDER LH	Bent	640.00 FL	*640.00 FL
5	1		*FRONT FENDER INNER SHIELD LH	Distorted	198.00 FL	*198.00 FL
6	1		*HEADLAMP	Mtg Cracked	1,209.00 FL	*1,209.00 FL
7	1		*FRONT DOOR LH	Repair	1,147.00 FL	*- FL
8	6		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
9	3		*FENDER CLIPS	Not Necessary	15.00 FS	*- FS
10	6		*FRONT FENDER INNER SHIELD CLIPS LH	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,601.00	2,770.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,131.50	677.68
Total Parts (\$\$)	3,469.50	2,093.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEATING ALL AFFECTED AREAS	New	600.00	400.00
2	TO PUTTY & SPRAY PAINT ALL AFFECTED AREAS	New	800.00	440.00
3	TO APPLY ANTI-RUST	New	100.00	30.00
Gross Labour Cost (\$\$)			1,500.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >