

ASS. REC. BY:

REF: CS/AIG/190070351 GS d302

Special Instruction:

SURVIVOR

G2

ASSIGNMENT (Office)

Mentor

From (Person): HOR Yihua

of

AIG

Date/Time: 22-5-2019 4.16pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PBF 425 C

Insured: SKR 8341M

at Workshop m/s Tachyon Motor

Tel: 67831948

of Blk 9004 Tampine Street 95 #01-108

Policy No:

Claim No: 25 5353498 456 003

Sum Insured:

Excess:

Make of Veh:

D.O.A. 9.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 22-5-2019 5.25p.m

Person Contacted: Ah Tak

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	PBF 425 C - x
	SKR 8341M - x
28/05/19	checked with Ah Tak (owner), Owner haven't provide GZA report.
16/07/19	checked with Ah Tak (owner), Owner haven't provide GZA report.

GA

REF: A19

ASSIGNMENT

From: . Date: 23.5.2019
 Estimated Cost:
 OD: TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: FBF 425 C
 at Workshop m/s Tachyon moto
 of B1K 9004 Tampinuse street 93 #01-108
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$6800

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS


rup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: FBF 425 C Yr Regt: 07 Jan 2011
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda CBR 600RR 599
 Colour: Yellow A/C: Insured / Std / NI / NA
 Sp. Reading: - T/Cadio: Insured / Std / NI / NA
 Eng/No:
 C/No: JH2PC 40C 3BK 400317
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Insider / Jammed / Leaked / Burnt or
 Brake: Insider / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 120/70-17
 R: 180/55-17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or TIMSUN
 Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. mm L/Bal. mm
 D.O.A. D.O.I. 23-05-19
 Survey held at w/s 5pm
 Des. of Damages: Frnt / Rear / O/S / N/S / UIC / Rooftop or
 and
 The UIC / Chassis frame / Body Structure affected due to collision.



Date / Time

Action / Instruction

16/7

Finalised \$5500 with Tak.

(\$ 10,900.65 Red - 67%)

RECEIVED 17 JUL 2019

Date/Time, File Pass 107

12/02/19

1) Typist

Date/Time, File Return in?

2)



: Preli. Report



: Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$ 5,500/- H/S)

Survey Fee:

Transportation:

: S + RS, \$

: Photos

: Others

TOTAL

290

11

301

16/7/2019

PRE-REPAIR INSPECTION REQUEST – FBF425C vs SKR8341M (OI) on D.O.A.: 09/05/2019

From: Hor, Yinnul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Fan, Winnie-LW; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur
Sent: 5/22/2019 4:16:51 PM
Attachments:  FBF425C vs SKR8341M.pdf  FBF425C vs SKR8341M.PDF

Hi,

Please refer to the enclosed request from **Catherine Lim LLC**.

Claim no : 2553534984SG003
Case Owner : WAN NUR SALIHA BINTE SYED YUSOFF

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Xing Guo Qiang** as Single Joint Expert as requested.*

Thanks & Regards,

Yin Rul, Hor (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Yinnul.Hor@aig.com | www.aig.sg

From: Catherine Lim LLC [mailto:info@catherinelimllc.com]
Sent: Wednesday, May 22, 2019 4:11 PM
To: Hor, Yinnul
Cc: Fong, Andy-SY; Fan, Winnie-LW; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur
Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKR8341M AND FBF425C ON 09/05/2019

This message is from an external sender; be cautious with links and attachments.

Dear Madam

Our client agreed to LKK Auto Consultants Pte Ltd - Xing Guo Qiang to conduct the pre-repair survey.

Tks/rgds
wendy
Catherine Lim LLC
20 Havelock Road #03-01
Central Square
Singapore 059765
Tel: 6438 5500
Fax: 6438 0111
email: info@catherinelimllc.com

From: Hor, Yinnul
Sent: Wednesday, May 22, 2019 2:35 PM
To: info@catherinelimllc.com
Cc: Fong, Andy-SY ; Fan, Winnie-LW ; Kaur, Baljit ; Abu Kassim, Noor Mariesa ; Azlan, Syazairdina ; Chan, Yoke Shi ; Lim, Sheng Yang ; Mithoosingh, Aashweenjeetkaur
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKR8341M AND FBF425C ON 09/05/2019

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยกับข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-05-29 14:36 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinnul.Hor@aig.com

To: info@catherinelimllc.com

Cc: Andy-SY.Fong@aig.com, Winnie-LW.Fan@aig.com, Baijit.Kaur@aig.com, NoorMariesa.AbuKessim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com

Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKR8341M AND FBF425C ON 09/05/2019

Date: Wed, 22 May 2019 08:35:57 +0000

Without Prejudice

Your Reference : CL/190536/T/TYM.wa

Our Reference : 2553534984SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rul, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Yinnul.Hor@aig.com | www.aig.sg

CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS
廖 NOTARY PUBLIC - 公证官
玲 COMMISSIONER FOR OATHS - 宣誓官
林
廖 CATHERINE C. LIM
玲 DIRECTOR
LL.B (HONS) SINGAPORE - 法律系-律师
M.B.A. (BUSINESS LAW) - 商业系-硕士

20 Havelock Road #03-01
Central Square Singapore 059765
UEN No. 201310922K
GST Registration No. 201310922K
Tel: (65) 6438 5500
Fax: (65) 6438 0111
www.catherinelimllc.com
Email: info@catherinelimllc.com
CATHERINE LIM LLC is a law corporation with
limited liability

Our Ref: CL/190536/T/TYM.wa
Your Ref: SKR 8341M

22 May 2019

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept

via fax: 64153727 only

Khoo Jean Nee
Blk 326 Yishun Ring Road #08-1342
Singapore 760326

CERTIFICATE OF POSTING
(Please be informed that all supporting documents
have been forwarded to your insurer.)

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**

**ACCIDENT INVOLVING FBF 425C / SKR 8341M ON 09.05.2019 ALONG SELETAR EXPRESSWAY
TOWARDS BTE**

We are instructed by CHIN JUN LIN to notify you of a road traffic accident on 09.05.2019 involving our client's vehicle No FBF 425C and vehicle No. SKR 8341M driven by you at the material time. A copy of the Singapore Accident Statement and/or Police Report is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

M/s Tachyon Motor
Venue: Blk 9004 Tampines Street 93 #01-108
Singapore 528838
Tel: 67831948 Fax: 67834013

Contact Person: Ah Tak

Yours faithfully

Enc

Cc: M/s Tachyon Motor
via fax only

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3891G
Vehicle Details	
Vehicle No.:	FBF425C
Vehicle to be Exported:	No
Intended Deregistration Date:	28 May 2019
Vehicle Make:	HONDA
Vehicle Model:	CBR600RR
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	PC40E2208015
Chassis No.:	JH2PC40C3BK400317
Maximum Power Output:	-
Open Market Value:	\$11,183.00
Original Registration Date:	07 Jan 2011
First Registration Date:	07 Jan 2011
Transfer Count:	3
Actual ARF Paid:	\$1,678.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jan 2021
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,503.00
COE Rebate Amount:	\$241.00
Total Rebate Amount:	\$241.00

The information contained herein is correct as at 28 May 2019

OK

MENU

HIGHLIGHTS

DESCRIPTION

SPECS

Get the app

Login

Sign up FREE

SELLER INFO

Honda CBR600

Price S\$7500.00



unknown



unknown



FBC-****-L



Class 2

Singapore
BIKES.

CHAT

[\(https://www.singaporebikes.com/bikemart/sg/\)](https://www.singaporebikes.com/bikemart/sg/)

(MESSAGES/U/47378)

Description

Selling 2003 CBR600rr. Quite highly done up:

- 2005 CBR600RR inverted fork
- Brembo Calipers (Gold)
- Brembo RCS Master Cylinder

- Stainless Steel Braided Brake Hose
- Ohlins fork spring (linear)
- Ohlins rear shocks



(Dyno chart will be provided)

- other accessories but too lazy to list

COE until 2022.

#honda #cbr #cbr600rr #brembo #ohlins #akrapovic
#sportsbike #race #mugen

Contact 9088-9.2.four.four

Singapore
BIKES.



Specifications

(<https://www.singaporebikes.com/bikemart/sg/>)

General Info.

Bike Make	Honda
Bike Model	CBR600
Bike Class	Class 2
Bike Type	Sports Bike

[REPORT ERROR > \(/LISTING/LISTING/ERROR/USEDBIKE/12826/\)](#)[+ ADD TO SHORTLIST](#)[Like 0](#)[Share](#)[SHARE \(WHATSAPP://SEND?TEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/HONDA-HONDA-CBR600RR/12826/\)](#)

Honda CBR600RR

Listing Type	Free Ad
Brand	Honda (/listing/usedbike/brand/honda/)
Model	Honda CBR600RR (/listing/usedbike/model/honda-cbr600rr/)
Engine Capacity	599cc
Classification	Class 2 (/listing/usedbike/model/motorcycle-for-sale/class/class-2/)
Registration Date	09/01/2012
COE Expiry Date	08/01/2022 (2 years 7 months left)
Mileage	63000km
No. of owners	3
Type of Vehicle	Sport Bikes (/listing/usedbike/model/motorcycle-for-sale/sport-bikes/)

Price: ^{SGD}\$10500

DETAILS

2012 Honda CBR600R with lots of accessories.

Accessories

Ohlins Rear shock. Gainelli slip on. Galfer Racing Rotors. HM quick Shifter. Vortex Rear sets. 520 Chain & Sprocket set 15/41. Rebuilt Engine. Brembo RCS. Steel Braided Brake hose. Gear Indicator. ZG windscreen. Lever Guards. Lithium batteries. Vesrah racing brake pads.

[SIMILAR BIKES](#)[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](#)


[REPORT ERROR > \(/LISTING/LISTING/ERROR/USEDBIKE/12753/\)](#)
[+ ADD TO SHORTLIST](#)
[Like 0](#)
[Share](#)
[@ SHARE \(WHATSAPP://SEND?TEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/HONDA-HONDA-CBR600RR/12753/\)](#)

Honda CBR600RR

Listing Type	Paid Ad
Brand	Honda (/listing/usedbike/brand/honda/)
Model	Honda CBR600RR (/listing/usedbike/model/honda-cbr600rr/)
Engine Capacity	599cc
Classification	Class 2 (/listing/usedbike/model/motorcycle-for-sale/class/class-2/)
Registration Date	14/10/2010
COE Expiry Date	13/10/2020 (1 years 4 months left)
Mileage	50000km
No. of owners	1
Type of Vehicle	Sport Bikes (/listing/usedbike/model/motorcycle-for-sale/sport-bikes/)

Price: ^{SGD}\$11800

DETAILS

Good conditions 2009 Honda CBR600R. Price comes with new 10 years COE. Well taken care by previous owner. Pls call us or visit us at no 36 Toh Guan Road east #01-32 Enterprise Hub. Singapore 608580.

Accessories

Yoshimura R77 Exhaust.

Bike model

Type

Any

Price From

Any

Price To

Any

Class


Any

MORE SEARCH OPTIONS ▼

Q SEARCH

VIEW ALL (/LISTING/USEDBIKES/LISTING/)

Q SEARCH ▼





SINGAPORE POLICE FORCE



T/20190509/2114

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461

Tel No: 1800-7818999

1 of 3

Report No. T/20190509/2114

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/05/2019 15:19	Vide Report No.:	Station Diary No.: 23
--	------------------	--------------------------

Informant's Particulars

Name of Informant: CHIN JUN LIN			Address: APT BLK 301 TAMPINES STREET 32 #04-22 SINGAPORE 520301		
ID Type / ID No.: NRIC NO / S8713891G			Contact No.: Home/Office: Mobile: 82993951		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 31	Date of Birth: 21/05/1987	Type of Informant: Rider		
Race: Chinese			Language: English		Institution / School Name:
Occupation: OPERATION SUPERINTENDENT			Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 09/05/2019 07:50	Type of Location:
Location: Along Road 1 SELETAR EXPRESSWAY TOWARDS BUKIT TIMAH EXPRESSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBF425C	Motorcycle	HONDA	CBR600	Yellow		0
SKR8341M	Car	VOLVO	XC60	Black		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBF425C	GREAT AMERICAN INSURANCE COMPANY	MT2018TR01400	07/07/2018	06/07/2019



**SINGAPORE
POLICE FORCE**



T/20190509/2114

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

2 of 3

Report No. T/20190509/2114

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	CHIN JUN LIN	ID No.	S8713891G
Related Vehicle	FBF425C (Motorcycle)	Contact No.	82993951
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	09/05/2019	Date Discharge	09/05/2019
No. of Days granted Medical Leave	14	Degree of Injury	NIL
Driver			
Name	KHOO JEAN NEE	ID No.	S8278068H
Related Vehicle	SKR8341M (Car)	Contact No.	91505559
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 09/05/2019, at about 7:50am, I was riding my motorcycle (FBF425C) along Seletar Expressway (Bukit Timah Expressway) towards Woodlands with no pillion on board in between lane 1 and lane 2.

As I was riding in between the lane at about 50 to 60km/hr, a car (SKR8341M) from lane 1 had make a change of lane to lane 2 without signalling in front of me. I could not brake in time as such I had collided onto the rear of the car and fell to the ground. I was not wearing any camera on my helmet or anywhere. The car (SKR8341M) had provided his assistance. Both the ambulance and police had attended to us.

I was conveyed to Khoo Teck Puat Hospital and was discharged thereafter with 14 days medical certificate. There were two people able to be my witness namely Afiq HP: 91013707, Muhsin HP: 96163569.



**SINGAPORE
POLICE FORCE**



T/20190509/2114

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

3 of 3

Report No. T/20190509/2114

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Staff Sgt CHAN DE MING	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 09/05/2019 15:19
Officer In Charge Of Case: TP / GIT / Staff Sgt NORAMEERA BINTE MOHAMED HUSSEIN Contact No.: 65476236	Classification Of Case:
Authentication Stamp NP168  SINGAPORE POLICE FORCE	 SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/05/2019 17:46
Date Of Accident	09/05/2019 07:50
Exact Location Of Accident	SLE TOWARDS BUKIT TIMAH EXPRESSWAY
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FBF425C
Insured/Policyholder	
Name Of Registered Owner	CHIN JUN LIN
NRIC No	S8713891G
Email Address	VERN0N87@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-82993951
Alternative Phone No	OFFICE-82993951
Vehicle Particulars	
Manufacturer	HONDA
Model	CBR600RR-599CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	
Cover Note Number	MT2018TR01400
Driver	
Name of Driver	CHIN JUN LIN
NRIC No	S8713891G
Date Of Birth	21/05/1987
Occupation	INDOOR
Date Of Driving Pass	08/06/2011
Driving Experience	7 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82993951
Fax Number	
Contact Number	OFFICE-82993951
EMail Address	VERN0N87@HOTMAIL.COM

Address	NO
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (Including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO TRAFFIC ACCIDENT REPORT NO. T/20190509/2114 ATTCHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	AFIQ
Phone Number	91013707
Email Address	

Details of Witness 2

Name	MUHSIN
Phone Number	96163569
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKR8341M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name CHIN JUN LIN

Approximate Age

Injuries Sustain

Injured person in which vehicle? FBF425C

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 10/5/2019 2:15pm

Driver's Signature

(if driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name: Tan Choe Koh

NRIC/FIN No.: 67715235R

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the traffic accident report no. T/20190509/2114 attached

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 10/5/2019 @ 2.15pm

SIAMAC SketchPlanForm_V3

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: Tan Aoi Lee

NRIC/FIN No.: GT152352

Traffic Accident Report Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190509/2114

1 of 3

Report No. T/20190509/2114

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/05/2019 15:19		Vide Report No.:		Station Diary No.: 23	
Informant's Particulars					
Name of Informant: CHIN JUN LIN			Address: APT BLK 301 TAMPINES STREET 32 #04-22 SINGAPORE 520301		
ID Type / ID No.: NRIC NO / S8713891G			Contact No.: Home/Office: Mobile: 82993951		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 31	Date of Birth: 21/05/1987	Type of Informant: Rider		
Race: Chinese			Language: English		Institution / School Name:
Occupation: OPERATION SUPERINTENDENT			Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 09/05/2019 07:50	Type of Location:
Location: Along Road 1 SELETAR EXPRESSWAY TOWARDS BUKIT TIMAH EXPRESSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

			Model	Color	Condition	No. of Passengers
FBF425C	Motorcycle	HONDA	CBR600	Yellow		0
SKR8341M	Car	VOLVO	XC60	Black		0

			Insurance	Policy No.	Policy Term
FBF425C	GREAT AMERICAN INSURANCE COMPANY	MT2018TR01400	07/07/2018	08/07/2019	

Scanned by CamScanner



**SINGAPORE
POLICE FORCE**



T/20190509/2114

2 of 3

Report No. T/20190509/2114

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHIN JUN LIN	ID No.	S8713891G
Related Vehicle	FBF425C (Motorcycle)	Contact No.	82993951
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	09/05/2019	Date Discharge	09/05/2019
No. of Days granted Medical Leave	14	Degree of Injury	NIL
Driver			
Name	KHOO JEAN NEE	ID No.	S8278088H
Related Vehicle	SKR8341M (Car)	Contact No.	91505559
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 09/05/2019, at about 7:50am, I was riding my motorcycle (FBF425C) along Seletar Expressway (Bukit Timah Expressway) towards Woodlands with no pillion on board in between lane 1 and lane 2.

As I was riding in between the lane at about 50 to 60km/hr, a car (SKR8341M) from lane 1 had make a change of lane to lane 2 without signalling in front of me. I could not brake in time as such I had collided onto the rear of the car and fell to the ground. I was not wearing any camera on my helmet or anywhere. The car (SKR8341M) had provided his assistance. Both the ambulance and police had attended to us.

I was conveyed to Khoo Teck Puat Hospital and was discharged thereafter with 14 days medical certificate. There were two people able to be my witness namely Afiq HP: 91013707, Muhsin HP: 96163569.

Scanned by CamScanner

Traffic Accident Report Pg. 1



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999



T/20190509/2114

3 of 3

Report No. T/20190509/2114

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Staff Sgt CHAN DE MING	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 09/05/2019 15:19
Officer In Charge Of Case: TP / GIT / Staff Sgt NORAMEERA BINTE MOHAMED HUSSEIN Contact No.: 65478238	Classification Of Case:
Authentication Stamp SP166	 SIGNATURE



TACHYON MOTOR PTE LTD

Blk 9004 Tampines St 93

#01-108 Singapore 528838

Tel: 67831948

Email: tyt_tak@hotmail.com

QUOTATION

R.O.C: 200704431R

ASSESSMENT FOR REPAIR :FBF425C

QTY	DESCRIPTION	PRICE \$
1PC	TOP COWLING / CAA	\$788.00
1PC	SIDE FARING LH / S N's	\$437.50
1PC	SIDE FARING PANEL LH	\$62.50
1PC	FRONT FENDER / cut	\$225.00
1PC	MIRROR LH / cut	\$156.25
1PC	WINDSCREEN	\$246.75
1PC	HANDLE BAR LH / BT	\$298.00
1PC	BALANCER LH / cut	\$80.00
1PC	EXHAUST MUFFLER / BT	\$1,980.00
1PC	LAMP STAY / cut	\$285.00
2PCS	AIR INTAKE / CAA	\$278.00
1PC	METER COVER / cut	\$325.00
1PC	HEAD LAMP ASSY / D's	\$750.00
1PC	TOP COWLING LOWER PANEL / CAA	\$65.00
1PC	HEAD LIGHT PANEL LH / S N's	\$45.00
1PC	FRONT SIGNAL LIGHT LH	\$195.00
1PC	LOWER FAIRING LH / CAA	\$356.00
1PC	RADIATOR ASSY / cut	\$985.00
2PCS	CLUTCH LEVER	\$65.00
1SET	STEERING CONE / S N's	\$180.00
1PC	STEERING STEM	\$688.00
1PC	FRONT FORK LH / local repair (150) SN	\$1,625.00
1PC	FRONT DISC ROTOR LH / X S N's	\$685.00
1PC	FRONT WHEEL / X	\$1,550.00
1PC	HANDLE SWITCH LH / cut	\$180.00
1PC	TANK COVER / cut CAA	\$937.50
1PC	FRONT FOOTREST LH / cut	\$125.00
2PCS	REAR SIGNAL LH RH / cut	\$390.00
1PC	EXHAUST COVER CENTER	\$125.00
1PC	EXHAUST COVER RH LH / CAA	\$250.00
1PC	PILLION SEAT / TN	\$680.00
1PC	REAR FENDER / X NN	\$125.00
1PC	SEAT PANEL / CAA	\$565.00
1PC	REAR SHAFT FRAME / repair X	\$950.00
	Fork end / 10%	\$16,678.50
		-\$1,667.85
		\$15,010.65
	GEAR SOCK / cut	\$45.00
	FRAME SLIDER / cut	\$220.00
	SWING ARM SLIDER / cut	\$120.00
	REAR WHEEL SLIDER / cut	\$160.00
	HEAD LIGHT PROTECTOR / m's	\$160.00
	TRANSPORT CHARGE 2 WAY	\$70.00

11743.5

10%: 10569.15

20
120
60
80
80
50. SN

FORK ALIGNED
NUMBER PLATE FRONT
LABOUR CHARGES

(YN)

\$280.00

\$15.00

\$320.00

\$16,400.65

60

250

885

11454.15

20%: 5500

3 Days.

Unpainted repair.

After repair photos.

Eric Quay - 82880282

23/5/19.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 May 2019 Edit Reg		22 May 2019 00:00 Edit Adj Rpt	S\$5,500.00 Edit Estimates	S\$5,500.00 View Rpt		Pending for Survey Report Cancel Case






































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: KHOO JEAN NEE , ID: 58278068H									
Main Claimant: -									
Vehicle Reg. No.: FBF425C		Date of Loss: 09/05/2019 00:00 - :59 [100 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 2553534984SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SKR8341M		Policy No. (Claimant):							
		Excess:							
Repairer: Tachyon Motor Pte Ltd (HQ) 9004 TAMPINES ST. 93, #01-108, 528838 Tampines - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 07/06/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (29/05/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





































Claim Documents

***FBF425C (2553534984SG)
[SKR8341M]**

TP

-
**May 9 2019 12:00AM
[KHOO JEAN NEE]
Tachyon Motor Pte Ltd**

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
2	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
3	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
4	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
5	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
6	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
7	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
8	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
9	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
10	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
11	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
12	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
13	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
14	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
15	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
16	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
17	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
18	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
19	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
20	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
21	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
22	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
23	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
24	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
25	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
26	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
27	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
28	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
29	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
30	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
31	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
32	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
33	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
34	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
35	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
36	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			
37	16/07/19 11:39	General View														Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
39	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
40	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
41	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
42	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
43	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
44	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
45	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
46	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
47	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
48	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
49	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
50	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
51	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
52	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
53	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
54	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
55	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
56	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
57	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
58	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
59	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
60	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
61	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
62	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
63	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
64	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
65	16/07/19 11:39	General View		<input checked="" type="checkbox"/>
66	16/07/19 11:39	Reinspection Photo		<input checked="" type="checkbox"/>
67	16/07/19 11:39	Reinspection Photo		<input checked="" type="checkbox"/>
68	16/07/19 11:39	Reinspection Photo		<input checked="" type="checkbox"/>
69	16/07/19 11:39	Reinspection Photo		<input checked="" type="checkbox"/>
70	16/07/19 11:39	Reinspection Photo		<input checked="" type="checkbox"/>
71	16/07/19 11:39	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/07/19 14:50	FBF425C_GIA REPORT.pdf		<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	29/05/19 10:33	OI GIA REPORT		<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19009035/GSD3E2

Date: 31/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FBF425C

Insured Vehicle No : SKR8341M

Date of Loss: 09/05/2019

Nature of Claim: TP

Claim No: 2553534984SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBF425C**

Make & Model: HONDA CBR600RR, 599cc

Engine No: PC40E2208015

Reg. Date: 07/01/2011 (Man. Year: 2010)

Chassis No: JH2PC40C3BK400317

Colour: Yellow

Odometer: 0 km

Engine Capacity: 599 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70-17

Rear Tyre Size: 180/55-17

Front Left Side: Timsun 4 mm

Rear Left Side: Timsun 4 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,730.65	11,094.15	4,636.50	29.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	670.00	360.00	310.00	46.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,400.65	11,454.15	4,946.50	30.16
Approved Total (Overridden) (S\$)		5,500.00		
Nett Amount (S\$)	16,400.65	5,500.00	10,900.65	66.46

INSPECTION

Date of Assignment: 22/05/2019

Date Inspected: 23/05/2019 Inspected At:

Tachyon Motor Pte Ltd (HQ)
9004 TAMPINES ST. 93, #01-108
Singapore 528838

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOP COWLING	Cracked	788.00 FL	*788.00 FL
2	1		*SIDE FAIRING LH	Distorted	437.50 FL	*437.50 FL
3	1		*SIDE FAIRING PANEL LH	Distorted	62.50 FL	*62.50 FL
4	1		*FRONT FENDER	Cut	225.00 FL	*225.00 FL
5	1		*MIRROR LH	Cut	156.25 FL	*156.25 FL
6	1		*WINDSCREEN	Cut	246.75 FL	*246.75 FL
7	1		*HANDLE BAR LH	Bent	298.00 FL	*298.00 FL
8	1		*BALANCER LH	Cut	80.00 FL	*80.00 FL
9	1		*EXHAUST MUFFLER	Bent	1,980.00 FL	*1,980.00 FL
10	1		*LAMP STAY	Broken	285.00 FL	*285.00 FL
11	2		*AIR INTAKE	Cracked	278.00 FL	*278.00 FL
12	1		*METER COVER	Cut	325.00 FL	*325.00 FL
13	1		*HEAD LAMP ASSY	Distorted	750.00 FL	*750.00 FL
14	1		*TOP COWLING LOWER PANEL	Cracked	65.00 FL	*65.00 FL
15	1		*HEAD LIGHT PANEL LH	Distorted	45.00 FL	*45.00 FL
16	1		*FRONT SIGNAL LIGHT LH	Distorted	195.00 FL	*195.00 FL
17	1		*LOWER FAIRING LH	Cracked	356.00 FL	*356.00 FL
18	1		*RADIATOR ASSY	Dented	985.00 FL	*985.00 FL
19	2		*CLUTCH LEVER	Cut	65.00 FL	*65.00 FL
20	1		*SET STEERING CONE	Necessary	180.00 FL	*180.00 FL
21	1		*STEERING STEM	Necessary	688.00 FL	*688.00 FL
22	1		*FRONT FORK LH (LOCAL REPAIR)	Bent	1,462.50 FS	*150.00 FS
23	1		*FRONT WHEEL	Not Necessary	1,550.00 FL	*- FL
24	1		*HANDLE SWITCH LH	Cut	180.00 FL	*180.00 FL
25	1		*TANK COVER	Cracked	937.50 FL	*937.50 FL
26	1		*FRONT FOOTREST LH	Cut	125.00 FL	*125.00 FL
27	2		*REAR SIGNAL LH RH	Cut	390.00 FL	*390.00 FL
28	1		*EXHAUST COVER CENTER	Cracked	125.00 FL	*125.00 FL
29	1		*EXHAUST COVER RH LH	Cracked	250.00 FL	*250.00 FL
30	1		*PILLION SEAT	Torn	680.00 FL	*680.00 FL
31	1		*REAR FENDER	Not Necessary	125.00 FL	*- FL
32	1		*SEAT PANEL	Cracked	565.00 FL	*565.00 FL
33	1		*REAR SHAFT FRAME	Repair	950.00 FL	*- FL
34	1		*GEAR SHOCK	Cut	45.00 FS	*20.00 FS
35	1		*FRAME SLIDER	Cut	220.00 FS	*120.00 FS
36	1		*SWING ARM SLIDER	Cut	120.00 FS	*60.00 FS
37	1		*REAR WHEEL SLIDER	Cut	160.00 FS	*80.00 FS
38	1		*HEAD LIGHT PROTECTOR	Missing	160.00 FS	*80.00 FS
39	1		*NUMBER PLATE FRONT	Necessary	15.00 FS	*15.00 FS
40	1		*FRONT DISC ROTOR LH	Not Necessary	685.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	17,236.00	12,268.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,505.35	1,174.35
Total Parts (\$\$)	15,730.65	11,094.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT CHARGE 2 WAY	New	70.00	50.00
2	FORK ALIGNED	New	280.00	60.00
3	LABOUR CHARGES	New	320.00	250.00
Gross Labour Cost (S\$)			670.00	360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >