

ASS. REC. BY:

REF: CS/CT119009061/ES d307

Special Instruction:

SURVAYOR AMEASSIGNMENT (Office)From (Person): ONG chin kiattof CTIDate/Time: 23.5.19 10.59 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMG 73351Insured: GBC 24201at Workshop m/s Volkswagen CentreTel: 92361399of 247 Alexandra RoadPolicy No: DM CR-N 30621618000Claim No: SM19D20229502

Sum Insured:

Excess:

Make of Veh:
(Client's Record)D.O.A. 21.5.2019

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 23.5.19 10.59 a.mPerson Contacted: charmaine

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SMG 73351 - X

GBC 24201 - CS/SM017000147/K10602

D.O.A. - 02/01/2017

ASKED BY

Steve

REF:

CTI

ASSIGNMENT

From:

Date:

27/5

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMG 7335Y

at Workshop m/s Volkswagen

of 247 Alexandra Rd

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

9:30am Driver Waiting

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMG 7335Y

Vt Regn:

2

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Skoda Superb

C.C.

1984

Colour:

Black

A/C: Insured / Std / NI / NA

Sp Reading:

8206

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

TM880 7NPSK 704 522

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/40R19

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal:

7

mm

R/Bal:

7

mm

L/Bal:

7

mm

L/Bal:

7

mm

D.O.A.

22/5/19

D.O.I.

27/5/19

Survey held at

Volkswagen

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Can't find out value

Steve

pls see my remarks

25/7/19

Finalize confirm \$14,684.78, 7 days (perlyn)

(\$3,049.00 Red - 17%)

RECEIVED 30 JUL 2019

31/5

Date/Time, File Name (v)

29/07/19

1) Typist

Date/Time, File Name (v)

2)

Report Format:

Lump Sum (LE)



Prel. Report



Final Report

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:



Site Insp (S)



Interview (S)



Tech. Insp (S)



Welding (S)

Survey Fee:

220

Transportation:

S + RD (S)

Hires:

+ Rem:

TOTAL

220

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Tuesday, 21 May 2019 2:49 PM
To: Mastura; 'Claims'
Cc: Cecilia Chong (LKK Auto); Admin A; CS A Team; assignments
Subject: RE: ACCIDENT INVOLVING SLQ 1900 P AND YOUR INSURED GBE6742C DATED ON 16/05/2019 *** LKK REF: CC4/ASM19008872/ga3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS


Dear Sir / Madam,

We refer to the above matter.

Please be informed that we are currently **pending verification for direct settlement.**

Fyi, OI has reported. Please refer to the below OI's sketch plan and statement.

Sketch Plan



Describe Circumstances of the Accident

I received a call at around 9:15 pm on 16/5/2019 from Mr. Deyu, claiming that my vehicle had hit his vehicle when reversing into the parking lot.

My driver was sure that when ~~they~~ she adjusted, ~~to~~ she went to the rear of the lorry to retrieve items for unloading, ~~about the small gap of 5cm~~ it ~~almost~~ ~~fully~~ ~~with~~ the small 5cm gap that was between the two vehicles when we were alerted to the accident.

Audi driver claims to enter carpark at 6+ pm, my lorry enter at 7:30 pm.

Audi driver claims to have reverse camera and will

Please provide us evidence i.e. video and scene photo and arrange for TP survey.

Please note that for liability, claim negotiation and settlement, please contact **Cecilia at 6749 4274**.

Our respective case handler will look into the matter and revert to you in due course.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 May 2019		23 May 2019 10:52 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:		LEADER FOOD PTE LTD, Co. Reg. No.: 201015207H		[Created by insurer]
Main Claimant:		AIRTAC INTERNATIONAL (SINGAPORE) PTE LTD, Co. Reg. No.: 201119044G		
Vehicle Reg. No.:	SMG7335Y	Date of Loss:	22/05/2019 08:00 - :59 [4 Months and 21 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM19D202295C02	Policy/Cover Note No.:	DMCVSN30621618000 (Comprehensive)	
Vehicle Reg. No. (Insured):	GBC2420T	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	Volkswagen Centre Singapore (HQ) 247 Alexandra Road, 159934 Alexandra - Tel: 63057288			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/06/2019]			
Adj Asg. Remarks:	please contact Charmaine at 9236 1399 for TP survey, thank you			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail



ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View All

Search Tasks

Create New Task

Complete

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9035E
Vehicle Details	
Vehicle No.:	SMG7335Y
Vehicle to be Exported:	No
Intended Deregistration Date:	30 May 2019
Vehicle Make:	SKODA
Vehicle Model:	SUPERB L&K 2.0 TSI (A)
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	CHH291524
Chassis No.:	TMBBD7NP5K7019522
Maximum Power Output:	162.0 kW (217 bhp)
Open Market Value:	\$30,573.00
Original Registration Date:	28 Dec 2018
First Registration Date:	28 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$34,803.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2028
PARF Rebate Amount:	\$26,102.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$31,809.00
COE Rebate Amount:	\$29,675.00
Total Rebate Amount:	\$55,777.00

The information contained herein is correct as at 30 May 2019

OK

AXA
 VS
 CHINA
 TAPING

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

047.

ACCIDENT STATEMENT

Date Of Report 22/05/2019 13:57
 Date Of Accident 22/05/2019 08:30
 Exact Location Of Accident CLEMENTI AVE 6
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMG7335Y
Insured/Policyholder
 Name Of Registered Owner AIRTAC INTERNATIONAL (SINGAPORE) PTE LTD
 Co Reg No 201119044G
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-91220736

Vehicle Particulars

Manufacturer SKODA
 Model SUPERB L&K 2.0 L TSI 162KW DSG

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number VPA / P2230500
 Cover Note Number

Driver

Name of Driver TUNG YUNN - TSONG
 NRIC No G5403379L
 Date Of Birth 14/01/1979
 Occupation INDOOR
 Date Of Driving Pass 08/01/2019
 Driving Experience 0 YEAR AND 4 MONTH
 Gender MALE
 Mobile Number (LOCAL) +65-91220736
 Fax Number
 Contact Number
 Email Address DONGYC@AIRTAC.COM

Address	06-26 11 KING ALBERT PARK
Postcode	598292
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO SIZE EXCEEDED
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC2420T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Driver details: TUNG YUNN TSONG
FIN : G5403379L.
~~FIN~~
DATE/TIME : 22 May 8:30 AM.
Entrapment to AYE, vehicle was hit from behind
when waiting the main road pass by.
car from

DECLARATION

(/We declare the foregoing particulars are true in every respect

Policyholder's Signature _____
Date & Time: _____

Driver's Signature: _____
 (If driver is not the policyholder)
 Date & Time: 2/2/2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

AXA INSURANCE PTE LTD
8 Shenton Way, #24-01
AXA Tower, Singapore 068811
Customer Centre #01-21
Tel: 1800 8504888
Website: www.axa.com.sg
GST Registration Number: 199903512M
customer.care@axa.com.sg



CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) Motor Vehicles (Third-Party Risks and Compensation) Rules, 1969 Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO. : VPA/P2230500 Account No. : 16720
Coverage : Comprehensive (SmartDrive ŠKODA)
Sum Insured : Market Value At The Time Of Loss
Name of Policy Holder : AIRTAC INTERNATIONAL (SINGAPORE) PTE LTD
Vehicle Registration No. : SMG7335Y
Period of Insurance : From 28/12/2018 To 27/12/2019 (Both Dates Inclusive)

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

- (a) The Policyholder.
The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employee or his partner.
(b) Any other person who is driving on the Policyholder's order or with his permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trader or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

(10)

Basic Own Damage Excess : SGD 900.00

An Additional Excess is applicable as follows:

\$52,500.00 for Young or Inexperienced Driver.

Young or Inexperienced Driver is defined as any driver whom is aged below 23 years old and/or less than one year of driving experience.

(Please refer to your policy on the terms & conditions)* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings:

I/we hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

ARF (Asia Pacific) Pte Ltd
7 Maxwell Road #01-100
MND Complex, Annex 5
Singapore 069111

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - SGOGOWT on 43476

IMPORTANT:

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189). The Premium Warranty Clause requires the premium to be paid in full within a specific period falling which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Driving License

EMPLOYMENT PASS
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer:
HARTAS INTERNATIONAL CONSULTANTS PTE. LTD.

Name:
TUNG YUNN-TSONG

Pass:
G5403379L

NO 00000000

REPUBLIC OF SINGAPORE DRIVING LICENCE

Passport Number: **G5403379L**

Name: **TUNG YUNN-TSONG**

Birth Date: **14 Jan 1979**

Issue Date: **06 Jan 2019**

Valid Till: **07-01-2024**

VISIT PASS
Immigration Regulations

Name:
TUNG YUNN-TSONG

Pass:
G5403379L

Date of Birth:
14-01-1979

Gender:
M

Nationality:
TUNG YUNN-TSONG

MULTIPLE JOURNEY VISA ISSUED

THIS PASS IS VALID FOR ENTRY TO SINGAPORE FOR TOUR PURPOSES. THE PASS IS NOT VALID FOR EMPLOYMENT.

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

EFFECTIVE DATE:

Class	Description	Effective Date
Class 2B	Motorcycles <= 200 cc	06 Jan 2019
Class 1	Motor cars with unladen weight <= 3000kg with <= 7 passengers, exclusive of driver and other motor vehicles with unladen weight <= 2500kg	06 Jan 2019

HP 435A

License No: G5403379L

SKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052

Steve CLKK
83228813

WHL Airjeda
P/P
Rery bnf spg
7 to chys

27/5/19, 10:00 am



Quotation
Non binding - Preview

Page 1 1/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Company
AIRTAC
INTERNATIONAL
12 GUL DRIVE
#01-00 AIRTAC INTERNATIONAL
Singapore 629483

Document no.
Document date 22-05-2019
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 39999
Job order number 2019000689/ 1
Job order date 22-05-2019
Service Advisor EDMUND, HUI HUANG
GOH

License plate	Model code	First registration	VIN	Model	Mileage
SMG7335Y	3V35SC	28-12-2018	TMBBD7NP5K7019522	Superb L&K 2.0 TSI 162kW DSG	17

Position no	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs	280.00	#1	280.00	299.60
3V5807421	Cover For <i>BD</i>	1	pcs	1,740.00	#1	1,740.00	1,861.80
3V5807521 9B9	Spoiler <i>CUT</i>	1	pcs	281.00	#1	281.00	300.67
3V5807305A	Reinforcem <i>? 2 ALK</i>	1	pcs	609.00	#1	609.00	651.63
3V5807863	Retaining <i>ALK</i>	1	pcs	72.30	#1	72.30	77.36
3V5807393A	Guide Piac <i>ALK</i>	1	pcs	43.30	#1	43.30	46.33
	(BUMPER GUIDE LH) <i>ALK</i>						
3V5807394A	Guide Piac <i>ALK</i>	1	pcs	43.30	#1	43.30	46.33
	(BUMPER GUIDE RH) <i>ALK</i>						
3V5807393	Guide Piac <i>ALK</i>	1	pcs	43.30	#1	43.30	46.33
	(BUMPER BRACKET LH) <i>ALK</i>						
3V5807394	Guide Piac <i>ALK</i>	1	pcs	43.30	#1	43.30	46.33
	(BUMPER BRACKET RH) <i>ALK</i>						
3V5919487	Sensor Bra	1	pcs	30.70	#1	30.70	32.85
3V5919485A	Sensor Bra <i>ALK</i>	1	pcs	45.00	#1	45.00	48.15
3V5919485	Sensor Bra	1	pcs	45.00	#1	45.00	48.15
3V5919486	Sensor Bra	1	pcs	45.00	#1	45.00	48.15
3V5919486A	Sensor Bra	1	pcs	45.00	#1	45.00	48.15
3V5919488	Sensor Bra	1	pcs	30.70	#1	30.70	32.85
D 822150A1	Bonding Agent For Plastic <i>ALK</i>	1	pcs	56.90	#1	56.90	60.88
D 180KU2A1	2k-Plastic Adhesive <i>ALK</i>	1	pcs	74.29	#1	74.29	79.49
3V5827023B	Rear Trunk <i>BD</i>	1	pcs	3,605.00	#1	3,605.00	3,857.35
3V0853687 2ZZ	Inscriptio <i>ALK</i>	1	pcs	74.30	#1	74.30	79.50
	(SKODA) <i>ALK</i>						
3V0853621A FOD	Skoda Embl <i>ALK</i>	1	pcs	63.80	#1	63.80	68.27
3V0853687A 2ZZ	Inscriptio <i>ALK</i>	1	pcs	100.00	#1	100.00	107.00
	(SUPERB) <i>ALK</i>						
D 189300M2	1k Window Adhesive <i>ALK</i>	1	pcs	49.88	#1	49.88	53.37
D 00920002	Primer <i>ALK</i>	1	pcs	25.92	#1	25.92	27.73
D 00950025	Applicator <i>ALK</i>	1	pcs	9.48	#1	9.48	10.14
D 181802M1	Activator For Precoated W <i>ALK</i>	1	pcs	23.63	#1	23.63	25.28
D 00940104	All Purpose Cleaner <i>ALK</i>	1	pcs	89.95	#1	89.95	96.25
	LABOUR <i>42</i>	1	pcs	840.00	#1 <i>1680</i>	3,360.00	3,595.20
	Spray Painting <i>42</i>	1	pcs	800.00	#1 <i>1600</i>	3,200.00	3,424.00
	TRANSFER BOOT MECHANISM PARTS	1	pcs	840.00	#1	840.00	898.80
	R&R REAR WINDSCREEN <i>ALK</i>	1	pcs	840.00	#1 <i>470</i>	840.00	898.80

Quotation valid till 29-05-2019
L&K Auto Consultants hence notify

the Repairer of the following:

• To carry out the following work:

• To display damaged parts for survey

• Parts prices are subject to confirmation

• The survey is on a "No Fault" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

17733.79

19043.78

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Volkswagen



ŠKODA



Commercial
Vehicles

Quotation

Non binding - Preview

Page

2/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Company
AIRTAC
INTERNATIONAL
12 GUL DRIVE
#01-00 AIRTAC INTERNATIONAL
Singapore 629463


Document no
Document date
Customer no
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
22-05-2019
5211001170
200208384E
39999
2019000689/ 1
22-05-2019
EDMUND, HUI HUANG
GOH

License plate	Model code	First registration	VIN	Model	Mileage
SMG7335Y	3V35SC	28-12-2018	TMBBD7NP5K7019522	Superb L&K 2.0 TSI 162kW DSG	17

Customer

Service Advisor

— VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions). —



Raul 10/7/19

Supplementary or Omitted List



VEHICLE NUMBER: **SMG7335Y**

MODEL **Superb**

CLAIMS DETAILS

	LABOUR DESCRIPTION	AMOUNT		
		Qty	Unit	Amount
1	SOLAR FILM <i>acc /</i>	1	\$ 400.00	\$ 400.00
1	R&R ROOF LINING	1.5	\$ 840.00	\$ 1,260.00
Total				\$400.00

No.	Item No.	Description	Qty	Unit Pricing	Discount	Amount
1	3V5845049R NVB	REAR WINDOW <i>acc /</i>	1	\$ 1,000.00		\$1,000.00
2	3V5860523 9B9	Strip <i>acc /</i>	1	\$ 20.70		\$ 20.70
3	WHT007341	Rivetted Cap Nut <i>acc /</i>	2	\$ 1.88		\$ 3.76
4	533867910A	Felt Strip <i>acc /</i>	1	\$ 19.27		\$ 19.27
5						
6						
7						
8						
9						
TOTAL:						\$1,043.73

Total Labour & Parts

\$1,443.73

Survey By

LKK

SKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Volkswagen



SKODA



Commercial Vehicles

Tax invoice

Preview

Page

1/3

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Company
AIRTAC
INTERNATIONAL
12 GUL DRIVE
#01-00 AIRTAC INTERNATIONAL
Singapore 629463

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
25-07-2019
5211001170
200208384E
39999
2019001020/ 1
18-06-2019
EDMUND, HUI HUANG
GOH

License plate	Model code	First registration	VIN	Model	Mileage		
SMG7335Y	3V35SC	28-12-2018	TMBBD7NP5K7019522	Superb L&K 2.0 TSI 162kW DSG	10,338		
Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	R&R ROOF LINING	1.5	pcs.	840.00	#1	1,260.00	1,348.20
3V5807421	Cover For XR-200619	1	pcs.	1,740.00	#1	1,740.00	1,861.80
3V5807521 989	Spoiler XR-200619	1	pcs.	281.00	#1	281.00	300.67
3V5807863	Retaining AO-210619	1	pcs.	72.30	#1	72.30	77.36
3V5807393A	Guide Piec (BUMPER GUIDE LH)*XR-200619	1	pcs.	43.30	#1	43.30	46.33
3V5807394A	Guide Piec (BUMPER GUIDE RH)*XR-200619	1	pcs.	43.30	#1	43.30	46.33
3V5807393	Guide Piec (BUMPER BRACKET LH)*XR-200619	1	pcs.	43.30	#1	43.30	46.33
3V5807394	Guide Piec (BUMPER BRACKET RH)*XR-200619	1	pcs.	43.30	#1	43.30	46.33
3V5919487	Sensor Bra AO-210619	1	pcs.	30.70	#1	30.70	32.85
3V5919485A	Sensor Bra AO-210619	1	pcs.	45.00	#1	45.00	48.15
3V5919485	Sensor Bra AO-210619	1	pcs.	45.00	#1	45.00	48.15
3V5919486	Sensor Bra AO-210619	1	pcs.	45.00	#1	45.00	48.15
3V5919486A	Sensor Bra AO-210619	1	pcs.	45.00	#1	45.00	48.15
3V5919488	Sensor Bra AO-210619	1	pcs.	30.70	#1	30.70	32.85
D 822150A1	Bonding Agent For Plastic AO-210619	1	pcs.	56.90	#1	56.90	60.88
D 180KU2A1	2k-Plastic Adhesive XR-200619	1	pcs.	74.29	#1	74.29	79.49
3V5827023B	Rear Trunk OS-210619	1	pcs.	3,605.00	#1	3,605.00	3,857.35
3V0853687 2ZZ	Inscriptio (SKODA)*AO-210619	1	pcs.	74.30	#1	74.30	79.50
3V0853621A FOD	Skoda Embl AO-210619	1	pcs.	63.80	#1	63.80	68.27
3V0853687A 2ZZ	Inscriptio (SUPERB)*AO-210619	1	pcs.	100.00	#1	100.00	107.00
D 169300M2	1k Window Adhesive XR-200619	1	pcs.	49.88	#1	49.88	53.37
D 00920002	Primer XR-200619	1	pcs.	25.92	#1	25.92	27.73
D 00950025	Applicator XR-200619	1	pcs.	9.48	#1	9.48	10.14

SKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Tax invoice Preview

Page 2/3

Document no.
Document date 25-07-2019
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 39999
Job order number 2019001020/ 1
Job order date 18-06-2019
Service Advisor EDMUND, HUI HUANG GOH

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Company
AIRTAC
INTERNATIONAL
12 GUL DRIVE
#01-00 AIRTAC INTERNATIONAL
Singapore 629463

License plate	Model code	First registration	VIN	Model	Mileage
SMG7335Y	3V35SC	28-12-2018	TM8BD7NP5K7019522	Superb L&K 2.0 TSI 162kW DSG	10,338

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
D 181802M1	Activator For Precoated W XR-200619	1	pcs.	23.63	#1	23.63	25.28
D 00940104	All Purpose Cleaner XR-200619	1	pcs.	89.95	#1	89.95	96.25
3V5845049R NVB	Rear Windo REAR W/SCREEN*OS-110719	1	pcs.	1,000.00	#1	1,000.00	1,070.00
3V5860523 9B9	Strip OS-110719	1	pcs.	20.70	#1	20.70	22.15
WHT007341	Riveted Cap Nut XR-110719	2	pcs.	1.88	#1	3.76	4.02
533867910A	Felt Strip XR-110719	1	pcs.	19.27	#1	19.27	20.62
	LABOUR	2	pcs.	840.00	#1	1,680.00	1,797.60
	Spray Painting	2	pcs.	800.00	#1	1,600.00	1,712.00
	TRANSFER BOOT MECHANISM PARTS	0.5	pcs.	840.00	#1	420.00	449.40
	R&R REAR WINDSCREEN	1	pcs.	840.00	#1	840.00	898.80
	REAR SOLAR FILM	1	pcs.	400.00	#1	400.00	428.00
	Supply of Car Window Film						
	SURVEYED BY LKK STEVE. DIRECT SETTLEMENT AGAINST CHINA TAIPING DOA: 22.5.19 TP VEH. GBC2420T CHINA TAIPING DIRECT SETTLEMENT, DOA 22.5.2019, SURVEYED BY LKK, TP VEHICLE GBC2420T						

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	2,020.00	12,664.78	7%	1,027.93	14,684.78	15,712.71
Total	2,020.00	12,664.78		1,027.93	14,684.78	15,712.71

Customer

Service Advisor

Please inspect your vehicle prior to leaving our premises; we seek your understanding that we are not able to honour claims on scratches, dents etc. after your car has left our premises.

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Volkswagen



ŠKODA



Commercial
Vehicles

Tax invoice

Preview

Page

3/3

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Company
AIRTAC
INTERNATIONAL
12 GUL DRIVE
#01-00 AIRTAC INTERNATIONAL
Singapore 629463

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
25-07-2019
5211001170
200208384E
39999
2019001020/ 1
18-06-2019
EDMUND, HUI HUANG
GOH

License plate	Model code	First registration	VIN	Model	Mileage
SMG7335Y	3V35SC	28-12-2018	TMBBD7NP5K7019522	Superb L&K 2.0 TSI 162kW DSG	10,338

—VISIT OUR WEBSITE: offersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All fund transfer payments should be made payable to Volkswagen Group Singapore Pte Ltd, Bank Name: Deutsche Bank AG (Singapore Branch), Bank Account: 2528214002, Swift Code: DEUTSGSG. Please indicate Customer Number (eg. 521XXXXXXX), Customer Name and Invoice Number in the payments.

Until payment of all goods (parts, accessories etc.) has been made in full to and received by Volkswagen Group Singapore (VGS), the goods remain in legal possession of VGS, irrespective if they have already been installed into your vehicle. However, the warranty of the goods (where applicable) starts with the issuance of the invoice or the collection of your car, whichever is earlier.

For warranty terms and conditions please visit our website www.volkswagen.com.sg

This is an authorised document. No signature is required.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 May 2019		23 May 2019 10:52 Edit Adj Rpt	S\$14,684.78 Edit Estimates	S\$14,684.78 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	LEADER FOOD PTE LTD, Co. Reg. No.: 201015207H								
Main Claimant:	AIRTAC INTERNATIONAL (SINGAPORE) PTE LTD, Co. Reg. No.: 201119044G								
Vehicle Reg. No.:	SMG7335Y	Date of Loss:	22/05/2019 08:00 - :59 [4 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202295C02	Policy/Cover Note No.:	DMCVSN30621618000 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBC2420T	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Volkswagen Centre Singapore (HQ) 247 Alexandra Road, 159934 Alexandra - Tel: 63057288								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 03/06/2019]								
Adj Asg. Remarks:	please contact Charmaine at 9236 1399 for TP survey. thank you								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMG7335Y (SNM19D202295C02)**
[GBC2420T]
TP
AIRTAC INTERNATIONAL (SINGAPORE) PTE LTD
May 22 2019 8:00AM
[LEADER FOOD PTE LTD]
Volkswagen Centre Singapore

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/06/19 14:41	Video - Accident	Load MP4	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/05/19 08:28	General View	Load JPG	☒
2	28/05/19 08:28	General View	Load JPG	☒
3	28/05/19 08:28	General View	Load JPG	☒
4	28/05/19 08:28	General View	Load JPG	☒
5	28/05/19 08:28	General View	Load JPG	☒
6	28/05/19 08:28	Odometer Reading	Load JPG	☒
7	28/05/19 08:28	Chassis Number	Load JPG	☒
8	28/05/19 08:28	General View	Load JPG	☒
9	28/05/19 08:28	General View	Load JPG	☒
10	28/05/19 08:28	General View	Load JPG	☒
11	28/05/19 08:28	General View	Load JPG	☒
12	28/05/19 08:28	General View	Load JPG	☒
13	28/05/19 08:28	General View	Load JPG	☒
14	28/05/19 08:28	General View	Load JPG	☒
15	28/05/19 08:28	General View	Load JPG	☒
16	28/05/19 08:28	General View	Load JPG	☒
17	28/05/19 08:28	General View	Load JPG	☒
18	28/05/19 08:28	General View	Load JPG	☒
19	28/05/19 08:28	General View	Load JPG	☒
20	28/05/19 08:28	General View	Load JPG	☒
21	28/05/19 08:28	General View	Load JPG	☒
22	28/05/19 08:28	General View	Load JPG	☒
23	28/05/19 08:28	General View	Load JPG	☒
24	28/05/19 08:28	General View	Load JPG	☒
25	25/07/19 18:29	Photographs of Damaged Items	Load JPG	☒
26	25/07/19 18:29	Photographs of Damaged Items	Load JPG	☒
27	25/07/19 18:29	Photographs of Damaged Items	Load JPG	☒
28	25/07/19 18:29	Photographs of Damaged Items	Load JPG	☒
29	25/07/19 18:29	Photographs of Damaged Items	Load JPG	☒
30	25/07/19 18:29	Photographs of Damaged Items	Load JPG	☒
31	25/07/19 18:29	Photographs of Damaged Items	Load JPG	☒
32	25/07/19 18:29	Photographs of Damaged Items	Load JPG	☒
33	25/07/19 18:29	Photographs of Damaged Items	Load JPG	☒
34	25/07/19 18:29	Photographs of Damaged Items	Load JPG	

Video			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
35	25/07/19 18:29	Photographs of Damaged Items	 Load JPG	☒
36	25/07/19 18:29	Photographs of Damaged Items	 Load JPG	☒
37	25/07/19 18:29	Photographs of Damaged Items	 Load JPG	☒
38	25/07/19 18:29	Photographs of Damaged Items	 Load JPG	☒
39	25/07/19 18:29	Photographs of Damaged Items	 Load JPG	☒
40	25/07/19 18:29	Photographs of Damaged Items	 Load JPG	☒
41	25/07/19 18:29	Photographs of Damaged Items	 Load JPG	☒
42	25/07/19 18:29	Photographs of Damaged Items	 Load JPG	☒
43	25/07/19 18:29	Photographs of Damaged Items	 Load JPG	☒
44	25/07/19 18:29	Photographs of Damaged Items	 Load JPG	☒
45	25/07/19 18:29	Photographs of Damaged Items	 Load JPG	☒
46	25/07/19 18:29	Photographs of Damaged Items	 Load JPG	☒
47	25/07/19 18:29	Photographs of Damaged Items	 Load JPG	☒
48	25/07/19 18:29	Photographs of Damaged Items	 Load JPG	☒
49	25/07/19 18:29	Photographs of Damaged Items	 Load JPG	☒
50	25/07/19 18:29	Photographs of Damaged Items	 Load JPG	☒
51	25/07/19 18:29	Photographs of Damaged Items	 Load JPG	☒
52	25/07/19 18:29	Photographs of Damaged Items	 Load JPG	☒
53	25/07/19 18:29	Photographs of Damaged Items	 Load JPG	☒
54	25/07/19 18:29	Photo After Spray	 Load JPG	☒
55	25/07/19 18:29	Photo After Spray	 Load JPG	☒
56	25/07/19 18:29	Photo After Spray	 Load JPG	☒
57	25/07/19 18:29	Photo After Spray	 Load JPG	☒
58	25/07/19 18:29	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/05/19 10:50	Estimate	 Load PDF	
2	23/05/19 10:50	TP SMG7335Y GIA Report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119009061/ESD3E2

Date: 13/08/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30621618000
Claimant Vehicle No :	SMG7335Y	Insured Vehicle No :	GBC2420T
Date of Loss:	22/05/2019	Nature of Claim:	TP
		Claim No:	SNM19D202295C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG7335Y	Engine No:	CHH291524
Make & Model:	SKODA SUPERB, 2.0 (A)	Chassis No:	TMBBD7NP5K7019522
Reg. Date:	28/12/2018 (Man. Year: 2018)	Odometer:	8206 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R19	Rear Tyre Size:	235/40 R19
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,333.78	7,724.78	609.00	7.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,660.00	6,960.00	3,700.00	34.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,993.78	14,684.78	4,309.00	22.69
+ GST 7.00/7.00% (S\$)	1,329.56	1,027.93	301.63	22.69
Nett Amount (S\$)	20,323.34	15,712.71	4,610.63	22.69

INSPECTION

Date of Assignment:	23/05/2019	
Date Inspected:	27/05/2019	Inspected At: Volkswagen Centre Singapore (HQ) 247 Alexandra Road Singapore 159934
Estimated Period of Repair:	7.0 days	

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Aug 2019)
Parts:	144	SKODA SUPERB 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG7335Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR	Dented	1,740.00 FS	*1,740.00 FS
2	1		*SPOILER	Cut	281.00 FS	*281.00 FS
3	1		*REINFORCEM	Not Necessary	609.00 FS	*- FS
4	1		*RETAINING	Necessary	72.30 FS	*72.30 FS
5	1		*GUIDE PIEC (BUMPER GUIDE LH)	Necessary	43.30 FS	*43.30 FS
6	1		*GUIDE PIEC (BUMPER GUIDE RH)	Necessary	43.30 FS	*43.30 FS
7	1		*GUIDE PIEC (BUMPER BRACKET LH)	Necessary	43.30 FS	*43.30 FS
8	1		*GUIDE PIEC (BUMPER BRACKET RH)	Necessary	43.30 FS	*43.30 FS
9	1		*SENSOR BRA	Necessary	30.70 FS	*30.70 FS
10	1		*SENSOR BRA	Necessary	45.00 FS	*45.00 FS
11	1		*SENSOR BRA	Necessary	45.00 FS	*45.00 FS
12	1		*SENSOR BRA	Necessary	45.00 FS	*45.00 FS
13	1		*SENSOR BRA	Necessary	45.00 FS	*45.00 FS
14	1		*SENSOR BRA	Necessary	30.70 FS	*30.70 FS
15	1		*BONDING AGENT FOR PLASTIC	Necessary	56.90 FS	*56.90 FS
16	1		*2K-PLASTIC ADHESIVE	Necessary	74.29 FS	*74.29 FS
17	1		*REAR TRUNK	Dented	3,605.00 FS	*3,605.00 FS
18	1		*INSCRIPTIO (SKODA)	Necessary	74.30 FS	*74.30 FS
19	1		*SKODA EMBL	Necessary	63.80 FS	*63.80 FS
20	1		*1K WINDOW ADHESIVE	Necessary	49.88 FS	*49.88 FS
21	1		*PRIMER	Necessary	25.92 FS	*25.92 FS
22	1		*APPLICATOR	Necessary	9.48 FS	*9.48 FS
23	1		*ACTIVATOR FOR PRECOATED W	Necessary	23.63 FS	*23.63 FS
24	1		*ALL PURPOSE CLEANER	Necessary	89.95 FS	*89.95 FS
25	1		*REAR WINDOW	Necessary	1,000.00 FS	*1,000.00 FS
26	1		*STRIP	Necessary	20.70 FS	*20.70 FS
27	2		*RIVETTED CAP NUT	Necessary	3.76 FS	*3.76 FS
28	1		*FELT STRIP	Necessary	19.27 FS	*19.27 FS
29	1		*INSCRIPTIO (SUPERB)	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	8,333.78	7,724.78
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	280.00
3	LABOUR	New	3,360.00	1,680.00
4	SPRAY PAINTING	New	3,200.00	1,600.00
5	TRANSFER BOOT MECHANISM PARTS	New	840.00	420.00
6	R&R REAR WINDSCREEN	New	840.00	840.00
7	SOLAR FILM	New	400.00	400.00
8	R&R ROOF LINING	New	1,260.00	1,260.00
Gross Labour Cost (S\$)			10,660.00	6,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >