

21/02/2019

ASS. REC. BY:

REF: 03/CTI/9009085/Bcd307

Special Instruction:

Assigner: Mr Lim

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CTI

Date/Time:

22/5/19 @ 2:18pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGU 33274

Insured:

PC76864

at Workshop m/s

My Car Consultant

Tel:

8866 8832

of

53 ubi Ave1 #01-33

Policy No:

DMB1SN18326718000

Claim No:

SNM19D202194C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:05am 23/5/19

Person Contacted:

Hui Qin

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction	Estimate (X)
	SGU 33274 - NA / TMI 19008822 / 24	DA: 15/5/2019
	PC 76864 - NA / TMI 19008822 / 24	DA: 15/5/2019
	Dismantle: 24/5/2019	
	After repair: 29/5/2019	

ASS. REC. BY:

REF: CTI

ASSIGNMENT

Denise

From:

Date:

23/5/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGU 3327U

at Workshop m/s

MyCar Consultant

of

53 ubi Ave 1 #01-33

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGU 3327U

Yr Regn:

11/5/2007

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Suzuki SX4

c.c 1586

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

184431

T/Radio:

Insured / Std / NI / NA

Eng/No:

M16A1249785

C/No:

JSAGYA2IS00104167

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/60/16

R: 205/60/16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

15/5/19

D.O.I.

23/5/2019

Survey held at

MyCar Consultant

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range 3000/- - 4000/-

29/7/2019

MV 24,000/-

PV 14,608/-

NV 9,392/-

TRIM line
3/6/19

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

150

Transportation:

S + RS, St

Photos

Others

TOTAL

150

Report Format:

PRG.

Lump Sum / L.B.I. %

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2019		28 May 2019 16:13 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: BRIGHTSTAR CAR RENTAL PTE LTD, Co. Reg. No.: 201319803H									
Vehicle Reg. No.:	SGU3327U	Date of Loss:	15/05/2019 17:00 - :59						
Claim Type:	TP / SNM19D202194C02	Policy/Cover Note No.:	DMB1SN18326718000						
Vehicle Reg. No. (Insured):	PC7686U	Policy No. (Claimant):	18-MI001503-R01						
		Excess:	S\$0.00						
Repairer:	My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park, 408934 Ubi - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by DENISE TAY KWEE CHENG] ... [Final Rpt due 07/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 22 May 2019 2:18 PM
To: admin@mycar.sg
Cc: 'assignments'
Subject: RE: OUR REF : SNM19D202194 -PC7686U - & YR REF: SGU3327U-PRE-REPAIR INSPECTION FOR SGU3327U

**WITHOUT PREJUDICE
SAVE AS TO COSTS**

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: My Car Consultant [mailto:admin@mycar.sg]
Sent: Tuesday, 21 May, 2019 11:34 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: OUR REF : SNM19D202194 -PC7686U - & YR REF: SGU3327U-PRE-REPAIR INSPECTION FOR SGU3327U

WITHOUT PREJUDICE

Dear Boon Sen,

We refer to your email on even date.

We disagree to your list of surveyor and propose the use of one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

- a. Alan Cheong
- b. TT Rajan
- c. Oh Han Cheong
- d. Andrew How
- e. Dave Ho Joo Koong
- f. Lee Kok Weng
- g. Seah Kwang Boon
- h. Lee K.W.
- i. Nicky Seah
- j. Winson Goh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors.

Best Regards,

Huiqin

Direct line: 88668832 | Fax: 69255219

My Car Consultant Pte Ltd

53 Ubi Avenue 1

Paya Ubi Industrial Park #01-33

Singapore 408934

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

From: "Chong Boon Sen" <boonsen.chong@sg.cntaiping.com>

Sent: Tuesday, May 21, 2019 9:46 AM

To: "admin@mycar.sg" <admin@mycar.sg>

Subject: RE: OUR REF : SNM19D202194 -PC7686U - & YR REF: SGU3327U-PRE-REPAIR INSPECTION FOR SGU3327U

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG

SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** ??? Taiping SG 3 Anson Road
#16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Tuesday, 21 May, 2019 9:36 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; admin@mycar.sg

Subject: OUR REF : SNM19D202194 -PC7686U - & YR REF: SGU3327U -PRE-REPAIR INSPECTION FOR SGU3327U

Dear Boon Sen,

Please conduct PRS – SGU3327U –soonest possible.

File with Office-In- Charge -Boon Sen – 6389 6171

Regards
Angie Foo

From: My Car Consultant [<mailto:admin@mycar.sg>]

Sent: Saturday, May 18, 2019 10:45 AM

To: Claims Dept of CTI

Subject: OUR REF: SGU3327U YOUR REF: PC7686U PRE-REPAIR INSPECTION FOR SGU3327U

WITHOUT PREJUDICE

OUR REF: SGU3327U
YOUR REF: PC7686U

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SGU3327U
ACCIDENT INVOLVING SGU3327U AND PC7686U

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction - Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention

Warm Regards,
Kai Ling

My Car Consultant Pte Ltd
53 Ubi Avenue 1
Paya Ubi Industrial Park
#01-33 S(408934)

Tel: +65 9868 6000 / Fax: 6925 5219

CONFIDENTIALITY NOTICE: This message (including any attachments) is confidential and may be privileged. It may be read, copied and used only by the intended recipient. If you have received it in error please contact the sender (by return e-mail) immediately and delete this message. Any unauthorized use or dissemination of this message in whole or in parts is strictly prohibited.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9803H
Vehicle Details	
Vehicle No.:	SGU3327U
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jun 2019
Vehicle Make:	SUZUKI
Vehicle Model:	SX4 1.6HB AT
Primary Colour:	Blue
Manufacturing Year:	2007
Engine No.:	M16A1249785
Chassis No.:	JSAGYA21500104167
Maximum Power Output:	75.0 kW (100 bhp)
Open Market Value:	\$12,743.00
Original Registration Date:	11 May 2007
First Registration Date:	11 May 2007
Transfer Count:	1
Actual ARF Paid:	\$14,018.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,115.00
COE Rebate Amount:	\$14,608.00
Total Rebate Amount:	\$14,608.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 03 Jun 2019

OK

Dep 5,150/yr

MV 24,000/2
PV 14,608/2
NV 9,392/2

hir
3/6/2019

BMW PREMIUM SELECTION.

CERTIFIED PRE-OWNED BY PERFORMANCE PREMIUM SELECTION.

[Find out more](#)


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

BMW X3 XDrive30i



Mint Condition, New Generation
G01 X3, Sapphire Black/ Mocha
Decor
Direct Owner [StarAC](#)

• Free VICOM evaluation
 • Free grooming and 8 months maintenance
 • In-house workshop ensures quality service
 • Member of SVTA and hire purchase association
 • 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

« Back (1 2) Next »

Sort by Date Posted

20 results/page

32 vehicles

Suzuki SX4

Advanced Search:

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Suzuki SX4		Any	Any	> 10 year(s) old	Any	Any	Any	All
	Suzuki	SX4 1.6A (New 5-yr COE)	-	N.A	22-Apr-2009	1,586 cc	-	Sedan	SOLD
Yet Another Beautiful And Well Maintained Car By A Meticulous Owner! Most Presentable Unit In Town! High Loan And Trade In Available! Lowest Interest Rate In Town! No Unnecessary Or Misc Charges! Try ...									
Posted: 17-Apr-2019 Tags: 2009 Suzuki SX4, 2009 suzuki sx4, Suzuki SX4, suzuki sx4, Suzuki, SX4, sx4, Used Suzuki									
	Suzuki	SX4 HB 1.6A (New 5-yr COE)	\$25,800	\$5,150 /yr	23-Apr-2009	1,586 cc	-	Hatchback	Available
Rare Sporty Crossover That Is Versatile And Good Looking. Excellent Bodywork And Interior Condition. Low Drivaway At \$500+ Per Month. High Over-Trade. Warranty. Free Servicing. Check It Out Now!									
Posted: 21-Apr-2019 Tags: 2009 Suzuki SX4, 2009 suzuki sx4, Suzuki SX4, suzuki sx4, Suzuki, SX4, sx4, Used Suzuki									
	Suzuki	SX4 1.6A (COE till 04/2024)	-	N.A	24-Apr-2009	1,586 cc	-	Sedan	SOLD
Selling Cheap! Hurry! View Now. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivalled Warranty Complete With Certificate And Test Report. Check Out Our...									
Classic Credit Pte Ltd									
Posted: 23-May-2019 Tags: 2009 Suzuki SX4, 2009 suzuki sx4, Suzuki SX4, suzuki sx4, Suzuki, SX4, sx4, Used Suzuki									
	Suzuki	SX4 1.6A (COE till 04/2024)	-	N.A	24-Apr-2009	1,586 cc	-	Sedan	SOLD
Low-Interest Rate Just At 3.18%! Very Well Maintained And Low Mileage, 2 Years Warranty/Servicing By Platinum Motoring In House Workshop. New Paint Color And New Pure Leather Seats Of Your Choice. 1 T...									
Posted: 04-May-2019 Tags: 2009 Suzuki SX4, 2009 suzuki sx4, Suzuki SX4, suzuki sx4, Suzuki, SX4, sx4, Used Suzuki									
GET YOUR COE RENEWAL LOAN Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.									
	Suzuki	SX4 1.6A (New 5-yr COE)	-	N.A	24-Apr-2009	1,586 cc	-	Sedan	SOLD
Posted: 30-Mar-2019 Tags: 2009 Suzuki SX4, 2009 suzuki sx4, Suzuki SX4, suzuki sx4, Suzuki, SX4, sx4, Used Suzuki									
	Suzuki	SX4 1.6A (New 5-yr COE)	-	N.A	27-Apr-2009	1,586 cc	-	Sedan	SOLD
1 Owner Only! High Loan Applicable. Rare Sports Model With Full Bodykit! Good Condition Inside Out. Best Looking SX4 In Town. 10 Years COE Can Be Arranged! Well Maintained That Requires No Further Rep...									
Posted: 28-Apr-2019 Tags: 2009 Suzuki SX4, 2009 suzuki sx4, Suzuki SX4, suzuki sx4, Suzuki, SX4, sx4, Used Suzuki									
	Suzuki	SX4 HB 1.6A	-	N.A	27-Apr-2009	1,586 cc	-	Hatchback	SOLD
Pristine Condition Vehicle With Auspicious Car Plate Number (8889)! Exterior And Interior Well-Maintained By Meticulous Owner. Typically Parked In Sheltered Areas. We Have In-house Mechanics To Ensure...									

[Compare](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/05/2019 17:03
Date Of Accident	15/05/2019 17:30
Exact Location Of Accident	FINLAYSON GREEN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGU3327U
Insured/Policyholder	
Name Of Registered Owner	BRIGHTSTAR CAR RENTAL PTE LTD
Co Reg No	201319803H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-899999999
Vehicle Particulars	
Manufacturer	SUZUKI
Model	SX4 1.6HB AT
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	18-MI001503-R01
Cover Note Number	
Driver	
Name of Driver	TAN SHUN ZHI, ANGELINA (CHEN SHUNZHI)
NRIC No	S8808161G
Date Of Birth	09/03/1988
Occupation	OUTDOOR
Date Of Driving Pass	29/12/2016
Driving Experience	2 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98003503

Fax Number	
Contact Number	OFFICE-98003503
E-Mail Address	NOEMAIL
Address	BLK 51 CHAI CHEE ROAD #12-304
Postcode	460051
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	Name: : WILSON SOH Gender: : Male
Passenger 2	Name: : LEE HONG RUI Gender: : Male
Passenger 3	Name: : DANEOL CHUA YUN HUR Gender: : Male

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20190517/7016.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Vehicle Registration Number PC7686U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category BUS

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAN SHUN ZHI, ANGELINA (CHEN SHUNZHI)

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? SGU3327U

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

DETAILS OF INJURED PERSON 2

Name WILSON SOH

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? SGU3327U

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

DETAILS OF INJURED PERSON 3

Name LEE HONG RUI

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? SGU3327U

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

DETAILS OF INJURED PERSON 4

Name DANEOL CHUA YUN HUR

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? SGU3327U

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- Refer to police report -

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

01/01/2017 10:00:00 AM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 May 2019		28 May 2019 16:13 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case






























Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	BRIGHTSTAR CAR RENTAL PTE LTD , Co. Reg. No.: 201319803H								
Vehicle Reg. No.:	SGU3327U	Date of Loss:	15/05/2019 17:00 - :59 [144 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202194C02	Policy/Cover Note No.:	DMB1SN18326718000						
Vehicle Reg. No. (Insured):	PC7686U	Policy No. (Claimant):	18-MI001503-R01						
		Excess:	S\$0.00						
Repairer:	My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park, 408934 Ubi - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CELINE FONG] ... [Final Rpt due 07/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents






*SGU3327U (SNM19D202194C02)
[PC7686U]
TP
BRIGHTSTAR CAR RENTAL PTE LTD
May 15 2019 5:00PM
[-]
My Car Consultant Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print					
1	17/05/19 17:18	Accident Statement		Load HTM						
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print					
1	17/05/19 17:15	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
2	17/05/19 17:15	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
3	17/05/19 17:15	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
4	17/05/19 17:15	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
5	17/05/19 17:15	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
6	17/05/19 17:15	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
7	17/05/19 17:15	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
8	17/05/19 17:15	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
9	17/05/19 17:15	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
10	17/05/19 17:15	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
11	17/05/19 17:15	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
12	17/05/19 17:15	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	29/07/19 15:35	General View		Load JPG	<input checked="" type="checkbox"/>					
2	29/07/19 15:35	General View		Load JPG	<input checked="" type="checkbox"/>					
3	29/07/19 15:35	General View		Load JPG	<input checked="" type="checkbox"/>					
4	29/07/19 15:35	General View		Load JPG	<input checked="" type="checkbox"/>					
5	29/07/19 15:35	General View		Load JPG	<input checked="" type="checkbox"/>					
6	29/07/19 15:35	General View		Load JPG	<input checked="" type="checkbox"/>					
7	29/07/19 15:35	General View		Load JPG	<input checked="" type="checkbox"/>					
8	29/07/19 15:35	General View		Load JPG	<input checked="" type="checkbox"/>					
9	29/07/19 15:35	General View		Load JPG	<input checked="" type="checkbox"/>					
10	29/07/19 15:35	General View		Load JPG	<input checked="" type="checkbox"/>					
11	29/07/19 15:35	General View		Load JPG	<input checked="" type="checkbox"/>					
12	29/07/19 15:35	General View		Load JPG	<input checked="" type="checkbox"/>					
13	29/07/19 15:35	General View		Load JPG	<input checked="" type="checkbox"/>					
14	29/07/19 15:35	General View		Load JPG	<input checked="" type="checkbox"/>					
15	29/07/19 15:35	General View		Load JPG	<input checked="" type="checkbox"/>					
16	29/07/19 15:35	General View		Load JPG	<input checked="" type="checkbox"/>					
17	29/07/19 15:35	General View		Load JPG						

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
				<input checked="" type="checkbox"/>
18	29/07/19 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
19	29/07/19 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
20	29/07/19 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
21	29/07/19 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
22	29/07/19 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
23	29/07/19 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
24	29/07/19 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
25	29/07/19 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
26	29/07/19 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
27	29/07/19 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
28	29/07/19 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
29	29/07/19 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
30	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
67	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	29/07/19 15:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	29/07/19 15:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	29/07/19 15:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	29/07/19 15:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	29/07/19 15:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	29/07/19 15:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
88	29/07/19 15:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/05/19 16:14	pri contact	 Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	17/05/19 17:15	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	17/05/19 17:15	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	17/05/19 17:15	Police Report [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	17/05/19 17:16	Police Report [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	17/05/19 17:16	Police Report [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	17/05/19 17:16	Police Report [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	17/05/19 17:18	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	17/05/19 17:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	17/05/19 17:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	17/05/19 17:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	17/05/19 17:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	17/05/19 17:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	17/05/19 17:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
7	17/05/19 17:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	17/05/19 17:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	17/05/19 17:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	17/05/19 17:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	17/05/19 17:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	17/05/19 17:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	17/05/19 17:15	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	17/05/19 17:15	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	17/05/19 17:15	Police Report	 Load JPG	<input checked="" type="checkbox"/>
4	17/05/19 17:16	Police Report	 Load JPG	<input checked="" type="checkbox"/>
5	17/05/19 17:16	Police Report	 Load JPG	<input checked="" type="checkbox"/>
6	17/05/19 17:16	Police Report	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19009085/BCD3E2

Date: 31/07/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMB1SN18326718000

Claimant Vehicle
No : SGU3327UInsured Vehicle
No : PC7686U

Date of Loss: 15/05/2019

Nature of Claim: TP

Claim
No: SNM19D202194C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGU3327U**

Make & Model: SUZUKI SX4, 1.6 HB (A)

Engine No: M16A1249785

Reg. Date: 11/05/2007 (Man. Year: 2007)

Chassis No: JSAGYA21S00104167

Colour: Blue

Odometer: 184431 km

Engine Capacity: 1586 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/05/2019

Date Inspected: 23/05/2019 Inspected At:

My Car Consultant Pte Ltd (Ubi)
53 Ubi Ave 1, #01-33, Paya Ubi Industrial
Park
Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: CELINE FONG

Manager: Lim Teow Guan

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2019)
Parts:	144	SUZUKI SX4 1.6 HB (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGU3327U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >