

22/02/2021

ASS. REC. RV

REF: CS3/AIG19009100/Ecd30

Special Instruction:

Surveyor:

McMullen

ASSIGNMENT (Office)

From (Person): Chin Lee Ying

of

AIG

Date/Time: 23/5/19 @ 10:26am

Estimated Cost:

Bill to:

OD - TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GY 28632

Insured:

SML 229R

at Workshop m/s

Tampines Auto

Tel:

6786 2884 / 97933147

of

Blk 9002 Tampines St. 93 # 01-36

Policy No:

Claim No:

6087040654SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/5/2019

CA / REV / REP. / REV 24 HRS

24/5/19 @ 11:30am

H.O.D. Endorsement:

Date/Time:

11:30am @ 23/5/19

Person Contacted:

Linda

Vehicle IN (OUT)

Date/Time

Action/Instruction Estimate (X)

GY 28632 - CS/CTP/80/8493/ Urd 3 q2

D.O.A. 10/10/18

SML 229R - X

Dismantle: 28/5/2019

After repair: 4/6/2019

ASS. REC. BY:

stuc

REF:

ALG

ASSIGNMENT

From:

Date:

24/5/2019

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

GY 28632

at Workshop m/s

Tampines Auto

of

BLK 9002 Tampines St-93 #01-36

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

11.30am (waiting)

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lup

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GY28632

Yr Regn:

24/2/05

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Urban

C.C

2953

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp.Reading

384562

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1MG4E 25Z0712579

Gen. Cond: Good (Fair) Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / Rim / STD A/Rim or

Tyre Size:

F:

R:

11

195R15C

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

21/5/19

D.O.I.

24/5/19

Survey held at

Tampines Auto

Des. of Damages: Frt / Rear / O/S (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 07 JUN 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

180

Transportation:

S + RS, SI

Photos

Others

TOTAL

11

191

Report Format:

DAR

Lump Sum / L.B. / \$

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 May 2019 Edit Reg		23 May 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	DSC FAR EAST (SINGAPORE) PTE. LTD., Co. Reg. No.: 201501439M		
Main Claimant:	MS CHARMING TRADING, Co. Reg. No.: 53013808E		
Vehicle Reg. No.:	GY2863Z	Date of Loss:	21/05/2019 00:00 - :59
Claim Type:	TP / 6087040654SG	Policy/Cover Note No.:	(Comprehensive) Coverage: 30/04/2019 - 29/04/2021
Vehicle Reg. No. (Insured):	SML229R	Policy No. (Claimant):	
		Excess:	
Repairer:	Tampines Auto Services (HQ) BLK 9002 TAMPINES ST 93, #01-34/36 INDUSTRIAL PARK A, 528836 Tampines - Tel: 67862884		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/06/2019]		
Claimant's Solicitor:	LEGAL OPTIONS LLC - Tel: 64388039		


ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (24/05/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 5/23/2019 10:26:30 AM
Attachments:  GY2863Z vs SML229R.PDF

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Joycelyn [mailto:joycelyn@legaloptions.biz]
Sent: Thursday, May 23, 2019 9:09 AM
To: Hor, Yinrul
Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SML229R AND GY2863Z ON 21/05/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Mdm,
We refer to your email dated 23rd May 2019.
Our client rejected your list of surveyors.

We provide you herewith our client's surveyors:-

	CONTACT PERSON
1	HOW ANDREW
2	LEE KOK WENG
3	SEAH KWANG BOON

Your said surveyor may liaise directly with our client's repairer,
Ms Linda at 6786 2884 for
the pre-repair inspection to be carried out.

The workshop is located at M/s Tampines Auto Services, Block 9002 Tampines Street 93, #01-36 Tampines Industrial Park A,
Singapore 528836.

*

If we do not hear from you within 2 days of this email, our clients shall deem that you have agree that the surveyor
appointed by our clients shall be our single joint expert for this matter.

Thanks n regards,

Joycelyn

Legal Secretary

LEGAL OPTIONS LLC

(GST Registration/UEN No. 201203825R)

Tel (65) 6513-2800 DID (65) 6513-2807 Fax (65) 6438-8275

Information in this message is confidential and may be legally privileged. It is intended solely for the person(s) to whom it is addressed. If you are not the intended recipient, please delete the message and any other record of it from your system, and notify the sender immediately.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

LEGAL OPTIONS LLC

ADVOCATES & SOLICITORS
Mediators ~ Commissioners for Oaths ~ Notary Public

法商律師事務所

Motor Accident & Personal Injuries

Tel: (65) 6513 2800 Fax: (65) 6438 8275

Commercial, Litigation, Property, Trust & Estate, Family

Tel: (65) 6438 8039 Fax: (65) 6734 8230

We do not accept service of Court Documents by fax

Your Ref : SML 229R
Our Ref : 19-A21-10382-VL.ts.js

22nd May 2019

M/S AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way #07-16

AIG Building

Singapore 079120

(Attn: Motor Claims Department)


Dear Sirs,

CLAIMANT : MS CHARMING TRADING
ACCIDENT INVOLVING GY 2863Z AND SML 229R ALONG AIRPORT ROAD TOWARDS
MACPHERSON ROAD ON 21/05/2019

We are instructed by **M/S MS CHARMING TRADING** to notify you of a road traffic accident on **21ST MAY 2019** at about **18:30 HOURS ALONG AIRPORT ROAD TOWARDS MACPHERSON ROAD** involving our client's vehicle registration number **GY 2863Z** and vehicle registration number **SML 229R** driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully



Cc: Client (GY 2863Z)

Directors

Joan Lim Pheok Hoon LL.B (Hons)

Victor Leong Wai Meng LL.B (Hons)

Teo Lip Hua Benedict LL.B (Hons) LL.M

Junior Secretary's DID: 6513 2807

Direct Fax: 6438 8275

(Email: joucelyn@legnloptions.biz)

Mailing Address for Accident Claims

Documents Support:

23 Kaki Bukit Avenue 4 #01-01 South Wing,
Singapore 415933

IMMEDIATE ATTENTION

By Fax: 6415 3727/Post

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 3808E

Vehicle Details

Vehicle No.: GY2863Z

Vehicle to be Exported: No

Intended Deregistration Date: 27 May 2019

Vehicle Make: NISSAN

Vehicle Model: URVAN 5DR

Primary Colour: Silver

Manufacturing Year: 2005

Engine No.: ZD30046033

Chassis No.: JN1MG4E25Z0712579

Maximum Power Output: -

Open Market Value: \$22,822.00

Original Registration Date: 24 Feb 2005

First Registration Date: 24 Feb 2005

Transfer Count: 1

Actual ARF Paid: \$1,142.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 23 Feb 2020

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 5

PQP Paid: \$29,236.00

COE Rebate Amount: \$4,347.00

Total Rebate Amount: \$4,347.00**Message**

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 27 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/05/2019 14:20
Date Of Accident	21/05/2019 18:30
Exact Location Of Accident	AIRPORT ROAD TOWARDS MACPHERSON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GY2863Z
Insured/Policyholder	
Name Of Registered Owner	MS CHARMING TRADING
Co Reg No	53013808E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62939737

Vehicle Particulars

Manufacturer	NISSAN
Model	URVAN 5DR

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	MS001191
Cover Note Number	24/02/2019 - 23/02/2020

Driver

Name of Driver	TAN KOON SENG
NRIC No	S2195770D
Date Of Birth	03/11/1959
Occupation	OUTDOOR
Date Of Driving Pass	18/03/1985
Driving Experience	34 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96274517
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 291D COMPASSVALE STREET #09-276
Postcode	544291
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) Involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE STATED DATE & TIME, I WAS DRIVING MY VEHICLE A (GY2863Z) ALONG AIRPORT ROAD TOWARDS MACPHERSON ROAD WHEN I FELT AN IMPACT AND REALISED THAT VEHICLE B (SML229R) HAD HIT ONTO THE LEFT SIDE OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SML229R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ICHHIA PARGAT SINGH
NRIC/Passport Number	S2727156A
Contact Number	91853366
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

MHWH9466166

G9Y28632

DCA: 21/5/19

TOKIC

K-SSan Urban

TP

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of this accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Refer to CIA Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time

Driver's Signature: 
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/PII No. _____



Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 6, Raffles Quay #18-01/1 Singapore 048581
 Tel: (65) 6224 0010 Fax: (65) 6224 0050
 Operating Hours: Monday to Friday 0900 - 1700
 UEN: S665500206 / GST Reg. No: A1400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No.: MHW119066166 Vehicle Registration No.: 7Y2863Z
 Name (as shown on NRIC): Tan Kim Song NRIC/FIN/Passport No.: S21957700
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 Address: Blk 291D Compassvale St #09-276 Singapore (744291)
 Contact (Tel): _____ Mobile No.: 9627 4517
 Email Address: _____
 Date of Accident: 21/5/2019 Time of Accident: 18:30
 Place of Accident: Airport Road towards Macpherson Road
 Insurance Company: Tokio Marine

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

- Amend sketch plan
- Change type of accident from side swipe to major/minor road

Ms Charming Trading
 Blk 67 Kallang Bahru
 #01-471, Singapore 330067
 Tel / Fax: 6393 9737

Policyholder / Driver's Signature
 Date:

[Signature]



Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:
 Date:

VAN / TRUCK (Rear)

Copyright © 2019

Vehicle No:

GY 28632

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993108	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Step Panel			
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate			
2054	993700	Rear Rubber Stopper			
2055	993701	Rear Rubber Stopper Bracket			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993454	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993365	Rear RH Chassis Member			

* Rear LH Fender DO ✓

NAC	INC	Item	CON	AC	Qty
2062	993748	Rear Sidegate			
2063	994225	Rear Sidegate Tool			
2064	993749	Rear Sidegate Hinge			
2065	994226	Sidegate Lower Panel			
2066	994227	Sidegate Railing			
2067	994208	Side Cover Hook			
2068	991965	Side Step Panel			
2069	994496	Side Step Panel Stopper			
2070	992857	Rear Body Panel			
2071	992866	Rear Body Panel Inner			
2072	995329	Sliding Door LH		R	
2073	995328	Sliding Door RH			
2074	994295	Sliding Door Handle			
2075	994300	Sliding Door Lock			
2076	994313	Sliding Door Rubber			
2077	994291	Sliding Door Bottom Roller			
2078	994317	Sliding Door Top Roller			
2079	994306	Sliding Door Panel			
2080	994315	Sliding Door Stepboard			
2081	994316	Sliding Door Stepboard Garnish			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim		BT ✓	
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre		CU7 ✓	
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1136	990247	Sticker			

[Signature]

28/5/19

5 days

...CLAIM SUBFOLDER...(Pending for Survey Report)




































PRI






















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 May 2019 Edit Reg		23 May 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	DSC FAR EAST (SINGAPORE) PTE. LTD., Co. Reg. No.: 201501439M								
Main Claimant:	MS CHARMING TRADING, Co. Reg. No.: 53013808E								
Vehicle Reg. No.:	GY2863Z	Date of Loss:	21/05/2019 00:00 - :59 [170 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6087040654SG	Policy/Cover Note No.:	(Comprehensive) Coverage: 30/04/2019 - 29/04/2021						
Vehicle Reg. No. (Insured):	SML229R	Policy No. (Claimant):							
		Excess:							
Repairer:	Tampines Auto Services (HQ) BLK 9002 TAMPINES ST 93, #01-34/36 INDUSTRIAL PARK A, 528836 Tampines - Tel: 67862884								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 03/06/2019]								
Claimant's Solicitor:	LEGAL OPTIONS LLC - Tel: 64388039								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (24/05/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GY2863Z (6087040654SG)**
[SML229R]
TP
MS CHARMING TRADING
May 21 2019 12:00AM
[DSC FAR EAST (SINGAPORE) PTE. LTD.]
Tampines Auto Services

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images											3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print		
1	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
2	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
3	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
4	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
5	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
6	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
7	27/05/19 08:57	Odometer Reading										Load JPG	<input checked="" type="checkbox"/>	
8	27/05/19 08:57	Chassis Number										Load JPG	<input checked="" type="checkbox"/>	
9	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
10	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
11	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
12	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
13	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
14	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
15	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
16	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
17	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
18	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
19	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
20	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
21	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
22	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
23	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
24	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
25	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
26	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
27	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
28	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
29	27/05/19 08:57	General View										Load JPG	<input checked="" type="checkbox"/>	
30	06/06/19 18:21	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
31	06/06/19 18:21	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
32	06/06/19 18:21	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
33	06/06/19 18:21	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
34	06/06/19 18:21	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
35	06/06/19 18:21	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
36	06/06/19 18:21	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
37	06/06/19 18:21	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	06/06/19 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	06/06/19 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	06/06/19 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	06/06/19 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	06/06/19 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	06/06/19 18:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	06/06/19 18:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	06/06/19 18:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	06/06/19 18:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	06/06/19 18:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	06/06/19 18:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	06/06/19 18:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	06/06/19 18:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	06/06/19 18:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	06/06/19 18:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	06/06/19 18:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	06/06/19 18:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	06/06/19 18:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	06/06/19 18:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	06/06/19 18:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	24/05/19 10:43	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19009100/ECD3E2

Date: 12/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GY2863Z

Insured Vehicle No : SML229R

Date of Loss: 21/05/2019

Nature of Claim: TP

Claim No: 6087040654SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GY2863Z

Make & Model: NISSAN URVAN 5DR(D), 3.0 (A)

Reg. Date: 24/02/2005 (Man. Year: 2005)

Colour: Silver

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: ZD30046033

Chassis No: JN1MG4E25Z0712579

Odometer: 384562 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 195 R15C

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/05/2019

Date Inspected: 24/05/2019 Inspected At:

Tampines Auto Services (HQ)
BLK 9002 TAMPINES ST 93, #01-34/36
INDUSTRIAL PARK A
Singapore 528836

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH FENDER	Dented	0.00 F	*- F
2	1		*SLIDING DOOR LH	Repair	0.00 F	*- F
3	1		*REAR LH WHEEL RIM	Bent	0.00 F	*- F
4	1		*REAR LH TYRE	Cut	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >