

ASS. REC. BY:

REF: CS/CTI190091061 Kt d3ed Special Instruction:

Meimun

Surveyor: _____ ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI Date/Time: 23.5.19 15.35 p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBF 9171A Insured: _____

at Workshop m/s Lai Huat (Mung Kee) motor Tel: 64538110

of 160 Sin Ming Drive #04-01

Policy No: DMCVSN1807921901 Claim No: SIM1910202273

Sum Insured: _____ Excess: \$500.00

Make of Veh: _____ D.O.A. 19.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS I.O.D. Endorsement: _____

Date/Time: 23.5.19 4.20 p.m Person Contacted: Deborah Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GBF 9171A - X
22/5/19 @ 2.07pm	visit to Chong Boon Sen via Meimun.
	Submit uneconomical total loss report.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 May 2019 Sendback Est	23 May 2019 14:46 S\$26,000.00	23 May 2019 15:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	METALIS PTE LTD, Co. Reg. No.: 199205491R		
Vehicle Reg. No.:	GBF9171A	Date of Loss:	19/05/2019 18:00 - :59 [25 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM19D202273	Policy/Cover Note No.:	DMCVSN1807921901 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/06/2019]		
Driver/Custodian:	LIM TONG YAM (58 / Male), NRIC: S14163231, Tel: +6593684591 Email: NOEMAIL		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 27 May 2019

Preliminary Advice

Vehicle No	: GBF9171A	Accident Date	: 19/05/2019
Make	: TOYOTA DYNA 150	Policy No.	: DMCVSN1807921901
Assignment Date	: 23/05/2019	Excess	: S\$500.00
Date of Inspection	: 24/05/2019	Est. Duration of Repair	: 0.00
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #04-01, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,000.00
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	
Total	:S\$	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	56,000.00
COE / PARF Rebate	:S\$	36,280.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,720.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 5491R

Vehicle Details

Vehicle No.: GBF9171A
Vehicle to be Exported: No
Intended Deregistration Date: 21 May 2019
Vehicle Make: TOYOTA
Vehicle Model: DYNA 150 5MT
Primary Colour: Silver
Manufacturing Year: 2016
Engine No.: 1KD2687581
Chassis No.: JTFAT35Y30K207621
Maximum Power Output: -
Open Market Value: \$26,436.00
Original Registration Date: 11 Apr 2017
First Registration Date: 11 Apr 2017
Transfer Count: 0
Actual ARF Paid: \$1,322.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 10 Apr 2027
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
PQP Paid: \$45,995.00
COE Rebate Amount: \$36,280.00
Total Rebate Amount: \$36,280.00

The information contained herein is correct as at 21 May 2019

OK

56

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/05/2019 11:19
Date Of Accident	19/05/2019 18:25
Exact Location Of Accident	ALONG BUKIT BATOK ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF9171A
Insured/Policyholder	
Name Of Registered Owner	METALIS PTE LTD
Co Reg No	199205491R
Email Address	RICKYHO@METALIS.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62667555
Vehicle Particulars	
Manufacturer	TOYOTA
Model	DYNA
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1807921901
Cover Note Number	
Driver	
Name of Driver	LIM TONG YAM
NRIC No	S1416323I
Date Of Birth	03/07/1960
Occupation	OUTDOOR
Date Of Driving Pass	20/06/1978
Driving Experience	40 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93684591
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address BLK 423 BUKIT BATOK WEST AVE 2
#07-149

Postcode 650423

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name BUKIT PANJANG

Police Station Address ROAD: 1 SEGAR ROAD , POSTCODE: 677738 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-8929999 - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT: T/20190520/2052.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: SD CARD WITH TRAFFIC POLICE

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC4205K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

GBC4205K

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 21 MAY 2018
11:50 AM


Driver's Signature
(If driver is not the policyholder)
Date & Time: 21 MAY 2018
11:19 AM


Reporting Centre Personnel's Signature
Name: Poh Kwee Shoo
NRIC/FIN No.: S6840583A


SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police report: T/20190520/2052.

On 19/5/2019 about 1730pm. I was traveling along Bukit Batok road towards Jurong town hall road. At the point of time, I was driving my lorry GBC 42051K approaching a traffic light which shows Red hence I was slowing down later. I turned my head towards the right and saw some people playing at the roadside. However, out of a sudden I knocked onto the rear of another lorry in front of me GBC 42051K. I would like to state that prior to the collision, I have tried applying emergency brake and also sway towards the right lane to reduce the impact of collision. However, I still knocked onto the rear right of the lorry.

Immediately, I alighted to assess the damage and check if anyone was injured. I noticed the other driver still seated on the driver seat and was bleeding. Immediately, I called for police assistance.

Thereafter ambulance came other driver was conveyed by ambulance to the hospital.

I would like to state my lorry has suffered dent at the front of my vehicle and the windscreen shattered. The left side of the vehicle door was damaged and unable to open.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Police Officer's Signature
Date & Time: 19/5/2019

Driver's Signature
(If driver is not the policyholder)
Date & Time: 19/5/2019

Reporting Centre Personnel's Signature
Name: Yee Choo
NRIC/FIN No.: JUB40583A

POLICE REPORT Pg. 3

Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

3 of 3
Report No: T20190520/2052

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan.

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Preparing The Report
SC2 WAFON PUARUCHIN HOW

Signature Of Interpreter
Not applicable

Officer In Charge Of Case
TP / GIT /
SI THABAGESH JEYATHESH
Contact No: 65476232

Authentication Stamp
NP259

Signature Of Informant

Date/Time
20/05/2019 13:41

Classification Of Case:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S14163231



Name
LIM TONG YAM

林東炎

Race
CHINESE

Date of Birth
03-07-1960

Sex
M

Country of Birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S14163231

Name
LIM TONG YAM

Birth Date: 03 Jul 1960

Issue Date: 19 Mar 2004




001168838A

2021590



NRIC No: S14163231



Blood Group: O+ Date of issue: 15-05-1994

PT. BLD. 123 BUKIT BATOK WEST AVENUE 2 407-149
SINGAPORE 67173

NRIC No: Date: No: 2076648

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	13 Jan 1993
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	20 Jun 1978
Class 4	Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kilograms	25 Sep 1981
Class 5	Motor Vehicles which are not constructed themselves to carry any load and the weight of which unladen exceeds 7250 kilograms	02 Dec 1981

Licence No: S14163231



NP 428A

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 May 2019 Sendback Est	23 May 2019 14:46 S\$26,000.00	23 May 2019 15:35 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	METALIS PTE LTD , Co. Reg. No.: 199205491R								
Vehicle Reg. No.:	GBF9171A	Date of Loss:	19/05/2019 18:00 - :59 [25 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D202273	Policy/Cover Note No.:	DMCVSN1807921901 (Comprehensive)						
		Excess:	S\$500.00						
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 03/06/2019]								
Driver/Custodian:	LIM TONG YAM (58 / Male), NRIC: S1416323I, Tel: +6593684591 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPING (03/06/2019): Alert - Adj Mandate Approved (S\$0.00) - GBF9171A - Claim Handler: Chong Boon Sen									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBF9171A (SNM19D202273)
OD
May 19 2019 6:00PM
[METALIS PTE LTD]
Lai Huat (Meng Kee) Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View <input type="button" value="View in Browser"/>	
Assessment Reports			1 per page <input type="button" value="1"/> <input checked="" type="checkbox"/>	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	21/05/19 18:01	Accident Statement	 Load HTM	<input type="checkbox"/>
2	23/05/19 14:46	Repairer Estimates	 Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/05/19 14:05	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="button" value="3"/> <input checked="" type="checkbox"/>	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	21/05/19 18:01	Accident Photo [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	21/05/19 18:01	Accident Photo [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	21/05/19 18:01	Accident Photo [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	21/05/19 18:01	CHASSIS NUMBER [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	23/05/19 11:51	Front View Right	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	23/05/19 11:51	Front View Left	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	23/05/19 11:51	Front View Left	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	23/05/19 11:51	Front View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	23/05/19 11:51	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	23/05/19 11:51	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	23/05/19 11:51	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	23/05/19 11:51	Photographs of Damaged Parts	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	23/05/19 11:51	Chassis Number	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/05/19 14:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	27/05/19 14:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	27/05/19 14:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	27/05/19 14:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	27/05/19 14:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	27/05/19 14:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	27/05/19 14:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	27/05/19 14:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	27/05/19 14:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	27/05/19 14:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	27/05/19 14:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	27/05/19 14:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	27/05/19 14:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	27/05/19 14:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	27/05/19 14:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	27/05/19 14:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	27/05/19 14:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	27/05/19 14:06	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
				<input checked="" type="checkbox"/>
19	27/05/19 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
20	27/05/19 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
21	27/05/19 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
22	27/05/19 14:06	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
23	27/05/19 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
24	27/05/19 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
25	27/05/19 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
26	27/05/19 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
27	27/05/19 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
28	27/05/19 14:06	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	21/05/19 12:04	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	21/05/19 12:05	POLICE REPORT [Linked Accident Report Documents]	Load TIF	
3	21/05/19 12:06	ACKNOWLEDGEMENT SLIP [Linked Accident Report Documents]	Load TIF	
4	21/05/19 12:06	CERTIFICATE OF INSURANCE [Linked Accident Report Documents]	Load TIF	
5	21/05/19 12:07	DRIVER'S NRIC + DRIVING LICENCE [Linked Accident Report Documents]	Load TIF	
6	23/05/19 11:55	E-filed GIA report	Load PDF	
7	23/05/19 11:55	Driver's NRIC & Driving Licence	Load PDF	
8	23/05/19 11:55	Certificate of Insurance	Load PDF	
9	23/05/19 11:55	Enquire PARF / COE Rebate for Registered Vehicle	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	21/05/19 18:01	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	21/05/19 18:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	21/05/19 18:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	21/05/19 18:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	21/05/19 18:01	CHASSIS NUMBER	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	21/05/19 12:04	Sketch Plan	Load TIF	
2	21/05/19 12:05	POLICE REPORT	Load TIF	
3	21/05/19 12:06	ACKNOWLEDGEMENT SLIP	Load TIF	
4	21/05/19 12:06	CERTIFICATE OF INSURANCE	Load TIF	
5	21/05/19 12:07	DRIVER'S NRIC + DRIVING LICENCE	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Repairer Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19009106/KTD3E2

Date: 04/06/2019

REFERENCE

Insured/Claimant: METALIS PTE LTD Policy No: DMCVSN1807921901
Date of Loss: 19/05/2019 Nature of Claim: OD Claim No: SNM19D202273

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF9171A**
Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2687581
Reg. Date: 11/04/2017 (Man. Year: 2016) Chassis No: JTFAT35Y30K207621
Colour: Silver Odometer: 0 km
Engine Capacity: 2982 cc
Market Value/New Car Price: S\$56,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/75 R15 Rear Tyre Size: 155 R12X8 (D)
Front Left Side: Bridgestone 9 mm Rear Left Side: Bridgestone 9/9 mm
Front Right Side: Bridgestone 9 mm Rear Right Side: Bridgestone 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,000.00	0.00	26,000.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,000.00	0.00	26,000.00	100.00
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	25,500.00	-500.00	26,000.00	101.96
+ GST 7.00/0.00% (S\$)	1,785.00	0.00	1,785.00	100.00
Nett Amount (S\$)	27,285.00	-500.00	27,785.00	101.83

INSPECTION

Date of Assignment: 23/05/2019 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected: 24/05/2019 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #04-01, Sin Ming
AutoCity
Singapore 575722
Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$56,000.00
OMV : \$26,436.00
PARF Rebate (1) : \$ 0.00
Quota Premium Paid : \$45,995.00
COE Rebate (2) : \$36,280.00
Total Rebate (1) + (2) = : \$36,280.00

The total amount incurred will be Market Value \$56,000.00 minus Total Rebate \$36,280.00 = \$19,720.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 04 Jun 2019)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF9171A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*Estimate Cost of Repair		26,000.00 F	*- F	
					Total Parts (S\$)	26,000.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >