

NS/INC19009109/Rev302

TAX/05/19/2019

Surveyor: NA2

REF: INC

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD  TP  WS  TP RES  OD RES  EVA  INV  MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: SKP 328T  
 Policy No. 510 0087942-01 (12/02/2019 - 11/02/2020)  
 Claims No. MT/1052657-001  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SHC 4628C Yr Regn: 3 SEP 2014  
 Type: M.Car / M.Cycle / BUS/ Van / Lorry  Taxi  Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: HONDA PRIO C.O. 1798  
 Colour: MAROON A/C: Insured / Std / NI / NA  
 Sp. Reading: 511,976 T/Radi: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JTDKN36U 405748033  
 Gen. Cond: Good /  Fair  Poor  Burnt  
 Steering:  In order  Jammed  Leaked  Burnt or  
 Brake:  In order  Jammed  Leaked  Burnt or  
 Mod: NII / SIRIm / STD / AIRIm or  
 Tyre Size: F: 195/65 R15  
 R: 11

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 G/A / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 2 days Res.: Yes or No  
 Linn Sum: \_\_\_\_\_ % J Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN/OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or NEUTON  
 Front R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 19/5/2019 U.O.I. 22/5/19  
 Survey held at SMT WOODLANDS  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
 O/S FRt  
 The UIC / Chassis frame / Body Structure affected due to collision

Date/Time	Action/Instruction
	SHC 4628C - NS/INC 13000473/51622
	SKP 328T - CS3/MSG 16014581/Avbc
	D.O.A. - 04/01/2018
	P.O.A. - 08/09/2016
9/7/19	LS \$300 confirmed by email (Ref 1034.40, 7710)

RECEIVED 10 JUL 2019

Date/Time, File Pass to?  : Prel: Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) 10/7 - typst  
 Report Format: TP  
 Lump Sum / L.B.I: (\$ LS \$300)

Days Of Repair: 2  
 Resurvey No. of Trip: 1  
 Add Fee:  : Site Insp (\$ \_\_\_\_\_)  : Interview (\$ \_\_\_\_\_)  : Tech. Invo (\$ \_\_\_\_\_)  : Weekend (\$ \_\_\_\_\_)  
 Survey Fee: 160  
 Transportation: \_\_\_\_\_  
 S + RS + SI: \_\_\_\_\_  
 Photos: \_\_\_\_\_  
 Other: \_\_\_\_\_  
 TOTAL: 160

**TP Claims against NTUC Income: Follow-Through Survey**

Date 9/7/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/1052656-001	SMRT TAXIS	SHC 4620Z	SHC 6057L	28/6/2019
2	MT/1050908-003	COMFORT TRANSPORTATON PTE LTD	SHC 8187G	SLR 3922H	25/6/2019
3	MT/1051069-002	SMRT TAXIS	SHB 601K	GY 544H	28/6/2019
4	MT/1052657-001	SMRT TAXIS	SHC 4628C	SKF 328Y	19/5/2019

Hello, NAC\_PAYA\_UBI\_800601

Change Language Change Password Log Out

My Desktop  
Notice of Loss

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="19/05/2019 16:48"/>
Vehicle No. (For Motor)	<input type="text" value="SKF328T"/>	Certificate Number	<input type="text"/>

Search

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="checkbox"/>	5100087942-01		TEO CAR RENTAL	53373922E	GPC	drive CLASSIC	SKF328T	SKF328T	12/02/2019	11/02/2020

Continue

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHC4628C
Vehicle to be Exported:	No
Intended Deregistration Date:	24 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR6116773
Chassis No.:	JTDKN36U405748033
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	03 Sep 2014
First Registration Date:	03 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Sep 2022
PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	02 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$20,752.00
<b>Total Rebate Amount:</b>	<b>\$26,818.00</b>
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 24 May 2019

OK

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	21/05/2019 15:37
Date Of Accident	19/05/2019 20:35
Exact Location Of Accident	GARDEN BY THE BAY DROP OFF BAY
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4628C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

#### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

#### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

#### Driver

Name of Driver	YUE SEE PENG
NRIC No	S1149443I
Date Of Birth	14/04/1955
Occupation	OUTDOOR
Date Of Driving Pass	05/04/1977
Driving Experience	42 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	323
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - OPENING DOOR OF VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

MY TAXI WAS STATIONARY ALONG THE DRIVE WAY OF DROP OFF BAY WAITING FOR THE FRONT VEHICLES TO MOVE. THE VEHICLE SKF328T CUT INTO MY PATH AND STOPPED BESIDE MY RIGHT SIDE TO ALIGHTED THE PASSENGER. WHILE THE VEHICLE SKF328T OPENED THE REAR SLIDING DOOR, IT BRUSHED AGAINST THE RIGHT FRONT PORTION OF MY TAXI.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKF328T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHANG CHIN
NRIC/Passport Number	S6815873G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

*[Handwritten Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Handwritten Signature]* 21/5/19

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No :




Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo





## Case Details

**Case Reference Number :**  
TAX/05/19/2091

**Type of Repair :** Accident Repair

**Vehicle Registration Number :**  
SHC4628C

**Company Type :** SMRT Taxis Pte Ltd

**Estimation ID :** EST-6950-ID

**Assigned By :** Taxi Claims Manager Team

**Insurance Company Name :** NTUC Income Insurance Co-operative Ltd

**Accident Date and Time :** 19/05/2019 12:36 PM

**Vehicle Age(In Months) :** 56

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			Remarks	
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)		Repair/Replace
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0	Repair	PR
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	XSVL
<b>Total Spare Part Cost</b>									<b>418.80</b>	<b>Surveyor Total</b>		<b>0.00</b>		
<b>Lump Sum Discount (%)</b>									<b>20.00</b>	<b>Lump Sum Dis (%)</b>		<b>20</b>		
<b>Final Spare Part Cost</b>									<b>335.04</b>	<b>Final Sur Total</b>		<b>0.00</b>		

### Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	338.00	200	
<b>Total:</b>			<b>338.00</b>	<b>200.00</b>	

### Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
<b>Total:</b>			<b>378.00</b>	<b>200.00</b>	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	NN
<b>Total:</b>			<b>60.00</b>	<b>0.00</b>	

## Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	335.04	0.00
Total Labour Cost	338.00	200.00
Total Spray Painting	378.00	200.00
Other	60.00	0.00
Overall Total	1,111.04	400.00
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	1,100.00	400.00
Surveyor Approved Amount		400.00
No of Repair Days*	3	0
Remarks	-	LUMP SUM REPAIR 2 DAYS AFTER REPAIR PHOTOS
Surveyor Name		Naz
Signature		  24/5/19
Survey Date	22/05/2019	<input type="button" value="Save"/> <input type="button" value="Clear"/>



22/5/19 1430  
LUMP SUM REPAIR  
2 DAYS  
AFTER REPAIR PHOTOS.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**  
Signature:  
Date:

Section A - Accident Details	
Registration Number	SHC4628C
Case Reference Number	TAX/05/19/2091
Registration Date	3/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	YUE SEE PENG
Type of Accident	Open Door Case
Accident Date and Time	19/5/2019 8:38 PM
Accident Reported Date and Time	21/5/2019 2:50 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24101573
Special Instruction to ARC, if any	TP
Prepared Date and Time	22/5/2019 11:19 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Prius

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$200.00
Total Spray Cost	\$378.00	\$200.00
Total Spare Part Cost	\$418.80	\$0.00
Total Other Cost	\$60.00	(\$100.00)
<b>TOTAL COST</b>	<b>\$1,194.80</b> <b>1334.40</b>	<b>\$300.00 (L/S)</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Tuck Foo Kok	Naz (LKK) / NTUC
ARC / Surveyor Sign Off Date	24/05/2019 9:02 AM	22/05/2019 3:24 PM
Signature		
Remarks	LUMP SUM REPAIR 2 DAYS AFTER REPAIR PHOTOS	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
 50 Woodlands Industrial Park E4, Singapore 757705  
 FAX Number : 63685592  
 Estimator Telephone Number: 68642623  
 Accident Reporting Number: 66642572

Date Generated : 07/07/2019  
 User ID : PehSuan

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-1907-0052	Invoice Number	
Quotation Date	03.07.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$338.00	\$200.00
<b>Total Labour</b>	<b>\$338.00</b>	<b>\$200.00</b>

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$378.00</b>	<b>\$200.00</b>

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$100.00)
TO WASH AND VACUUM	\$60.00	\$0.00
<b>Total Other Costs</b>	<b>\$60.00</b>	<b>(\$100.00)</b>

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair <i>R</i>
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given <i>X SVL</i>
<b>Total</b>					<b>\$558.40</b>		<b>\$0.00</b>		

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

$$\begin{array}{r}
 0.00 \\
 + 200.00 \\
 + 200.00 \\
 \hline
 400.00 \\
 - 20\% \\
 \hline
 320.00
 \end{array}$$
 45 \$300/-  
 1334 40

## Veron Chen (LKKAuto)

---

**From:** Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>  
**Sent:** Tuesday, 9 July 2019 11:04 AM  
**To:** Veron Chen (LKKAuto); Naz (LKKAuto)  
**Cc:** SUR; CS A Team  
**Subject:** RE: SHC4628C

Hi,

Amount confirmed as per your recommendation,  
thanks.

Regards  
Poh Suan

---

**From:** Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]  
**Sent:** Tuesday, 9 July 2019 9:31 AM  
**To:** Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis); Naz (LKKAuto)  
**Cc:** SUR; CS A Team  
**Subject:** RE: SHC4628C

Dear Poh Suan,

WITHOUT PREJUDICE

Amount confirmed \$300 @ 2 working days under lump sum repair.

Best Regards,  
Veron Chen | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

**From:** Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>  
**Sent:** Monday, 8 July 2019 8:28 AM  
**To:** Naz (LKKAuto) <Naz@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>  
**Subject:** SHC4628C

Hi Naz,

Attached herewith the repair estimate of SHC 4628C having Case No: TAX/05/19/2091.

There is no change to the approved amount of \$300 @ 2 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards  
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Sent: Sunday, 7 July 2019 1:01 PM

To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Subject: Scan Data from FX-D421D6



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19009109/Nvd3e2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 17-07-2019	
		Code: INC4	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SKF 328T	Veh. Inspected	SHC 4628C
Policy No.	5100087942-01	Coverage (\$)	0.00
Claim No.	MT/1052657-001	Excess (\$)	0.00
Assign From		Assign Date	22/05/2019
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U405748033	Colour	MAROON
Odometer	511976	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	NEUTON	5 mm
L/H Front Tyre	195/65 R15	NEUTON	5 mm
R/H Rear Tyre	195/65 R15	NEUTON	5 mm
L/H Rear Tyre	195/65 R15	NEUTON	5 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	19/05/2019	Inspection Date	22/05/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>	



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4628C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	BUMPER SUPPORT F/RH	SERVICEABLE	76.40	-
1	BUMPER FRT	TO REPAIR SEE LABOUR	482.00	-
			558.40	-
	<b>LABOUR</b>			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF BUMPER FRT.		338.00	200.00
	SPRAY PAINT.		378.00	200.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			776.00	400.00
	<b>GRAND TOTAL</b>		<b>1,334.40</b>	<b>400.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>300.00</b>

Report Ref No. NS/INC19009109/Nvd3e2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.