

ASS. REC. BY:

REF: CS3/CT119009123/Ucd3L7

Special Instruction:

Surveyor: MARLUSASSIGNMENT (Office)From (Person): Chong Boon Senof CTIDate/Time: 22/5/19 @ 4:58pm

Estimated Cost: \_\_\_\_\_

Bill to: \_\_\_\_\_

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: GBH 8364GInsured: AKR33 GBH 46730at Workshop m/s Fastech AutoTel: 67465405of 1 Kaki Bukit Ave 6 #01-46Policy No: DMORN30395018000Claim No: SNM190202253000

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_

(Client's Record)

D.O.A. 16/4/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endowment: \_\_\_\_\_

Date/Time: 23/5/19 @ 3:20pmPerson Contacted: NancyVehicle IN / OUT

Date/Time	Action/Instruction
	Estimated <u>X</u>
	<u>GBH 8364G - X</u>
	<u>AKR33 - X</u>
	<u>Dismantle: 23/5/2019</u>
	<u>— : 24/5/2019</u>
	<u>After repair: 27/5/2019</u>

(03/1/13) wel

ASS. REC. BY: Morcos

REF:

CY11

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Velt:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

PRS No colln. - 0. LTA 25400

~~9-10K~~

10-11K

Veh No:

GBH 8364G

Yr Regn:

10/18

Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna

C.O

2882

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

16688

T/Radio:

Insured / Std / NI / NA

Eng/No.

C/No:

JTFAT 35Y20K21159X

Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-175R15

R:

155-1212

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Saller

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

16/4/19

D.O.A.

23/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear L

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

7

Resurvey No. of Trip:

3

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) \$ - RS \$:

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

PRS

Lump Sum / I.B.I: (\$

TOTAL

150

150

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd
Main	08 Oct 2019		08 Oct 2019 13:31 <a href="#">Edit Adj Rpt</a>			
						<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by Insurer]

Insured:				
Main Claimant:	<b>MAKOTO-YA (S) PTE LTD,</b> Co, Reg. No.: 199200460E			
Vehicle Reg. No.:	<b>GBH8364G</b>	Date of Loss:	16/04/2019 18:00 - :59	
Claim Type:	<b>TP / SNM19D202253C02</b>	Policy/Cover Note No.:	DMCVSN30395018000	
Vehicle Reg. No. (Insured):	<b>GBH4678C</b>	Policy No. (Claimant):	D18MCV0002417	
		Excess:	S\$0.00	
Repairer:	<b>Fastech Auto Pte Ltd (HQ)</b> 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405			
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd, (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]			
Claimant's Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100			
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... <b>[Final Rpt due 17/10/2019]</b>			

**ASSOCIATED MAIL RECEIVED**

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS**

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Nivitha (LKK Auto)**

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Wednesday, 22 May 2019 4:58 PM  
**To:** ct-admin@visionlawllc.com  
**Cc:** assignments  
**Subject:** RE: Scan Image / OUR REF: SNM19D202253

**WITHOUT PREJUDICE  
SAVE AS TO COSTS**

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**From:** ct-admin@visionlawllc.com [mailto:ct-admin@visionlawllc.com]  
**Sent:** Wednesday, 22 May, 2019 4:47 PM  
**To:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** Scan Image

# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths  
Agents for Trade Marks  
(Incorporated with limited liability)

ERIC NG CHING BOON  
WONG KENG LEONG RAYNEY  
AUDREY WONG SU-HSEN  
PAUL YAP TAI SAN  
ANJALLI DIO MUNIANDY  
SEGA PARAM  
ANG KIM NOI DIANE  
RAVENDRA KRISHNASAMY  
JANICE HAN JIA LIN  
TAN YINGXIAN, SELWYN  
CHEONG YUNHUI, CLARISSA  
EDISON TAM CHYI EU  
SONIA LIM WEI LEI

Unique Entity Number : 200721148H  
✓HEAD OFFICE: 133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413

Branch: 490 Toa Payoh Lorong 6  
#03-11 HDB Hub  
Singapore 310490

✓HEAD OFFICE  
TEL : (65) 65342811 (Hunting)  
FAX ✓ : (65) 65356802 (General)  
: (65) 65355905 (Litigation)  
E-mail : jactan@visionlawllc.com  
**BRANCH**  
TEL : 65 63580703  
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.ins.F15.110479.19 (sj)  
Your Ref: SNM19D202253

23 May 2019

**CHINA TAIPING INSURANCE (S'PORE) PTE LTD**  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909  
Attention: Motor Claims Department

**BY FAX: 6224 7175**  
email: claimsdept@sg.cntaiping.com  
email: boonsen.chong@sg.cntaiping.com

Dear Sirs,

**ACCIDENT INVOLVING GBH 8364 G & AKR 33 & GBH 4678 C & SMG 7766 L & SBP 1888 R ON 16 APRIL 2019 ALONG VICTORIA STREET TOWARDS KALLANG ROAD AT ABOUT 1835 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email dated 22 May 2019 informing that your wish to conduct a pre-repair survey on our client's vehicle **GBH 8364 G**.

Please be informed that the said vehicle can be inspected at:

FASTECH AUTO PTE LTD  
1 Kaki Bukit Avenue 6  
#01-46/48/50 Autobay  
Singapore 417883  
Contact Person: Nancy / Lina / Jason (6746-5405)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

Anjalli M  
(Head Office)

cc: **GBH 8364 G** – By fax: 6745-8520 only

## FOR SURVEYOR

Please initial here after completion of pre-repair inspection.  
Thank you.

1<sup>st</sup> Survey on \_\_\_\_\_  
Appointed surveyor  
(Name & Signature)

2<sup>nd</sup> Survey on \_\_\_\_\_  
Appointed surveyor  
(Name & Signature)

3<sup>rd</sup> Survey on \_\_\_\_\_  
Appointed Surveyor  
(Name & signature)

**NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.**

## CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	0460E
<b>Vehicle Details</b>	
Vehicle No.:	GBH8364G
Vehicle to be Exported:	No
Intended Deregistration Date:	24 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	1KD2825341
Chassis No.:	JTFAT35Y20K211594
Maximum Power Output:	-
Open Market Value:	\$27,082.00
Original Registration Date:	09 Oct 2018
First Registration Date:	09 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$1,355.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	08 Oct 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$27,104.00
COE Rebate Amount:	\$25,400.00
<b>Total Rebate Amount:</b>	<b>\$25,400.00</b>

The information contained herein is correct as at 24 May 2019

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



## ANNOUNCING Auto Zoom Enterprise Pte Ltd as sgCarMart Premium Dealer 2019



### Post an Advertisement

Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Mercedes-Benz C180 Blue Efficiency.



Excellent Price Well Maintained  
And Regular Servicing Done.  
Direct Owner StarAll

Aut  
An Inspiration

click here to view  
our **PRISTINE**  
at

[Browse by Category](#)
[« Back \( 1 2 \) Next »](#)
[Sort by Date Posted](#)

23 vehicles

toyota dyna

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
<b>Search Selection</b>	toyota dyna		Any	Any	2018	Any	Any	
	<b>Toyota Dyna 150 3.0M</b>		<b>\$64,000</b>	<b>\$7,200 /yr</b>	<b>12-Apr-2018</b>	<b>2,982 cc</b>	-	
	<b>Fuel Type:</b> Diesel 3 Years Or 100k Km Warranty. Prime Motor & Leasing Posted: 23-May-2019 Tags: 2018 Toyota Dyna, 2018 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota							
	<b>Toyota Dyna 150 3.0M</b>		-	N.A	<b>06-Sep-2018</b>	<b>2,982 cc</b>	<b>22,495 km</b>	
	<b>Fuel Type:</b> Diesel <b>Auction Closing Time:</b> 29th May 2019 at 11:00 PM With Key. This Vehicle Is Non GST Chargeable, Kindly Download The Non GST Chargeable Tender Form At This Link: <a href="https://goo.gl/FBn">https://goo.gl/FBn</a> Posted: 23-May-2019 Tags: 2018 Toyota Dyna, 2018 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota							
	<b>Toyota Dyna 150 3.0M</b>		<b>\$69,800</b>	<b>\$7,290 /yr</b>	<b>20-Dec-2018</b>	<b>2,982 cc</b>	<b>40 km</b>	
	<b>Fuel Type:</b> Diesel Newly Registered! Totally Legit, GST/ARF/COE All Incl Toyota Dyna Diesel. (Box Separate Cost) Borneo Motors 3 Years Or 100k Km Warr Hurry Call Now! 24 Hours Serving You! ABWIN (1994) Pte Ltd Posted: 22-May-2019 Tags: 2018 Toyota Dyna, 2018 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota							
	<b>Toyota Dyna 150 3.0A</b>		<b>\$72,800</b>	<b>\$7,650 /yr</b>	<b>27-Nov-2018</b>	<b>2,982 cc</b>	-	
	<b>Fuel Type:</b> Diesel Auto Transmission. Newly Arrived, Cheapest, Best Auto 10 Feet, 100% Loan, High Trade In, Call, For This Smooth And Efficient Beast. SG Motor Link Pte Ltd Posted: 22-May-2019 Tags: 2018 Toyota Dyna, 2018 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota							



### 195/55/15 Kumho PS31 Tyre Promotion @ \$68!

195/55/15 Kumho Ecsta PS31 Tyre Promotion 1pc Selling @ \$68 Only (Min 2pcs Tyre Purchase)! Call Us Now While Stock Last!  
Find out more!

**Toyota Dyna 150 3.0M** **\$61,800** **\$6,820 /yr** **14-Jun-2018** **2,982 cc** **30,000 km**  
**e: Diesel**

[Complete](#)
[Automobile & Trading](#)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/04/2019 17:38
Date Of Accident	16/04/2019 18:35
Exact Location Of Accident	VICTORIA ST TWDS KALLANG RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH8364G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MAKOTO-YA (S) PTE LTD
Co Reg No	199200460E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67413511

### Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MCV0002417
Cover Note Number	

### Driver

Name of Driver	LIM BUAY HIN
NRIC No	S1615800C
Date Of Birth	04/12/1963
Occupation	INDOOR
Date Of Driving Pass	19/12/1983
Driving Experience	35 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97600603
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 57 GEYLANG BAHRU #15-3513  
Postcode 330057  
Was driver an employee of the Insured's Company YES  
If No, Relationship of the Driver with the Insured  
Vehicle Registration Number of Driver's Own Vehicle -  
Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident CHAIN COLLISION  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 5  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? YES  
If Yes, Please state which Police Station  
Police Station Name EUNOS NPP  
Police Station Address ROAD: 629 BEDOK RESERVOIR ROAD #01-1620 , POSTCODE: 470629 , COUNTRY: SINGAPORE  
Police Station Contact TEL NO: - FAX NO:  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

REFER TO POLICE REPORT: T/20190417/2125.

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number AKR33  
Vehicle Make/Model/Colour  
Details Of Properties VEHICLE B  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver ARIF BIN MOHAMAD ZAWI  
NRIC/Passport Number 690114085331  
Contact Number 0105338099  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SMG7766L  
Vehicle Make/Model/Colour  
Details Of Properties VEHICLE C  
Vehicle Category PRIVATE CAR  
Name of Driver MUHAMMAD SUFIAN BIN ANUAR  
NRIC/Passport Number S9331194I  
Contact Number 84447685

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number GBH4678C  
Vehicle Make/Model/Colour  
Details Of Properties VEHICLE D  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver LIM BUAY HIN  
NRIC/Passport Number S1615800C  
Contact Number 97600603

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SBP1888R  
Vehicle Make/Model/Colour  
Details Of Properties VEHICLE E  
Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

**MAKOTO-YA (S) PTE LTD**

No. 9, Kaki Bukit Road 2  
#01-05, Gordon Warehouse Building  
Singapore 417842

Tel: (65) 6741 2666, (65) 6841 0991

Fax: (65) 6742 4895

GET Reg No: 117-11-04014-9

Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



*ll*

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

*Refer to police report.*

DECLARATION

I/We declare the foregoing particulars are true in every respect.

**MAKOTO-YA (S) PTE LTD**

No. 9, Keki Sukil Road 2

#01-05, Gordon Warehouse Building

Policyholder's Signature

Tel: (65) 6741 2690, (65) 6841 0951

Fax: (65) 6742 4936

GST Reg. No: M2-0134014-9

*ll*  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# SINGAPORE POLICE FORCE



T/20190417/2125

Police Station Of Origin:  
Eunos NPP  
629 Bedok Reservoir Road #01-1620  
SINGAPORE 470629  
Tel No: 1800-4439999

1 of 4

Report No. T/20190417/2125

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/04/2019 15:51		Vide Report No.:		Station Diary No.: 21
<b>Informant's Particulars</b>				
Name of Informant: LIM BUAY HIN		Address: APT BLK 57 GEYLANG BAHRU #15-3513 SINGAPORE 330057		
ID Type / ID No.: NRIC NO / S1615800C		Contact No.: Home/Office: Mobile: 97600603		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 55	Date of Birth: 04/12/1963	Type of Informant: Driver	
Race: Chinese		Language:	Institution / School Name:	
Occupation: DELIVERY DRIVER		Driving Licence Information: Class: 3 Date of Expiry:		

## General Information of the Accident

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 16/04/2019 18:35	Type of Location: Straight Road
Location: Along Road 1 VICTORIA STREET  NEAR TO HOTEL BOSS				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
AKR33	Bus/Coach/Minibus				Slightly Damaged	0
GBH4678C	Lorry	TOYOTA	DYNA 3.0 M	White	Slightly Damaged	8
GBH8364G	Lorry	TOYOTA	DYNA 150 5MT	White	Slightly Damaged	0
SBP1888R	Car	JAGUAR	XJ 2.0 TSS SWB SR	Black	Slightly Damaged	0



**SINGAPORE  
POLICE FORCE**



T/20190417/2125

Police Station Of Origin:  
Eunos NPP  
629 Bedok Reservoir Road #01-1620  
SINGAPORE 470629  
Tel No: 1800-4439999

2 of 4

Report No. T/20190417/2125

**CONTINUATION OF REPORT**

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SMG7766L	Car	MITSUBISHI	LANCER 1.5 MIVEC GLX AT ABS D/AB 2WD 4DR	Silver	Slightly Damaged	1

Details of Person Involved					
Any Pedestrian Involved: No					
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA		
<b>Driver</b>					
Name	ARIF BIN MOHAMAD ZAWI			ID No.	690114085331
Related Vehicle	AKR33 (Bus/Coach/Minibus)			Contact No.	0105338099
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL	
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL	
<b>Driver</b>					
Name	LIM BUAY HIN			ID No.	S1615800C
Related Vehicle	GBH8364G (Lorry)			Contact No.	97600603
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL	
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL	
<b>Driver</b>					
Name	MUHAMMAD SUFIAN BIN ANUAR			ID No.	S9331194I
Related Vehicle	SMG7766L (Car)			Contact No.	84447685
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL	
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL	



**SINGAPORE  
POLICE FORCE**



T/20190417/2125

Police Station Of Origin:  
Eunos NPP  
629 Bedok Reservoir Road #01-1620  
SINGAPORE 470629  
Tel No: 1800-4439999

3 of 4

Report No. T/20190417/2125

**CONTINUATION OF REPORT**

**Brief Details.**

On 16/04/2019 at around 1835hrs, I was driving along Victoria street near to hotel boss when I stopped at the traffic light junction as it was red light. Moments later, On Malaysian Bus collided with my vehicle causing me to jerk forward and in turn collided with another car in front of me which also collided with a car in front of him. Shortly after, one other lorry collided with the bus behind me. We then all alighted and exchanged particulars with all other drivers and left the scene as no one was injured. I am lodging this report for insurance claims.



**SINGAPORE  
POLICE FORCE**



T/20190417/2125

Police Station Of Origin:  
Eunos NPP  
629 Bedok Reservoir Road #01-1620  
SINGAPORE 470629  
Tel No: 1800-4439999

4 of 4

Report No. T/20190417/2125

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 LIEW CHONG XIANG, VINCENT

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

17/04/2019 15:51

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt ONG YONG HOCK

Contact No.: 65476436

Classification Of Case:

Authentication Stamp

NP168

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Oct 2019		08 Oct 2019 13:31 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>





































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: -, Co. Reg. No.: -									
Main Claimant: <b>MAKOTO-YA (S) PTE LTD</b> , Co. Reg. No.: 199200460E									
Vehicle Reg. No.:	<b>GBH8364G</b>	Date of Loss:	16/04/2019 18:00 - :59 [6 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D202253C02</b>	Policy/Cover Note No.:	DMCVSN30395018000						
Vehicle Reg. No. (Insured):	<b>GBH4678C</b>	Policy No. (Claimant):	D18MCV0002417						
		Excess:	S\$0.00						
Repairer:	<b>Fastech Auto Pte Ltd (HQ)</b> 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 17/10/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									























































## Claim Documents

\*GBH8364G (SNM19D202253C02)  
[GBH4678C]


















TP  
MAKOTO-YA (S) PTE LTD  
Apr 16 2019 6:00PM  
[-]  
Fastech Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
**View**
[View in Browser](#)


Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
2	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
3	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
4	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
5	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
6	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
7	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
8	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
9	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
10	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
11	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
12	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
13	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
14	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
15	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
16	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
17	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
18	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
19	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
20	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
21	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
22	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
23	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
24	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
25	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
26	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
27	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
28	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
29	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
30	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
31	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
32	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
33	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
34	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
35	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
36	08/10/19 13:59	General View	 Load JPG	<input checked="" type="checkbox"/>
37	08/10/19 13:59	General View	Load JPG	<input checked="" type="checkbox"/>
38	08/10/19 13:59	General View	Load JPG	<input checked="" type="checkbox"/>
39	08/10/19 13:59	General View	Load JPG	<input checked="" type="checkbox"/>
40	08/10/19 13:59	General View	Load JPG	<input checked="" type="checkbox"/>
41	08/10/19 13:59	General View	Load JPG	<input checked="" type="checkbox"/>
42	08/10/19 13:59	General View	Load JPG	<input checked="" type="checkbox"/>
43	08/10/19 13:59	General View	Load JPG	<input checked="" type="checkbox"/>

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
44	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
45	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
46	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
47	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
48	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
49	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
50	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
51	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
52	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
53	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
54	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
55	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
56	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
57	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
58	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
59	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
60	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
61	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
62	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
63	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
64	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
65	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
66	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
67	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
68	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
69	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
70	08/10/19 13:59	General View		Load JPG	<input checked="" type="checkbox"/>
71	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
72	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
73	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
74	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
75	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
76	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
77	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
78	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
79	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
80	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
81	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
82	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
83	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
84	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
85	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
86	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
87	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
88	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
89	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
90	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
91	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
92	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
93	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
94	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
95	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
96	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
97	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
98	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
99	08/10/19 14:01	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>











Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
101	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
102	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
103	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
104	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
105	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
106	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
107	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
108	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
109	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
110	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
111	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
112	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
113	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
114	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
115	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
116	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
117	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
118	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
119	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
120	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
121	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
122	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
123	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
124	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
125	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
126	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
127	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
128	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
129	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
130	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
131	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
132	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
133	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
134	08/10/19 14:01	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
135	08/10/19 14:02	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
136	08/10/19 14:02	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
137	08/10/19 14:02	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
138	08/10/19 14:02	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
139	08/10/19 14:02	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
140	08/10/19 14:02	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
141	08/10/19 14:02	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
142	08/10/19 14:02	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
143	08/10/19 14:02	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
144	08/10/19 14:02	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
145	08/10/19 14:02	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
146	08/10/19 14:02	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
147	08/10/19 14:02	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
148	08/10/19 14:02	After Repair Photo		<input checked="" type="checkbox"/>
149	08/10/19 14:02	After Repair Photo		<input checked="" type="checkbox"/>
150	08/10/19 14:02	After Repair Photo		<input checked="" type="checkbox"/>
151	08/10/19 14:02	After Repair Photo		<input checked="" type="checkbox"/>
152	08/10/19 14:02	After Repair Photo		<input checked="" type="checkbox"/>
153	08/10/19 14:02	After Repair Photo		<input checked="" type="checkbox"/>
154	08/10/19 14:02	After Repair Photo		<input checked="" type="checkbox"/>
155	08/10/19 14:02	After Repair Photo		<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
156	08/10/19 14:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
157	08/10/19 14:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
158	08/10/19 14:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
159	08/10/19 14:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
160	08/10/19 14:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
161	08/10/19 14:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
162	08/10/19 14:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
163	08/10/19 14:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
164	08/10/19 14:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
165	08/10/19 14:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
166	08/10/19 14:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
167	08/10/19 14:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
168	08/10/19 14:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
169	08/10/19 14:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
170	08/10/19 14:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
171	08/10/19 14:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
172	08/10/19 14:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>









### Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	17/04/19 17:43	Accident Statement	 Load HTML	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	17/04/19 17:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	17/04/19 17:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	17/04/19 17:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	17/04/19 17:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	17/04/19 17:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	17/04/19 17:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	17/04/19 17:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	17/04/19 17:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	17/04/19 17:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	17/04/19 17:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	17/04/19 17:42	Sketch Plan	 Load TIF	
2	17/04/19 17:42	Sketch Plan #2	 Load TIF	
3	17/04/19 17:42	Sketch Plan #3	 Load TIF	
4	17/04/19 17:42	Sketch Plan #4	 Load TIF	
5	17/04/19 17:42	Sketch Plan #5	 Load TIF	
6	17/04/19 17:42	Sketch Plan #6	 Load TIF	
7	17/04/19 17:42	Accident Sketch Plan	 Load TIF	
8	17/04/19 17:42	Accident Sketch Plan	 Load TIF	

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19009123/UCD3E2

Date: 17/10/2019

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN30395018000

Claimant  
Vehicle No : GBH8364GInsured  
Vehicle No : GBH4678C

Date of Loss: 16/04/2019

Nature of Claim: TP

Claim  
No: SNM19D202253C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GBH8364G

Make &amp; Model: TOYOTA DYNA 150, 3.0 D 5MT (M)

Engine No: 1KD2825341

Reg. Date: 09/10/2018 (Man. Year: 2018)

Chassis No: JTFAT35Y20K211594

Colour: White

Odometer: 16688 km

Engine Capacity: 2982 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/75 R15

Rear Tyre Size: 155 R12 (D)

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6/6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 08/10/2019

Date Inspected: 23/05/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, #01-46/48/50  
Autobay  
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000.00 - \$11,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 17 Oct 2019)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBH8364G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >