

REF: CS/TM119009134 / NSD-30 Special Instruction:

Surveyor: Naiz
Mentor: Naiz

ASSIGNMENT (Office)

From (Person): Ng Kwai Kay of TMI Date/Time: 23/5/19 6:54pm

Estimated Cost: _____ Bill to: _____

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 3225H Insured: SJA 41004

at Workshop m/s Comfort Delgro Tel: 62148360

of 591 Jackson Drive

Policy No: MT109333 Claim No: M1903725

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 23/5/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN/OUT

[illegible]

(08/11/13)

ASS. REC. BY:

NA2

REF TMI

ASSIGNMENT

From:

Date: 24.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHD 3225H

at Workshop m/s Comfortdigno

of 59 Loyang Drive

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 34 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp1)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHD 3225H

Yr Regn: 30 JUN 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HYUNDAI 140

C.C. 1,685

Colour:

BLUE

A/C:

Insured / Std / NI / NA

Sp. Reading:

391, 709

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMH LB41UMG40.9/602

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 216

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

HANKOOK

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

23/5/19

D.O.I.

24/5/19

Survey held at

EDGE LOYANG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
20/6/19	FINALIZED PART BY PART \$ 2,792.30 / 4 REPAIR DAYS (\$ 4,329.76 Red - 61%)

RECEIVED 24 JUN 2019

20/6/2019

Date/Time, File Pass to?

21/06/19

1)

Typ: 4

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

250

Transportation:

S + RS, SI

Photos

Others

11

TOTAL

261

Report Format :

Lump Sum / I.B.F. (\$) 2,792.30 P/A

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 May 2019 16:53 Sendback Est	23 May 2019 17:05 \$7,121.06	23 May 2019 18:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHD3225H	Date of Loss:	23/05/2019 08:00 - :59 [34 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1903725	Policy/Cover Note No.:	MT109333 (Third Party Only) Coverage: 08/12/2018 - 07/12/2019
Vehicle Reg. No. (Insured):	SJA4100U	Policy No. (Claimant):	MCOM0015
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ng Kwai Kay Francis]		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/06/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

member of COMFORTDELGRO

Date/Time: 23.05.2019 16:41 Page : 1

Team: ARC Repair TP(CLS0)1 JOB CARD Sales Order: 3924701 JC NO.: 305297759


TOMER		REGN NO.: SHD3225H	MILEAGE
AS COMFORT TRANSPORTATION PTE LTD		MAKE : HYUNDAI	FUEL
7010045		MODEL I-40	E.....1/2.....F
TOMER NO. 383 SIN MING DRIVE		YR OF MANU 30.06.2016	DATE/TIME IN 23.05.2019 14:20
RESS Singapore SINGAPORE 575717		CHASSIS CODE KMHLB41UMGU091602	TARGET DATE
65508755			COMPLETION DATE/TIME:
(R)	(O)		
(P)			
OUNT CARD NO.			

Accident Date: 23.05.2019
NATURE: 3P 23.05.19/B

JOB DESCRIPTION

T-MARINE

S/NO LABOR CODE DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

edgement Slip		Exit Pass	
o.: SHD3225H	FZ T-MARINE	Vehicle No.: SHD3225H	
Service Advisor	Signature/Date	Name of Service Advisor	Date
urned to Service Reception upon collection		To be kept by Security Guard	

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 21 June 2019 10:25 AM
To: 'Fauzy Bin Mokhtar'
Cc: 'Naz@lkkauto.com'
Subject: RE: SHD3225H - FINALIZE (TOKIO MARINE)

Hi Fauzy Mokhtar,

Merimen fee from \$ 10/- change to \$ 11/-.

Please re-amend the final bill to \$ 2,792.30. We will submit our report accordingly.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Fauzy Bin Mokhtar [mailto:fauzy@sparkcarcare.com]
Sent: Tuesday, 18 June 2019 3:38 PM
To: Naz@lkkauto.com
Cc: Calvin Ang (LKKAuto) <kalvinang@lkkauto.com>
Subject: Re: SHD3225H - FINALIZE (TOKIO MARINE)

Hi Naz,

Attached is Finalize and parts damaged photo.

1) Rear Bumper sponge.

Best Regards,

Fauzy Mokhtar

Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd

Off:62148319 / Fax:65468156

From: Fauzy Bin Mokhtar
Sent: Wednesday, 29 May 2019 6:02 PM
To: Naz@lkkauto.com
Cc: Calvin Ang (LKKAuto)
Subject: SHD3225H - FINALIZE (TOKIO MARINE)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/05/2019 15:06
Date Of Accident	23/05/2019 08:30
Exact Location Of Accident	ALONG AYE TOWARDS TUAS AFTER EXIT 9
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD3225H
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	LOW KEOK THONG
NRIC No	S1224652H
Date Of Birth	20/12/1956
Occupation	OUTDOOR
Date Of Driving Pass	06/12/1975
Driving Experience	43 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98383930
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address,	BLK 26 CHAI CHEE ROAD #10-407
Postcode	460026
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJA4100U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEONG KENG HUI
NRIC/Passport Number	S7977265H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR AND FRT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SME386G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	INGRID GENEVIEVE KINNEN CAES
NRIC/Passport Number	S7955897D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT
No. Of Passenger (Including Driver)	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Olivia Wendy

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: 23 MAY 2019

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Statement as per attached.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Olivia Wendy

Reporting Centre Personnel's Signature
Name: 23 MAY 2019
NRIC/FIN No.:

Describe Circumstances of the Accident.
On the 23/05/2019 @ about 08:30hrs, I was driving along AYE towards Tuas after Exit 9
direction.
The front vehicle slow down and stop so I slowed down and stop as well. Suddenly there's an
impact from behind my taxi and I step out to checked and found out a vehicle of SJA4100U
front portion had collided onto my rear portion of my taxi. There's another vehicle of
SME386G involved in this chain collision.
01 female passenger on board my taxi and no injury reported at the point of accident.

Declaration

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R




Policyholder's Signature/Date &
Time






Driver's Signature(if driver is not the policyholder)/Date
& Time

Olivia Wendy

Witnessed by Reporting
Centre Personnel

23 MAY 2019





ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
 59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

(FZ)

T-Maxine
Rear

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
 COMFORT TRANSPORTATION PTE LTD

Singapore

Claimant Insurer: India International Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	23/05/2019
Vehicle Reg. No.:	SHD3225H	Driveable?	NO
Party At Fault:	UNKNOWN		
Driver (TP):	LOW KEOK THONG		
Make/Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Vehicle Reg. Date:	30/06/2016
Vehicle Colour:	BLUE	Gen Condition:	FAIR
Engine No:	D4FDFU500077	Chassis No:	KMHLB41UMGU091602
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	PLS REFER TO ATTACHED		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	4,421.06
Miscellaneous Items	10.00
Labour	2,690.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,121.06
+ GST 7.00% (S\$)	498.47
Nett Amount (S\$)	7,619.53

This claim is handled by: FAUZY BIN MOKHTAR

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 May 2019)

Parts: 143 HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHD3225H/23/05/2019 17:05

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*BOOTLID	20.00	0.00	*2,174.90 FL	X Svc X1
2	1		*BOOTLID LOCK UPPER	20.00	0.00	*102.60 FL	? XSVL
3	1		*BOOTLID LOCK LOWER	20.00	0.00	*31.70 FL	? XSVL
4	1		*BOOTLID H EMBLEM	20.00	0.00	*28.70 FL	X Svc X1
5	1		*BOOTLID CRDI PLATE	20.00	0.00	*27.90 FL	X Svc X1
6	1		*BOOTLID MOULDING	20.00	0.00	*85.00 FL	X Svc X1
7	1		*BOOTLID (I40) EMBLEM	20.00	0.00	*27.90 FL	X Svc X1
8	1		*BOOTLID LOWER GARNISH	20.00	0.00	*227.00 FL	/ Svc
9	1		*REAR BUMPER	20.00	0.00	*553.00 FL	/ CRIC
10	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*428.40 FL	? BT
11	1		*REAR BUMPER REINFORCEMENT BRACKET LH	20.00	0.00	*80.30 FL	? BT
12	1		*REAR BUMPER REINFORCEMENT BRACKET RH	20.00	0.00	*80.30 FL	? BT
13	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL	/ NEC
14	2		*REAR BUMPER BRACKET	20.00	0.00	*71.20 FL	? XSVL
15	1		*REAR BUMPER SPONGE	20.00	0.00	*103.50 FL	? CRK
16	1		*REAR BUMPER UNDER COVER	20.00	0.00	*228.00 FL	/ DEF
17	1		*REAR END PANEL	20.00	0.00	*526.70 FL	? XSVL
18	1		*REAR END PANEL GARNISH	20.00	0.00	*57.70 FL	? XSVL
19	1		*REAR LOWER PANEL	20.00	0.00	*87.40 FL	? XSVL
20	1		*BOOTLID COMFORT LOGO & TEL NO. STICKER	0	0.00	*30.00 FS	/ NEC
21	1		*BOOTLID BUMPER REVERSE SENSOR	0	0.00	*135.70 FS	/ not working
22	1		*BOOTLID BUMPER RUBBER MAT	0	0.00	*50.00 FS	/ NEC
23	1		*BOOTLID BUMPER ADVERTISEMENT LOGO	0	0.00	*50.00 FS	/ NEC
24	1		*REAR FENDER ADVERTISEMENT LOGO RH	0	0.00	*100.00 FS	/ NEC
25	1		*REAR FENDER ADVERTISEMENT LOGO LH	0	0.00	*100.00 FS	/ NEC

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,409.90
- List Item Discount on L Items (\$\$)	988.84
Total Parts (\$\$)	4,421.06

ComfortDelGro Engineering Pte Ltd/SHD3225H/23/05/2019 17:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	1,200.00
2	SPRAY PAINTING CHARGE	New	1,200.00
3	WIRING CHARGE	New	80.00
4	TUFF KOTE	New	90.00
5	REMOVE / REFIX REVERSE SENSOR	New	120.00
Gross Labour Cost (S\$)			2,690.00

ComfortDelGro Engineering Pte Ltd/SHD3225H/23/05/2019 17:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NA2 LKK

24/5/19 1515

PIP

3 DAYS

CHECK ITEMS PHOTOS

BEFORE PAINT PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305297759
Date : 17.06.2019

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SHD3225H

Date of Accident : 23.05.2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SJA4100U

2. The finalized amount shall be:

(a) Spare Parts after List discount	\$1,661.30
(b) Labour Charges	\$4,430.00 \$1,131.00
Total for Part-By-Part Repair Cost	\$2,791.30 \$2,792.30
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less:	20% \$0.00
Final Lumpsum Repair cost	\$0.00

3. Estimated normal period for repairs: 4 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : FAUZY BIN MOKHTAR

Tel : 62148319

Fax : 65468156

Signature : 

Name : NAZ LKK

Date : 30/6/19

* Merimen fee \$11.00

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 17.06.2019
Time: 18:14:34
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305297759
REGN NO : SHD3225H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 30.06.2016
DATE/TIME IN : 23.05.2019 14:20
ACCIDENT DATE : 23.05.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0784-G	I40VC MLDG-BACK PANEL	1	227.00	20.00	181.60	✓
0002	04-01-0103-0786-G	I40VC EMBLEM-CRDI	1	27.90	20.00	22.32	✓
0003	04-01-0103-0787-G	I40VC EMBLEM-I40	1	27.90	20.00	22.32	✓
0004	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	553.00	20.00	442.40	✓
0005	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	✓
0006	04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	228.00	20.00	182.40	✓
0007	28-01-0103-0005-A	(I40/SONATA)REAR BOOT LOG	1	20.00	2.00-	20.00	✓
0008	28-01-0103-0006-A	(I40/SONATA)REAR BOOT TEL	1	10.00	0.20	10.00	✓
0009	04-01-0103-0800-G	I40VC SYMBOL MARK-TRUNK L	1	28.70	20.00	22.96	✓
0010	09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1	135.70	2.00-	135.70	✓
0011	04-01-0103-1150-A	I40VC PROTECTOR MAT	1	50.00	0.20	50.00	✓
0012	04-01-0103-0742-G	I40VC STAY-RR BUMPER LH	1	80.30	20.00	64.24	✓
0013	04-01-0103-0740-G	I40VC BEAM-RR BUMPER#	1	428.40	20.00	342.72	✓

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 17.06.2019

Time: 18:14:34

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305297759
REGN NO : SHD3225H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 30.06.2016
DATE/TIME IN : 23.05.2019 14:20
ACCIDENT DATE : 23.05.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0103-0743-G I40VC STAY-RR BUMPER RH 1 80.30 20.00 64.24 ✓

0015 04-01-0103-0739-G I40VC ABSORBER-RR BUMPER 1 103.50 20.00 82.80 ✓

SUB-TOTAL : 1,661.30

JOB NATURE

0000 20-05	REAR FENDER ADVERTISEMENT LOGO LH	100.00 ✓
0001 20-05	REAR FENDER ADVERTISEMENT LOGO RH	100.00 ✓
0002 20-05	REAR BUMPER ADVERTISEMENT LOGO	50.00 ✓
0003 L	MERIMEN FEE	10.00
0004 L	PANEL BEATING	400.00 ✓
0005 L	SPRAY PAINTING CHARGE	400.00 ✓
0006 L	TUFF KOTE	40.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 17.06.2019

Time: 18:14:34

Page: 3

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305297759
REGN NO : SHD3225H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 30.06.2016
DATE/TIME IN : 23.05.2019 14:20
ACCIDENT DATE : 23.05.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0007 L REMOVE/REFIX REVERSE SENSOR

30.00

SUB-TOTAL : 1,130.00

TOTAL : 2,791.30

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed
Main	23 May 2019 16:53 Sendback Est	23 May 2019 17:05 S\$7,121.06	23 May 2019 18:54 Edit Adj Rpt	S\$2,792.30 Edit Estimates	S\$2,792.30 View Rpt	
						Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHD3225H	Date of Loss:	23/05/2019 08:00 - :59 [34 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1903725	Policy/Cover Note No.:	MT109333 (Third Party Only) Coverage: 08/12/2018 - 07/12/2019
Vehicle Reg. No. (Insured):	SJA4100U	Policy No. (Claimant):	MCOM0015
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ng Kwai Kay Francis]		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 03/06/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHD3225H (M1903725)
[SJA4100U]
TP
COMFORT TRANSPORTATION PTE LTD
May 23 2019 8:00AM
[COMFORT TRANSPORTATION PTE LTD]
ComfortDelGro Engineering Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	23/05/19 17:05	Repairer Estimates	i	Load HTM	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	23/05/19 18:54	Accident Statement <small>From: SC - Reg. No: SJA4100U, Claimant: LEONG KENG HUI</small>	i	Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/06/19 09:31	General View	i	Load JPG	<input checked="" type="checkbox"/>
2	20/06/19 09:31	General View	i	Load JPG	<input checked="" type="checkbox"/>
3	20/06/19 09:31	General View	i	Load JPG	<input checked="" type="checkbox"/>
4	20/06/19 09:31	General View	i	Load JPG	<input checked="" type="checkbox"/>
5	20/06/19 09:31	General View	i	Load JPG	<input checked="" type="checkbox"/>
6	20/06/19 09:31	General View	i	Load JPG	<input checked="" type="checkbox"/>
7	20/06/19 09:32	Dismantled Parts	i	Load JPG	<input checked="" type="checkbox"/>
8	20/06/19 09:32	Dismantled Parts	i	Load JPG	<input checked="" type="checkbox"/>
9	20/06/19 09:32	Dismantled Parts	i	Load JPG	<input checked="" type="checkbox"/>
10	20/06/19 09:32	Dismantled Parts	i	Load JPG	<input checked="" type="checkbox"/>
11	20/06/19 09:32	Dismantled Parts	i	Load JPG	<input checked="" type="checkbox"/>
12	20/06/19 09:32	Dismantled Parts	i	Load JPG	<input checked="" type="checkbox"/>
13	20/06/19 09:32	Dismantled Parts	i	Load JPG	<input checked="" type="checkbox"/>
14	20/06/19 09:32	Dismantled Parts	i	Load JPG	<input checked="" type="checkbox"/>
15	20/06/19 09:32	Dismantled Parts	i	Load JPG	<input checked="" type="checkbox"/>
16	20/06/19 09:32	Dismantled Parts	i	Load JPG	<input checked="" type="checkbox"/>
17	20/06/19 09:32	Dismantled Parts	i	Load JPG	<input checked="" type="checkbox"/>
18	20/06/19 09:32	Dismantled Parts	i	Load JPG	<input checked="" type="checkbox"/>
19	20/06/19 09:32	Replacement Part Photo	i	Load JPG	<input checked="" type="checkbox"/>
20	20/06/19 09:32	Replacement Part Photo	i	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI19009134/NSD3E2

Date: 25/06/2019

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MT109333

Claimant Vehicle No : SHD3225H

Insured Vehicle No : SJA4100U

Date of Loss: 23/05/2019

Nature of Claim: TP

Claim No: M1903725

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD3225H

Make & Model: HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)

Engine No: D4FDEU500077

Reg. Date: 30/06/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMGU091602

Colour: Blue

Odometer: 391709 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes

Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No

Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 205/60R16

Rear Tyre Size: 205/60R16

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,421.06	1,911.30	2,509.76	56.77
Miscellaneous Items	10.00	11.00	-1.00	-10.00
Labour	2,690.00	870.00	1,820.00	67.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,121.06	2,792.30	4,328.76	60.79
+ GST 7.00/7.00% (S\$)	498.47	195.46	303.01	60.79
Nett Amount (S\$)	7,619.53	2,987.76	4,631.77	60.79

INSPECTION

Date of Assignment: 23/05/2019 Present Location:

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 24/05/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 4.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jun 2019)
Parts:	143	HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD3225H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	2,174.90 FL	*- FL
2	1		*BOOTLID LOCK UPPER	Serviceable	102.60 FL	*- FL
3	1		*BOOTLID LOCK LOWER	Serviceable	31.70 FL	*- FL
4	1		*BOOTLID H EMBLEM	Necessary	28.70 FL	*28.70 FL
5	1		*BOOTLID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
6	1		*BOOTLID MOULDING	Not Necessary	85.00 FL	*- FL
7	1		*BOOTLID (I40) EMBLEM	Necessary	27.90 FL	*27.90 FL
8	1		*BOOTLID LOWER GARNISH	Scratched	227.00 FL	*227.00 FL
9	1		*REAR BUMPER	Cracked	553.00 FL	*553.00 FL
10	1		*REAR BUMPER REINFORCEMENT	Bent	428.40 FL	*428.40 FL
11	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Bent	80.30 FL	*80.30 FL
12	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Bent	80.30 FL	*80.30 FL
13	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
14	2		*REAR BUMPER BRACKET	Serviceable	71.20 FL	*- FL
15	1		*REAR BUMPER SPONGE	Cracked	103.50 FL	*103.50 FL
16	1		*REAR BUMPER UNDER COVER	Deformed	228.00 FL	*228.00 FL
17	1		*REAR END PANEL	Serviceable	526.70 FL	*- FL
18	1		*REAR END PANEL GARNISH	Serviceable	57.70 FL	*- FL
19	1		*REAR LOWER PANEL	Serviceable	87.40 FL	*- FL
20	1		*BOOTLID COMFORT LOGO & TEL NO. STICKER	Necessary	30.00 FS	*30.00 FS
21	1		*BOOTLID BUMPER REVERSE SENSOR	Not Working	135.70 FS	*135.70 FS
22	1		*BOOTLID BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
23	1		*BOOTLID BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
24	1		*REAR FENDER ADVERTISEMENT LOGO RH	Necessary	100.00 FS	*100.00 FS
25	1		*REAR FENDER ADVERTISEMENT LOGO LH	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,409.90	2,272.70
- List Item Discount on L Items 20.00/20.00% (S\$)	988.84	361.40
Total Parts (S\$)	4,421.06	1,911.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	10.00	11.00
Sub Total (\$\$)			10.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	400.00
2	SPRAY PAINTING CHARGE	New	1,200.00	400.00
3	WIRING CHARGE	New	80.00	0.00
4	TUFF KOTE	New	90.00	40.00
5	REMOVE / REFIX REVERSE SENSOR	New	120.00	30.00
Gross Labour Cost (\$\$)			2,690.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >