



SMRT Accident Vehicle Repair Estimates

Cecilia

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/06/2019

User ID : CatherineLee


Section A - Accident Details

Registration Number	SG5810J
Case Reference Number	BUS/05/19/7025
Registration Date	6/6/2017
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN A95
Name of Driver	Sandra Mohan
Type of Accident	Side Swipe
Accident Date and Time	15/5/2019 6:15 AM
Accident Reported Date and Time	15/5/2019 9:15 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101633
Special Instruction to ARC, if any	SG5810J - REAR RIGHT PORTION DAMAGED SMG2240U - TP INSURED WITH AIG - LEFT SIDE MIRROR DAMAGED
Prepared Date and Time	23/5/2019 8:55 AM
Chassis Number	WMAA95ZZ7G7003457
Mileage	
Work Shop	
Repair Completion Date and Time	

P/P \$353/- 0.5 day.

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$265.00	\$132.50
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$220.50	\$220.50
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$485.50	\$353.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	1.0	0.5
Prepared / Adjusted By	Kok Khoo Goh	HWEE JIE.
ARC / Surveyor Sign Off Date	23/05/2019 8:57 AM	23/05/2019 1:54 PM
Signature		L+k
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/06/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$265.00	\$132.50
Total Labour	\$265.00	\$132.50

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Spray Painting & Panel Beating		

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6012635	VE		REAR LAMP BULB (A95 MAN)	1.00	\$245.00	10.00	\$220.50	Replace	Replace
Total					\$245.00		\$220.50		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									