

ASS. REC. BY:

REF:

Q2/SPF19009197/ETd321

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Hafizul

of SPF

Date/Time: 23/5/2019 3.30pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FU 8247X

Insured:

QX511P

at Workshop m/s G.N.G Motor

Tel:

62836560

of BIRG Dehu Lane 10 #01-564

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/5/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

22/5

Person Contacted:

Mr Ong

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (V)
	FU 8247X - X	
	QX511P - X	
	Submit lump sum \$114501 - (Red: 545, 27%)	

Do Not Finalise

ASS. REC. BY:

Steve

REF:

SPF

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FU 8247X

at Workshop m/s

GNG

of

BLK 6 Debu Lane 10 #01-564

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

X			
	N/S	O/S	
			X

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FU 8247X

Yr Regn:

30/12/13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda CB400

C.C

399

Colour:

Black

N/C:

Insured / Std / NI / NA

Sp. Reading

2779

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JH2NC4290BK309556

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

140/60R17

R:

160/60R17

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

22/5/19

D.O.I.

24/5/19

Survey held at

G-M 6

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair Range - 1K - 2K

3 repair days

Repair Range - 1K - 2K.

Repair day 3

Weekend : 2

Total : 5.

RECEIVED 30 MAY 2019.

Date/Time, File Pass to?



Preli. Report



Final Report

1) 30/5 Typist

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

-

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Survey Fee:

220

Transportation:

S + RS \$

Photos

Others

TOTAL

220

Report Format:

Lump Sum / L.B.E. C

Tp

1450/-

Denise Tay (LKKAUTO)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Tuesday, 4 June 2019 8:41 AM
To: Admin-D (LKKAUTO); Veron Chen (LKKAUTO); assignments; SUR
Cc: Olivia Lau (LKKAUTO); Frankie THAY (SPF); Abdul Rahman MOHAMAD SALIM (SPF)
Subject: RE: Pre-Repair Inspection for vehicle FU 8247X (vs QX511P on 22/5/19)

Hi,

The ref number is **AEMD/105/009/2019/067**.

Thank you.

Best Regards,

Hafizul Farhan Bin Rahmat

AEMD / PLD

Singapore Police Force

DID: (65) 6478 4840 | FAX: (65) 6478 4850



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Monday, 3 June 2019 1:31 PM
To: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>; Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>; Abdul Rahman MOHAMAD SALIM (SPF) <Abdul_Rahman_Mohamad_Salim@spf.gov.sg>
Subject: RE: Pre-Repair Inspection for vehicle FU 8247X (vs QX511P on 22/5/19)

Dear Hafizul,

Please provide reference or claim number

Best Regards,

G.Nivitha| Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]

Sent: Friday, 24 May 2019 9:51 AM

To: 'Hafizul Farhan RAHMAT (SPF)' <Hafizul_Farhan_RAHMAT@spf.gov.sg>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; 'Frankie THAY (SPF)' <Frankie_THAY@spf.gov.sg>; 'Abdul Rahman MOHAMAD SALIM (SPF)' <Abdul_Rahman_Mohamad_Salim@spf.gov.sg>

Subject: RE: Pre-Repair Inspection for vehicle FU 8247X (vs QX511P on 22/5/19)

Dear Sir,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hafizul Farhan RAHMAT (SPF) [mailto:Hafizul_Farhan_RAHMAT@spf.gov.sg]

Sent: Thursday, 23 May 2019 3:30 PM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>; Abdul Rahman MOHAMAD SALIM (SPF) <Abdul_Rahman_Mohamad_Salim@spf.gov.sg>

Subject: Pre-Repair Inspection for vehicle FU 8247X (vs QX511P on 22/5/19)

Hi LKK,

Please conduct a Pre-Repair Inspection for vehicle **FU 8247X** at the below stated workshop:

G.N.G Motor Trading
Blk 6 Defu Lane 10
#01-564
Singapore 539187

Please contact Mr. Ong at 6283 6560 / 9664 8992 for appointment.

Thank you

Best Regards,

Hafizul Farhan Bin Rahmat


AEMD / PLD

Singapore Police Force

DID: (65) 6478 4840 | FAX: (65) 6478 4850



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Nivitha (LKK Auto)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Thursday, 23 May 2019 3:30 PM
To: Admin-D (LKKAUTO); Veron Chen (LKKAUTO); assignments
Cc: Olivia Lau (LKKAUTO); Frankie THAY (SPF); Abdul Rahman MOHAMAD SALIM (SPF)
Subject: Pre-Repair Inspection for vehicle FU 8247X (vs QX511P on 22/5/19)

Hi LKK,

Please conduct a Pre-Repair Inspection for vehicle **FU 8247X** at the below stated workshop:

G.N.G Motor Trading
Blk 6 Defu Lane 10
#01-564
Singapore 539187

Please contact Mr. Ong at 6283 6560 / 9664 8992 for appointment.

Thank you

Best Regards,

Hafizul Farhan Bin Rahmat

AEMD / PLD

Singapore Police Force

DID: (65) 6478 4840 / FAX: (65) 6478 4850



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

Veh In.
Est ✓

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Steve

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 20631

Vehicle Details

Vehicle No.: FU8247X

Vehicle to be Exported: No

Intended Deregistration Date: 27 May 2019

Vehicle Make: HONDA

Vehicle Model: CB400

Primary Colour: Black

Manufacturing Year: 2013

Engine No.: NC42E1126023

Chassis No.: JH2NC4290BK300586

Maximum Power Output: _____

Open Market Value: \$6,706.00

Original Registration Date: 30 Dec 2013

First Registration Date: 30 Dec 2013

Transfer Count: 1

Actual ARF Paid: \$1,006.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount:	\$0.00
---------------------	--------

Intended COE Rebate Details

COE Expiry Date: 29 Dec 2023

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$1,804.00

COE Rebate Amount: \$827.00

Total Rebate Amount: \$827.00

The information contained herein is correct as at 27 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	23/05/2019 13:32
Date Of Accident	22/05/2019 21:45
Exact Location Of Accident	DORSET ROAD & TRURO ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FU8247X
Insured/Policyholder	
Name Of Registered Owner	TAN AH GUAN
NRIC No	S2762063I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97453239
Alternative Phone No	OTHERS-97453239
Vehicle Particulars	
Manufacturer	HONDA
Model	CB400
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MSD/VMS/19-393615-CA
Cover Note Number	
Driver	
Name of Driver	TAN AH GUAN
NRIC No	S2762063I
Date Of Birth	02/09/1961
Occupation	INDOOR
Date Of Driving Pass	13/08/1984
Driving Experience	34 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97453239
Fax Number	
Contact Number	OTHERS-97453239
EEmail Address	NOEMAIL

Address	BLK 236 YISHUN RING ROAD #06-1014
Postcode	760236
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8529999 - FAX NO: 68522299
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20190523/2023;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX511P
Vehicle Make/Model/Colour	TOYOTA COROLLA ALTIS 1.6 AUTO
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1	
Name	TAN AH GUAN
Approximate Age	57
Injuries Sustain	
Injured person in which vehicle?	FU8247X
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 236 YISHUN RING ROAD #06-1014
Postcode	760236

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:

23 MAY 2019

IDAC KAKI BUKIT (VAC)

Reporting Centre
Name: 23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg
NRIC/ID:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer e-file / Police Report

2

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

23 MAY 2019

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Reporting Centre Personnel's Signature
Name:
NRIC No.:
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg



SINGAPORE POLICE FORCE



T/20190523/2023

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

1 of 3

Report No. T/20190523/2023

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/05/2019 09:34		Vide Report No.: A/20190522/0117		Station Diary No.: 61	
Informant's Particulars					
Name of Informant: TAN AH GUAN			Address: APT BLK 236 YISHUN RING ROAD #06-1014 SINGAPORE 760236		
ID Type / ID No.: NRIC NO / S27620631			Contact No.: Home/Office: Mobile: 97453239		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 57	Date of Birth: 02/09/1961	Type of Informant: Rider		
Race: Chinese			Language:		Institution / School Name:
Occupation: Carpenter			Driving Licence Information: Class: 2B,2A,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 22/05/2019 21:45	Type of Location:
Location: Along Road 1 DORSET ROAD TRURO ROAD Lamp Post Number: 15				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FU8247X	Motorcycle	HONDA	CB400	Black	Slightly Damaged	0
QX511P	Police Vehicle					0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Exp
FU8247X	MSIG INSURANCE (SINGAPORE) PTE. LTD.	72142140	30/12/2018	



Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20190523/2023

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	TAN AH GUAN	ID No.	S2762063I
Related Vehicle	FU8247X (Motorcycle)	Contact No.	97453239
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Pillion			
Name	Choy Shu Fan	ID No.	S6967305H
Related Vehicle	FU8247X (Motorcycle)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details.

On 22/05/2019 at about 2200hrs, I was riding along Dorset Road with my wife pillion.

2) I had then wanted to negotiate a right turn into Truro road. I then signaled right.

3) As I was turning right, I suddenly felt a collision on the right side of my motorcycle which sent both me and my wife stumbling off the motorcycle to the road.

4) Both myself and my wife got up and discovered that a Police car (QX511P) had actually collided with us. I also observed that my motorcycle's exhaust pipe and my left side view mirror was damaged. The Police officers who were in the Police car (Chinese and Indian male) then called for ambulance but we both (my wife and I) did not want to be conveyed. I suffered abrasions to my right knee cap and pain at my back whilst my wife felt pain in the back. We will be seeing a doctor soon to see medical assistance.

5) I wish to state that I do not have a camera fitted on my camera. That is all.



**SINGAPORE
POLICE FORCE**



T/20190523/2023

3 of 3

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20190523/2023

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

L /

SI LEE YAO MING, KEVIN GABRIEL

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / DDGVT /

SI NORASHIKIN BINTE DAUD

Contact No.: 65476439

Signature Of Informant:

X

Date/Time:

23/05/2019 09:34

Classification Of Case:

Authentication Stamp

NP168

Singapore Police Force



REG. NO. 247124/00-A

南藝摩哆

G. N. G. MOTOR TRADING CO.

Block 6, Defu Industrial Estate Park C, Avenue 1

Defu Lane 10, #01-564, Singapore 1953

TEL: 2836560, 2805065

代理各種摩哆西卡及保險
AGENT FOR ALL TYPES OF MOTOR-CYCLE & INSURANCE

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date:

Your Ref: QX 511 P

Our Ref: FU 8247X HONDA CB400

Date, 23/5/2019

1pc. REAR EXHAUST MUFFLER - \$1240 / DD

1pc. EXHAUST JOINT PROTECTOR - \$85 / DD

RIGHT SIDE FOOTREST BRACKET - \$185 / BT

1pc. REAR GIVI BOX - \$180 / CAT

1pc. HANDLE BAR - \$125 / BT

P- 1815
- 10%
1633-50

L- 180
1813-50

LABOUR CHARGE - \$180 /

L/S - 145280
= 1450

G.



ONH BNH CHUAN

56845566E.

STEVE CLKK)

8322 8813

WH PM

3 day

L/S

Ry AL sy

24/5/19, 12.30pm

21/5/2019



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION			Ref : CS/SPF19009197/Etd3e2	
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE)1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333			Date : 11-06-2019 <div style="text-align: right;"> </div>	
ATTN : HAFIZUL FARHAN			Code : SPF	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 511P	Veh. Inspected	FU 8247X	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2019/067	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN	Assign Date	23/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB400	c.c	399	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	JH2NC4290BK300586	Colour	BLACK	
Odometer	2779	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	140/60 R17	BRIDGESTONE	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/05/2019	Inspection Date	24/05/2019	
Survey held at	G.N.G MOTOR TRADING CO. BLK 6 DEFU LANE 10 #01-564 SINGAPORE 539187			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FU 8247X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR EXHAUST MUFFLER	DENTED	1,240.00	1,240.00
1	EXHAUST JOINT PROTECTOR	DENTED	85.00	85.00
1	RIGHT SIDE FOOTREST BRACKET	BENT	185.00	185.00
1	REAR GIVI BOX	CUT	180.00	180.00
1	HANDLE BAR	BENT	125.00	125.00
	LESS 10% DISCOUNT		-	-181.50
			1,815.00	1,633.50
	<u>LABOUR</u>			
	LABOUR CHARGE.		180.00	180.00
			180.00	180.00
	GRAND TOTAL		1,995.00	1,813.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,450.00

Report Ref No. CS/SPF19009197/Etd3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000

RECOMMENDED REPAIR DAYS : 3

WEEKEND : 2

TOTAL DAYS : 5

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.