

22/03/2019

ASS. REC. BY:

REF: CS3/FWD 1900 9211/T/CD302

Special Instruction:

Surveyor: TaufikASSIGNMENT (Office)From (Person): Claraof FWDDate/Time: 24/5/2019

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJR 8603UInsured: FX 7311Jat Workshop m/s Heng Huet MotorTel: 84983980 Mr Angof 5033 AMK #01261Policy No: PNMC2019-00000339Claim No: 1201900014045

Sum Insured: _____

Excess: _____

Make of Veh:

(Client's Record)

D.O.A. 22/5/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: _____

Person Contacted: _____

Vehicle IN / OUT


| Date/Time | Action/Instruction | Estimate (X) |
|-----------|----------------------------------|--------------------|
| | SJR 8603U - CC2/MIDA 10011268/g1 | P.O.A - 19/05/2010 |
| | PX 7311J - X | |
| | Dismantle: 27/5/2019 | |
| | | |
| | | |
| | | |

Taughlin

RE

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 TP / WS / TP / RS / OD / RS / LVA / INV / MV
 To inspect Vehicle: Ho
 at Workshop: _____
 of _____
 Insured _____
 Policy No _____
 Claim No _____
 Sum Insured _____ Excess: *thn*
 (Client's Record) _____
 Make of Veh: _____



(Policy Condition)
 Remarks: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: *\$14,500*
 IDAC Accident Report: Consistent? Yes or No
 GIA / PR Score: Consistent? Yes or No
 Est. Repairs: *5* days Res: Yes or No
 Est. Sum: % 3 Val: Yes or No
 GA / REV / REP: / 24 HRS
- PRS

Date: _____ Person Contacted: _____

Veh No: *SSR 86034* Date: *Jul-09*
 Type: *MC* / MCycle / Bus / Van / Lorry / Truck / Prime Mover /
 Truck / Trailer or _____
 Make: *Nissan Lafeta* 1997
 Color: *Grey* A/C: Insured / 3rd / 4th / 5th
 Cap Reading: *249798* 1/3rd / Insured / 3rd / 4th / 5th

Eng/No: *JN1TAAB30Z000160*
 C/No: _____
 Gen. Cond: *Good* / Fair / Poor / Burnt
 Steering: *Good* / Jammed / Leaked / Burnt or
 Brake: *Good* / Jammed / Leaked / Burnt or
 Mod: *Nil* / 1st / 2nd / STD A/Rim or
 Tyre Size: *E: 195/60R15*
R: _____
 BS / DUN / EXNOVA / GY / FS / LEZA / *MC* / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front: _____ Rear: _____
 R/Bal: *6* mm R/Bal: *6* mm
 L/Bal: *6* mm L/Bal: *6* mm
 D.O.A. *24/5/19 @ 2:50pm*
 Survey held at: *Henry Street Motor*
 Des. of Damages: F/R / Rear / O/S / 1/3rd / 4th / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: _____

no 617
 Estimated repair range *\$4,000 - \$5,000*

5033 AMK Ind PK2
#01-261

5/1/2019

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair: *5*

Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

3 x 100.00

190.00

Others:

130

TOTAL

Report Format: *PRS*

Lump Sum / L.B.I. (\$)

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Insp (\$)

☐ Weekend (\$)

80
50

130

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|---|---------|---------------|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 24 May 2019 Edit Reg | | 24 May 2019 00:00 Edit Adj Rpt | | | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|-----------|------------------------|-----------------------------------|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: CHUA HUI SIANG , ID: S8774149D | | | | | | | | | |
| Main Claimant: CHEONG LIMOUSINE , Co. Reg. No.: 53334086A | | | | | | | | | |
| Vehicle Reg. No.: SJR8603U | | Date of Loss: | 22/05/2019 22:00 - :59 | | | | | | |
| Claim Type: TP / 1201900014045 | | Policy/Cover Note No.: | PNMC2019-00000339 (Comprehensive) | | | | | | |
| Vehicle Reg. No. (Insured): FX7311J | | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: Heng Huat Motor (AMK) Bk 5033 AMK INDUSTRIAL PARK 2 #01-261, 569536 Ang Mo Kio - Tel: 84983980 | | | | | | | | | |
| Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong] | | | | | | | | | |
| Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 04/06/2019] | | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Nivitha (LKK Auto)

From: clara.li@fwd.com
Sent: Friday, 24 May 2019 11:34 AM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: Our client's vehicle no. SJR8603U (HHM); Your insured's vehicle no. FX7311J - PRI Our Ref: PNMC2019-00000339/CL
Attachments: Heng Huat Motor - Pre-Repair Notice (FWD)(SJR8603U).pdf

Hi LKK team,

Please assist with TP PRS and create the case in Merimen.

Our insured has yet to lodge accident report.

Thank you.

Regards,
Clara

From: Hui Ting [mailto:huiting@crossbordersllc.com]
Sent: Friday, 24 May, 2019 11:29 AM
To: Clara Li Zirong - SGUser
Cc: Corene; Motor Claims SG - SG Common
Subject: RE: Our client's vehicle no. SJR8603U (HHM); Your insured's vehicle no. FX7311J - PRI Our Ref: PNMC2019-00000339/CL

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Clara

1. We refer to your email dated 24 May 2019.
2. Our client objects appointing your surveyors as a single joint expert.
3. We propose one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:-

- | | |
|------------------|---|
| 1) Dave Chang | Sincere Appraisal Services |
| 2) Sebastian Lim | Constant Appraiser Services |
| 3) Alan Cheong | CL Appraiser Pte Ltd |
| 4) Yap Teck Chye | MC-Coy Appraiser Pte Ltd |
| 5) Andrew How | Prominent Appraiser Services |
| 6) Marc Ananda | United Appraisal and Management Pte Ltd |
| 7) Dennis Yap | PAL'S Appraiser Pte Ltd |
| 8) Yap Teck Lee | LCW Appraiser Pte Ltd |
| 9) Dixon Yeo | Treasure Appraiser Pte Ltd |
| 10) T.T. Rajan | ST Appraisal Services |

4. Please let us know within two (2) working days whether you are agreeable to the appointment of any of the above motor surveyors as a single joint expert.

CROSSBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk. HHM (SJR8603U)
Your Ref: FX7311J

24 May 2019

FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower Four
Singapore 038986
Attn: Motor Claims Department

BY EMAIL ONLY

URGENT

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
CLAIMANT: CHEONG LIMOUSINE
TRAFFIC ACCIDENT ON 22 MAY 2019 AT 22:00 HRS ALONG TIONG BAHRU ROAD
JUNCTION SENG POH ROAD INVOLVING VEHICLES NO. SJR8603U & FX7311J

We are instructed by Cheong Limousine to notify you of a road accident 22 May 2019 at about 22:00 hrs along Tiong Bahru Road Junction Seng Poh Road involving our clients' vehicle registration number SJR8603U and vehicle registration number FX7311J driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.


As a result of the accident, our clients' vehicle has been damaged. Before our clients proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our clients shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: Heng Huat Motor Repair Workshop
Address: 5033 Ang Mo Kio Industrial Park 2
#01-261 Ang Mo Kio Industrial Park 2
Singapore 569536
Contact: Mr Ang (8498 3980)

Please liaise with the above workshop directly.

Yours faithfully


Crossborders LLC
Email: corene@crossbordersllc.com /
huiting@crossbordersllc.com
encs

PLEASE LET US KNOW THE DATE
OF THE PRE-REPAIR INSPECTION

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413
TEL: 6438 1323
FAX: 6438 2313

BRANCH OFFICE
1 JALAN BERSIH
#03-12 NEW WORLD CENTRE
SINGAPORE 209037

PLEASE SEND ALL
CORRESPONDENCES TO
THE MAIN OFFICE

WE DO NOT ACCEPT
SERVICE BY FAX

CONFIDENTIALITY CAUTION
THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE
SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

CROSSBORDERS LLC

A LIMITED LIABILITY CORPORATION. REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

> Back to OneMotoring

Enquire Transfer Fee

| Vehicle Details | | | |
|--|--|---------------------|---------------------------|
| Vehicle No. : | SJR8603U | | |
| Vehicle Type : | Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover | | |
| Vehicle Attachment 1 : | With Sun Roof | | |
| Vehicle Scheme : | Normal | | |
| Vehicle Make : | NISSAN | | |
| Vehicle Model : | LAFESTA 2.0L CVT ABS AIRBAG SUNROOF | | |
| Chassis No. : | JN1TAAB30Z0200160 | | |
| Propellant : | Petrol | | |
| Engine No. : | MR20789453A | | |
| Engine Capacity : | 1997 cc | | |
| Maximum Power Output : | 101.0 kW (135 bhp) | | |
| Maximum Laden Weight : | 1890 kg | | |
| Unladen Weight : | 1445 kg | | |
| Year Of Manufacture : | 2009 | | |
| Original Registration Date : | 16 Jul 2009 | | |
| Lifespan Expiry Date : | - | | |
| COE Category : | B - Car (1601cc & above) | | |
| Quota Premium : | \$16,801.00 | | |
| COE Expiry Date : | 15 Jul 2019 | | |
| Road Tax Expiry Date : | 15 Jul 2019 | | |
| PARF Eligibility Expiry Date : | 15 Jul 2019 | | |
| Inspection Due Date : | 15 Jul 2020 | | |
| Intended Transfer Date : | 06 Jun 2019 | | |
| CO2 Emission : | - | | |
| CO Emission : | - | | |
| HC Emission : | - | | |
| NOx Emission : | - | | |
| PM Emission : | - | | |
| Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable. | | | |
| Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred. | | | |
| Amount Payable | | | |
| | Amount Before GST (S\$) | GST Amount (S\$) | Amount After GST (S\$) |
| Transfer Fee : | 25.00 | - | 25.00 |
| Total Amount Payable : | | | 25.00 |
| Message | | | |
| From 18 Feb 2019, the Government has further reduced the annual special tax by \$100 and \$850 for diesel and diesel-hybrid cars and taxis respectively. The Government will also grant road tax rebates for diesel and diesel-hybrid buses and goods vehicles for a 3-year period from 1 Aug 2019. The current enquiry result does not include the revised special tax reduction and road tax rebate commencing 1 Aug 2019. Please refer to the Press Release for more information. | | | |

You may print this page for reference.

OK Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|-------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Business |
| Owner ID: | 4086A |
| Vehicle Details | |
| Vehicle No.: | SJR8603U |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 06 Jun 2019 |
| Vehicle Make: | NISSAN |
| Vehicle Model: | LAFESTA 2.0L CVT ABS AIRBAG SUNROOF |
| Primary Colour: | Gold |
| Manufacturing Year: | 2009 |
| Engine No.: | MR20789453A |
| Chassis No.: | JN1TAAB30Z0200160 |
| Maximum Power Output: | 101.0 kW (135 bhp) |
| Open Market Value: | \$24,971.00 |
| Original Registration Date: | 16 Jul 2009 |
| First Registration Date: | 16 Jul 2009 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$24,971.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 15 Jul 2019 |
| PARF Rebate Amount: | \$12,485.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 15 Jul 2019 |
| COE Category: | B - Car (1601cc & above) |
| COE Period(Years): | 10 |
| QP Paid: | \$16,801.00 |
| COE Rebate Amount: | \$180.00 |
| Total Rebate Amount: | \$12,665.00 |

The information contained herein is correct as at 06 Jun 2019

OK

m.v. ?

2. This Form must be completed by the Policyholder and/or the Authorized Person.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/05/2019 12:52
 Date Of Accident 22/05/2019 22:00
 Exact Location Of Accident TIONG BAHRU RD JUNCTION SENG POH RD
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJR8603U
 Insured/Policyholder
 Name Of Registered Owner CHEONG LIMOUSINE
 Co Reg No 53334086A
 Email Address LYT.BRONSON@GMAIL.COM
 Mobile Phone No (LOCAL) +65-90998991
 Alternative Phone No OFFICE-90998991

Vehicle Particulars

Manufacturer NISSAN
 Model LAFESTA
 Exact Purpose for which vehicle was being used at time of accident WORK PURPOSE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage THIRD PARTY
 Fleet Policy YES
 Policy Number 5107830932 (TP)
 Cover Note Number

Driver

Name of Driver LEE CHOON NAM
 NRIC No S7201437E
 Date Of Birth 13/01/1972
 Occupation OUTDOOR
 Date Of Driving Pass 19/03/1990
 Driving Experience 29 YEARS AND 2 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-90998991
 Fax Number
 Contact Number OTHERS-90998991
 Email Address NOEMAIL

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

| | |
|---|---|
| Number of vehicles (including own vehicle) involved in the accident | 2 |
|---|---|

Was any body injured in the Accident? YES

| | |
|--|----|
| Was any injured conveyed to hospital by ambulance? | NO |
|--|----|

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

| | |
|---|---|
| Number of Passengers (Including Driver) | 2 |
|---|---|

| | | |
|-------------|-------|---------|
| Passenger 1 | NAME: | UNKNOWN |
|-------------|-------|---------|

GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

I WAS DRIVING STRAIGHT ALONG TIONG BAHRU ROAD TOWARDS OUTRAM ROAD. A MOTORCYCLE FX 7311J SUDDENLY DROVE OUT FROM THE SIDE ROAD ON MY LEFT WITHOUT STOPPING AT THE STOP LINE. THUS, MOTORCYCLE FX 7311J FRONT PORTION COLLIDED INTO THE LEFT SIDE PORTION OF MY VEHICLE. (ATTEND CHRISTINA)

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FX7311J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category MOTORCYCLE

| | |
|----------------|---------|
| Name of Driver | UNKNOWN |
|----------------|---------|

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LEE CHOON NAM

Approximate Age

Injuries Sustain

NECK AND SHOULDER PAIN

Injured person in which vehicle?

SJR8603U

Were seat belts worn?

YES

Was this injured conveyed to hospital by
ambulance?

NO

Address

Postcode

- report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application to interested parties.
 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to the report being made available aforesaid.
 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices which could involve disclosure of certain personal data about me to bring about delivery of the same as well as external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing claims, regulators, law enforcement and government agencies as reasonably required for the purposes stated;
 - (ii) for complying with requirements under any regulations, laws or court orders.



23 MAY 2019



Policyholder's Signature

Insurer's Signature

Reporting Centre Personnel



NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|---|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 24 May 2019 Edit Reg | | 24 May 2019 00:00 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|--|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | CHUA HUI SIANG , ID: S8774149D | | | | | | | | |
| Main Claimant: | CHEONG LIMOUSINE , Co. Reg. No.: 53334086A | | | | | | | | |
| Vehicle Reg. No.: | SJR8603U | Date of Loss: | 22/05/2019 22:00 - :59 [118 Months and 6 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 1201900014045 | Policy/Cover Note No.: | PNMC2019-00000339 (Comprehensive) | | | | | | |
| Vehicle Reg. No. (Insured): | FX7311J | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Heng Huat Motor (AMK) Bk 5033 AMK INDUSTRIAL PARK 2 #01-261, 569536 Ang Mo Kio - Tel: 84983980 | | | | | | | | |
| Handling Insurer: | FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 04/06/2019] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SJR8603U (1201900014045)

[FX7311J]






































TP

CHEONG LIMOUSINE

May 22 2019 10:00PM

[CHUA HUI SIANG]

Heng Huat Motor

| Upload Documents Upload Photos Compose New Letter | | | View View in Browser | |
|---|-----------------|-----------------------------------|--|-------------------------------------|
| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 12 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 13 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 14 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 15 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 16 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 17 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 18 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 19 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 06/06/19 18:47 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 29 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 31 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 38 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 06/06/19 18:48 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | FWD Singapore Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 24/05/19 19:25 | E-filed GIA report |  Load PDF | |

Documents Checklist

| | | | |
|--|--------------------------------------|-------------------------------------|--------------------------------------|
| DOCUMENTS CHECKLIST | <input type="button" value="Reset"/> | <input type="button" value="Save"/> | <input type="button" value="Print"/> |
| There are no document checklists configured. | | | |

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD19009211/T1CD3E2

Date: 12/07/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNMC2019-00000339
Claimant Vehicle No : SJR8603U **Insured Vehicle No :** FX7311J
 Date of Loss: 22/05/2019 Nature of Claim: TP Claim No: 1201900014045

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR8603U**
 Make & Model: NISSAN LAFESTA, 2.0 (A) Engine No: MR20789453A
 Reg. Date: 16/07/2009 (Man. Year: 2009) Chassis No: JN1TAAB30Z0200160
 Colour: Beige Odometer: 249798 km
 Engine Capacity: 1997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 24/05/2019
 Date Inspected: 24/05/2019 Inspected At: Heng Huat Motor (AMK)
 Bk 5033 AMK INDUSTRIAL PARK 2 #01-261
 Singapore 569536
 Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

| | | |
|----------------------|--|--|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 12 Jul 2019) |
| Parts: | M1-MPV | NISSAN LAFESTA 2.0 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJR8603U) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >