

Surveyor

REF:

CSI/FCI19009219/Ptd352

Special Instruction:

L\$53501

ASSIGNMENT (Office)

From (Person): Henry Kao of FCI Date/Time: 24/5/2019

Estimated Cost: Bill to:

Third Parties:

Claimant: Owner

Surveyor: Premier Appraiser

Workshop: Autopox

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SGV4417G

Insured: SHC7H60Z

at Workshop m/s Autopox House

Tel:

of 176 Sin Ming Drive #02-01

Policy No:

Claim No: D13001384/CCPL/CJ-TPD1

Sum Insured:

Excess:

Make of Veh:

D.O.A. 24/1/2013

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 6 days)

Date/Time: 14/6/2019 Submit Final Fig 25501, 3 days (Red \$ 2700 / 51 %; Original 6 days)

Date/Time

Action/Instruction

SGV4417G-X

SHC7H60Z-NC/INC13001826/H1ZU2 DON: 24/1/2013

14/06/19 To submit 1/5 25501 - with 3 days of rev.

Minor damage to most items not given as photo show no damage and also unlikely to be damaged. From minor impact.

RECEIVED 14 JUN 2019

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

120

1) Date/Time 14/6/2019 File Pass to Typist

2) Date/Time File Return to

3) Date/Time File Pass to

4) Date/Time File Return to

5) Date/Time File Pass to

6) Date/Time File Return to