

ASS. REC. BY:

REF: CS/MSG19009241/Gsd3⁹²

Special Instruction:

Surveyor:

GA

ASSIGNMENT (Office)

From (Person):

Jawyn Tay New Ling

of

MSG

Date/Time:

27.5.19 10:23p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDF 2445H

Insured:

SLV 2331Z

at Workshop m/s

MOE Motor

Tel:

64 54 2203

of

BLK I Sin Ming Sector C # 01-82

Policy No:

29089136 MCT

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time:

27.5.19 10:56a.m

Person Contacted:

Joyce

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SDF 2445H-NA/CTJ1900845/24

D.O.A - 02/05/2019

SLV 2331Z - X

Circulator:

CUL

REF:

MS6

1975H

ASSIGNMENT

(-2020)

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

NIE Motor

of

6454 2203

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

\$7200

IDAC Accident Rpt.:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SDF2445H

Yr Regn:

08 Mar 2005

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan defiro 2.3 cc 2349

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

260536

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1BAUJ3180010279

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD/A/Rim or

Tyre Size:

F:

25/60R16

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

D.O.I.

27-05-19

Survey held at

W/S

11:30

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Total loss - Noneconomic to repair.
Repair limit \$1543.

Submit Total Loss as Extensive

MV - \$3,200/-

LTA - \$5,657.00

Nett - \$1,543.00

RECEIVED 30 MAY 2019

29/5/2019

Date/Time, File Pass to?

30/05/19

1) Typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

\$ + RS, \$ SI

Photos

Others

TOTAL

Report Format:

Total Loss

Lump Sum / I.B.I. (\$)

150
10

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Advised	Status
Main	24 May 2019 15:46		27 May 2019 10:23 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS		[Created by insurer]		
Insured:	BORNEO MOTORS (SINGAPORE) PTE LTD , Co. Reg. No.: 196700086Z			
Main Claimant:	PHUA CHENG KOON , ID: S1581975H			
Vehicle Reg. No.:	SDF2445H	Date of Loss:	23/05/2019 00:00 - :59 [170 Months and 15 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP	Policy/Cover Note No.:	29089136MCY (Comprehensive) Coverage: 01/07/2018 - 30/06/2019	
Vehicle Reg. No. (Insured):	SLV2331Z	Policy No. (Claimant):		
Repairer:	Excess:			
Handling Insurer:	Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82, 575642 Sin Ming - Tel: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/05/2019]			
Driver/Custodian (Insured):	CHONG CHA MEI () , NRIC: G8174451W Email:			
Adj Asg. Remarks:	on WP. Liab: 100%(BOLA S28). TP disagree on SJE- assign LKK. Contact: 6454 2203.			
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail		
There are no mail for this case.				
ALL ASSOCIATED TASKS				
View All		Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 29 May 2019

Preliminary Advice

Insured Vehicle No	: SLV2331Z	Accident Date	: 23/05/2019
TP Vehicle No	: SDF2445H	Assignment Date	: 27/05/2019
Make	: NISSAN CEFIRO	Est. Duration of Repair	: -
Date of Inspection	: 27/05/2019		
Inspection At	: Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82 Singapore 575642		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	TOTAL LOSS

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis. Vehicle recommended total loss due to not economical for repair.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/05/2019 14:55
Date Of Accident	23/05/2019 08:50
Exact Location Of Accident	ALONG PIE TOWARDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDF2445H
Insured/Policyholder	
Name Of Registered Owner	PHUA CHENG KOON
NRIC No	S1581975H
Email Address	PHUAPHUA1963@GMAIL.COM
Mobile Phone No	(LOCAL) +65-83132991
Alternative Phone No	OTHERS-83132991

Vehicle Particulars

Manufacturer	NISSAN
Model	CEFIRO 2.3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	0100505602-14
Cover Note Number	

Driver

Name of Driver	PHUA CHENG KOON
NRIC No	S1581975H
Date Of Birth	10/03/1963
Occupation	INDOOR
Date Of Driving Pass	22/04/1985
Driving Experience	34 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-83132991
Fax Number	
Contact Number	OTHERS-83132991
EMail Address	PHUAPHUA1963@GMAIL.COM

Address	1 PUNGGOL FIELD WALK #09-02
Postcode	828739
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV2331Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHC1811D
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SLD744Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

SKT60288X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 3 MAY 2019

14-5510

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Kwee Choo
NRIC/FIN No.: S8840583A

SKETCH PLAN


A: SDF2445H

B: SLV2331Z

C: SHD1811D

D: SLD744Z

E: SK16028X



Date: 23/5/2019

Time: 8:50 Am


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along PIE towards TUAS in lane 2. The vehicle in front of me slowed to a stop. I slowed down and came to a complete stop as well. My vehicle was about half car length away from the front vehicle. My vehicle was stationary when suddenly there was a heavy impact on the rear of my vehicle followed by a few loud bangs. Vehicle B collided into the rear of my vehicle. Due to the heavy impact my vehicle surged forward and contacted the rear of the vehicle in front. I felt my body lift off the driver seat despite the seatbelt restraint. There was immediate neck and upper back stiffness. I alighted and saw the back of my car suffered severe damage. Frontal damage was minimal. A total of 5 cars involved in the accident.

Damage to vehicle is obvious. Rear damage is visible. Frontal damage is minimal. I have to consult a doctor for this discomfort in my neck and upper back. Upper back feels tight and very stiff.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature

Date & Time:

23 MAY 2019

Driver's Signature

(If driver is not the policyholder)


 Reporting Centre Personnel's Signature
 Name: Kwee Choo
 66840583A

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	1975H
Vehicle No.:	SDF2445H
Vehicle to be Exported:	No
Intended Deregistration Date:	27 May 2019
Vehicle Make:	NISSAN
Vehicle Model:	CEFIRO 2.3A
Primary Colour:	Black
Manufacturing Year:	2004
Engine No.:	VQ23059682A
Chassis No.:	JN1BAUJ31Z0010279
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$29,028.00
Original Registration Date:	08 Mar 2005
First Registration Date:	08 Mar 2005
Transfer Count:	0
Actual ARF Paid:	\$31,931.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	07 Mar 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$36,518.00
COE Rebate Amount:	\$3,657.00
Total Rebate Amount:	\$5,657.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 May 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 May 2019 15:46		27 May 2019 10:23 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	BORNEO MOTORS (SINGAPORE) PTE LTD , Co. Reg. No.: 196700086Z		
Main Claimant:	PHUA CHENG KOON , ID: S1581975H		
Vehicle Reg. No.:	SDF2445H	Date of Loss:	23/05/2019 08:00 - :59 [170 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 594324	Policy/Cover Note No.:	29089136 (Comprehensive) Coverage: 01/07/2018 - 30/06/2019
Vehicle Reg. No. (Insured):	SLV2331Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82, 575642 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 26/06/2019]		
Driver/Custodian (Insured):	CHONG CHA MEI (); NRIC: G8174451W Email:		
Adj Asg. Remarks:	on WP. Liab: 100%(BOLA S28). TP disagree on SJE- assign LKK. Contact: 6454 2203.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)


































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





Claim Documents

***SDF2445H (594324)**
[SLV2331Z]
TP
PHUA CHENG KOON
May 23 2019 8:00AM
[BORNEO MOTORS (SINGAPORE) PTE LTD]
Mje Motor

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/05/19 17:20	Adjuster Immediate Advice	 Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/05/19 15:01	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
3	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
4	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
5	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
6	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
7	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
8	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
9	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
10	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
11	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
12	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
13	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
14	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
15	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
16	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
17	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
18	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
19	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
20	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
21	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
22	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
23	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
24	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
25	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
26	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
27	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
28	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
29	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
30	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
31	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
32	28/05/19 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	28/05/19 15:01	General View	 Load JPG	✓
34	28/05/19 15:01	General View	 Load JPG	✓
35	28/05/19 15:01	General View	 Load JPG	✓
36	28/05/19 15:01	General View	 Load JPG	✓
37	28/05/19 15:01	General View	 Load JPG	✓
38	28/05/19 15:01	General View	 Load JPG	✓
39	28/05/19 15:01	General View	 Load JPG	✓
40	28/05/19 15:01	General View	 Load JPG	✓
41	28/05/19 15:01	General View	 Load JPG	✓
42	28/05/19 15:01	General View	 Load JPG	✓
43	28/05/19 15:01	General View	 Load JPG	✓
44	28/05/19 15:01	General View	 Load JPG	✓
45	28/05/19 15:01	General View	 Load JPG	✓
46	28/05/19 15:01	General View	 Load JPG	✓
47	28/05/19 15:01	General View	 Load JPG	✓
48	28/05/19 15:01	General View	 Load JPG	✓
49	28/05/19 15:01	General View	 Load JPG	✓
50	28/05/19 15:01	General View	 Load JPG	✓
51	28/05/19 15:01	General View	 Load JPG	✓
52	28/05/19 15:01	General View	 Load JPG	✓
53	28/05/19 15:01	General View	 Load JPG	✓
54	28/05/19 15:01	General View	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/05/19 15:47	OI GIA	 Load PDF	
2	24/05/19 15:48	PRI	 Load PDF	
3	27/05/19 17:49	SDF2445H E-FILE 2/5	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/05/19 14:08	LTA REBATE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19009241/GSD3S2

Date: 30/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29089136

Claimant Vehicle No : SDF2445H

Insured Vehicle No : SLV2331Z

Date of Loss: 23/05/2019

Nature of Claim: TP

Claim No: 594324

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDF2445H

Make & Model: NISSAN CEFIRO, 2.3 J31 (A)

Engine No: VQ23059682A

Reg. Date: 08/03/2005 (Man. Year: 2004)

Chassis No: JN1BAUJ31Z0010279

Colour: Black

Odometer: 260536 km

Engine Capacity: 2349 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size: 215/60R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/05/2019

Date Inspected: 27/05/2019

Inspected At:

Mje Motor (HQ)

BLK 7 SIN MING SECTOR C, #01-82

Singapore 575642

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

MARKET VALUE - \$ 7,200.00

LTA - \$ 5,657.00

NETT VALUE - \$ 1,543.00

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2019)
Parts:	143	NISSAN CEFIRO 2.3 J31 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDF2445H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >