

NATIONAL Assessment Centre Services

Date In: 27/05/2019 10:54	Job description	Date & Time Completed	Done by
Ref No: NA/INC19004244/K4	SAS e-filing		
Veh No: SGD 95Y	E-mail (within 8hrs. AIC 2hrs)		
D.O.A: 26/05/2019 12:20	i-Motor Claim Form	MT/1046193-002	27/5/19 14:54
OD TP Reporting Only	i-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	i-Photo Uploaded		
TP Insurer:	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (	Tel:	Fax:
TP Particulars:	Veh No: SMA6869L	INC () / Non-INC ()
Owner / Driver: (	Tel:	
Policy No: (	Period: (	Cover Type: (
Confirmed by: (	Date:	Time:
Insured/Driver Liability: (	% [Note-Est. Status (WO): N: 0-20%; P: 21-79%; F: 80-100%]	
Year of Registration: (	Warranty: YES () / NO ()	
Excess: (\$	Loading: \$1,000 () / \$2,000 ()	

General Remarks:-

() Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In () / Towed-In (); Invoice: YES () / NO (); Towing Co. ()

Remarks:- (INC hotline: 6788 6616)	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury: _____

Date/Time	Actions

NA1904171

Claimant's Particulars :-	Invoice Preparation Checklist	Amt (\$) 1st Bill	Amt (\$) Add Bill
Driver/Owner:	1) AR: Accident Reporting (\$30);		
Contact No:	2) DA: Damage Assessment (\$100); INC (\$80)		
Damaged Portion:	3) TF: Towing Fee \$40/\$45		
QC Checked by (Engr-In-Charge):	4) FT: Follow-Through Survey \$120		
	5) FT: Follow-Through Survey (Resurvey) \$30		
	For claiming against INC Only (wef 10 Jan 2005)		
	6) TR: Re-inspection \$75		
	7) N1: Idac DA + SMRT Survey \$160		
	8) NTUC Additional Services:-		
	OD*		
	*N5: Courtesy Car / Tpt Allowance \$5		
	*N6: Repair Co-ordination \$10		
	*N7: Post Repair Inspection \$25		
	*N8: DV / Collect Excess Coordination \$5		
	TP (N11): TP (Non INC) against INC \$20		
	9) N12: Idac Mobile 30		
	Invoice dated	Fee Charged	
	Invoice dated	Fee Charged	

Auditors' Comments :-

Cat. 1:

Cat. 2 / 3:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/05/2019 10:54
Date Of Accident	26/05/2019 12:20
Exact Location Of Accident	ANG MO KIO AVE 3 TWDS ANG MO KIO AVE 10
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGD95Y
Insured/Policyholder	
Name Of Registered Owner	CHAN SOON CHEE
NRIC No	S7322277Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97669855
Alternative Phone No	OTHERS-97669855

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER 2.0 ELEGANCE AT ABS D/AIRBAG 2WD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5075506281-03
Cover Note Number	

Driver

Name of Driver	CHAN SOON CHEE
NRIC No	S7322277Z
Date Of Birth	13/06/1973
Occupation	INDOOR
Date Of Driving Pass	30/11/1993
Driving Experience	25 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97669855
Fax Number	
Contact Number	OTHERS-97669855
EMail Address	NOEMAIL

Address	34 CHUAN HOE AVENUE
Postcode	549837
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMA6869L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	KOH CHEE KEONG
NRIC/Passport Number	S6901616B
Contact Number	96322773
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



27/5/2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

1 - SGD 95Y
3 - SMA 6869L

ANG MO KIO AVE 10

← [B] [C]

ANG MO KIO AVE 3

B-SMA 6869L

946 No. 10 Ave. 10

Ang mo K.O Ave 3

Vehicle A was driving along Ang Mo Kio Ave 3.
Vehicle B suddenly stop and vehicle A hit vehicle B.
Vehicle A was damaged badly in the front position.

Vehicle A was driving along Ang Mo Kio Ave 3.
Vehicle B suddenly stop and vehicle A hit vehicle B.
Vehicle A was damaged badly in the front portion.

I/We declare the foregoing particulars are true in every respect.

I/We declare the foregoing particulars

are true in every respect.

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Guidance Note

This Guidance Note is intended to assist you with your policy details and the accident reporting procedures.

If you require further assistance, please call our Command Centre (24-hour hotline) at **6789 5000**.

Ref: OF/2016-2020/10284

Policy Number		Vehicle Number	
Cover Type ☐ Prestige ☐ Prestige Third Party Fire & Theft ☐ Prestige Third Party ☐ Drivo Premium ☒ Drivo Classic ☐ Comprehensive (PWP) ☐ Comprehensive ☐ Third Party Fire & Theft ☐ Third Party			
No Claim Discount (NCD) %		Excess (Subject to Prevailing GST) Standard Excess \$ Unnamed Excess \$ Additional Excess \$ Third Party Excess \$	
NCD Protector ☐ Yes ☐ No (1 accident within the period of insurance)			
Transport Allowance ☐ Yes ☐ No (SGD50 a day up to 7 days from the first day of repair for first 2 claims within the period of insurance)			
Excess Waiver ☐ Yes ☐ No (To waive the Standard Excess of \$600 only for first 2 claims within the period of insurance)			

Accident Report to be made at any of our Income Accident Reporting Centres within 24 hours of the accident

Items to note:

- ✓ Driver of Vehicle must make report personally.
- ✓ Bring Vehicle & Vehicle Key to Reporting Centre.
- ✓ Bring Driver's NRIC, Driving Licence, Insurance Cert.

- ☐ Bring a Copy of Policyholder's NRIC (Front & Back).
- ☐ Bring Company's Stamp.
- ☐ Bring Police Report; Driver is to lodge Police Report as soon as possible or within 24 hours of the accident if the accident involves:

- Damage to government property
- Foreign vehicle
- Injury cases where anyone involved in the accident was conveyed to hospital or has obtained MC for 3 days or more

- Pedestrian / Cyclist
- Hit-and-run
- Fatality

- ✓ Your NCD will be affected if you fail to report the accident within the stipulated time.
- ✓ Submit video recording from your in-car camera if available.

53 uni ave 1 #01-25
 Paya uni
 6841 0055 .

Authorised Driver/Person's Name		For video recording up to 10MB, you may ➤ email to motorvideo@income.com.sg. For video recording more than 10MB, you may ➤ submit the storage device (non-returnable) at our Income branches or Accident Reporting Centres where you file your accident report.
NRIC/ID no.	Relationship to Policyholder	
Contact no.	Signature	

For Official Use

Issued by	Staff Code	Date (dd/mm/yyyy)	Time
------------------	-------------------	--------------------------	-------------

Reported on 27/5/2019
@ 10:50 AM

ACCIDENT STATEMENT

ACCIDENT DATE: 26/5/2019 (DD/MM/YYYY), TIME: 12:20 (HH:MM)

LOCATION: Ang Mo Kio Ave 3 towards Ang Mo Kio Ave 10

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: SGD 954
b) INSURANCE COMPANY: _____
c) POLICY NUMBER: _____
d) POLICY TYPE: (COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE & THEFT)
e) MAKE & MODEL: _____
f) TYPE: (SALOON / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS)
g) VEHICLE CATEGORY: (PRIVATE / COMMERCIAL / MOTORCYCLE)
h) PURPOSE OF USING AT ACCIDENT TIME: _____
i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO) (NO) ✓
IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

2. INSURED / POLICY HOLDER

- A) NAME: _____ (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: _____ CONTACT: _____
c) ADDRESS: _____

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

- a) NAME: _____ (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: _____ CONTACT: 97669855
c) ADDRESS: _____

* d) DATE OF BIRTH: () / () / () (DD/MM/YYYY)

e) OCCUPATION: (INDOOR / OUTDOOR)

f) YEARS OF DRIVING EXPERIENCE: _____

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO) OWNER
IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED: _____

5. a) WEATHER CONDITION: (CLEAR / RAINING / OTHERS) _____

b) ROAD SURFACE: (DRY / WET / OTHERS) _____

6. WAS ANYBODY INJURED (YES / NO) (NO)

7. a) REPORTED TO POLICE (YES / NO) (NO)

IF YES, PLEASE STATE WHICH POLICE STATION: _____

8. THIRD PARTY VEHICLE

- a) VEHICLE NUMBER: SMA 6869L MODEL: _____
b) DRIVER'S NAME: Koh Chee Keong
c) NRIC/FIN/PASSPORT: S 6901616B CONTACT: 96322773

9. THIRD PARTY VEHICLE

- d) VEHICLE NUMBER: _____ MODEL: _____
e) DRIVER'S NAME: _____
f) NRIC/FIN/PASSPORT: _____ CONTACT: _____

Email =

Fax =

VIDEO =

* Vehicle
Tow In to idac
on 26/5/2019
and Driver taken
all the belongs
and Engineer
cannot be start
or move
Vehicle:

Enquire Transfer Fee

You may print this page for reference.

Print

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7322277Z



Name
CHAN SOON CHEE
(ZENG SHUNZHI)
曾 顺 志

Race
CHINESE

Date of Birth
13-06-1973

Country of Birth
SINGAPORE

Sex
M

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S7322277Z

Name
CHAN SOON CHEE
(ZENG SHUNZHI)

Birth Date 13 Jun 1973

Issue Date 08 Oct 2003




2526488



NRIC No: S7322277Z



Blood Group Date of issue
B+ 17-11-1994

34 CHUAN HOE AVENUE
SINGAPORE 549837
NRIC No: S7322277Z


Date: 01/01/2011 No: 6689124

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	06 Apr 1994
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	30 Nov 1993

NP 428A

Licence No: S7322277Z



Hello, NAC_PAYA_UBI_800601

[Change Language](#) [Change Password](#) [Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	26/05/2019 12:20
Vehicle No.(For Motor)	SGD95Y	Certificate Number	
Search			

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5075506281-03		CHAN SOON CHEE	S7322277Z	GPC	drive CLASSIC	SGD95Y	SGD95Y	13/11/2018	12/11/2019

▼ Policy Information

Policy No.	5075506281-03	Policyholder Name	CHAN SOON CHEE	Policyholder NRIC	S7322277Z
Certificate No.					
Address	34 CHUAN HOE AVENUE CHUAN HOE GARDENS SINGAPORE 549837				
Product Name	PRIVATE CAR INSURANCE	Plan		Group Policy Flag	N
Policy Issue Date	30/10/2018	Effective Date	13/11/2018 00:00	Expiry Date	12/11/2019 23:59
Third Party Excess	0	Own damage Excess	600	Windscreen Excess	100
Additional Excess	0	OS Premium	0		
Outside Singapore OD Excess	600	Outside Singapore TP Excess	0		
Agent	THINK ONE AUTOMOBILE & TRA	Agent Tel.	65553300	GST Flag	Y
Co-insurance Flag	No				
Open Policy Info					
Certificate Info					

▼ Policyholder Mailing Address

Address 1	34 CHUAN HOE AVENUE	Address 2	CHUAN HOE GARDENS	Address 3	SINGAPORE 549837
Address 4		Address Type	Singapore address	Post Code	549837
Unit No.		Related Policy Number	5075506281-03		

► Insured Object: SGD95Y

▼ Endorsements

Sequence	Date of Endorsement	Endorsement Type	Endorsement Status	Endorsement Content
Continue Cancel				

Claim Handling

Accident MT/1046193

Policy No.	5075506281-03	Vehicle No.	SGD95Y	GST Registration No.
Certificate No.				
Policyholder Name	CHAN SOON CHEE			Policyholder NRIC
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading
Contact No.(Mobile)	97669855	Contact No.(Office)		Contact No.(Home)
Email Address		Special Remark		eCode
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason
NCD Protection	Yes	NCD Entitlement(%)	50	Private Hire

▼ Accident Details

Report Date	27/05/2019 14:43	Accident Report Within 24 hrs	Yes	Accident Type
Date of Accident	26/05/2019	Time of Accident hh:mm	12:20	Country of Accident
Reporting Centre		Orange Force		ICM No.
Accident Location	ANG MO KIO AVE 3 TWDS ANG MO KIO AVE 10			

▼ Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00	
Third Party Excess	0.00	Outside Singapore TP Excess	0.00	

▼ Benefits

▼ GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

▼ Policyholder Mailing Address

Address 1	34 CHUAN HOE AVENUE	Address 2	CHUAN HOE GARDENS	Address 3
Address 4		Address Type	Singapore address	Post Code
Unit No.		Related Policy Number	5075506281-03	

▼ OI Driver Info

Driver Name	CHAN SOON CHEE	Driver Type	Main Driver	
Unnamed driver Name		Driver NRIC	S7322277Z	Driver DOB
Register Date of Driver License	30/11/1993	Driver Age	45	Driving Experience
Contact No.(Mobile)	97669855	Contact No.(Office)		Contact No.(Home)
Address 1	34 CHUAN HOE AVENUE	Address 2	CHUAN HOE GARDENS	Address 3
Address 4		Address Type	Singapore address	Post Code
Unit No.				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Com

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
-------------------------------------	------	-------------	---

Modification History

Claim 002 OD-MD

New

Claim Type *

Contact No.(Mobile)

Email Address

Claim Description

Preferred Workshop		Insured Liability	Fully at Fault	GIA report	Received	27/05/2019 14:54	Claim Close Date	
Finalisation	Yes	Repair Option	Preferred Workshop, Name unknown					
Date Registered								
Report Taken By								Workshop Repairer

☒ Print AK letter

Save Submit

Attachment



Accident No.	MT/1046193	Claim No.	002
Last Doc. Received	☒ Yes ☐ No	Upload Date	27/05/2019 14:50

Path *		Category *		Confidential
Choose File	No file chosen	Clear	Please Select	NO
Choose File	No file chosen	Clear	Please Select	NO
Choose File	No file chosen	Clear	Please Select	NO
Choose File	No file chosen	Clear	Please Select	NO
Choose File	No file chosen	Clear	Please Select	NO
Choose File	No file chosen	Clear	Please Select	NO
Choose File	No file chosen	Clear	Please Select	NO

Message Read

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 27 May 2019 14:54	NRIC/ Driving License	Normal	NRIC/ Driving License
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 27 May 2019 14:52	SAS	Normal	SAS 2
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 27 May 2019 14:52	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 27 May 2019 14:52	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 27 May 2019 14:52	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 27 May 2019 14:52	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 27 May 2019 14:52	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 27 May 2019 14:52	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 27 May 2019 14:52	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 27 May 2019 14:51	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 27 May 2019 14:51	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 27 May 2019 14:51	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 27 May 2019 14:51	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 27 May 2019 14:51	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 27 May 2019 14:51	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 27 May 2019 14:51	Photos	Normal	Photos
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 27 May 2019 14:51	Photos	Normal	Photos

ASSIGNMENT (IDAC)

By CSO - Nature of Accident:

- 1) Vehicle hit Vehicle:
 - a) Motor car ()
 - b) Motorcycle ()
 - c) Bicycle ()
- 2) Vehicle hit ??
 - a) Pedestrian ()
 - b) Animal ()
- 3) Vehicle hit Road Side Objects:
 - a) Govn Property ()
(E.g. signboard, barrier, roadside)
 - b) Road Work Object ()
 - c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
 - a) Fallen Object ()
 - b) Flood ()
 - c) Other ()
- 6) Parked & Found Damaged:
 - a) Vandalism ()
 - b) Hit by Moving Object ()
- 7) Theft Case
 - a) Stolen ()
 - b) Damage found when recovered ()
- 8) Fire
 - a) Whilst driving ()
 - b) Parked ()
- 9) Accident date more than 24hrs ()

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor- 1) Vehicle Information

Veh No: **SG'D 95 Y** Yr Regn: **13 Nov 2015**

Type: **M. Car** / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Motor / Truck / Trailer or

Make & Model: **Toyota Harrier** Yr: **1986**

Colour: **Black** Transmission Type: **Auto** / Manual

Eng/Blr: Sp. Reading: **55580**

C/Ho: **254 60 005 8.70**

Gen. Cond: **Good** / Fair / Poor / Burnt or

Slewing: **Good** / Jammed / Leaked / Burnt or

Brake: **Good** / Jammed / Leaked / Burnt or

Mod: **Nil** / **AS/Run** / STD A/Rin or

Tyre Size: F: **225/65 R17**
R: **225/65 R17**

BS: **DUN** / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal: 4 mm	R/Bal: 5 mm
L/Bal: 4 mm	L/Bal: 5 mm

Parallel Import: **Yes** / No

Towed-In: **Yes** / No

Repair Type: **LS** / L.B.I

Towing Required: **Yes** / No

No of Repair Days: **8**

Vehicle in Idac: **Yes** / No

D.O.I: **28/5/2019**

Time: **9.30am**

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
 - a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
 - e. Animal () f. Govn Object () g. Road Work Object ()
 - h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()
- 3) Vehicle does not seem damaged as a result of:
 - a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
 - e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started

Time completed

1) CSO

2) ASS

3) Entire Operation Completed Time

MOTOR CAR (Frt)

ACTUAL (AC)

(1) Replace (✓) (2) Repair (✓) (3) Check (✓)

(4) For Constant (✓)

Aug 2005

Front Portion

Vehicle No: **SGD 95Y**

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	CRA	✓	✓
1002	991887	Frt Number Plate Base	CRA	✓	✓
1003	991889	Frt Number Plate Garnish	DD	✓	✓
1004	991300	Frt Bumper	DD	✓	✓
1005	992341	Frt Bumper Clips	DD	✓	✓
1006	991325	Frt Bumper Bracket	DD	✓	✓
1007	991462	Frt Bumper Side Retainer	DD	✓	✓
1008	991433	Frt Bumper Reinforcement	DD	✓	✓
1009	991318	Frt Bumper Beam	DD	✓	✓
1010	991468	Frt Bumper Sponge	CRA	✓	✓
1011	991427	Frt Bumper Tow Eye Cover	CRA	✓	✓
1012	991420	Frt Bumper	CRA	✓	✓
1013	991363	Frt Bumper Grille	CRA	✓	✓
1014	991301	Frt Bumper Moulding	CRA	✓	✓
1015	991407	Frt Bumper Lower Spoiler	CRA	✓	✓
1016	991438	Frt Bumper Sensor	CRA	✓	✓
1017	995100	Frt LH Bumper Fog Lamp Cover	CRA	✓	✓
1018	991355	Frt RH Bumper Fog Lamp Cover	CRA	✓	✓
1019	995079	Frt LH Bumper Fog Lamp	CRA	✓	✓
1020	995080	Frt RH Bumper Fog Lamp	CRA	✓	✓
1021	991793	Frt Grille	CRA	✓	✓
1022	991328	Frt Grille Emblem	CRA	✓	✓
1023	991799	Frt Grille Chrome Moulding	CRA	✓	✓
1024	991222	Frt Apron Panel	CRA	✓	✓
1025	992013	Frt Support Panel	CRA	✓	✓
1026	992025	Frt Support Panel Top Garnish Cover	CRA	✓	✓
1027	992416	Horn	CRA	✓	✓
1028	991277	Frt Brace Panel	CRA	✓	✓
1029	995153	Frt LH Headlamp Assy	CRA	✓	✓
1030	991821	Frt RH Headlamp Assy	CRA	✓	✓
1031	995088	Frt LH Side Lamp	CRA	✓	✓
1032	995089	Frt RH Side Lamp	CRA	✓	✓
1033	990248	Bonnet	CRA	✓	✓
1034	991328	Bonnet Chrome Moulding	CRA	✓	✓
1035	990287	Bonnet Lock	CRA	✓	✓
1036	990285	Bonnet Insulator	CRA	✓	✓
1037	990273	Bonnet Hinge	CRA	✓	✓
1038	990261	Bonnet Damper	CRA	✓	✓
1039	990305	Bonnet Rubber	CRA	✓	✓
1040	990252	Bonnet Cable	CRA	✓	✓
1041	990311	Bonnet Stand	CRA	✓	✓
1042	990119	Air Con Condenser	CRA	✓	✓
1043	990122	Air Con Fan Assy	CRA	✓	✓
1044	990134	Air Con Suction Pipe (Low Pressure)	CRA	✓	✓
1045	990118	Air Con Suction Hose	CRA	✓	✓
1046	990133	Air Con Discharge Pipe (High Pressure)	CRA	✓	✓
1047	990114	Air Con Discharge Hose	CRA	✓	✓
1048	990149	Air Con Liquid Pipe	CRA	✓	✓
1049	995066	Air Con Receiver Drier	CRA	✓	✓
1050	990111	Air Con Compressor Assy	CRA	✓	✓
1051	995294	Air-Con Condenser Side Air Deflector	CRA	✓	✓
1052	995074	Radiator	CRA	✓	✓
1053	992738	Radiator Cowling	CRA	✓	✓
1054	992742	Radiator Fan Assy	CRA	✓	✓
1055	992745	Radiator Fan Clutch	CRA	✓	✓
1056	992758	Radiator Hose Top	CRA	✓	✓
1057	992757	Radiator Hose Bottom	CRA	✓	✓
1058	992741	Radiator Expansion Tank	CRA	✓	✓
1059	990151	Air Duct	CRA	✓	✓
1060	990070	Air Cleaner Assy	CRA	✓	✓
1061	990056	Air Cleaner Hose	CRA	✓	✓
1062	990089	Air Cleaner Resonator	CRA	✓	✓
1063	991712	Frt Exhaust Manifold	CRA	✓	✓
1064	991713	Frt Exhaust Manifold Cover	CRA	✓	✓
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)	CRA	✓	✓
1066	991714	Front Exhaust Pipe	CRA	✓	✓
1067	990219	Battery	CRA	✓	✓
1068	990224	Battery Cover	CRA	✓	✓
1069	990223	Battery Bracket	CRA	✓	✓
1070	990229	Battery Tray	CRA	✓	✓

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box	CRA	✓	✓
1072	994011	Relay Box	CRA	✓	✓
1073	995053	Wiper Washer Tank	CRA	✓	✓
1074	995052	Wiper Washer Tank Motor	CRA	✓	✓
1075	990159	Alternator Assy	CRA	✓	✓
1076	990160	Alternator Belt	CRA	✓	✓
1077	992688	Power Steering Pump	CRA	✓	✓
1078	992669	Power Steering Belt	CRA	✓	✓
1079	994431	Power Steering Cooler Pipe	CRA	✓	✓
1080	992692	Power Steering Hose	CRA	✓	✓
1081	990010	ABS Pump Control Unit	CRA	✓	✓
1082	990427	Brake Master Pump Assy	CRA	✓	✓
1083	990403	Brake Booster Pump Assy	CRA	✓	✓
1084	991005	Engine Top Cover	CRA	✓	✓
1085	991011	Engine Under Cover	CRA	✓	✓
1086	990946	Engine Mounting	CRA	✓	✓
1087	990949	Engine Mounting Frt	CRA	✓	✓
1088	990950	Engine Mounting LH	CRA	✓	✓
1089	990952	Engine Mounting RH	CRA	✓	✓
1090	990951	Engine Mounting Rear	CRA	✓	✓
1091	992234	Gear Box Mounting	CRA	✓	✓
1092	991520	Frt LH Chassis Member	CRA	✓	✓
1093	991520	Frt RH Chassis Member	CRA	✓	✓
1094	990728	Frt Vertical Cross Member	CRA	✓	✓
1095	991863	Frt Lower Cross Member	CRA	✓	✓
1096	995070	Frt LH Fender	CRA	✓	✓
1097	995072	Frt LH Fender Inner Panel	CRA	✓	✓
1098	995147	Frt LH Fender Triangle Garnish	CRA	✓	✓
1099	995148	Frt LH Fender P	CRA	✓	✓
1100	991740	Frt LH Fender Inner Shield	CRA	✓	✓
1101	995179	Frt LH Mudflap	CRA	✓	✓
1102	995170	Frt LH Wheel Rim	CRA	✓	✓
1103	994025	Frt LH Rim Cover	CRA	✓	✓
1104	995065	Frt LH Tyre	CRA	✓	✓
1105	995071	Frt RH Fender	CRA	✓	✓
1106	991739	Frt RH Fender Inner Panel	CRA	✓	✓
1107	991744	Frt RH Fender Triangle Garnish	CRA	✓	✓
1108	991752	Frt RH Fender	CRA	✓	✓
1109	991740	Frt RH Fender Inner Shield	CRA	✓	✓
1110	991884	Frt RH Mudflap	CRA	✓	✓
1111	992087	Frt RH Wheel Rim	CRA	✓	✓
1112	994025	Frt RH Rim Cover	CRA	✓	✓
1113	995065	Frt RH Tyre	CRA	✓	✓
1114	992093	Frt Windscreen Glass	CRA	✓	✓
1115	992117	Frt Windscreen Rubber	CRA	✓	✓
1116	992108	Frt Windscreen Moulding	CRA	✓	✓
1117	992098	Frt Windscreen Sealant	CRA	✓	✓
1118	991019	ERP Bracket	CRA	✓	✓
1119	991020	ERP Unit	CRA	✓	✓
1120	992140	Frt Wiper Arm	CRA	✓	✓
1121	992142	Frt Wiper Blade	CRA	✓	✓
1122	995045	Wiper Panel Garnish	CRA	✓	✓
1123	991126	Firewall Panel	CRA	✓	✓
1124	990753	Dashboard Assy	CRA	✓	✓
1125	992282	Glove Box Cover	CRA	✓	✓
1126	992281	Glove Box Compartment	CRA	✓	✓
1127	994483	Steering Wheel Airbag	CRA	✓	✓
1128	994485	Steering Wheel Airbag Sensor	CRA	✓	✓
1129	990749	Dashboard Airbag	CRA	✓	✓
1130	990750	Dashboard Airbag Sensor	CRA	✓	✓
1131	990029	Airbag Control Unit	CRA	✓	✓
1132	990864	Frt Driver Seat	CRA	✓	✓
1133	991922	Frt RH Seat Belt Assy	CRA	✓	✓
1134	991899	Frt Passenger Seat	CRA	✓	✓
1135	995182	Frt LH Seat Belt Assy	CRA	✓	✓
1136	990247	Sticker	CRA	✓	✓
		Frt LH Door	CRA	✓	✓
		" RH "	CRA	✓	✓
		Headlamp Lower Bracket	CRA	✓	✓
		L & R	CRA	✓	✓

No of Items:

Accessories:

> Back to OneMotoring

goK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	2277Z

Vehicle Details

Vehicle No.:	SGD95Y
Vehicle to be Exported:	No
Intended Deregistration Date:	29 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER 2.0 ELEGANCE AT ABS D/AIRBAG 2WD

Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	3ZRB642371
Chassis No.:	ZSU600058170
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$26,490.00
Original Registration Date:	13 Nov 2015
First Registration Date:	13 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$24,086.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Nov 2025
PARF Rebate Amount:	\$18,064.00

Intended COE Rebate Details

COE Expiry Date:	12 Nov 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,501.00
COE Rebate Amount:	\$37,119.00
Total Rebate Amount:	\$55,183.00

The information contained herein is correct as at 27 May 2019

OK

Claim Handling

Accident MT/1046193

Policy No.	5075506281-03	Vehicle No.	SGD95Y	GST Registration No.	
Certificate No.					
Policyholder Name	CHAN SOON CHEE			Policyholder NRIC	S7322277Z
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	97669855	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	Yes	NCD Entitlement(%)	50	Private Hire	No

Accident Details

Report Date	27/05/2019 14:43	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head to Rear
Date of Accident	26/05/2019	Time of Accident hh:mm	12:20	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	Yes	ICM No.	4030651
Accident Location	ANG MO KIO AVE 3 TWDS ANG MO KIO AVE 10				

Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	34 CHUAN HOE AVENUE	Address 2	CHUAN HOE GARDENS	Address 3	SINGAPORE 549837
Address 4		Address Type	Singapore address	Post Code	549837
Unit No.		Related Policy Number	5075506281-03		

OI Driver Info

Driver Name	CHAN SOON CHEE	Driver Type	Main Driver	Driver DOB	13/06/1973
Unnamed driver Name		Driver NRIC	S7322277Z	Driving Experience	25
Register Date of Driver License	30/11/1993	Driver Age	45	Contact No.(Home)	
Contact No.(Mobile)	97669855	Contact No.(Office)		Address 3	SINGAPORE 549837
Address 1	34 CHUAN HOE AVENUE	Address 2	CHUAN HOE GARDENS	Post Code	549837
Address 4		Address Type	Singapore address		
Unit No.					
Does he own a Singapore Registered car?	☒ Yes ☐ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
Modification History	27/05/2019 15:41 s990621 Modify Orange Force(N-->Y) 27/05/2019 15:41 s990621 Modify ICM No(-->4030651)		

Investigation

Claim 002 OD-MD

Claim Case Officer Yap Chee Ling

Claim Type	OD-MD	Insured Name	CHAN SOON CHEE	Insured NRIC	S7322277Z
Contact No.(Mobile)	97669855	Contact No. (Home)	63163956	Contact No. (Office)	
Email Address	JOE.CHANSC@UOBGROUP.COM	O1 Vehicle Number	SGD95Y	TP Vehicle Number	SMA6869L
Claim Description	SGD95Y / SMA6869L ON 26 May 2019			Name of Preferred Workshop	
Preferred Workshop Contact	Yes	Preferred Repair Option	Preferred Workshop, Name unknown	Insured Liability report	Fully at Fault
Date Registered	27/05/2019 14:55	Claim Close Date		Date Received	27/05/2019 14:55
Report Taken By		Workshop Repairer		Total Loss but Repaired	
				OD Excess Collected by Workshop	

Print AK letter

Modification History

Special Claim Creation Approval

Approval	Reason
Remarks	

damage assessment Activity Handling Attachment

Vehicle Info

Vehicle Make	TOYOTA	Vehicle Model	HARRIER	Engine Capacity
Date of Registration	13/11/2015	Classis No.	ZSU600058170	
Towing Required *	☒ Yes ☐ No	Vehicle in IDAC *	☒ Yes ☐ No	Parallel Import *
Type of Tender *	Own Damage	Assessor Name *	SIMON	Survey Current Status
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA	
Windscreen Parts & Labour Cost		Total Loss *	☐ Yes ☒ No	
Market Value(\$)		Scrape Value(\$)		Economical Repair Value(\$)

Remark

NO OF REPAIR DAYS : 8 /2X FRT BUMPER SIDE RETAINER REPLACE/3X FRT BUMPER SPONGE CTE,LH,&RH REPLACE/2X FRT BUMPER TOW EYE COVER REPLACE/1X FRT GRILLE CH REPLACE/1X HORN UNCONFIRM/1X BONNET CHROME MOULDING REPLACE/1XBONNET LOCK REPLACE/2X BONNET HINGE REPLACE/2X BONNET DAMPER UNCONFIRM/1X AIR COI LOW PRESSURE REPLACE/1X AIR CON SUCTION HOSE UNCONFIRM/1X AIR CON DISCHARGE PIPE HIGH PRESSURE REPLACE/1X AIR CON LIQUID PIPE REPLACE/2X AIR CON CON DEFLECTOR REPLACE/1X AIR DUCT REPLACE/1X ENGINE UNDER COVER REPLACE/1X FRT LH FENDER TRIANGDE GARNISH REPLACE/1X FRT RH FENDER TRIANGE GARNISH REPL PANEL GARNISH L & R,CUT REPLACE/2X HEADLAMP BRACKET L & R REPLACE/

Remark for
Supplementary

Damage Listing

No.	Part No.	Description	Qty *	Repair Code *
1	32200101	NUMBER PLATE (FRONT)	1	Replace
2	16000101	BUMPER (FRONT)	1	Replace
3	16005001	BUMPER REINFORCEMENT (FRONT)	1	Replace
4	16002901	BUMPER FOG LAMP COVER (FRONT LEFT)	1	Unconfirm
5	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Unconfirm
6	27100101	GRILLE (FRONT)	1	Replace
7	41300101	SUPPORT PANEL (FRONT)	1	Replace
8	15600101	BRACE PANEL (FRONT)	1	Replace
9	27700101	HEAD LAMP (LEFT)	1	Replace
10	27700102	HEAD LAMP (RIGHT)	1	Replace
11	32200201	NUMBER PLATE BASE (FRONT)	1	Replace
12	16002401	BUMPER CLIPS (FRONT)	6	Replace
13	16003201	BUMPER GRILLE (FRONT)	1	Replace
14	16002701	BUMPER FOG LAMP (FRONT LEFT)	1	Unconfirm
15	16002702	BUMPER FOG LAMP (FRONT RIGHT)	1	Unconfirm
16	27100801	GRILLE EMBLEM (FRONT)	1	Replace
17	41300801	SUPPORT PANEL TOP GARNISH (FRONT)	1	Replace
18	149001	BONNET	1	Replace
19	149029	BONNET INSULATOR	1	Replace
20	112023	AIR CON CONDENSER	1	Replace
21	112060	AIR CON FAN	1	Replace
22	112043	AIR CON DISCHARGE HOSE	1	Unconfirm
23	344011	RADIATOR FAN CLUTCH	1	Unconfirm
24	344001	RADIATOR	1	Replace
25	344005	RADIATOR COWLING	1	Replace
26	344008	RADIATOR FAN	1	Replace
27	344007	RADIATOR EXPANSION TANK	1	Unconfirm
28	34402802	RADIATOR HOSE (TOP)	1	Replace
29	34402801	RADIATOR HOSE (BOTTOM)	1	Unconfirm
30	141005	BATTERY COVER	1	Unconfirm

Find a Part

root

Not Applicable

ABS

ABSORBER

ACCELERATOR

ACTUATOR

ADVERTISEMENT STICKER

AIR BAG

AIR BLOWER

AIR BOX

AIR CHAMBER BOX

AIR CLEANER

AIR COMPRESSOR

AIR CON

AIR CON (VAN)

AIR COOLER

AIR DISTRIBUTOR

AIR FILTER

AIR FLOW

AIR GRILLE

AIR HORN

AIR INTAKE

AIR RESONATOR BOX

AIR THROTTLE BODY AND SENSOR

ALARM

ALTERNATOR

ALUMINIUM PANEL - SIDE

AMPLIFIER

ANTENNA

ANTI ROLL

APRON

ARCH

ARM REST

ASH TRAY

AUTO CLUTCH

AUTO COOLER PIPE

AUTO CRUISE MOTOR

AUTO TRANSMISSION

AXLE

BACK REST (M/C)

BACK SEAT

BALANCER

BATTERY

BEADING (M/C)

BELT COVER (M/C)

BELT TENSIONER

BODY

BODY (M/C)

BOLT CAP (M/C)

BOLT HEAD COVER (M/C)

BONNET

BOOT

31	25400102	FENDER (FRONT LEFT)	1	Replace
32	25400103	FENDER (FRONT RIGHT)	1	Replace
33	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Replace
34	23300201	DOOR (FRONT LEFT)	1	Repair
35	23300202	DOOR (FRONT RIGHT)	1	Repair
36	141001	BATTERY	1	Unconfirm
37	141002	BATTERY BRACKET	1	Replace
38	25400801	FENDER INNER PANEL (FRONT LEFT)	1	Repair
39	25400901	FENDER INNER SHIELD (FRONT LEFT)	1	Replace
40	25400802	FENDER INNER PANEL (FRONT RIGHT)	1	Repair

Claim Handling

Accident MT/1046193

Policy No.	5075506281-03	Vehicle No.	SGD95Y	GST Registration No.	
Certificate No.					
Policyholder Name	CHAN SOON CHEE			Policyholder NRIC	S7322277Z
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	97669855	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	Yes	NCD Entitlement(%)	50	Private Hire	No

Accident Details

Report Date	27/05/2019 14:43	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head to Rear
Date of Accident	26/05/2019	Time of Accident hh:mm	12:20	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	Yes	ICM No.	4030651
Accident Location	ANG MO KIO AVE 3 TWDS ANG MO KIO AVE 10				

Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	34 CHUAN HOE AVENUE	Address 2	CHUAN HOE GARDENS	Address 3	SINGAPORE 549837
Address 4		Address Type	Singapore address	Post Code	549837
Unit No.		Related Policy Number	5075506281-03		

OI Driver Info

Driver Name	CHAN SOON CHEE	Driver Type	Main Driver	Driver DOB	13/06/1973
Unnamed driver Name		Driver NRIC	S7322277Z	Driving Experience	25
Register Date of Driver License	30/11/1993	Driver Age	45	Contact No.(Home)	
Contact No.(Mobile)	97669855	Contact No.(Office)		Address 3	SINGAPORE 549837
Address 1	34 CHUAN HOE AVENUE	Address 2	CHUAN HOE GARDENS	Post Code	549837
Address 4		Address Type	Singapore address		
Unit No.					
Does he own a Singapore Registered car?	☒ Yes ☐ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☒ Yes ☐ No
Modification History	27/05/2019 15:41 s990621 Modify Orange Force(N-->Y) 27/05/2019 15:41 s990621 Modify ICM No(-->4030651)		

Investigation

Claim 002 OD-MD

Claim Case Officer Yap Chee Ling

Claim Type	OD-MD	Insured Name	CHAN SOON CHEE	Insured NRIC	S7322277Z
Contact No.(Mobile)	97669855	Contact No.(Home)	63163956	Contact No.(Office)	
Email Address	JOE.CHANSC@UOBGROUP.COM	OI Vehicle Number	SGD95Y	TP Vehicle Number	SMA68
Claim Description	SGD95Y / SMA6869L ON 26 May 2019				
Preferred Workshop	Yes	Preferred Repair Option	Preferred Workshop Name	Insured liability report	Fully at Receiver
Contact Realisation					
Date Registered			27/05/2019 14:55	Claim Close Date	
Report Taken By			Workshop Repairer	Date Received	28/05/
				Total Loss but Repaired	
				OD Excess Collected by Workshop	
Print AK letter					
Modification History					

Special Claim Creation Approval

Approval Reason

Remarks

damage assessment Activity Handling Attachment

Accident No. MT/1046193 Claim No. 002
Last Doc. Received Yes No Upload Date 28/05/2019 10:43

Path *

Choose File No file chosen
Choose File No file chosen
Choose File No file chosen
Choose File No file chosen
Choose File No file chosen
Choose File No file chosen

Message Read

Category *	Confidential	Urgency *
Clear Please Select	NO	Normal
Clear Please Select	NO	Normal
Clear Please Select	NO	Normal
Clear Please Select	NO	Normal
Clear Please Select	NO	Normal
Clear Please Select	NO	Normal
Clear Please Select	NO	Normal

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 28 May 2019 10:43	Photos	Normal	Photos 2019-5-28
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 28 May 2019 10:43	Photos	Normal	Photos 2019-5-28
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 28 May 2019 10:43	Photos	Normal	Photos 2019-5-28
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 28 May 2019 10:43	Photos	Normal	Photos 2019-5-28
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 28 May 2019 10:43	Photos	Normal	Photos 2019-5-28
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 28 May 2019 10:43	Photos	Normal	Photos 2019-5-28
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 28 May 2019 10:43	Photos	Normal	Photos 2019-5-28
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 28 May 2019 10:42	Photos	Normal	Photos 2019-5-28
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 28 May 2019 10:42	Photos	Normal	Photos 2019-5-28
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 28 May 2019 10:42	Photos	Normal	Photos 2019-5-28
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 28 May 2019 10:42	Photos	Normal	Photos 2019-5-28
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 28 May 2019 10:42	Photos	Normal	Photos 2019-5-28
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 28 May 2019 10:42	Photos	Normal	Photos 2019-5-28
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 28 May 2019 10:42	Photos	Normal	Photos 2019-5-28
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 28 May 2019 10:42	Photos	Normal	Photos 2019-5-28
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 28 May 2019 10:42	Photos	Normal	Photos 2019-5-28
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 28 May 2019 10:42	Photos	Normal	Photos 2019-5-28

VICES) on 28 May 2019 10:42

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 28 May 2019 10:42

Photos

Normal

Photos 2019-5-28

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 28 May 2019 10:41

Photos

Normal

Photos 2019-5-28

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 28 May 2019 10:41

Photos

Normal

Photos 2019-5-28

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 28 May 2019 10:41

Photos

Normal

Photos 2019-5-28

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 28 May 2019 10:41

Photos

Normal

Photos 2019-5-28

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 28 May 2019 10:41

Photos

Normal

Photos 2019-5-28

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 28 May 2019 10:41

Photos

Normal

Photos 2019-5-28

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 28 May 2019 10:41

Photos

Normal

Photos 2019-5-28

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 28 May 2019 10:41

Photos

Normal

Photos 2019-5-28

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 28 May 2019 10:41

Photos

Normal

Photos 2019-5-28

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 28 May 2019 10:41

Photos

Normal

Photos 2019-5-28

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 28 May 2019 10:41

Photos

Normal

Photos 2019-5-28

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 28 May 2019 10:41

Photos

Normal

Photos 2019-5-28

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 28 May 2019 10:40

Photos

Normal

Photos 2019-5-28

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 28 May 2019 10:40

Photos

Normal

Photos 2019-5-28

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 28 May 2019 10:40

Photos

Normal

Photos 2019-5-28

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 28 May 2019 10:40

Photos

Normal

Photos 2019-5-28

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 28 May 2019 10:40

Photos

Normal

Photos 2019-5-28

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 28 May 2019 10:40

Photos

Normal

Photos 2019-5-28

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 27 May 2019 14:54

NRIC/ Driving License

Normal

NRIC/ Driving License 2019-5-27

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 27 May 2019 14:52

SAS

Normal

SAS 2019-5-27

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 27 May 2019 14:52

Photos

Normal

Photos 2019-5-27

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 27 May 2019 14:52

Photos

Normal

Photos 2019-5-27

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 27 May 2019 14:52

Photos

Normal

Photos 2019-5-27

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 27 May 2019 14:52

Photos

Normal

Photos 2019-5-27

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER
VICES) on 27 May 2019 14:52

Photos

Normal

Photos 2019-5-27



NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 27 May 2019 14:52

Photos

Normal

Photos 2019-5-27

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 27 May 2019 14:52

Photos

Normal

Photos 2019-5-27

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 27 May 2019 14:51

Photos

Normal

Photos 2019-5-27

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 27 May 2019 14:51

Photos

Normal

Photos 2019-5-27

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 27 May 2019 14:51

Photos

Normal

Photos 2019-5-27

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 27 May 2019 14:51

Photos

Normal

Photos 2019-5-27

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 27 May 2019 14:51

Photos

Normal

Photos 2019-5-27

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 27 May 2019 14:51

Photos

Normal

Photos 2019-5-27

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 27 May 2019 14:51

Photos

Normal

Photos 2019-5-27

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 27 May 2019 14:51

Photos

Normal

Photos 2019-5-27

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 27 May 2019 14:51

Photos

Normal

Photos 2019-5-27

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 27 May 2019 14:51

Photos

Normal

Photos 2019-5-27

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 27 May 2019 14:51

Photos

Normal

Photos 2019-5-27

NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 27 May 2019 14:51

Photos

Normal

Photos 2019-5-27

Video List

Uploaded By/Date

Folder Date

File Name



Source

Display in New Window

Scan and uploading



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315



Vehicle Movement Form

Vehicle Check-In

Vehicle No: SGD 954 Date In: _____ Time In: _____ with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: ARWIN SERVICE PTE LTD

Collection Date: 01/06/19 Time: 12:15 PM with Keys: Yes / No

Tow Truck No: 4D783T Tow Man: AUG WILLIAM NRIC: 579174831A

Signature: [Signature]

94888857

For office use

Attended by: Sham Hui.

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____

LKK Paya Ubi

From: Yap Chee Ling <CheeLing.Yap@income.com.sg>
Sent: Tuesday, 28 May 2019 5:38 PM
To: 'AbwinM9 - Yvonne Wong'; AbwinM9 - Linda Liao; LKK Paya Ubi
Subject: SGD95Y | MT/1046193 (Awarding Letter to Abwin Service)

Importance: High

Hi IDAC and Abwin Service,

Vehicle is currently in IDAC.

Excess of \$600 is applicable.

Please liaise with the owner – Mr Chan Soon Chee at tel: 9766 9855 on the necessary.

Thank you.

Yap Chee Ling (Ms)
Executive
Motor Insurance
T +65 6430 7893
www.income.com.sg

 income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers

in with you

Our Ref: MT/CA/OD/051/1046193-002/YCL

28 May 2019

ABWIN SERVICE PTE. LTD.
8 KAKI BUKIT AVENUE 4
#07-48 PREMIER @ KAKI BUKIT GATE 2
SINGAPORE 415875

Dear Sir

CLAIM NUMBER: MT/1046193-002
REPAIR OF VEHICLE NUMBER: SGD95Y

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 28 May 2019
Make: TOYOTA

Model: HARRIER

Estimated Repair Days: 10

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits: Not applicable

Excess Applicable: 600

Please note that supplementary items will not be allowed.

If you have any queries, please contact Yap Chee Ling at 6430-7893 or email us at motor@income.com.sg.

Yours sincerely

Jenny Pe

Deputy Vice President

Motor Insurance

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.