

ASS. REC. BY:

REF:

C83/GA119009249/Jeds

Special Instruction:

Surveyor: Hwa Jie

ASSIGNMENT (Office)

From (Person): Sharon Ng of GAI Date/Time: 27/5 5.50pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBD9728E Insured: SGJ7799Y

at Workshop m/s Eng Soon Tel: 67606271

of BIK 4 Yeo Pte Ind Est. 393-J

Policy No: Claim No: CLMOMVP000000992

Sum Insured: Excess:

Make of Veh: D.O.A. 20/5/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 27/5 Person Contacted: Vehicle IN/OUT

| Date/Time | Action/Instruction |
|-----------|--------------------|
| | Estimate (X) |
| | GBD9728E-X |
| | SGJ7799Y-X |
| | Demand: 27/5/2019 |
| | |
| | |
| | |
| | |

REF: GAI

Hue Jie

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBD9728E Yr Regn: 13 Aug 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV350 C.C. 2488Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 100714 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/N: JN1MC2E26Z0004314

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15C

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 22/5/19 D.O.I. 27/5/19 U.E/LanSurvey held at Eng SoonDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PRS

Range: \$5000-\$6000
6 days.

13/6/2019

Date/Time. File Pass to?

☐ : Preli. ReportDays Of Repair: 6

1)

☐ : Final ReportResurvey No. of Trip: 1

Date/Time. File Return to?

Survey Fee:

Transportation:

2)

Add Fee: ☐ : Site Insp (\$

) S + PS. \$1

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others:

☐ : Weekend (\$Report Format: PRE

Lump Sum / I.B. / C



Nivitha (LKK Auto)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com> on behalf of Motor Claims <MotorClaims@sg.gaig.com>
Sent: Friday, 24 May 2019 5:50 PM
To: SUR
Cc: assignments; Ngian, Kelvyna
Subject: Our ref: CLMOMVP000000992- Urgent: Pre-Repair Inspection: Your Vehicle: SGJ 7799 Y; EngSoon's Vehicle: GBD 9728 E; Accident Involving GBD 9728 E & SGJ 7799 Y on 22 May 2019
Attachments: SGJ7799Y (OI).pdf; GBD9728E.pdf

Dear LKK

Please contact the repairers, M/s Eng Soon Painting Services at 6760 6271 and survey **GBD9728E** on a without prejudice basis.

Regards

Sharon Ng

Great American

From: bonnie kwok <litigation@bonniekwok.com>

Sent: Friday, May 24, 2019 2:33 PM

To: Motor Claims <MotorClaims@sg.gaig.com>

Subject: [External] Re: Urgent: Pre-Repair Inspection: Your Vehicle: SGJ 7799 Y; EngSoon's Vehicle: GBD 9728 E; Accident Involving GBD 9728 E & SGJ 7799 Y on 22 May 2019

Dear Sirs,

Your list of surveyors is rejected.

We have been instructed to propose the following list of surveyors for the Single Joint Expert:-

1. Fong Kok Heng
2. Danny Yap
3. Willy Goh
4. Francis Ng
5. Dennis Yap
6. Louis Ng
7. Michael Yap
8. Lim Yong Tian
9. Patrick Ng
10. Philip Foo

Kindly contact the repairers, M/s Eng Soon Painting Services at 6760 6271 for pre-repair inspection arrangements.

Regards,
ST

--

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

Veh lu.

Hwee Jie

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

From: bonnie kwok <litigation@bonniekwok.com>

Sent: Thursday, May 23, 2019 3:57 PM

To: Motor Claims <MotorClaims@sg.gaig.com>

Subject: [External] Urgent: Pre-Repair Inspection: Your Vehicle: SGJ 7799 Y; EngSoon's Vehicle: GBD 9728 E; Accident Involving GBD 9728 E & SGJ 7799 Y on 22 May 2019

Urgent

Dear Sirs,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle no. GBD 9728 E at M/s Eng Soon Painting Services, Block 4 Yew Tee Industrial Estate 393-J Woodlands Road Singapore 677978.

Regards,

ST

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/05/2019 15:43
Date Of Accident 22/05/2019 15:20
Exact Location Of Accident BUYONG ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBD9728E
Insured/Policyholder
Name Of Registered Owner SUNLIGHT PLUMBING & ELECTRICAL SERVICE
Co Reg No 52834648B
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-82180205
Vehicle Particulars
Manufacturer NISSAN
Model NV350-2.5 D PANEL VAN (M)
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE
Insurance Company
Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number DMCVSN1540151803
Cover Note Number
Driver
Name of Driver DARREN LIM JUN JIE
NRIC No S9226601Z
Date Of Birth 09/07/1992
Occupation OUTDOOR
Date Of Driving Pass 28/07/2012
Driving Experience 6 YEARS AND 9 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-82180205
Fax Number
Contact Number
Email Address DARREN_LJJ@HOTMAIL.COM

Address BLK 738 JURONG WEST ST 75 #13-43
Postcode 640738
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle
Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

STATEMENT, KINDLY REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGY7799Y
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver TANG KUAN PING
NRIC/Passport Number S8039313Z
Contact Number 91008745
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

Vehicle A: SGT 7799Y

Vehicle B: SGT 7799Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22nd May 2019 At 1522pm While proceeding straight towards CTE, vehicle B SGT 7799Y suddenly cut into my lane and hit the left side of my van. After alighting, the driver wanted to pay for my damages and later negotiated via whatsapp, however we wanted him to pay for the rental van thus the driver say to proceed to claim his insurance company.

DECLARATION

Sunlight Plumbing And Electrical Service
46 East Coast Road #07-03
Singapore 428766
H/P: 9382 0980

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Teo Hong Eng
NRIC/PRN No:

S1100072/E

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report promptly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to revoke policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Sunlight Plumbing And Electrical Service
46 East Coast Road #07-03
Singapore 428766
H/P: 9382 0980

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

23/5/19 1530pm

Reporting Centre Personnel's Signature
Name: Teo Hong Gup
NRIC/PIN No.: S110007212

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

| | |
|-------------------------------------|------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Business |
| Owner ID: | 4648B |
| Vehicle Details | |
| Vehicle No.: | GBD9728E |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 29 May 2019 |
| Vehicle Make: | NISSAN |
| Vehicle Model: | NV350 PANEL VAN 2.5 5MT 5DR EURO V |
| Primary Colour: | Grey |
| Manufacturing Year: | 2015 |
| Engine No.: | YD25364849A |
| Chassis No.: | JN1MC2E26Z0004314 |
| Maximum Power Output: | - |
| Open Market Value: | \$25,153.00 |
| Original Registration Date: | 13 Aug 2015 |
| First Registration Date: | 13 Aug 2015 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$1,258.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 12 Aug 2025 |
| COE Category: | C - Goods Vehicle & Bus |
| COE Period(Years): | 10 |
| PQP Paid: | \$23,731.00 |
| COE Rebate Amount: | \$14,723.00 |
| Total Rebate Amount: | \$14,723.00 |

The information contained herein is correct as at 29 May 2019

OK

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | |
|--|--|---|---|
| GREAT AMERICAN INSURANCE COMPANY | | Ref: CS3/GAI19009249/Jcd3s2 | |
| 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWERS SINGAPORE 039190 | | Date: 17-06-2019 |  |
| | | Code: GAI | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | |
| Insured Veh. | SGJ 7799Y | Veh. Inspected | GBD 9728E |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | CLMOMVP000000992 | Excess (\$) | 0.00 |
| Assign From | SHARON NG | Assign Date | 24/05/2019 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | NISSAN NV350 | c.c | 2488 |
| Engine No. | HIDDEN | Year of Reg. | 2015 |
| Chassis No. | JN1MC2E26Z0004314 | Colour | GREY |
| Odometer | 100714 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 195 R15C | BRIDGESTONE | 7 mm |
| L/H Front Tyre | 195 R15C | BRIDGESTONE | 7 mm |
| R/H Rear Tyre | 195 R15C | BRIDGESTONE | 7 mm |
| L/H Rear Tyre | 195 R15C | BRIDGESTONE | 7 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. | |  | |
| 5. General Information | | | |
| Accident Date | 22/05/2019 | Inspect Date / Time | 27/05/2019 (11:41 AM) |
| Survey held at | ENG SOON PAINTING SVC BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969 | | |
| 5a. Remarks | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000- \$6,000 | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 6 Working Days | |

Report Ref No. CS3/GAI19009249/Jcd3s2

Inspected By



ONG HWEI JIE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.