

22/05/2019

ASS. REC. BY:

REF:

C83/AIG/A009250/Gcd322

Special Instruction:

Surveyor: GA

ASSIGNMENT (Office)

From (Person): Winnie Fan

of AIG

Date/Time: 24/5/2019

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SKV4111R

Insured: SL8134E

at Workshop m/s Sin Leng Hong Spray

Tel: 96278521 Andy

of BLK 3033A Ubi Rd #01-63

Policy No:

Claim No: 789695110286

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 18/5/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 22/5

Person Contacted: Andy

Vehicle IN/OUT

Date/Time	Action/Instruction
	Estimate (X)
	SKV4111R-X
	SL8134E-X
	Dismantle: 28/5/2019
	After repair: 31/5/2019

(08/12/11)

Surveyor

PILS
GL

REF:

AIG

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt.: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

DAR

☐

: Preli. Report

☐

: Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

180

11

191

Veh No:

SKV011R

Yr Regn:

-19 Nov 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Suzuki S-cross

C.G

1586

Colour:

white

A/C: Insured / Std / NI / NA

Sp.Reading

65386

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

TSMJYA22S 00404190

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45 R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

D.O.I.

27-05-19

Survey held at

WS

2:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 May 2019 Edit Reg		28 May 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	TAN XIWEN, ID: S9207091C		
Main Claimant:	-		
Vehicle Reg. No.:	SKV4111R	Date of Loss:	18/05/2019 00:00 - :59
Claim Type:	TP / 7896951103SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SLS134E	Policy No. (Claimant):	
		Excess:	
Repairer:	Sin Seng Hong Spray Painting & Service (HQ) BLK 3022A UBI ROAD 1 #01-53, 408716 Ubi - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 07/06/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (29/05/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING YOUR INSURED VEH...

From: Fan, Winnie-LW

To:

Cc: Fong, Andy-SY, Chin, Lee-Ying

Sent: 5/27/2019 9:06:39 AM

Attachments:  [PRI-SKV4111R-SSH.PDF](#)

Hi LKK,

Kindly assist to survey.

Winnie Fan

AIG

Claims Service Associate

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors

UEN NO : 201523418E

(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16

MANHATTAN HOUSE

SINGAPORE 169876

TEL : (65) 6532 2455

FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: lhling@tcmg.com.sg

Our Ref: TCMG/SKV4111R/0519/SSH

Your Ref: SLS 134 E

21 May 2019

M/s AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16

AIG Building

Singapore 079120

Singapore 068811

BY E-MAIL ONLY
(shengyang.lim@aig.com)

Attn: Motor Claims Department

Dear Sirs,

PRE-REPAIR INSPECTION NOTICE

We act for **Yeo Siok Eng**, the owner and/or driver of motor vehicle no. **SKV 4111 R**, which was involved in an accident along Bartley Road slip road towards Upper Serangoon Road on 18 May 2019 at 07:45 hrs.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. **SLS 134 E** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Sin Seng Hong Spray Painting & Service, (3023A #01-63, Ubi Road 1, Singapore 408717 - Andy Yeo @ 9627 8521).

3020A #01-38

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

Yours faithfully,



MR LING-LEONG HUI

cc. M/s Sin Seng Hong Spray Painting & Svc
(Yref: SKV4111R)

BY E-MAIL ONLY

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	359B
Vehicle Details	
Vehicle No.:	SKV4111R
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2019
Vehicle Make:	SUZUKI
Vehicle Model:	S-CROSS 1.6 GLX 2WD CVT
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	M16A1983600
Chassis No.:	TSMJYA22S00404190
Maximum Power Output:	86.0 kW (115 bhp)
Open Market Value:	\$17,108.00
Original Registration Date:	19 Nov 2015
First Registration Date:	19 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$17,108.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Nov 2025
PARF Rebate Amount:	\$12,831.00
Intended COE Rebate Details	
COE Expiry Date:	18 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,889.00
COE Rebate Amount:	\$33,918.00
Total Rebate Amount:	\$46,749.00

The information contained herein is correct as at 24 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/05/2019 12:43
Date Of Accident	18/05/2019 07:45
Exact Location Of Accident	BARTLEY RD SLIP RD TOWARDS UPPER SERANGOON RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKV4111R
Insured/Policyholder	
Name Of Registered Owner	YEO SIOK ENG
NRIC No	S1639359B
Email Address	YEOSEAHG@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-97673272
Alternative Phone No	OTHERS-97673272

Vehicle Particulars

Manufacturer	SUZUKI
Model	S-CROSS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA405196
Cover Note Number	

Driver

Name of Driver	YEO SIOK ENG
NRIC No	S1639359B
Date Of Birth	08/04/1964
Occupation	INDOOR
Date Of Driving Pass	30/12/1989
Driving Experience	29 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	+65-97673272
Fax Number	
Contact Number	OTHERS-97673272
EEmail Address	YEOSEAHG@SINGNET.COM.SG

Address	BLK 169 HOUGANG AVENUE 1 #05-1415 SINGAPORE
Postcode	530169
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TOH AI PING GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS134E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

18/5/19
1pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

penen

Sketch Plan #2

SKETCH PLAN

<p style="text-align: center;">Upper Serangoon Road</p> <p style="text-align: center;">Bartley Road</p>	<p>Vehicle</p> <p>A-SKV4111 R</p> <p>B-SLS134E</p> <p>Legend</p> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> Vehicle </div> <div style="text-align: center;"> Motorcycle </div> </div>
---	---

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18/5/19 at 0745 hrs I was driving my car SKV4111R from Bartley Road and turning toward Upper Serangoon Road junction. At the give way junction while I stopped my car to give way for the car coming from direction of upper serangoon road, I suddenly I heard a loud bang from behind my car, then I notice there was a Honda Car SLS134E hit from behind, the accident caused a damage to my bumper. And the driver confirmed he made the mistake and ~~willing to hold the responsibility for the accident~~ he admitted his fault causing the collision with my car. Ay

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature

Date & Time:

18/5/19
1pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

penan

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (X) (3) Check (C)
(4) Not Consistent (NC)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	Re	/	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	BR	Re	/
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	Re	/	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	Re	/	2
1149	993045	Rear Bumper Reinforcement	BT	/	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad Garnish	Re	/	
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM	/	
1159	993327	Rear End Panel	Repair		
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	Scr	/	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	Scr	/	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	Repair		
1182	991328	Tailgate Emblem	Re	/	2
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber	Tw	/	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate inner Board			

Vehicle No:

SKV 411R

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items:

Assessor:

07/02/2017

...CLAIM SUBFOLDER...(Pending for Survey Report)



CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 May 2019 Edit Reg		27 May 2019 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: TAN XIWEN , ID: S9207091C									
Main Claimant: -									
Vehicle Reg. No.: SKV4111R		Date of Loss: 18/05/2019 00:00 - :59 [41 Months and 29 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 7896951103SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SLS134E		Policy No. (Claimant):							
		Excess:							
Repairer: Sin Seng Hong Spray Painting & Service (HQ) BLK 3022A UBI ROAD 1 #01-53, 408716 Ubi - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 07/06/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (29/05/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKV4111R (7896951103SG)
[SLS134E]
TP
-
May 18 2019 12:00AM
[TAN XIWEN]
Sin Seng Hong Spray Painting & Service

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
2	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
3	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
4	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
5	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
6	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
7	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
8	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
9	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
10	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
11	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
12	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
13	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
14	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
15	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
16	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
17	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
18	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
19	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
20	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
21	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
22	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
23	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
24	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
25	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
26	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
27	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
28	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
29	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
30	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
31	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
32	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
33	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
34	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
35	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
36	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
37	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
38	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
39	19/06/19 12:29	General View														Load JPG	<input checked="" type="checkbox"/>	
40	19/06/19 12:30	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
41	19/06/19 12:30	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
42	19/06/19 12:30	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
43	19/06/19 12:30	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	19/06/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	19/06/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	19/06/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	19/06/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	19/06/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	19/06/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	19/06/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	19/06/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	19/06/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	19/06/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	19/06/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	19/06/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	19/06/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	19/06/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
88	19/06/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	19/06/19 12:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	19/06/19 12:30	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
91	19/06/19 12:30	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
92	19/06/19 12:30	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
93	19/06/19 12:30	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
94	19/06/19 12:30	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	29/05/19 09:45	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19009250/GCD3E2

Date: 29/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SKV4111R

Insured Vehicle No : SLS134E

Date of Loss: 18/05/2019

Nature of Claim: TP

Claim No: 7896951103SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKV4111R

Make & Model: SUZUKI S-CROSS, 1.6 2WD (A)

Engine No: M16A1983600

Reg. Date: 19/11/2015 (Man. Year: 2015)

Chassis No: TSMJYA22S00404190

Colour: White

Odometer: 65386 km

Engine Capacity: 1586 cc

Market Value/New Car Price: N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/05/2019

Date Inspected: 27/05/2019 Inspected At:

Blk 3023A Ubi Road 1 #01-63

Repairer : Sin Seng Hong Spray

Painting & Service (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER LOWER	Broken	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	2		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
6	1		*REAR BUMPER GARNISH	Deformed	0.00 F	*- F
7	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
8	1		*REAR END PANEL	Repair	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Scratched	0.00 F	*- F
10	1		*REAR RH TAILLAMP	Scratched	0.00 F	*- F
11	1		*TAILGATE	Repair	0.00 F	*- F
12	2		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
13	1		*TAILGATE RUBBER	Twisted	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >