

ASS. REC. BY:

REF: CS1 sm019009256/ Btd3E2

Special Instruction:

Surveyor : Lim

### ASSIGNMENT (Office)

From (Person): Agnes Chan Shu Hui

of SMO

Date/Time: 27.5.19 12.29 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PC 5587K

Insured:

S2Q 3313 X

at Workshop m/s Team Auto pro

Tel: 90 927279

of 160 Sh Ming Drive # 01-14

Policy No: D18MTPV 01010178

Claim No: CMTD1902352

Sum Insured:

Excess:

Make of Veh:

D.O.A. 14.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 27.5.19 1.12p.m

Person Contacted:

Alan

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	PC5587K - X
	SLQ 3313 - X

Surveys

REF: SMO

## ASSIGNMENT

From: \_\_\_\_\_ Date: 27.5.2019

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PC 5587K

at Workshop m/s Team AutoPro

of 160 Sin Ming Drive # 01-14

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS mp

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: PC 5587K Yr Regn: 16/12/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Jayda Commuter GL 3.0 cc 2982

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 171165 T/Radio: Insured / Std / NI / NA

Eng/No: 1KD2602497

C/No: KD42230027637

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/15C Journey

R: 195/15C BS

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Journey &amp; BS rear

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 14/5/19 D.O.I. 27/5/19

Survey held at Team AutoPro

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range 4000/2 - 5000/2
	Lim,
	Pls see my remarks.
	confirm
	RECEIVED 16 JUL 2019
	MV 76,000/2 4/5 3650/2 (3362.80/51%)
	PV 32,893/2
	NV 43,107/2
	28/6/19
	30/5 Team Lim
	23/5/19

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 7

1) 17/7 TYPST

☒ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: 290

Transportation: \_\_\_\_\_

S + RS, SI

Photos

Others

TOTAL

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$) 36501

261

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 May 2019		27 May 2019 12:29 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LING KUOK TUNG, ID: S7287960J, Tel: +6596662963, Email: KTLING@HOTMAIL.COM		
Main Claimant:	LIMOCARS & TRANSPORTATION PTE LTD, Co. Reg. No.: 201721325E		
Vehicle Reg. No.:	PC5587K	Date of Loss:	14/05/2019 11:00 - :59
Claim Type:	TP / CMTD1902352	Policy/Cover Note No.:	D18MTPV01010178 (Comprehensive)
Vehicle Reg. No. (Insured):	SLQ3313X	Policy No. (Claimant):	
		Excess:	
Repairer:	Team Autopro Pte Ltd - Sin Ming (HQ) 160 SIN MING DRIVE #01-14 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 9674 6635 / 9092 7279		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/06/2019]		
Driver/Custodian (Insured):	LING KUOK TUNG (47 / Male), NRIC: S7287960J, Tel: +6596662963 Email: KTLING@HOTMAIL.COM		
Adj Asg. Remarks:	ALAN 90927279 / FREDERICK 96746635		

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



**Toyota Hiace 3.0M**      \$50,800      \$7,450 /yr      22-Mar-2016      2,982 cc      -      Van      Available

**Fuel Type:** Diesel

Toyota Hiace 5 Door. Well Taken Care By Previous Owner. Fully Borneo Serviced! Price Negotiable! Contact Our Friendly Sales Consultant Today For Enquiries.

Posted: 17-Apr-2019    Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



**Toyota Hiace 3.0M**      -      N.A      21-Mar-2016      2,982 cc      -      Van      **SOLD**

**Fuel Type:** Diesel

Monthly \$800 And 1 Owner Only! Serviced And Maintained Regularly! Vehicle Is Under Utilised By Previous Owner! Vehicle Is In Pristine Condition, As Good As New! Loan Scheme! Over 100 Unit Of New And U...

**PREMIUM AD**

Car (S) Pte Ltd

Posted: 16-Apr-2019    Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



**Toyota Hiace Commuter 3.0A**      \$78,000      \$10,450 /yr      14-Nov-2016      2,982 cc      128,645 km      Bus      Available

**Fuel Type:** Diesel

Single Owner Used Fuel Stations Diesel, (Non Industrial), Accident Free, Regular Service At 10,000 Km Or Every 2 Months.

**DIRECT OWNER**

Posted: 07-Apr-2019    Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make    Model    Price    Depreciation    Reg Date    Eng Cap    Mileage    Veh Type    Status

For old advertisements, view [Expired ads](#)

« Back ( 1 2 3 ) Next »

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota, Toyota Singapore, used Toyota Singapore, used Toyota, used vehicles Singapore or even buy used Toyota Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

**Follow sgCarMart.com**

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

[Compare](#)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	15/05/2019 12:32
Date Of Accident	14/05/2019 11:20
Exact Location Of Accident	ADMIRALTY ROAD WEST
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	PC5587K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIMOCARS & TRANSPORTATION PTE LTD
Co Reg No	201721325E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98599589
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	HIACE COMMUTER
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097669616
Cover Note Number	
<b>Driver</b>	
Name of Driver	NOR AIDI IDRIS
NRIC No	S7205324I
Date Of Birth	20/02/1972
Occupation	OUTDOOR
Date Of Driving Pass	23/07/1992
Driving Experience	26 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86857699
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 306 JURONG EAST ST 32 #08-196 SINGAPORE
Postcode	600306
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	8

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLQ3313X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	96662963
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle A stopped as the vehicle in front of me stopped. All vehicles are waiting for the traffic light to turn green. One minutes later, Vehicle B suddenly hit onto my stationary vehicle rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



<b>SJE :</b>	_____	<b>Vehicle Nos :</b>	<b>PC 5587K</b>
<b>Date of Survey :</b>	_____	<b>Model :</b>	<b>HIACE</b>
<b>Date of ReSurvey:</b>	<b>After-Paint:</b>	<b>Year :</b>	_____
<b>Contacts :</b>	_____	<b>Chassis No :</b>	_____

**\* AGREED Cost Of Repair and Repair Day/s with SJE \***

**Amount:** \_\_\_\_\_ **Working Day:** \_\_\_\_\_

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Tailgate	1	\$ 1,198.70	\$ 1,198.70	DDV ✓
2	Tailgate logo	1	\$ 71.20	\$ 71.20	NECV ✓
3	Tailgate emblem 'HIACE'	1	\$ 55.00	\$ 55.00	NECV ✓
4	Tailgate emblem "G.L"	1	\$ 35.00	\$ 35.00	NECV ✓
5	Tailgate outer moulding	1	\$ 224.40	\$ 224.40	NNX ✓
6	Tailgate weatherstrip	1	\$ 196.60	\$ 196.60	CUTV ✓
7	Tailgate windscreen moulding	1	\$ 128.60	\$ 128.60	NECV ✓
8	Tail lamp LH	1	\$ 482.50	\$ 305.10	BRV ✓
9	Tail lamp lower garnish	1	\$ 97.80	\$ 97.80	BRV ✓
10	Rear bumper	1	\$ 426.80	\$ 426.80	DDV ✓
11	Rear bumper side retainer	2	\$ 34.50	\$ 69.00	NECV ✓
12	Rear bumper bracket	1	\$ 158.00	\$ 158.00	NECV ✓
14	Rear end panel	1	\$ 282.00	\$ 282.00	DDV ✓
16	Rear body panel outer LH	1	\$ 1,658.00	\$ 1,658.00	DDV ✓
17	Rear body panel inner board LH	1	\$ 146.80	\$ 146.80	NNX ✓
Parts Sub Total :				\$ 3,023.80	5,230.40
25% Discount				\$ 755.95	1,307.60
<b>PARTS TOTAL :</b>				<b>\$ 2,267.85</b>	<b>3,922.80</b>

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Tailgate windscreen inner seal	1	\$ 150.00	\$ 60.00	NECV ✓
2	Rear windscreen sealant	1	\$ 100.00	\$ 60.00	NECV ✓
3	Rear bumper clips	1	\$ 50.00	\$ 30.00	NECV ✓
4	Tailgate sticker "60km/h"	1	\$ 30.00	\$ 30.00	NECV ✓
5	Rear end panel sealant	1	\$ 100.00	\$ 60.00	NECV ✓
6	Sundries	1	\$ 80.00	\$ -80.00	NNX ✓
<b>SPECIAL NETT TOTAL :</b>				<b>\$ 240.00</b>	<b>510.00</b>

Nos.	LABOUR	S\$	
1	R&R tailgate component	\$ 60.00	100.00 ✓
2	R&R rear windscreen	\$ 180.00	250.00 ✓
3	R&R reverse sensor	\$ 60.00	80.00 ✓
4	Panel beat	\$ 700.00	1,200.00 ✓
5	Rust proofing	\$ 100.00	200.00 ✓
6	Spray painting	\$ 900.00	1,200.00 ✓
7	Spray reverse sensor	\$ -50.00	NNX ✓
<b>LABOUR TOTAL :</b>		<b>\$ 2,100.00</b>	<b>3,080.00</b>

Survey and Resurvey  
on 28/5/19 at 1530 hrs  
Lump sum Repair  
Repair days 7

Team Lin  
Lick

PARTS TOTAL : \$ 3,922.80  
SPECIAL NETT TOTAL : \$ 510.00  
LABOUR TOTAL : \$ 3,080.00  
**GRAND TOTAL : \$ 7,512.80**

➔ Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1325E
Vehicle Details	
Vehicle No.:	PC5587K
Vehicle to be Exported:	No
Intended Deregistration Date:	29 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER GL 3.0 AUTO
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1KD2602497
Chassis No.:	KDH2230027637
Maximum Power Output:	-
Open Market Value:	\$40,955.00
Original Registration Date:	16 Dec 2016
First Registration Date:	16 Dec 2016
Transfer Count:	1
Actual ARF Paid:	\$2,048.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Dec 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$43,608.00
COE Rebate Amount:	\$32,893.00
<b>Total Rebate Amount:</b>	<b>\$32,893.00</b>

The information contained herein is correct as at 29 May 2019

OK

Dep 10,450/yr  
871/mx

Parts	22 67.80
SN	2 40.00
Labour	21 00.00
	<hr/>
	46 07.80
@ 20%	9 21.56
	<hr/>
	36 86.24

4/5 3,650/2

MV 76,000/2  
PV 32,893/2  
NV 43,107/2

TG Lim Min  
29/5/19

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 May 2019		27 May 2019 12:29 <a href="#">Edit Adj Rpt</a>	<b>S\$3,650.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,650.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>LING KUOK TUNG</b> , ID: S7287960J, Tel: +6596662963, Email: KTLING@HOTMAIL.COM									
Main Claimant: <b>LIMOCARS &amp; TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 201721325E									
Vehicle Reg. No.: <b>PC5587K</b>		Date of Loss: 14/05/2019 11:00 - :59 [28 Months and 28 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / CMTD1902352</b>		Policy/Cover Note No.: D18MTPV01010178 (Comprehensive)							
Vehicle Reg. No. (Insured): <b>SLQ3313X</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Team Autopro Pte Ltd - Sin Ming (HQ)</b> 160 SIN MING DRIVE #01-14 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 9674 6635 / 9092 7279									
Handling Insurer: <b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>CHAN SHU HUI AGNES</b> - 6329 5327]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... [Final Rpt due 06/06/2019]									
Driver/Custodian (Insured): LING KUOK TUNG (47 / Male) , NRIC: S7287960J, Tel: +6596662963 Email: KTLING@HOTMAIL.COM									
Adj Asg. Remarks: ALAN 90927279 / FREDERICK 96746635									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*PC5587K (CMTD1902352)**  
**[SLQ3313X]**  
**TP**  
**LIMOCARS & TRANSPORTATION PTE LTD**  
**May 14 2019 11:00AM**  
**[LING KUOK TUNG]**  
**Team Autopro Pte Ltd - Sin Ming**


































[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View** View in Browser

<b>Assessment Reports</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	27/05/19 12:28	<b>Accident Statement</b> <small>From: OD - Reg. No: SLQ3313X, Claimant: LING KUOK TUNG</small>		Load HTM	

<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
2	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
3	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
4	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
5	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
6	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
7	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
8	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
9	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
10	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
11	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
12	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
13	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
14	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
15	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
16	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
17	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
18	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
19	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
20	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
21	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
22	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
23	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
24	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
25	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
26	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
27	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
28	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
29	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
30	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
31	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
32	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>
33	12/07/19 17:56	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
34	12/07/19 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
35	12/07/19 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
36	12/07/19 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
37	12/07/19 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
38	12/07/19 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
39	12/07/19 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
40	12/07/19 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
41	15/07/19 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	15/07/19 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	15/07/19 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	15/07/19 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	15/07/19 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	15/07/19 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	15/07/19 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	15/07/19 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	15/07/19 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	15/07/19 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	15/07/19 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	15/07/19 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	15/07/19 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	15/07/19 09:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	15/07/19 09:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	15/07/19 09:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	15/07/19 09:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	15/07/19 09:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	15/07/19 09:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	15/07/19 09:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	15/07/19 09:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	15/07/19 09:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	15/07/19 09:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	15/07/19 09:31	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	27/05/19 08:51	Pre-Repair Survey+GIA	 Load PDF	
2	27/05/19 12:28	Pre-Repair Survey - AGREED LKK	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19009256/BTD3E2

Date: 25/07/2019

### REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01010178

Claimant Vehicle No: PC5587K

Insured Vehicle No: SLQ3313X

Date of Loss: 14/05/2019

Nature of Claim: TP

Claim No: CMTD1902352

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PC5587K

Make &amp; Model: TOYOTA HIACE, 3.0 D Commuter (M)

Engine No: 1KD2602497

Reg. Date: 16/12/2016 (Man. Year: 2016)

Chassis No: KDH2230027637

Colour: White

Odometer: 171165 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 195 R15C

Front Left Side: Journey 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Journey 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,432.80	2,507.85	1,924.95	43.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	2,100.00	980.00	31.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,512.80</b>	<b>4,607.85</b>	<b>2,904.95</b>	<b>38.67</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,650.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,512.80</b>	<b>3,650.00</b>	<b>3,862.80</b>	<b>51.42</b>

### INSPECTION

Date of Assignment: 27/05/2019

Date Inspected: 27/05/2019 Inspected At:

Team Autopro Pte Ltd - Sin Ming (HQ)  
160 SIN MING DRIVE #01-14 SIN MING  
AUTOCITY  
Singapore 575722

Estimated Period of Repair: 7.0 days

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 25 Jul 2019)
Parts:	N/A	TOYOTA HIACE 3.0 D Commuter (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for PC5587K)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,198.70 FL	*1,198.70 FL
2	1		*TAILGATE LOGO	Necessary	71.20 FL	*71.20 FL
3	1		*TAILGATE EMBLEM HIACE	Necessary	55.00 FL	*55.00 FL
4	1		*TAILGATE EMBLEM G.L	Necessary	35.00 FL	*35.00 FL
5	1		*TAILGATE OUTER MOULDING	Not Necessary	224.40 FL	*- FL
6	1		*TAILGATE WEATHERSTRIP	Cut	196.60 FL	*196.60 FL
7	1		*TAILGATE WINDSCREEN MOULDING	Necessary	128.60 FL	*128.60 FL
8	1		*TAIL LAMP LH	Broken	482.50 FL	*305.10 FL
9	1		*TAIL LAMP LOWER GARNISH	Broken	97.80 FL	*97.80 FL
10	1		*REAR BUMPER	Dented	426.80 FL	*426.80 FL
11	2		*REAR BUMPER SIDE RETAINER	Necessary	69.00 FL	*69.00 FL
12	1		*REAR BUMPER BRACKET	Necessary	158.00 FL	*158.00 FL
13	1		*REAR END PANEL	Dented	282.00 FL	*282.00 FL
14	1		*REAR BODY PANEL OUTER LH	Repair	1,658.00 FL	*- FL
15	1		*REAR BODY PANEL INNER BOARD LH	Not Necessary	146.80 FL	*- FL
16	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	150.00 FS	*60.00 FS
17	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
18	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
19	1		*TAILGATE STICKER 60KM/H	Necessary	30.00 FS	*30.00 FS
20	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
21	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
<b>Sub Total (\$\$)</b>					<b>5,740.40</b>	<b>3,263.80</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>					<b>1,307.60</b>	<b>755.95</b>
<b>Total Parts (\$\$)</b>					<b>4,432.80</b>	<b>2,507.85</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	R&R TAILGATE COMPONENT.	New	100.00	60.00
2	R&R REAR WINDSCREEN.	New	250.00	180.00
3	R&R REVERSE SENSOR.	New	80.00	60.00
4	PANEL BEAT.	New	1,200.00	800.00
5	RUST PROOFING.	New	200.00	100.00
6	SPRAY PAINTING.	New	1,200.00	900.00
7	SPRAY REVERSE SENSOR.	New	50.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,080.00</b>	<b>2,100.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >