

22/03/2002

ASS. REC. BY:

REF: CS3/CT119009263/ Gcd302

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Ong chin Kiat

of CT1

Date/Time: 24.5.2019 17:36 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBN 5804 S

Insured: GBA 7383 U

at Workshop m/s Asia Motorsports Solution

Tel: 67453811

of NO 568 Gaylang Road

Policy No: DMCVSN 180304/8000

Claim No: SNM19D202329 C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 22.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 27.5.2019 10.16 a.m

Person Contacted:

Loo

H.O.D. Endorsement:

Vehicle: IN / OUT

Date/Time	Action/Instruction (X) Estimate
	FBN 5804 S - X
	GBA 7383 U - CS/ P1218022886/ Kcd 302 ROA- 17/12/2018
	Dismantle: 31/5/2019

PR5
Gul

REF: CT1

ASSIGNMENT

From: _____ Date: 27.5.2016

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBN 5804 S

at Workshop m/s Asia Motorsports
of 568 Geylang Road

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

24 days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

rep

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: FBN 5804 S Yr Regn: Oct / 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha

XMAX 300 c.c 292

Colour

Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

4635

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

120/70-15

R:

140/70-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5 mm

R/Bal.

5 mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

21-05-19

Survey held at

n/s

2:50pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$4000 - \$5000
	28/5/2019

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

Report Format : PR5

Lump Sum / I.B.I: (\$

150

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 May 2019		24 May 2019 17:36 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MT SINGAPORE CAR RENTAL PTE LTD, Co. Reg. No.: 201630785W		
Main Claimant:	MOHAMMAD TARMIZIE BIN PAIMAN, ID: S7915998J		
Vehicle Reg. No.:	FBN5804S	Date of Loss:	22/05/2019 18:00 - :59 [6 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D202329C02	Policy/Cover Note No.:	DMCVSN18030418000 (Comprehensive)
Vehicle Reg. No. (Insured):	GBA7383U	Policy No. (Claimant):	AN3169523
		Excess:	S\$0.00
Repairer:	Asia Motorsports Solution Pte Ltd (HQ) No 568 Geylang Road, 389514 Geylang - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/06/2019]		
Driver/Custodian (Insured):	THAM WON JIE (30 / Male) , NRIC: S8845654H Email:		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5998J
Vehicle Details	
Vehicle No.:	FBN5804S
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Jun 2019
Vehicle Make:	YAMAHA
Vehicle Model:	CZD300A / XMAX300
Primary Colour:	Brown
Manufacturing Year:	2018
Engine No.:	H336E0040474
Chassis No.:	MH3SH0848JK004992
Maximum Power Output:	-
Open Market Value:	\$4,408.00
Original Registration Date:	31 Oct 2018
First Registration Date:	31 Oct 2018
Transfer Count:	1
Actual ARF Paid:	\$662.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Oct 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,951.00
COE Rebate Amount:	\$3,705.00
Total Rebate Amount:	\$3,705.00

The information contained herein is correct as at 13 Jun 2019

OK

MALP19066874 / Alpine Motors Pte Ltd - HQ
ENTRY DATE & TIME: 23/05/2019 16:35
SUBMITTED BY: Mohd Suhaimi Bin Mohd Suadi Ong

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/05/2019 16:35
Date Of Accident	22/05/2019 18:20
Exact Location Of Accident	WOODLANDS AVENUE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBN5804S
Insured/Policyholder	
Name Of Registered Owner	MOHAMMAD TARMIZIE BIN PAIMAN
NRIC No	S7915998J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83823693
Alternative Phone No	Others-83823693

Vehicle Particulars

Manufacturer	YAMAHA
Model	CZD300A / XMAX300
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	AN3169523
Cover Note Number	

Driver

Name of Driver	MOHAMMAD TARMIZIE BIN PAIMAN
NRIC No	S7915998J
Date Of Birth	30/05/1979
Occupation	INDOOR
Date Of Driving Pass	21/12/1995
Driving Experience	23 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83823693

Fax Number

Contact Number

OTHERS-83823693

EMail Address

NOEMAIL

Address

670 WOODLANDS DRIVE 71 #03-31 SPORE 730670

Postcode

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own Vehicle

-
-
-

Insurance Company of Driver's Own Vehicle

-
-
-**General Information of the Accident**

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

WOODLANDS EAST N.P.C

Police Station Address

ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBA7383U

Vehicle Make/Model/Colour

TOYOTA HIACE MANUAL

Details Of Properties

Vehicle Category

GOODS VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

MOHAMMAD TARMIZIE BIN PAIMAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBN5804S

Were seat belts worn?

NO

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: S. P. S. S. S. S.
NRIC/FIN No.: S. S. S. S.

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per police report T/20190522/2167

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Signature of Policyholder

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: J. K. M.
NRIC/FIN No: J2019037712


































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 May 2019		24 May 2019 17:36 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: MT SINGAPORE CAR RENTAL PTE LTD, Co. Reg. No.: 201630785W									
Main Claimant: MOHAMMAD TARMIZIE BIN PAIMAN, ID: S7915998J									
Vehicle Reg. No.: FBN5804S		Date of Loss: 22/05/2019 18:00 - :59 [6 Months and 22 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D202329C02		Policy/Cover Note No.: DMCVSN18030418000 (Comprehensive)							
Vehicle Reg. No. (Insured): GBA7383U		Policy No. (Claimant): AN3169523							
		Excess: S\$0.00							
Repairer: Asia Motorsports Solution Pte Ltd (HQ) 37A Everitt, 428586 Joo Chiat - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 04/06/2019]									
Driver/Custodian (Insured): THAM WON JIE (30 / Male), NRIC: S8845654H Email:									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBN5804S (SNM19D202329C02)
[GBA7383U]
TP
MOHAMMAD TARMIZIE BIN PAIMAN
May 22 2019 6:00PM
[MT SINGAPORE CAR RENTAL PTE LTD]
Asia Motorsports Solution Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser		
Assessment Reports							1 per page		<input checked="" type="checkbox"/>		
No	Finalized On	Alpine Motors Pte Ltd (HQ)		Thumbnail	Print						
1	23/05/19 16:46	Accident Statement			Load HTM						
Photos/Images							3 per page		<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
2	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
3	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
4	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
5	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
6	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
7	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
8	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
9	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
10	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
11	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
12	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
13	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
14	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
15	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
16	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
17	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
18	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
19	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
20	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
21	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
22	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
23	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
24	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
25	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
26	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
27	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
28	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
29	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
30	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
31	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
32	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
33	13/06/19 11:53	General View			Load JPG		<input checked="" type="checkbox"/>				
34	13/06/19 11:53	General View			Load JPG						

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	13/06/19 11:53	General View	Load JPG	<input checked="" type="checkbox"/>
36	13/06/19 11:53	General View	Load JPG	<input checked="" type="checkbox"/>
37	13/06/19 11:53	General View	Load JPG	<input checked="" type="checkbox"/>
38	13/06/19 11:53	General View	Load JPG	<input checked="" type="checkbox"/>
39	13/06/19 11:53	General View	Load JPG	<input checked="" type="checkbox"/>
40	13/06/19 11:53	General View	Load JPG	<input checked="" type="checkbox"/>
41	13/06/19 11:53	General View	Load JPG	<input checked="" type="checkbox"/>
42	13/06/19 11:53	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/05/19 17:37	INSD GBA7383U GIA REPORT	Load PDF	
2	24/05/19 17:37	prs	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	23/05/19 16:46	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	23/05/19 16:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	23/05/19 16:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	23/05/19 16:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	23/05/19 16:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	23/05/19 16:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	23/05/19 16:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	23/05/19 16:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	23/05/19 16:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	23/05/19 16:43	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	23/05/19 16:45	Driving License	Load JPG	<input checked="" type="checkbox"/>
11	23/05/19 16:45	INSURANCE POLICY	Load JPG	<input checked="" type="checkbox"/>
12	23/05/19 16:45	Police Report	Load JPG	<input checked="" type="checkbox"/>
13	23/05/19 16:45	Police Report	Load JPG	<input checked="" type="checkbox"/>
14	23/05/19 16:45	Police Report	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	23/05/19 16:45	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	23/05/19 16:45	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119009263/GCD3E2

Date: 20/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN18030418000

Claimant Vehicle
No: FBN5804SInsured Vehicle
No: GBA7383U

Date of Loss: 22/05/2019

Nature of Claim: TP

Claim
No: SNM19D202329C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBN5804S

Make & Model: YAMAHA CZD300A / XMAX300, 292cc

Reg. Date: 31/10/2018 (Man. Year: 2018)

Colour: Maroon

Engine Capacity: 292 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: H336E0040474

Chassis No: MH3SH0848JK004992

Odometer: 4635 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70-15

Front Left Side: Dunlop 5 mm

Front Right Side: 0 mm

Rear Tyre Size: 140/70-14

Rear Left Side: Dunlop 5 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 24/05/2019

Date Inspected: 27/05/2019 Inspected At:

Asia Motorsports Solution Pte Ltd (HQ)
568 GEYLANG ROAD
SINGAPORE 389514

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 20 Jun 2019)	
Parts:	N/A	YAMAHA CZD300A / XMAX300 292cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN5804S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >