

NTUC Hwee Jie

REF: NTUC VS/INC/K1009300/3+135

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: GBH 7227B

Policy No: 5103344522 (01/09/2018 - 31/08/2019)

Claims No: MT/1044269-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMB1541J Yr Regn: 12 Dec 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAN A22 c.c. 10518

Colour: Multi Colour A/C: Insured / Std / NI / NA

Sp. Reading: 330710 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WMAA22ZZ 2E 7002426

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/70R22.5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Fireenza

Front Rear

R/Bal. 7 mm R/Bal. 7/7 mm

L/Bal. 7 mm L/Bal. 7/7 mm

D.O.A. 12/5/19 D.O.I. 24/5/19

Survey held at smrt

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SMB 1541J - CC3 / MSG 18019382 / T1 / the 2
	GBH 7227B - X
	Confirmed U/S \$800/- 2days of repair. U/Rd. 1507.70 (65%)
	RECEIVED 1 JUN 2019

Date/Time, File Pass to? ☐ : Preli. Report

1) 11/6 Typist ☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation

\$ + PS. \$

Photos

Others

Report Format:

Lump Sum / LB I: (3

Good

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

TOTAL

TP Claims against NTUC Income: Follow-Through Survey

Date : 10/6/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
	MT/1044269-002	SMRT BUSES	SMB 1541J	GBH 7227B	12/5/2019	12:20	\$ 2,307.70
	MT/1036852-002	SMRT BUSES	SG 1043H	SLP 9066A	20/3/2019	15:50	\$ 6,210.88
	MT/1048342-001	comfort delgro	SHA 1184X	GBD 6706M	31/5/2019	15:20	\$ 990.00

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No. (For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5103348522		7/7	53365582W	GCV	Comprehensive	GBH7227B	GBH7227B	01/09/2018	31/08/2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/05/2019 10:46
Date Of Accident	12/05/2019 12:20
Exact Location Of Accident	BRAS BASAH RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB1541J
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MAN
Model	NL320F (A22)-10.5 D ABS TURBO (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-19093203MFBP
Cover Note Number	

Driver

Name of Driver	LIM CHOW LONG
NRIC No	S1828640H
Date Of Birth	11/11/1967
Occupation	OUTDOOR
Date Of Driving Pass	21/11/1991
Driving Experience	27 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	6 ANG MO KIO STREET 62
Postcode	569140
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	10

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ON THE LEFT MOST LANE ALONG BRAS BASAH ROAD WHEN SUDDENLY A VAN (GBH7227B) THAT WAS FROM THE THIRD LANE SPEED PASSED MY BUS AND TRIED TO OVERTAKE AND CUT INTO MY PATH TO ENTER QUEEN STREET (MINOR ROAD). I WAS UNABLE TO BRAKE ON TIME HENCE COLLIDED ONTO THE REAR PORTION OF THE VAN. MY BUS SUSTAINED SCRATCHES ON THE FRONT LEFT PORTION. NO INJURIES REPORTED.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING DOWNLOAD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH7227B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	

No. Of Passenger (Including Driver) •

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Handwritten Signature]


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: BALQISH
NRIC/FIN No.: S83403252

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signat
Date & Time:



Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: BALQISH
NRIC/FIN No.: S8340325Z



> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SMB1541J		
Vehicle Type :	H20 - Public Transport Bus/Coach/Minibus		
Vehicle Attachment 1 :	Air-Conditioned		
Vehicle Scheme :	OmniBus (SMRT - ARF-exempted)		
Vehicle Make :	MAN		
Vehicle Model :	NL 320F (A22) 11L AUTO ABS TURBO		
Chassis No. :	WMAA22ZZ2E7002426		
Propellant :	Diesel		
Engine No. :	50338711733876		
Engine Capacity :	10518 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	18000 kg		
Unladen Weight :	11280 kg		
Year Of Manufacture :	2014		
Original Registration Date :	12 Dec 2014		
Lifespan Expiry Date :	11 Dec 2031		
Road Tax Expiry Date :	13 Jul 2019		
Inspection Due Date :	13 Jul 2020		
Intended Transfer Date :	24 Jun 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 13 Jul 2019. You may renew the road tax from 14 Apr 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 13 Jul 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 14 Jul 2019 to 13 Jan 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	850.00	-	850.00
Total Amount Payable :			875.00
Amount Payable (From 14 Jul 2019 to 13 Jul 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	1,700.00	-	1,700.00
Total Amount Payable :			1,725.00

You may print this page for reference.

OK

Print

SMRT Accident Vehicle Repair Estimates

Section A - Accident Details

Vehicle Number	SMB1541J
Accident Date	BUS/05/19/1029
Accident Time	12/12/2014
Company Name	SMRT Buses Ltd
Vehicle Model	MAN
Vehicle Type	A22
Driver Name	Lim Chow Long
Accident Location	Head to Rear
Accident Time	12/5/2019 12:24 PM
Date and Time	14/5/2019 10:38 AM
Accident Reported?	Yes
Accident Reported?	
Accident Reported?	
Accident Reported?	No
Accident Reported?	
Accident Reported?	
Accident Reported?	No
Accident Reported?	24101643
Accident Reported?	SMB1541J - FRONT LEFT PORTION GBH7227B (TP) - INSURED WITH NTUC
Accident Reported?	17/5/2019 10:02 AM
Accident Reported?	WMAA22ZZ2E7002426
Accident Reported?	
Accident Reported?	
Accident Reported?	
Date and Time	

Section B - Summary of Repair Estimates

Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
	\$795.00	\$530.00
	\$538.00	\$446.00
Subtotal	\$701.78	\$0.00
	\$0.00	(\$195.20)
	\$2,034.78	\$780.80
	\$2,050.00	\$800.00

SMRT Accident Vehicle Repair Estimates

Section D - Details of Repair Estimates

Works

	Quotation from AR	Adj
TALL ALL ABOVE ITEMS AND REPAIR OTHERS ED AREAS.	\$795.00	\$530
	\$795.00	\$530

Painting & Panel Beating Related Works

	Quotation from ARC	Adj
AND MATERIAL TO PUTTY AND RESPRAY ABOVE	\$538.00	\$446
ing & Panel Beating	\$538.00	\$446

Costs - Accident and Accident Repair Related Expense

	Quotation from ARC	Adj
ent by Surveyor	\$0.00	(\$19)
	\$0.00	(\$19)

Parts / Material Usage

Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Esti
dy	F01001-CW264	COVER,HEADLAMP:FRT ,LH,FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repl
				\$974.70		\$0.00	

Parts / Material Usage After Surveyor Signed off

Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/05/2019

User ID : BoonChewTay

Section A - Accident Details

Registration Number	SMB1541J
Case Reference Number	BUS/05/19/1029
Registration Date	12/12/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Lim Chow Long
Type of Accident	Head to Rear
Accident Date and Time	12/5/2019 12:24 PM
Accident Reported Date and Time	14/5/2019 10:38 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1541J - FRONT LEFT PORTION GBH7227B (TP) - INSURED WITH NTUC
Prepared Date and Time	17/5/2019 10:02 AM
Chassis Number	WMAA22ZZ2E7002426
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$538.00	\$0.00
Total Spare Part Cost	\$701.78	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,034.78	\$0.00
Lump Sum Total	\$2,050.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date		
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

PRE-REPAIR INSPECTION REQUEST – SJR195H vs SLB3941L (OI) on D.O.A.: 06/06/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Fan, Winnie-LW, Kaur, Bajit, Abu Kassim, Noor Manisa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Tc
Sent: 6/10/2019 2:42:58 PM
Attachments:  

Hi,

Please refer to the enclosed request from **CK Teo & Co.**

Claim no : 74742871235G003
Case Owner : Bennie Tan Wei Zhong

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.*

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Yinrul.Hor@aig.com | www.aig.ae

From: Willow Tuang [<mailto:wtuang@gmail.com>]
Sent: Monday, June 10, 2019 1:18 PM
To: Hor, Yinrul
Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLB3941L AND SJR195H ON 06/06/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir

We refer to your email of even date.

We are agreeable of appointing KENNETH KONG (LKK AUTO) as a Single Joint Expert.

Our client's vehicle is available for pre-repair survey at:

Venue	:	Guan Motor Works 176 Sin Ming Drive #02-03 Sin Ming AutoCare Singapore 575721 Tel: 6453 6111 (AH HENG)
-------	---	--

Error! Filename not specified.Regards

Tuang Willow
CK TEO & CO
Tel: 65354788
Fax: 65354245

On Mon, Jun 10, 2019 at 11:34 AM Hor, Yinrul <Yinrul.Hor@aig.com> wrote:

This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la pièce jointe.

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2019-06-16 22:34 CDT to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

From: Yinrul.Hor@aig.com
To: wtuang@gmail.com
Cc: Andy-SY.Fong@aig.com ,Winnie-LW.Fan@aig.com ,Baljit.Kaur@aig.com ,NoorMariesa.AbuKassim@aig.com ,Syazairdina.Azlan@aig.com ,yokeshi.chan@aig.com ,ShengYang.Lim@aig.com ,Aashweenjeetkaur.Mithoosingh@aig.com ,Divyashni.Subramaniam@aig.com ,Wahxin.Tong@aig.com
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLB3941L AND SJR195H ON 06/06/2019
Date: Mon, 10 Jun 2019 03:34:18 +0000
Without Prejudice

Your Reference : SJR195H
Our Reference : SLB3941L

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Yinrul.Hor@aig.com | www.aig.sg



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19009300/Jtd3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 24-06-2019



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 7227B	Veh. Inspected	SMB 1541J
Policy No.	5103348522	Coverage (\$)	0.00
Claim No.	MT/1044269-002	Excess (\$)	0.00
Assign From		Assign Date	24/05/2019

2. Vehicle Particulars & Condition

Make & Model	MAN A22	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WMAA22ZZ2E7002426	Colour	MULTI COLOUR
Odometer	330710	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	FIRENZA	7 mm
L/H Front Tyre	275/70 R22.5	FIRENZA	7 mm
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	7/7 mm
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	7/7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/05/2019	Inspection Date	24/05/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 1541J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REPLACEMENT OF PARTS	TO REPAIR SEE LABOUR		
	COVER, HEADLAMP: FRT, LH, FOR MAN A22 BUS		974.70	-
			974.70	-
	LABOUR			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF COVER, HEADLAMP: FRT, LH, FOR MAN A22 BUS.		795.00	530.00
	PROVIDE LABOUR AND METRIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		538.00	446.00
			1,333.00	976.00
GRAND TOTAL			2,307.70	976.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				800.00

Report Ref No. NS/INC19009300/Jtd3s2

ONG HWEE JIE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.