

ASS. REC. BY:

REF: CS/MSG19009342/ E1d3n2

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Christina Wong of MSIGDate/Time: 27.5.19 18.25pm

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SJN 77LInsured: SLG 2473Rat Workshop m/s Performance Motors limitedTel: 63190174of 303 Alexandra RoadPolicy No: 29114756Claim No: 591401

Sum Insured: _____

Excess: _____

Make of Veh:
(Client's Record)D.O.A. 21.4.2019

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement: _____

Date/Time: 28.5.19 9.31a.mPerson Contacted: CarolineVehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SJN 77L - X</u>
	<u>SLG 2473R - X</u>
<u>30/5@16:49pm</u>	<u>revised preli advice via messenger</u>

Surveyor

Steve

REF: MSIG

ASSIGNMENT

From:

Date:

28.9.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJN 77L

at Workshop m/s Performance motors

of 303 Alexandra road

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"up"

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJN 77L

Yr Regn:

28/12/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Moyer /

Truck / Trailer or

Make:

BMW 730 LI

C.C

1998

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

11590

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

113799 96 B 488208

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/50R18

R:

"11"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

21/4/19

D.O.I.

28/5/19

Survey held at

Performance

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/7/19

NIV- 270 K

Finalite (gr. fin) \$4113.50, 3 days (Red: 1373.90, 25%)

RECEIVED 04 JUL 2019

2/7/2019

Date/Time, File Pass to?



: Preli. Report



: Final Report

1) 217 Typist

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 4113.50)

150

"

161

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 30 May 2019

Preliminary Advice

Insured Vehicle No	: SLG2477R	Accident Date	: 21/04/2019
TP Vehicle No	: SJN77L	Assignment Date	: 27/05/2019
Make	: BMW 730LI	Est. Duration of Repair	: 3.00
Date of Inspection	: 28/05/2019		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,871.52
Revised Amount	:S\$	3,790.60
Check Items (Estimated)	:S\$	1,140.80
Total	:S\$	4,931.40
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Tris Auth'd	Status
Main	24 Apr 2019		27 May 2019 18:25 Assign				New Assignment Cancel Case

Main Reference Claim Details Documents Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Main Claimant:	LIM KIAN MENG, ID: S7215571H		
Vehicle Reg. No.:	SJN77L	Date of Loss:	21/04/2019 01:00 - :59 [15 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 591401	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	SLG2477R	Policy No. (Claimant):	
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/05/2019]		
Driver/Custodian (Insured):	CHEN JUE YU (), NRIC: S89206181, Tel: +6596477757 Email:		
Adj Asg. Remarks:	LIABILITY: 100% CONTACT: CAROLINE 6319 0174, Car in 28/05/2019		

ASSOCIATED MAIL RECEIVED

[View All](#)

Compose Case Mail

There are no mail for this case.

 ALL ASSOCIATED TASKS

[View All](#)

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 10 Years Coe Renewal Toyota Wish 1.8A

2.98%P.A \$0 Admin Fees@GV
Finance.2 Years Warranty.
Monthly From \$788.
GV Credit Pte Ltd StarAd

PRIME MOTOR & LEASING

(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category ▼

« Back (1 2 3 4 5) Next »

Sort by Date Posted ▼

20 results/page

81 vehicles

bmw 730li

Advanced Search 🔍

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	bmw 730li		Any	Any	Any	Any	Any	Any	All
	BMW 7 Series 730Li Sunroof (New 10-yr COE)		\$100,800	\$10,070 /yr	18-Jan-2010	2,996 cc	91,000 km	Luxury	Available
Well Kept Condition. View To Appreciate. Low Depreciation. Low Interest Rates. Look No Further. Call Now For An Appointment.									
Posted: 28-May-2019 Tags: 2010 BMW 730Li, 2010 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW									
	BMW 7 Series 730Li Sunroof		\$297,800	\$26,780 /yr	31-May-2018	1,998 cc	14,900 km	Luxury	Available
Latest Certified Pre-owned BMW G12/730Li In The Market. The Epitome Of Luxury And Driving Dynamics Clad In Glacier Silver With Dakota Cognac Leather. BMW 360 Degree Technical And Optical Checks For Yo...									
Performance Premium Selection Limited									
Posted: 28-May-2019 Tags: 2018 BMW 730Li, 2018 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW									
	BMW 7 Series 730Li Sunroof		\$297,800	\$26,780 /yr	31-May-2018	1,998 cc	14,000 km	Luxury	Available
Latest Certified Pre-owned BMW G12/730Li In The Market. The Epitome Of Luxury And Driving Dynamics Clad In Glacier Silver With Cognac Leather. BMW 360 Degree Technical And Optical Checks For Your Adde...									
Performance Premium Selection Limited									
Posted: 28-May-2019 Tags: 2018 BMW 730Li, 2018 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW									
	BMW 7 Series 730Li Sunroof		\$53,300	\$14,830 /yr	30-Aug-2010	2,996 cc	127,000 km	Luxury	Available
Selling Close To Paper Plus Body Value! Optional 5 Or 10 Years Renew Very Well Maintained! Come And View Now.									
Posted: 27-May-2019 Tags: 2010 BMW 730Li, 2010 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW									
	Toyota Camry takes on Volkswagen's Passat								
The Toyota Camry offers more legroom for rear passengers, is sportier around corners and has more safety systems but the Volkswagen Passat is more affordable and feels more premium overall.									
Find out more!									
	BMW 7 Series 730Li Sunroof		\$144,800	\$18,740 /yr	28-Feb-2014	2,996 cc	114,000 km	Luxury	Available
Extended 12 Months Warranty! High Specifications Luxury Unit With HUD, Adaptive LED HeadLight, Pearl White On Black. High OMV/ARF \$111,317, PARF \$55,659. Shelter Park, Conditions Like New! Trade In. F...									
Posted: 27-May-2019 Tags: 2014 BMW 730Li, 2014 bmw 730li, BMW 730Li, bmw 730li, BMW, 730Li, 730li, Used BMW									
Compare	BMW 7 Series 730Li Sunroof		\$299,800	\$26,160 /yr	29-Jun-2018	1,998 cc	11,000 km	Luxury	Available

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5571H
Vehicle Details	
Vehicle No.:	SJN77L
Vehicle to be Exported:	No
Intended Deregistration Date:	28 May 2019
Vehicle Make:	B.M.W.
Vehicle Model:	730LI LED NAV HUD SR RCP
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	11379996B48B20B
Chassis No.:	WBA7E02080G245369
Maximum Power Output:	190.0 kW (254 bhp)
Open Market Value:	\$78,250.00
Original Registration Date:	28 Dec 2017
First Registration Date:	28 Dec 2017
Transfer Count:	1
Actual ARF Paid:	\$112,850.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2027
PARF Rebate Amount:	\$84,637.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$57,501.00
COE Rebate Amount:	\$49,229.00
Total Rebate Amount:	\$133,866.00

The information contained herein is correct as at 28 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/04/2019 15:20
Date Of Accident	21/04/2019 00:30
Exact Location Of Accident	SLE/BKE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN77L
Insured/Policyholder	
Name Of Registered Owner	LIM KIAN MENG
NRIC No	S7215571H
Email Address	RAYMOND@AIRCONSPECIALIST.COM.SG
Mobile Phone No	(LOCAL) +65-97479141
Alternative Phone No	OTHERS-63836630

Vehicle Particulars

Manufacturer	BMW
Model	730LI
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	UNAVAILABLE
Cover Note Number	

Driver

Name of Driver	LIM KIAN MENG
NRIC No	S7215571H
Date Of Birth	10/05/1972
Occupation	INDOOR
Date Of Driving Pass	20/01/1996
Driving Experience	23 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97479141
Fax Number	
Contact Number	OTHERS-63836630
EMail Address	RAYMOND@AIRCONSPECIALIST.COM.SG

Address	BLK 181 JELEBU ROAD #20-10
Postcode	670181
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : JEN KHONG SUET LIN GENDER: : FEMALE
Passenger 2	NAME: : LIM EDISON GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG2477R
Vehicle Make/Model/Colour	TOYOTA GREY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHENG JUE YU
NRIC/Passport Number	S8920618I
Contact Number	96477757
Address	
Postcode	

Insurance Company Name

MSIG INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 23/11/19
Bookin

NRIC/Identification No.:

Driver's Signature


(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

SLE

On 21/4/19 at 1230am, I (3257921) was travelling home on SLE toward BKE. At Exit 11, a car (xxx 4116) stopped at the left exit and tried to go straight back to SLE. I braked in time to avoid hitting. However, SLG 2477R behind was unable to stop and hit my vehicle.

4116 just left (Grey)
2477 in a car cum

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax, 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax, 63449773

280, Kampong Arang Road
Sime Darby Business Centre
Singapore 159944
Fax, 64796601 (AfterSales)
64796624 (Motorrad)

Signature:

Date:

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

25 APR 2019

Estimate No. : b1 50980
Date Estimated : 25/04/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Lim Kian Meng
Block 1 Defu Lane 10
#01-555

Singapore 539182

- ACCOUNT - 66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJN77L	G245369	28/12/2017	730Li	0

DESCRIPTION

To replace rear bumper and attachments.

859 1,275.00

Painting rear bumper.

934 1,038.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

80.00

Total Labour 1: 2,570.00

DESCRIPTION

REAR BUMPER ADAPTER

QTY PRIC

1 82.80

VALUE

✓ 82.80

REAR BUMPER CARRIER

1 971.25

971.25

REAR BUMPER CENTRE GUARD

1 85.85

✓ 85.85

LH RUBBER STRIP

1 86.75

86.75

REAR BUMPER PANEL PRIMED (PDC/PMA)

1 1,690.75

✓ 1,690.75

Total Parts : 2,917.40

30/5/19
Star CLKK) LL P/L
3 ch
P/P
28/5/19, 11:00am

5727.50
5487.40

Labour 1	:	2,570.00
Parts	:	2,917.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	384.12
Grand Total	:	5,871.52

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sino Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 50980
Date Estimated : 25/04/2019
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Lim Kian Meng
Block 1 Defu Lane 10
#01-555

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 539182

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJN77L	G245369	28/12/2017	730Li	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include knocking out dents caused by the accident	850.00		850.00 ✓
To spray paint rear bumper	934.00		934.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00 ✓
Sundries	80.00		80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLIP BOTTOM PART *	4.10	4.00		16.40 ✓
REAR BUMPER ADAPTER	82.80	1.00		82.80 ✓
REAR BUMPER CENTRE GUARD	85.85	1.00		85.85 ✓
# REAR BUMPER GUARD *	105.50	1.00		105.50 ✓
# REAR BUMPER COVER *	109.20	1.00		109.20 ✓
REAR BUMPER PANEL PRIMED (PDC/PMA)	1,690.75	1.00		1,690.75 ✓
# PLUG BLACK D=5MM *	0.90	10.00		9.00 ✓

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	2,099.50
Total Labour & Parts :	4,113.50 ✓
Deduction for Excess :	0.00
Total Repair Costs less Excess:	4,113.50
GST @7%:	287.95
Grand Total :	4,401.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 50980
Date Estimated : 25/04/2019
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Lim Kian Meng
Block 1 Defu Lane 10
#01-555

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 539182

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJN77L	G245369	28/12/2017	730Li	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLIP BOTTOM PART * / n/c	4.10	4.00		16.40
# REAR BUMPER GUARD * / BR	105.50	1.00		105.50
# REAR BUMPER COVER * / BR	109.20	1.00		109.20
# PLUG BLACK D=5MM * / n/c	0.90	10.00		9.00

Total Labour :	0.00
Total Parts :	240.10
Total Labour & Parts :	240.10

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19009342/ETD3N2

Date: 10/07/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114756
Claimant Vehicle No :	SJN77L	Insured Vehicle No :	SLG2477R
Date of Loss:	21/04/2019	Nature of Claim:	TP
		Claim No:	591401

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN77L	Engine No:	11379996B48B20B
Make & Model:	BMW 730Li, 2.0 LED NAV HUD SR (A)	Chassis No:	WBA7E02080G245369
Reg. Date:	28/12/2017 (Man. Year: 2017)	Odometer:	11500 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/50R18	Rear Tyre Size:	245/50R18
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,237.50	2,179.50	1,058.00	32.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,934.00	556.00	22.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,727.50	4,113.50	1,614.00	28.18
+ GST 7.00/7.00% (S\$)	400.93	287.95	112.98	28.18
Nett Amount (S\$)	6,128.43	4,401.45	1,726.98	28.18

INSPECTION

Date of Assignment:	27/05/2019	
Date Inspected:	28/05/2019	Inspected At:
		Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941

Estimated Period of Repair: 3.0 days**Adjuster:** CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2019)
Parts:	143	BMW 730LI 2.0 LED NAV HUD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN77L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ADAPTER	Cut	82.80 FS	*82.80 FS
2	1		*REAR BUMPER CARRIER	Not Necessary	971.25 FS	*- FS
3	1		*REAR BUMPER CENTRE GUARD	Cut	85.85 FS	*85.85 FS
4	1		*LH RUBBER STRIP	Not Necessary	86.75 FS	*- FS
5	1		*REAR BUMPER PANEL PRIMED (PDC/PMA)	Dented	1,690.75 FS	*1,690.75 FS
6	4		*CLIP BOTTOM PART	Necessary	16.40 FS	*16.40 FS
7	1		*REAR BUMPER GUARD	Broken	105.50 FS	*105.50 FS
8	1		*REAR BUMPER COVER	Broken	109.20 FS	*109.20 FS
9	10		*PLUG BLACK D=5MM	Necessary	9.00 FS	*9.00 FS
10	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **3,237.50** **2,179.50**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER AND ATTACHMENTS	New	1,275.00	850.00
2	PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$\$)			2,490.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >