

ASS. REC. BY:

REF: CS/MSG 19009344/TLVD352

Special Instruction:

Surveyor: TAN H K Y

ASSIGNMENT (Office)

From (Person): Jocelyn Ng Shin Bun of MS19

Date/Time: 23.5.19 9:41 a.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKL 1618T

Insured:

at Workshop m/s Performance Motors

Tel: 91165700

of 303, Alexandra Road

Policy No: B276173115 MP

Claim No:

Sum Insured:

Excess: \$1000.00

Make of Veh:

D.O.A. 25.5.2019

(Client's Record)

After 10:30 a.m. 29/5/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 23.5.19 9:30 a.m.

Person Contacted: Han

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKL 1618T - X
29/5/19	Revert via merimen
29/5/19	Rece approved \$3732.90 from Jocelyn by merimen
30/5/19	Informed Han c/A ex \$1000 by email
18/6/19	Final fig \$4000.95 (Red 5419.20, 5581.75) confirmed by email

ASS. REC. BY: Tan JHREF MS19**ASSIGNMENT**From: _____ Date: 29.5.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SKL 1618Tat Workshop n/s Performana motor
of 303 Alexandra Road

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: \$1000.00

(Client's Record)

Make of Veh: After 10.30.9.17

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$68K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKL 1618T Yr Regn: 2013, NovType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 316i c.c. 1598Colour: white A/C: Insured / Std / NI / NASp. Reading: 35237 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WR13AR20105721321Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 2 mm

D.O.A. _____

D.O.I. 29/5/19 @ 1130Survey held at PML.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Vehicle: \$50,773

RECEIVED 18 JUN 2019

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 18/6 - typistDays Of Repair: 4Resurvey No. of Trip: 1Survey Fee: 150

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

S + RS, \$ _____

Photos

Others

TOTAL

Report Format: merimenLump Sum / I.B.I. (\$) 4000.95

150
11

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 May 2019 16:58		28 May 2019 09:46 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS		[Created by insurer]																						
Insured:	ONG HIAN KOON, ID: S6825462], Tel: +6596169358																							
Vehicle Reg. No.:	SKL1618T	Date of Loss:	25/05/2019 13:00 - :59 [65 Months and 28 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	OD	Policy/Cover Note No.:	B27617311SMP (Comprehensive) Coverage: 27/11/2018 - 26/11/2019																					
		Excess:	S\$1,000.00																					
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174																							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/05/2019]																							
Driver/Custodian:	TEO WAN CHUAN (47 / Female), NRIC: S7215143G, Tel: +6596939089 Email: KELLY.TEO123@YAHOO.COM.SG																							
Adj Asg. Remarks:	Car in on 28/05/2019 10AM. Survey & revert. Please contact us ASAP if you cannot attend this assignment.																							
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail																						
There are no mail for this case.																								
<div> ALL ASSOCIATED TASKS </div> <div> View All Search Tasks Create New Task Complete </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

View Received Message

This mail is associated with :

***SKL1618T (594714)**

OD

May 25 2019 1:00PM

[ONG HIAN KOON]

Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 18/06/2019 14:50 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$4000.95) - SKL1618T - Claim Handler: Jocelyn Ng Shin Bun

Approved:4000.95:a if c

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Jocelyn Ng Shin Bun	Date: 18 Jun 2019
Preliminary Advice	

Vehicle No	: SKL1618T	Accident Date	: 25/05/2019
Make	: BMW 316I	Policy No.	: B27617311SMP
Assignment Date	: 28/05/2019	Excess	: S\$1,000.00
Date of Inspection	: 29/05/2019	Est. Duration of Repair	: 4.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,420.15
Revised Amount	:S\$	4,000.95
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,000.95
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	50,773.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,227.00

Remarks

(X)	The vehicle is economical for repair.
()	The above survey was conducted on a 'without prejudice' basis.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 30 May 2019 8:30 AM
To: SUR; han.kwan.yong@simeдарby.com.sg
Subject: SKL 1618T-DOA: 25/5/2019 (MSIG OD)

Dear Mr Han,

As instructed by our client , please proceed to repair the **insured vehicle SKL 1618T (Excess \$1000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SKL1618T (594714)**

OD

May 25 2019 1:00PM

[ONG HIAN KOON]

Performance Motors Limited

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 29/05/2019 17:45 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$3732.90) - SKL1618T - Claim Handler: Jocelyn Ng Shin Bun

Approved:3732.90:a if c

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 29 May 2019

Preliminary Advice

Vehicle No	: SKL1618T	Accident Date	: 25/05/2019
Make	: BMW 316I	Policy No.	: B27617311SMP
Assignment Date	: 28/05/2019	Excess	: S\$1,000.00
Date of Inspection	: 29/05/2019	Est. Duration of Repair	: 5.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,420.15
Revised Amount	:S\$	3,732.90
Check Items (Estimated)	:S\$	3,856.25
Total	:S\$	7,589.15

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	50,773.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,227.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/05/2019 13:25
Date Of Accident	25/05/2019 13:35
Exact Location Of Accident	JURONG EAST CENTRAL (AROUND JCUBE YELLOW BOX JUNC
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL1618T
Insured/Policyholder	
Name Of Registered Owner	ONG HIAN KOON
NRIC No	S6825462J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96169388
Alternative Phone No	OTHERS-96939089

Vehicle Particulars

Manufacturer	BMW
Model	316i
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B27617311
Cover Note Number	

Driver

Name of Driver	TEO WAN CHUAN
NRIC No	S7215143G
Date Of Birth	01/05/1972
Occupation	INDOOR
Date Of Driving Pass	20/05/2011
Driving Experience	8 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96939089
Fax Number	
Contact Number	
EMail Address	KELLY.TEO123@YAHOO.COM.SG

Address	33 MOUNT SINAI RISE #24-08
Postcode	276954
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ONG LI JING EMILY
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC7910S
Vehicle Make/Model/Colour	COMFORT DELGRO HYUNDAI
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	AZMAN BIN AWANG
NRIC/Passport Number	S6901827J
Contact Number	90582605
Address	BLK 308 JURONG EAST STREET 32 #02-260
Postcode	600308
Insurance Company Name	INDIA INTERNATIONAL INSURANCE PTE LTD
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	2



Passenger 1

NAME: :
GENDER: :


SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

27/05/19 (9.55am)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 25/5/2019 at around 1:35pm, my car SKL1618T collided with Comfort Taxi SHC 7910S at yellow box outside Jcube. At that moment, I was waiting for traffic on my right side to clear so that I can enter into the yellow box to go the Lane 3 while looking out traffic a yellow taxi SHC 7910S moved into the yellow box.

When it was cleared for me to proceed, I continued to turn left but the taxi suddenly stopped and my car bumped into his rear. There was a red car in front of him that had stopped/jam, braked suddenly so he also braked.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Signature of Driver/Policyholder

27/05/19 (9.55am)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	5462J

Vehicle Details

Vehicle No.:	SKL1618T
Vehicle to be Exported:	No
Intended Deregistration Date:	29 May 2019
Vehicle Make:	B.M.W.
Vehicle Model:	316i 1.6 AT D/AB 4DR ABS HID
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	B177J554N13B16A
Chassis No.:	WBA3A12010J721321
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$30,277.00
Original Registration Date:	27 Nov 2013
First Registration Date:	27 Nov 2013
Transfer Count:	0
Actual ARF Paid:	\$24,388.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Nov 2023
PARF Rebate Amount:	\$17,071.00

Intended COE Rebate Details

COE Expiry Date:	26 Nov 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$74,991.00
COE Rebate Amount:	\$33,702.00
Total Rebate Amount:	\$50,773.00

The information contained herein is correct as at 29 May 2019

OK

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 436180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 51313
Date Estimated : 27/05/2019
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Ong Hian Koon
33 Mount Sinai Rise
#24-08

Singapore 276954

- ACCOUNT -

66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL1618T	J721321	27/11/2013	316iA/4	0

DESCRIPTION

To replace front bumper & attachments, front center air duct top & bottom, cross link including to knock out dented area caused by the accident

To respray front bumper

To replace left headlight.

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

To supply front emboss number plate.

Sundries.

VALUE

✓ 1275 2,975.00

✓ 934 1,038.00

nn x 451? 481.00

✓ 150 177.00

✓ 61- 83.00

new ✓ ? 80.00

Total Labour 1: 4,834.00

DESCRIPTION

SHEET METAL NUT SELF-LOCKING RIVET

FRONT SHOCK ABSORBER

FRT BUMPER TOP MOUNT

INSERT AIR INTAKE CENTER

FRT BUMPER TRIM PRIMED (SRA)

SUPPORT CENTRAL

MOUNT FOR SUPPORT

FRT LH GRILLE (BASIS)

FRT RH GRILLE (BASIS)

LICENCE PLATE BASE (ECE)

GROMMET

FRONT PANEL V STRUT

FRT BUMPER LOWER MOUNT

FRONT CROSSLINK

AIR DUCT RADIATOR

AIR DUCT BOTTOM

PLAQUE 82MM

QTY	PRIC	VALUE
10	1.00	10.00
10	0.50	5.00
1	43.00	43.00
1	378.10	378.10
1	97.90	97.90
1	1,027.25	1,027.25
1	11.35	11.35
1	6.90	6.90
1	106.65	106.65
1	106.65	106.65
1	69.25	69.25
2	0.75	1.50
1	112.15	112.15
1	133.80	133.80
1	168.25	168.25
1	61.50	61.50
1	55.95	55.95
1	71.25	71.25

nn } X
nn } X
de } ✓
de } ✓
? } X
? } X
an } ✓
an } ✓
de } ✓
de } ✓
nn } X
nn } X
nn } ✓
nn } ✓

Performance Motors Limited

A Sime Darby Motors Company

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 51313
Date Estimated : 27/05/2019
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL1618T	J721321	27/11/2013	316iA/4	0

DESCRIPTION
LH HEADLIGHT (XENON)

QTY	PRIC	VALUE
1	2,119.70	2,119.70

Total Parts : 4,586.15

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
 Date & Time 29/5/19 11:30 Excess S\$ 1000
 Surveyor's Name Tanpin Sign [Signature]
 Surveyor's Tel 97445249 Authorised Yes/No
 Authorised Date 29/5/19 Time _____
 RESURVEY PARTS PHOTO BY SURVEYOR Yes/No PML Yes/No
 Surveyor's E-mail tanpin@kuanpin.com
 No. of Working Days Recommend 4-5 days

Labour 1	:	4,834.00
Parts	:	4,586.15
Labour 2	:	9420.15 0.00
Excess	:	0.00
Total GST @ 7%	:	659.41
Grand Total	:	10,079.56

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 51313
Date Estimated : 27/05/2019
Prepared By : Han Kwan Yong

Page No. : 3 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL1618T	J721321	27/11/2013	316iA/4	0

Terms & Conditions of Service

- All requests for servicing, repairs, replacements or installations to the Vehicle (collectively, "Repairs") are subject to acceptance by Performance Motors Limited ("PML") and PML shall have the absolute discretion to reject or deny any request for the Repairs.
- The list of the Repairs or quantum of charges for the Repairs printed overleaf are estimates only and PML shall be entitled to carry out additional repairs or replacements ("Additional Works") if, in its absolute discretion, Additional Works are necessary provided that, where the cost of additional Works exceed S\$250, PML shall obtain the customer's prior consent (whether given orally or otherwise) before carrying out the additional Works.
- Subject to clause 2 above and save in the case of manifest error or gross negligence, in the event where PML's estimation of the Repairs recommended for the Vehicle differs from the Customer's own estimation of repairs needed, PML's estimate shall prevail.
- The Vehicle accepted by PML for the Repairs shall remain, at all times, at the Customer's own risk while the Vehicle undergoes the Repairs at PML's premises. PML's visual inspection and record of the physical condition of the Vehicle made prior to the commencement of the Repairs shall be binding and conclusive as between PML and the Customer. The Customer shall ensure that all valuables are removed from the Vehicle prior to delivering it to PML for the Repairs. PML shall not be liable, in any way, for theft, fire, accident, loss of or damage to the Vehicle, its contents or accessories whatsoever.
- The Vehicle may be driven on the road if and when PML, in its absolute discretion, decides that it is necessary for the purposes of carrying out tests in connection with the Repairs. Should any damage occur to the Vehicle in such an instance, PML's liability will be limited to the rectification of damage, free of charge.
- PML's entire liability whether, in respect of faulty workmanship or otherwise, shall be limited to the rectification of any faulty workmanship or other faults, free of charge, such faults being reasonably determined by PML to have been caused by PML in the course of the Repairs. The Customer shall, nevertheless, be responsible for all costs for the disassembly, diagnosis, inspection of the Vehicle etc., at PML's current labour charge-out rate, necessarily incurred for the purpose of determining the cause of the fault(s) if it is found that the fault(s) is or are not caused by PML.
- Except as provided in clause 6 above, PML makes no warranty (whether expressed or implied) in respect of the Repairs and shall not, to the fullest extent permitted by law, be liable under any circumstances for special, consequential or incidental damages including but not limited to the loss of use of or depreciation in value of the Vehicle.
- Unless otherwise agreed by PML in writing, the Customer shall pay the costs of the Repairs owing to PML, in cash, upon the completion of the Repairs and before the Customer collects the Vehicle. In the event any credit is granted by PML at its absolute discretion, and the Customer fails to make payment of the costs of the Repairs (or any part thereof) by the agreed payment date, interest shall be imposed on the sum remaining unpaid at the rate of 1% per month (or part thereof) from the due date of payment until the date all payments are actually received by PML. PML reserves the right, at any time, to suspend or withdraw any credit facility granted to the Customer without assigning any reason whatsoever.
- The Customer shall collect the Vehicle within 48 hours from the date PML notifies the Customer, (whether orally or otherwise), that the Vehicle is ready for collection. In the event that the Customer fails to collect the Vehicle within 48 hours, the Customer shall, in addition to the costs of the Repairs owing to PML, pay all storage charges, at a rate to be determined by PML provided always that the Customer shall not, under any circumstances, hold PML liable for any loss of or damage to the Vehicle, its contents or accessories or for any deterioration in the quality of or damage to the Vehicle arising from such storage. In the event that the Customer fails to collect the Vehicle for more than 14 days, PML shall be entitled, at its absolute discretion, to dispose of the Vehicle & deduct, from the proceeds of disposal, PML's costs in connection with the disposal as well as all other monies owing to PML.
- If PML does not receive any notification of faulty workmanship from the Customer within 7 days from the date the Customer collects the Vehicle from PML, the Customer shall be deemed to have accepted the Repairs as satisfactory.
- If the Vehicle is sent to PML for the Repairs by any person other than the Customer, PML shall be entitled, without need to make any inquiry, to treat such third party as acting for and on the Customer's behalf. PML shall be entitled to rely on this ostensible authority to carry out the repairs in compliance with such third party's instructions and the Customer shall not hold PML liable for any loss or damage suffered by the Customer as a result and shall pay for the costs of the Repairs owing to PML and further indemnify PML against all claims, losses, expenses, damages suffered or incurred by PML arising from PML's reliance on such authority and/or compliance with such instructions.
- PML may, in its absolute discretion and upon the Customer's request, provide a driver to deliver the Vehicle from the Customer to PML's premises or vice versa provided always that the driver shall, during the time of such conveyance of the Vehicle, be deemed to be the servant of the Customer and not that of PML's and the Customer shall not hold PML liable for any accident, loss of or damage to the Vehicle or its contents or accessories while the same is under the custody of the driver.
- These Terms & Conditions of Service including all annexes and attachments hereto contains the entire agreement between PML and the Customer with respect to the Services described in the Repair Order and supersedes all previous agreements and understandings between PML and the Customer relating to the subject matter herein. No amendments or changes to these Terms & Conditions of Service shall be effective unless made in writing and signed by authorized representatives of both PML and the Customer.
- If any term or provision of these Terms & Conditions of Service shall be held to be invalid, illegal or unenforceable, the remaining terms and provisions of these Terms & Conditions of Service not affected by such invalidity, illegality or unenforceability shall remain in force and effect.

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 51313
Date Estimated : 27/05/2019
Prepared By : Han Kwan Yong

Page No. : 4 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL1618T	J721321	27/11/2013	316iA/4	0

15. A person not party to these Terms & Conditions of Service shall have no right under any legislation for the enforcement of contractual terms by a third party (whether in force now or to be enacted in the future and as the same may be modified, adapted or supplemented from time to time) to enforce any term in these Terms & Conditions of Service.
16. The laws of the Republic of Singapore shall govern the validity and interpretation of these Terms & Conditions of Service and the Parties submit to the exclusive jurisdiction of the Courts of the Republic of Singapore.
17. The Sime Darby Motors Group companies in Singapore are committed to ensuring that your personal data is protected. The purpose of this document is to explain how we collect information about you, the procedures that we have in place to safeguard your privacy and how you can instruct us if you prefer to limit the use of that information.
- 17.1 The Vendor shall collect and use the Customer's personal data for any of the following purposes, including but not limited to:
- (a) the registration of the Vehicle with the relevant transportation authorities, including but not limited to Land Transport Authority;
 - (b) sharing of the Customer's personal data with the Vendor's principal, its related corporations and contractors, whether within Singapore or overseas, and/or insurance companies, so as to provide the necessary warranties and/or extended warranties for the Vehicle to the Customer;
 - (c) sharing of the Customer's personal data with financial institutions and motor vehicle insurers, on the Customer's behalf, in order for the Customer to obtain financing for the purchase of the Vehicle and the motor insurance on the Vehicle and when necessary, to obtain the loan amounts outstanding from financial institutions, on the Customer's behalf so as to assist the Customer in effecting the Vehicle loan redemptions;
 - (d) servicing of Vehicle and to update the Vendor's after-sales service records. The relevant personal data shall be used by the Vendor, its appointed after-sales service dealers, agents and sub-contractors and/or the Vendor's principal and/or its related corporations whether within or outside Singapore to provide the relevant after-sales service and/or to repair the Vehicle and to communicate with the Customer on any matter relating to the provision of the services in general including to notify the Customer by any means, including by short message services ("SMS") of the next/ subsequent date/mileage for routine service for the Vehicle;
 - (e) administrative, research and analysis purposes to enable it to monitor and improve the services it provides; and
 - (f) organizing events for the Customer, to inform the Customer of such events by any means (including through SMS, multi-media services ("MMS"), phone call, fax, magazines, or brochures) any new products, promotions or services provided by the Vendor in Singapore.
- 17.2 The Vendor shall also disclose the Customer's personal data:
- (a) to its service providers, for example, providers of web hosting or maintenance services, for the purpose of supplying itself with the inter connected servers and/or web site links with the relevant authorities;
 - (b) to its customer service agencies whether within or outside Singapore for administrative, research and analysis purposes to enable it to monitor and improve the services it provides;
 - (c) to the Vendor's service providers and/or the Vendor's principal, its related corporations and contractors whether within or outside Singapore for the purpose of organizing events for the Customer, to inform the Customer of and send to the Customer by any means (including through SMS, MMS, phone call, fax, magazine or brochures) any new products or promotions or services that are provided by the Vendor and/or the Vendor's principal whether within or outside Singapore;
 - (d) to the Vendor's business partners for the purpose of carrying out product promotions;
 - (e) to the Vendor's stakeholders and the Vendor's principal and its/their related corporations and contractors for the purpose of carrying out audits;
 - (f) to the Vendor's principal and/or the Vendor's stakeholders and their respective related corporations and contractors whether within or outside Singapore for the purposes of carrying out audits; and
 - (g) to the Vendor's principal and its related corporations whether located within or outside Singapore for the purpose of responding to any of the Customer's enquiries.
- 17.3 The Vendor shall retain the Customer's personal data either for the period of the business relationship or, for the requisite retention periods as stipulated in any contractual arrangements or under any applicable law, whichever is later.
- 17.4 If the Vendor amends any provision in this clause 17, it will notify the Customer via e-mail and may place notices on the Vendor's web site. The Vendor's email to the Customer shall require the Customer's consent to its change of use of the Customer's personal data. Continued use of the Vendor's services shall signify the Customer's agreement to any such changes.
- 17.5 The personal data the Customer provides may be transferred to the Vendor's principal within or outside Singapore for surveys and research purposes conducted with the objective of enhancing the Customer's satisfaction.
- 17.6 The Customer shall have a right to request a copy of the personal data the Vendor holds about the Customer and information about the ways in which the Customer's personal data has been or may have been used or disclosed within a year before the date the Customer's request. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing and indicate whether he would like to have a copy of his personal data or he wishes to have information about the ways in which his personal data is used or disclosed during the past year or both;
 - (b) include proof of his identity and address (e.g. a copy of the Customer's driving licence and a recent credit card bill); and
 - (c) specify the personal data he wants access to, including any account or reference numbers where applicable.

The Vendor shall reply to the Customer as soon as reasonably possible upon its receipt of the Customer's request.

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 51313**
Date Estimated : **27/05/2019**
Prepared By : **Han Kwan Yong**

Page No. : **5 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL1618T	J721321	27/11/2013	316iA/4	0

- 17.7 The Customer shall pay an amount to access his personal data in the manner stated in Clause 17.6(a) above.
- 17.8 The Customer shall have the right to correct any inaccuracies in his personal data free of charge. If the Customer wishes to exercise this right, the Customer shall:
- (a) put his request in writing;
 - (b) provide the Vendor with enough information to identify himself (e.g. the Customer's account number, username, registration details); and
 - (c) specify the information that is incorrect and what it should be replaced with.
- The Vendor shall reply to the Customer as soon as practicable upon its receipt of the Customer's request.
- 17.9 The Customer's access or correction request will not be granted as of right; the Vendor's ability to accede to the Customer's access or correction request is subjected to the prohibitions and exceptions set out or which may be set out in the Singapore Personal Data Protection Act ("PDPA") and its accompanying regulations.
- 17.10 The Customer shall have the right to ask the Vendor to stop collecting, using or disclosing his personal data for any of the abovementioned purposes set out in Clauses 17.1 and 17.2. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing by way of an email sent to the Vendor;
 - (b) provide the Vendor with his name, NRIC number, mobile number, email and Vehicle registration number to identify the Customer; and
 - (c) if the Customer's objection is not to direct marketing in general, but to direct marketing by a particular channel (e.g. voice call, SMS, MMS, fax, mailers or email), the Customer has to specify the channel he is withdrawing his consent to.
- 17.11 In the event that the Customer withdraws consent to the collection, use or disclosure of his personal data such that it materially affects this Agreement and it renders the Vendor unable to, or such that it becomes difficult for the Vendor to perform or properly perform or discharge its obligations under this Agreement, at law, under the warranty undertakings, or its role as a responsible dealer of BMW vehicles, the Vendor may at its discretion, be entitled to terminate this Agreement with the Customer.
- 17.12 The obtaining the Customer's consent for the collection, use or disclosure of his personal data under this clause 17 is subject to the exceptions set out or which may be set out in the PDPA.
- 17.13 The Customer shall address all communications pertaining to this Clause 17 to:

The Data Protection Officer
Performance Motors Limited

Address:
Sime Darby Performance Centre
303 Alexandra Road
Singapore 159941

Email address:
dataprotection@pml.com.sg

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 51313
Date Estimated : 27/05/2019
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Ong Hian Koon
33 Mount Sinai Rise
#24-08

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 276954

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SML7216G	J721321	27/11/2013	316iA/4	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments, intake center air intake include knocking out dents caused by the accident	1275.00		1,275.00	
To respray front bumper	934.00		934.00	
To check electrical wiring systems at the front section for proper function	150.00		150.00	
To supply front emboss number plate	83.00		83.00	
Sundries	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
INSERT AIR INTAKE CENTER	97.90	1.00		97.90
FRT BUMPER TRIM PRIMED (SRA)	1,027.25	1.00		1,027.25
FRT LH GRILLE (BASIS)	106.65	1.00		106.65
FRT RH GRILLE (BASIS)	106.65	1.00		106.65
LICENCE PLATE BASE (ECE)	69.25	1.00		69.25
PLAQUE 82MM	71.25	1.00		71.25

SUPPLEMENTARY ITEMS

Total Labour :	2,522.00
Total Parts :	1,478.95
Total Labour & Parts :	4,000.95
Deduction for Excess :	1,000.00
Total Repair Costs less Excess:	3,000.95
GST @7%:	210.07
Grand Total :	3,211.02

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 18 June 2019 3:31 PM
To: PBSP; SUR; Keith Leo Chi Yung
Subject: RE: FINAL REPORT/ SKL1618T (NEW PLATE SML7216G)

Dear Caroline,

Confirmed amount \$4,000.95 before excess \$1000

Repair days: 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Monday, 17 June 2019 4:52 PM
To: PBSP <pml-pbsp@simedarby.com.sg>; SUR <sur@lkkauto.com>; Keith Leo Chi Yung <keith.leo.chiyung@simedarby.com.sg>
Subject: FW: FINAL REPORT/ SKL1618T (NEW PLATE SML7216G)

Dear Caroline,

Kindly forward us check items and before paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Monday, 17 June 2019 4:43 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT/ SKL1618T (NEW PLATE SML7216G)

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,522.00

Total Parts : 1,478.95

Total Labour & Parts : 4,000.95

Repair days: 4

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 May 2019		28 May 2019 09:46 Edit Adj Rpt	S\$4,000.95 Edit Estimates	S\$4,000.95 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: ONG HIAN KOON , ID: S6825462J, Tel: +6596169358	Date of Loss: 25/05/2019 13:00 - :59 [65 Months and 28 Days From LTA Reg Date (Man Yr)]
Vehicle Reg. No.: SKL1618T	Policy/Cover Note No.: B27617311SMP (Comprehensive) Coverage: 27/11/2018 - 26/11/2019
Claim Type: OD / 594714	Excess: S\$1,000.00
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174	
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 27/06/2019]	
Driver/Custodian: TEO WAN CHUAN (47 / Female), NRIC: S7215143G, Tel: +6596939089 Email: KELLY.TEO123@YAHOO.COM.SG	
Adj Asg. Remarks: Car in on 28/05/2019 10AM. Survey & revert. Please contact us ASAP if you cannot attend this assignment.	

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)



































- MSIG_SG (18/06/2019): Alert - Adj Mandate Approved (S\$4000.95) - SKL1618T - Claim Handler: Jocelyn Ng ...
- MSIG_SG (29/05/2019): Alert - Adj Mandate Approved (S\$3732.90) - SKL1618T - Claim Handler: Jocelyn Ng ...







ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									














Claim Documents

***SKL1618T (594714)**
OD
May 25 2019 1:00PM
[ONG HIAN KOON]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼	
Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	27/05/19 14:25	Accident Statement	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/05/19 16:11	Adjuster Immediate Advice	 Load HTM	
2	18/06/19 10:35	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
2	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
3	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
4	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
5	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
6	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
7	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
8	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
9	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
10	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
11	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
12	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
13	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
14	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
15	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
16	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
17	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
18	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
19	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
20	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
21	18/06/19 10:24	General View	 Load JPG	<input checked="" type="checkbox"/>
22	18/06/19 10:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
23	18/06/19 10:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
24	18/06/19 10:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
25	18/06/19 10:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	18/06/19 10:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	18/06/19 10:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	18/06/19 10:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	18/06/19 10:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	18/06/19 10:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	18/06/19 10:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
Documentation			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/05/19 16:59	PARF COE	 Load PDF	
2	27/05/19 16:59	Transfer Fee Details	 Load PDF	
3	27/05/19 17:01	Estimate Repair Cost + GIA Report + CI + IC (OID) + IC (OI) + DL (OID)	 Load PDF	
4	27/05/19 17:01	TP GIA Report - SHC7910S	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/05/19 17:22	MARK ESTIMATE	 Load PDF	
2	18/06/19 10:29	MARKING	 Load PDF	

Linked Accident Report Documents

			View	View In Browser ▾
Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	27/05/19 14:25	Accident Statement	 Load HTM	
Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	27/05/19 13:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	27/05/19 13:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	27/05/19 13:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	27/05/19 13:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	27/05/19 13:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	27/05/19 13:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	27/05/19 13:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	27/05/19 13:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	27/05/19 13:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	27/05/19 13:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	27/05/19 13:33	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	27/05/19 13:32	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19009344/T1VD3S2

Date: 21/06/2019

REFERENCE

Insured/Claimant:	ONG HIAN KOON	Policy No:	B27617311SMP	
Date of Loss:	25/05/2019	Nature of Claim:	OD	Claim No: 594714

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL1618T	Engine No:	B177J554N13B16A
Make & Model:	BMW 316I, 1.6 AT D/AB 4DR ABS HID (A)	Chassis No:	WBA3A12010J721321
Reg. Date:	27/11/2013 (Man. Year: 2013)	Odometer:	35237 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$68,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,749.15	1,641.95	3,107.20	65.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,671.00	2,359.00	2,312.00	49.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,420.15	4,000.95	5,419.20	57.53
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	8,420.15	3,000.95	5,419.20	64.36
+ GST 7.00/7.00% (S\$)	589.41	210.07	379.34	64.36
Nett Amount (S\$)	9,009.56	3,211.02	5,798.54	64.36

INSPECTION

Date of Assignment:	28/05/2019	
Date Inspected:	29/05/2019 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Jun 2019)

Parts: 143 BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKL1618T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	10		*SHEET METAL NUT SLF-LOCKING	Not Necessary	10.00 FS	*- FS
2	10		*RIVET	Not Necessary	5.00 FS	*- FS
3	1		*FRONT SHOCK ABSORBER	Not Necessary	43.00 FS	*- FS
4	1		*FRT BUMPER TOP MOUNT	Not Necessary	378.10 FS	*- FS
5	1		*INSERT AIR INTAKE CENTER	Deformed	97.90 FS	*97.90 FS
6	1		*FRT BUMPER TRIM PRIMED (SRA)	Deformed	1,027.25 FS	*1,027.25 FS
7	1		*SUPPORT CENTRAL	Not Necessary	11.35 FS	*- FS
8	1		*MOUNT FOR SUPPORT	Not Necessary	6.90 FS	*- FS
9	1		*FRT LH GRILLE (BASIS)	Cracked	106.65 FS	*106.65 FS
10	1		*FRT RH GRILLE (BASIS)	Cracked	106.65 FS	*106.65 FS
11	1		*LICENCE PLATE BASE (ECE)	Deformed	69.25 FS	*69.25 FS
12	2		*GROMMET	Not Necessary	1.50 FS	*- FS
13	1		*FRONT PANEL V STRUT	Not Necessary	112.15 FS	*- FS
14	1		*FRT BUMPER LOWER MOUNT	Not Necessary	133.80 FS	*- FS
15	1		*FRONT CROSSLINK	Not Necessary	168.25 FS	*- FS
16	1		*AIR DUCT RADIATOR	Not Necessary	61.50 FS	*- FS
17	1		*AIR DUCT BOTTOM	Not Necessary	55.95 FS	*- FS
18	1		*PLAQUE 82MM	Necessary	71.25 FS	*71.25 FS
19	1		*LH HEADLIGHT (XENON)	Not Necessary	2,119.70 FS	*- FS
20	1		*FRONT EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
21	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	4,749.15	1,641.95
--------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER & ATTACHMENTS, FRONT CARRIER AIR DUCT TOP & BOTTOM, CROSS LINK INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT.	New	2,975.00	1,275.00
2	TO RESPRAY FRONT BUMPER.	New	1,038.00	934.00
3	TO REPLACE LEFT HEADLIGHT.	New	481.00	0.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS.	New	177.00	150.00
Gross Labour Cost (S\$)			4,671.00	2,359.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >