

ASS. REC. BY:

REF: CSKMD19009347 / Nvd302

Special Instruction:

Survivor: NAZ

## ASSIGNMENT (Office)

From (Person): Thuma Choo

of SMD

Date/Time: 24.5.2019 10.39am

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 2858T

Insured: Ym 9258A

at Workshop m/s Comfortdigo

Tel: 96355305

of 59 Louang Driv

Policy No: D18MTRVE003224

Claim No: CMTD1902494

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22.5.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 28.5.19 11.30am

Person Contacted:

Junwin

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 2858T - CC4 / AIG 091002346 / 2001

DOA - 17/00/2009

Ym 9258A - 1

28/5/19

Send preli revised via merimen

10/11/19

Surveyor:

NAL

REF:

Sampo

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

X	
N/S	O/S

Est. or Market Value: \_\_\_\_\_

WAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GLA / PR Score: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % J Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: \_\_\_\_\_

SH C 2858 T

Yr Regn: 11 DEC 18

Type: M.Car / M.Cycle / BUS / Van / Lorry (Taxi) Prime Mover /

Truck / Troller or

Make: \_\_\_\_\_

14WDA1 10N/Q co. 1 580

Colour: \_\_\_\_\_

BLUE

A/C: (Insured) d/Std / NI / NA

Sp. Reading \_\_\_\_\_

51, 268

T/Radio: (Insured) d/Std / NI / NA

Eng/No: \_\_\_\_\_

C/N: \_\_\_\_\_

10MHC851 CV KU 122245

Gen. Cond: Good / Fair / Poor / Burnt

Steering: (Inorder) Jammed / Leaked / Burnt or

Brake: (Inorder) Jammed / Leaked / Burnt or

Mod: Nil / SIRIm / (STD) A/RIm or

Tyre Size: F: \_\_\_\_\_

195 / 65 R15

R: \_\_\_\_\_

11

BS / DUN / EXNOVA / GY / FS / LIZA (MIC) OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. \_\_\_\_\_

5 mm

R/Bal. \_\_\_\_\_

5 mm

L/Bal. \_\_\_\_\_

5 mm

L/Bal. \_\_\_\_\_

5 mm

D.O.A. 22/5/19

D.O.A. 24/5/19

Survey held at

COKE LUYANG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT N/S

The U/C / Chassis frame / Body Structure affected due to collision

PIP

Date / Time	Action / Instruction
17/6/19	FINALIZED PART BY PART REPAIR \$2,150.48 / 3 REPAIR DAYS
	(Red 398, 1619)
	RECEIVED: 1 JUN 2019
	20/6/2019

Date/Time, File Pass to?

☐

: Prelim Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 21/6- typist

Report Format:

Merimen

Lump Sum / L.B. / L.S.

2150.48

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

)

☐

: Interview (\$

)

☐

: Tech. Invs (\$

)

☐

: Weekend (\$

)

Photos

Others

TOTAL

250
11
261

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Thelma Choo

Date: 28 May 2019

## Preliminary Advice

Insured Vehicle No	: YM9258A	Accident Date	: 22/05/2019
TP Vehicle No	: SHC2858T	Assignment Date	: 24/05/2019
Make	: HYUNDAI IONIQ HYBRID	Est. Duration of Repair	: 3
Date of Inspection	: 24/5/2019		
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,461.68
Revised Amount	:S\$	2081.28
Check Items (Estimated)	:S\$	50.40
Total	:S\$	2,131.68

Lump Sum Repair	:S\$	
-----------------	------	--

### Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

### Remarks

( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments :The above survey was conducted on a 'Without Prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 May 2019		24 May 2019 10:33 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	PERFECT PACKAGING PTE LTD, Co. Reg. No.: 2004018122								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHC2858T	Date of Loss:	22/05/2019 16:00 - 59						
Claim Type:	TP / CMTD1902494	Policy/Cover Note No.:	D18MTPCVE003224 (Comprehensive)						
Vehicle Reg. No. (Insured):	YM9258A	Policy No. (Claimant):							
		Excess:							
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Sampo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by <b>Thelma Choo</b> - 6322 4661]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Final Rpt due 04/06/2019]</b>								
Adj Asg. Remarks:	WS: JUMANI BIN MASUDIN 62148315 / 96355305 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT								
<b>ASSOCIATED MAIL RECEIVED</b>		View All   Compose Case Mail							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		View All   Search Tasks   Create New Task   Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Friday, 21 June 2019 9:03 AM  
**To:** Jumani Bin Masudin; Naz (LKKAuto)  
**Cc:** SUR  
**Subject:** RE: DOA.22.05.19 SHC2858T - FINALIZATION

Dear Jumani,

Amount should be part by part **\$2150.48** and 3 days repair.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Jumani Bin Masudin <jumanibm@cdge.com.sg>  
**Sent:** Thursday, 20 June 2019 6:21 PM  
**To:** Naz (LKKAuto) <Naz@lkkauto.com>  
**Subject:** Re: DOA.22.05.19 SHC2858T - FINALIZATION

Hi Naz

Please confirm COR part by part \$2150.40 and 3 days repair

Best Regards

**Jumani Masudin**

Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd  
Tel. 6214-8315 / Fax. 6546-8156

---

**From:** Naz (LKKAuto) <Naz@lkkauto.com>  
**Sent:** Thursday, 20 June 2019 1:07 PM  
**To:** Jumani Bin Masudin

Cc: Veron Chen (LKKAuto); SUR  
Subject: Re: DOA.22.05.19 SHC2858T - FINALIZATION

Dear Mr Jumarni,

Agreeable with new finalization amount.

Thank you.

Best Regards,

**Naz** | Technical Investigator

**LKK Auto Consultants**

Phone: 6841-2157 | Email: [Naz@lkkauto.com](mailto:Naz@lkkauto.com) | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Jumani Bin Masudin <[jumanibm@cde.com.sg](mailto:jumanibm@cde.com.sg)>

**Sent:** Tuesday, 28 May 2019 12:41 PM

**To:** Naz (LKKAuto)

**Subject:** DOA.22.05.19 SHC2858T - FINALIZATION

HI NAZ

Please expedite by this month (May)

COR part by part 2064.19 and 3 days repair

Supplementary item :Frt bumper centre moulding \$108.50

Photo with Kalvin camera.

Best Regards

**Jumani Masudin**

Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd

Tel. 6214-8315 / Fax. 6546-8156

---

**From:** ApeosPort-IV C5570 <[sbs-singnalling@sbstransit.com.sg](mailto:sbs-singnalling@sbstransit.com.sg)>

**Sent:** Tuesday, 28 May 2019 12:26 PM

**To:** Jumani Bin Masudin

**Subject:** Scan Data from CDG\_LO\_AW\_A5570

Number of Images: 2  
Attachment File Type: PDF

Device Name: ApeosPort-IV C5570  
Device Location:

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

SBS Transit Ltd [Registration No. 199206653M]

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

---

**Veron Chen (LKKAUTO)**

---

**From:** Naz (LKKAUTO)  
**Sent:** Thursday, 20 June 2019 1:07 PM  
**To:** Juman Bin Masudin  
**Cc:** Veron Chen (LKKAUTO); SUR  
**Subject:** Re: DOA.22.05.19 SHC2858T - FINALIZATION

Dear Mr Juman Bin,

Agreeable with new finalization amount.

Thank you.

Best Regards,

**Naz** | Technical Investigator

**LKK Auto Consultants**

Phone: 6841-2157 | Email: [Naz@lkkauto.com](mailto:Naz@lkkauto.com) | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Juman Bin Masudin <jumanibm@cdge.com.sg>  
**Sent:** Tuesday, 28 May 2019 12:41 PM  
**To:** Naz (LKKAUTO)  
**Subject:** DOA.22.05.19 SHC2858T - FINALIZATION

HI NAZ

Please expedite by this month (May)  
COR part by part 2064.19 and 3 days repair

Supplementary item :Frt bumper centre moulding \$108.50  
Photo with Calvin camera.

Best Regards  
**Jumani Masudin**



---

**From:** ApeosPort-IV C5570 <sbs-singnalling@sbstransit.com.sg>  
**Sent:** Tuesday, 28 May 2019 12:26 PM  
**To:** Juman Bin Masudin  
**Subject:** Scan Data from CDG\_LO\_AW\_A5570

Number of Images: 2  
Attachment File Type: PDF

Device Name: ApeosPort-IV C5570  
Device Location:

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

SBS Transit Ltd [Registration No. 199206653M]

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/05/2019 14:05
Date Of Accident	22/05/2019 16:15
Exact Location Of Accident	SIM MING ROAD T JUNCTION UPP THOMSON RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC2858T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	IONIQ HYBRID

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	NG BOON AIK
NRIC No	S0856495G
Date Of Birth	09/06/1954
Occupation	OUTDOOR
Date Of Driving Pass	20/09/1975
Driving Experience	43 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97397552
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 561 WOODLANDS RING ROAD #10-152
Postcode	730661
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO ATTACHED / Type Of Accident : HEAD TO SIDE

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM9258A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	SOMPO INSURANCE SINGAPORE PTE. LTD.
Nature Of Damage	RIGHT FRT
No. Of Passenger (Including Driver)	

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

(Updated Sketch Plan Form, 2013)



SKETCH PLAN



Along Sin Ming Road T Junction Upp Thomson Road  
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22.05.2019 at about 16:15 hours I was travelling along Sin Ming Road T Junction Upp
Thomson Road with no passenger onboard .
While making a right turn suddenly Veh B ( YM 9258A ) dash out from my left and collided
into my taxi A - Front Left Portion .
As it took place too fast I could not take evasive action to prevent the accident
I have company photo and videos at scene to support my claims .
No injury in this accident .
Veh B ( YM 9258A ) - Male Driver

DECLARATION


I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 23.05.2019  
@ 12:00 hrs

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:







**\*REPAIR ESTIMATE\***

VEHICLE NO : SHC 2858T

DATE 23/5/2019 15:10

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 418.30
	Front Bumper Bracket Top (RH)			\$ 35.00
	Front Bumper Bracket (RH)			\$ 28.00
	Front Bumper Clips 10 pcs			\$ 22.00
	Headlamp (RH)			\$ 1,198.80
	<b>SUB TOTAL</b>			<b>\$ 1,702.10</b>
	<b>LESS 20%</b>			<b>\$ 340.42</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,361.68</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	<b>TOTAL LABOUR</b>			<b>\$ 1,100.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,461.68</b>
				2548.48

24/5/19 1500  
PIC  
3 DAYS  
CHECK ITEMS & HOTOS  
BEFORE PAINT & HOTOS

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



Team: ARC Repair TP(CLS0)1

## JOB CARD

Sales Order:


JO NO: 305297754

TOMER:	REGN NO.	SHC2858T	MILEAGE
MS	MAKE	HYUNDAI	FUEL
TOMER NO	MODEL	IONIQ(G2)	DATE/TIME IN
RESS:	YR OF MANU	11.12.2018	TARGET DATE
(R)	CHASSIS CODE	KMHC851CVKU122245	COMPLETION DATE/TIME
(P)			

Accident Date: 22.05.2019  
NATURE: 3P 22.05.19

## JOB DESCRIPTION

S/NO      LABOR CODE      DESCRIPTION



BOOKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No. SHC2858T      JU SOMPO

Vehicle No. SHC2858T

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

Date: 19.06.2019

REPAIR ESTIMATE

Time: 15:18:05

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305297754  
REGN NO : SHC2858T  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G2)  
DATE OF REGN : 11.12.2018  
DATE/TIME IN : 23.05.2019 10:40  
ACCIDENT DATE : 22.05.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2534-G	IONIQV2 COVER-FR BUMPER#	1	418.30	20.00	334.64	✓	CRK
0002 04-01-0104-2815-G	IONIQVC LAMP ASSY-HEAD LH	1	1,198.80	20.00	959.04	✓	SLR
0003 04-01-0104-2361-G	IONIQ MOULDING-FRONT BUMP	1	108.50	20.00	86.80	✓	SLR (A)

SUB-TOTAL : 1,380.48

JOB NATURE

0000 PB	PANEL BEATING	300.00
0001 SP	SPRAYPAINT CHARGE	400.00
0002 17-01	CHECK ALL LIGHTING	30.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	40.00

SUB-TOTAL : 770.00

TOTAL : 2,150.48

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

# COMFORTDELGRO ENGINEERING

Our Job Ref No 305297754

Date : 28/05/2019

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :


Attn : NAZ


: SHC2858T

Date of Accident : 22/05/2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: SOMPO --- YM9258A  
###
2. The finalized amount shall be:
  - (a) Spare Parts after List discount 1380.48
  - (b) Labour Charges ### \$770.00  
**Total for Part-By-Part Repair Cost** 2150.48
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20%  
**Final Lumpsum Repair cost** \_\_\_\_\_
3. Estimated normal period for repairs: 3 working days
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature :   
Name : JUMANI  
Tel : 6214 8315  
Fax : 65468156

Signature :   
Name : NAZ LKK  
Date : 17/6/19

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day	1251.91	YES		
2. Loss of Income Paid	400.00	N		
3. Survey Fees		✓		
4. LTA Search Fee	\$7.48	Yes		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

photo

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19009347/NVD3N2

Date: 24/06/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE003224
Claimant Vehicle No :	SHC2858T	Insured Vehicle No :	YM9258A
Date of Loss:	22/05/2019	Nature of Claim:	TP
		Claim No:	CMTD1902494

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHC2858T	Engine No:	G4LEJU133533
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU122245
Reg. Date:	11/12/2018 (Man. Year: 2018)	Odometer:	51768 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,448.48	1,380.48	68.00	4.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	770.00	330.00	30.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>2,548.48</b>	<b>2,150.48</b>	<b>398.00</b>	<b>15.62</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>178.39</b>	<b>150.53</b>	<b>27.86</b>	<b>15.62</b>
<b>Nett Amount (\$\$)</b>	<b>2,726.87</b>	<b>2,301.01</b>	<b>425.86</b>	<b>15.62</b>

## INSPECTION

Date of Assignment:	24/05/2019	
Date Inspected:	24/05/2019	Inspected At:
		ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

Adjuster: Muhammad Nazri Bin Abdullah

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jun 2019)
<b>Parts:</b>	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC2858T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Cracked	418.30 FL	*418.30 FL
2	1		*FRONT BUMPER BRACKET TOP (RH)	Serviceable	35.00 FL	*- FL
3	1		*FRONT BUMPER BRACKET (RH)	Serviceable	28.00 FL	*- FL
4	10		*FRONT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
5	1		*HEADLAMP (RH)	Scratched	1,198.80 FL	*1,198.80 FL
6	1		*IONIQ MOULDING-FRONT BUMP	Scratched	108.50 FL	*108.50 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>1,810.60</b>	<b>1,725.60</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>362.12</b>	<b>345.12</b>
<b>Total Parts (S\$)</b>	<b>1,448.48</b>	<b>1,380.48</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	400.00	300.00
2	SPRAY PAINTING CHARGE	New	600.00	400.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,100.00</b>	<b>770.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >