

ASS. REC. BY:

REF: CS3/MSG19007705/1903-07

Special Instructions:

Survey: N/A

ASSIGNMENT (Office)

From (Person): Monica Chung Rizlan of MS24

Date/Time: 27/05/2019

Estimated Cost:

Bill to:

OD: TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: GBC 8186E

Insured: WD 20682

at Workshop m/s Blumel Automotive

Tel: 67452088

of 1 Kali Bukit Ave 6, #01-28

Policy No: B29077583 TMV

Claim No: 592101

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 29.4.2019

3.5.2019

CA / REV / REP. / REV 24 HRS

Pap

H.O.D. Endorsement:

Date/Time: 2.5.19

2.42p.m

Person Contacted:

Sally

Vehicle IN/OUT

Date/Time	Action/Instruction
	3/5/19 (X)
	GBC 8186E - WA 3/5/19 1/13
	WD 20682 - WA 3/5/19 1/13
	Diagnosed 3/5/2019
	After repair 7/5/2019

3/5/19 Sumul 4/5 4/50 4/5  
 (Red to 1750, 73%)

Do Not Finalise

RECEIVED 30 MAY 2019

REF: MS19

PRs

## ASSIGNMENT

Form

Date 3-5-2019

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBC 8186E

at Workshop no: Blawie Automotive  
of 1 Kaki Bukit Ave 6 # 01-23

Insured:

Policy No.

Claims No.


Sum Insured

Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection

Bal. or Market Value

IDAC Accident Report

Consistent? Yes or No

GIA / FR Seen

Consistent? Yes or No

Est. Repairs:

4 days Rep. Yes or No

Lump Sum:

3 Vtd Yes or No

CA / REV / REP. / 24 HRS

"wp"

Vehicle: IN / OUT

Date:

Person Contacted:

Vehicle: GBC8186E Yr Rem 1 / 13

Type: M/C / H/C / Jc / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make:

Nissan NV350 cc 2488

Colour:

white Insured / Std / Nil / N/A

Sp. Release:

203526 (Rear) Insured / Std / Nil / N/A

Engine:

C/No:

JN1MC2E26X0001395

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Locked / Jammed / Leaked / Burnt or

Brake: Locked / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size:

F: 185 R15

R:

BS / TAN / EXNOVA / GY / ES / LZA / MIC / OHTSU / PIR / SUM /

TOYO / YOKO

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A

29/4/19

D.O.I

3/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / W/S / UIC / Rooltop or

At o/s.

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

No repair.

3-4/19.

RECEIVED 6 5 2019

Date/Time, File Pass in:

☐

: Prelim. Report

1)

☐

: Final Report

Date/Time, File Return in:

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:

☐

Site Map (\$

☐

In/Travel (\$

☐

In/Travel (\$

☐

In/Travel (\$

Survey For:

Transportation

1) S + RS 5

2) Photo

3) Video

4) Other

TOTAL

Report Format

PRE

Lump Sum / I.B.L. (\$)

120
10
130

## Nivitha (LKK Auto)

---

**From:** Accounts (LKKAuto) <account@lkkauto.com>  
**Sent:** Monday, 27 May 2019 9:49 AM  
**To:** Admin-D (LKKAuto)  
**Cc:** assignments; Accounts (LKKAuto)  
**Subject:** Report Send Back Alerts - GBC8186E (TP)

Dear Nivitha / Summer,

FYNA Please..

**- Pending for Survey Report-CS3/MSG19007705/UCD3E2**

20 27 May 2019 08:52	<b>Ins Send Back Adj Rpt</b>	Paper adjustment	[1] Monica Chung Pei Zhen
21 27 May 2019 08:52	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2019/05/29	[1] Merimen Administrator
22 27 May 2019 08:52	<b>Adj Mandate Set</b>	Maintained.	[1] Merimen Administrator

Thank You

Best Regards,

SuthaShelia (Shelia) | Accounts Dept.

LKK Auto Consultants Pte Ltd

Phone: 6841 1891 | email: [account@lkkauto.com](mailto:account@lkkauto.com) | fax: 6844-8805

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Do-Not-Reply [mailto:do-not-reply@merimen.com]  
**Sent:** Monday, 27 May 2019 9:00 AM  
**To:** account@lkkauto.com  
**Subject:** Report Send Back Alerts - GBC8186E (TP)

Dear Sir / Madam,

Please login to Merimen Online at [www.merimen.com.sg](http://www.merimen.com.sg) for more information.

Thanks,  
The Merimen Team



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)



# BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28  
(Unit C) #01-51/53/55 Singapore 417883  
Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088  
Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg  
Co. Reg. No.: 200704951N  
GST Reg. No.: 200704951N

Vehicle No : GBC 8186 E Date : 14-May-19  
Make/Model : Nissan NV350 Urvan  
Name : M/S The Green Box  
Address : c/o No.1 Kaki Bukit Ave 6  
#01-53/55 AutoBay@ Kaki Bukit  
Singapore 417883

QTY	ITEM	AMT (\$)
-----	------	----------

Lump sum repair costs	\$	5,400.00
GST 7 %	\$	378.00
Grand-total	\$	5,778.00

Dollars : Five Thousand Seven Hundred And Seventy Eight Only

# MC-COY

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-23 AutoBay @ Kaki Bukit Singapore 417883  
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Invoice No. 19006-05/AY

Date 14 May 2019

Billing Name & Address

M/S The Green Box  
c/o No.1 Kaki Bukit Ave 6  
#01-53/55 AutoBay@ Kaki Bukit  
Singapore 417883

Vehicle No : GBC 8186 E

Model : Nissan NV350 Urvan

Item	Descriptions	Amount S\$
1	Date of inspection : <u>3 May 2019</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Develop photographs - Storage of digital photographs - Submission of photographs <u>84</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 644.00</u>
	SDLS : SIX HUNDRED AND FORTY-FOUR ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Mc-Coy Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O E



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883  
Tel: 6743 6653 Fax: 67471017 Registration No: 200723252D

Report Reference : TP / 19006-05/AY / 2019  
Date of Report : 14 May 2019

M/S The Green Box  
c/o No.1 Kaki Bukit Ave 6  
#01-53/55 AutoBay@ Kaki Bukit  
Singapore 417883

**THIRD PARTY SURVEY**  
**ACCIDENT HAPPENED ON 29 Apr 2019**

Workshop Address : Bluwel Automotive Service Pte Ltd  
No.1 Kaki Bukit Ave 6  
#01-53/55 AutoBay@ Kaki Bukit  
Singapore 417883

As per your instruction dated 3 May 2019 with regard to the above matter, We have carried out a physical inspection on the said vehicle **GBC 8186 E**. We enclosed herewith our report and findings as follows:

**1. VEHICLE PARTICULARS**

Registration No	: GBC 8186 E	Engine No	: YD25337502A
Model	: Nissan NV350 Urvan	Mileage	: 203526
Year / Capacity	: 2013/2488	Colour	: White
Chassis No	: JN1MC2E26Z0001395		

**2. TYRES CONDITION**

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	: 195 R15	Bridgestone	6.00	mm	Normal
REAR O/S	: 195 R15	Bridgestone	6.00	mm	Normal
FRONT N/S	: 195 R15	Bridgestone	6.00	mm	Normal
REAR N/S	: 195 R15	Bridgestone	6.00	mm	Normal



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883  
Tel: 6748 6653 Fax: 67471017 Registration No: 200723251D

### 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the front o/s portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 6 working days to complete.
5. Enclosed number of photograph : 84 copies.
6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

#### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

63D 95365

Vehicle No: GBC 8186 E  
Report No: TP/ 19006-05/AY / 2019

**SPARE PARTS**

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Front grille	Damage CM	\$ 528.50	\$ 528.50 ✓
1	Front bumper 107.	Damage DIS	\$ 892.70	\$ 892.70 ✓
1	Front bumper o/s side bracket	Damage CM	\$ 91.70	\$ 342 91.70 ✓
			\$ 1512.90	\$ 1512.90 ✓
	Discount 10% 30.0%		\$ 453.87	\$ 453.87
			\$ 1059.03	\$ 1059.03
<u>Nett Items</u>				
1	Front o/s corner panel	Damage DD	\$ 437.10	\$ 437.10 ✓
1	Front o/s headlamp	Damage CM	\$ 412.60	\$ 412.60 ✓
1	Front grille logo	Necessary 11	\$ 42.80	\$ 42.80 X
1	Front o/s door step garnish	Damage CM	\$ 142.60	\$ 142.60 ✓
1	Front bumper o/s fog lamp	Damage CM	\$ 311.80	\$ 311.80 ✓
1	Front bumper o/s fog lamp cover 65.80	Damage 10.1	\$ 107.80	\$ 107.80 ✓
1	Air con condenser 26	Damage 11	\$ 1052.80	\$ 1052.80 X
1	Turbo cooler	Damage PM	\$ 2121.60	\$ 2121.60 ✓
			\$ 4629.10	\$ 4629.10
	Discount 10.0%		\$ 462.91	\$ 462.91
			\$ 4166.19	\$ 4166.19

L - 622.20  
302  
434.14

N - 4006.2  
107  
3605.58

Spare Parts Total \$ 5225.22 \$ 5225.22



Vehicle No: GBC 8186 E  
Report No: TP/ 19006-05/AY / 2019

# LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 5225.22	\$ 5225.22
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 50.00	\$ 40.00 20
2	To remove and replace air-con system, refill gas and test for leakages.	\$ 200.00	\$ 120.00 X
3	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 900.00	\$ 660.00 500
4	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 900.00	\$ 660.00 /
5	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 100.00	Not Required X
Total		\$ 7375.22	\$ 6705.22
The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:		\$ 5400.00	5211.72

SDLS: FIVE THOUSAND FOUR HUNDRED ONLY

  
Qualified Appraiser

1180

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/04/2019 14:28
Date Of Accident	29/04/2019 11:30
Exact Location Of Accident	PASIR PANJANG WHOLESALE CENTRE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC8186E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	M/S THE GREEN BOX
Co Reg No	53349872D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-82364635

### Vehicle Particulars

Manufacturer	NISSAN
Model	-
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3033951800
Cover Note Number	

### Driver

Name of Driver	DAVID ELIAS JASON
NRIC No	S7247527E
Date Of Birth	12/12/1972
Occupation	OUTDOOR
Date Of Driving Pass	13/07/2009
Driving Experience	9 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82364635
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	219 LOYANG RISE
Postcode	507382
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WD2068Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAN BOCK HOCK
NRIC/Passport Number	
Contact Number	97314055
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

30/8/19, 10:45:00

Driver's Signature

(If driver is not the policyholder)

Date & Time:

30/8/19, 10:45:00


Reporting Centre Personnel's Signature

Name:

NRIC/TIN No.:

# Individual Statement

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29/4/19 at about 1130am I was in a lot waiting for vehicle B to drive off but the driver made a reverse. I wind down the window (R/H) and shouted at him but he still proceed to reverse and hit the front R/H side of my car (A).

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 30/4/19, 10:10am

Driver's Signature

(If driver is not the policyholder)

Date & Time: 30/4/19, 10:10am

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

GAARAC, Skudai, Johore Bahru, 81300

Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



# Identification Card

REPUBLIC OF SINGAPORE  
IDENTITY CARD No. 57247527E



NAME  
DAVID ELIAS JASON

RACE  
MALAY  
Date of birth  
12-12-1972  
Country of birth  
SINGAPORE

Sex  
M

Height  
1.70M



IC No. 57247527E



Date of issue  
22-06-2009

Address  
218 LUYANG GSC  
SINGAPORE 517353



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GiA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/04/2019 11:34
Date Of Accident	29/04/2019 11:30
Exact Location Of Accident	BLK 26 PASIR PANJANG WHOLESALSE CENTRE #01-213
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	WD2068Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	PTKN VEG TRADING
Co Reg No	5232300J
Email Address	PTKN88@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-97314055
Alternative Phone No	Office-97314055

### Vehicle Particulars

Manufacturer	TOYOTA
Model	FORKLIFT
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	B 29077585 TMV
Cover Note Number	

### Driver

Name of Driver	TAN BOCK HOCK
NRIC No	S1336979H
Date Of Birth	07/06/1958
Occupation	INDOOR
Date Of Driving Pass	05/12/2006
Driving Experience	12 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97314055

Fax Number	
Contact Number	OTHERS-97314055
EMail Address	PTKN88@SINGNET.COM.SG
Address	17 TAMARIND ROAD
Postcode	806026
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance,	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC8186E
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	



Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GI&A Records Management Centre established by the General Insurance Association of Singapore (GI&A) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GI&A") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GI&A to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
  - (e) the information so collected under (d) above may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
    - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personnel Signature  
Name: *80106/2005*  
NRIC/FIN No: *80106/2005*

**SKETCH PLAN** EHC 26 H.C. 22 P. 70 Verordende Voorzitter van de Raad



A) WD7061Z

2) GAC 9126E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DATE 29/4/19 I was doing work me reverse my  
Forklift hit behind the ~~left~~ vehicle no 888 8156E  
at his right side head light

## DECLARATION

☐ We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Paul J. Wright  
NRIC/TIN No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



# Identification Card





































## ...CLAIM SUBFOLDER...(Pending for Survey Report)

















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2019		02 May 2019 14:27 <a href="#">Edit Adj Rpt</a>	<b>S\$4,150.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,150.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by Insurer]</span>									
Insured:	PTKN VEG TRADING, Co. Reg. No.: 52323003								
Main Claimant:	THE GREEN BOX								
Vehicle Reg. No.:	GBC8186E	Date of Loss:	29/04/2019 11:00 - :59 [65 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 592101	Policy/Cover Note No.:	B29077585TMV (Third Party Only) Coverage: 02/04/2019 - 01/04/2020						
Vehicle Reg. No. (Insured):	WD2068Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 03/06/2019]								
Driver/Custodian (Insured):	TAN BOCK HOCK (), NRIC: S1336979H, Tel: +6597314055 Email:								
Adj Asg. Remarks:	on WP. (MANUAL ASSIGNED) SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: 100% CONTACT:6745 2088								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (30/05/2019): Report Send Back Alerts - GBC8186E (TP)</li> <li>MSIG_SG (27/05/2019): Report Send Back Alerts - GBC8186E (TP)</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*GBC8186E (592101)**  
**[WD2068Z]**  
**TP**  
**THE GREEN BOX**  
**Apr 29 2019 11:00AM**  
**[PTKN VEG TRADING]**  
**Bluwel Automotive Service Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/05/19 11:40	<b>Accident Statement</b> <small>Prom-SC - Reg. No: WD2068Z, Claimant: PTKN VEG TRADING</small>	 <a href="#">Load HTM</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
2	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
3	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
4	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
5	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
6	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
7	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
8	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
9	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
10	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
11	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
12	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
13	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
14	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
15	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
16	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
17	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
18	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
19	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
20	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
21	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
22	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
23	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
24	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
25	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
26	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
27	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
28	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
29	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
30	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
31	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
32	09/05/19 11:31	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
33	09/05/19 11:32	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	09/05/19 11:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	09/05/19 11:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	09/05/19 11:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	09/05/19 11:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	09/05/19 11:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	09/05/19 11:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	09/05/19 11:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	09/05/19 11:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	09/05/19 11:32	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/05/19 11:40	E-FILE REPORT (GBC8186E) From: SC - Reg. No: WD20682, Claimant: PTKN VEG TRADING	 Load PDF	
2	02/05/19 11:54	TP PRI & SKETCH PLAN	 Load PDF	
3	02/05/19 14:08	SURVEY DISAGREE ON SJE - ASSIGN LKK OI REVERSED & HIT TP	 Load PDF	
4	27/05/19 08:42	COLOURED SURVEY PHOTOS1	 Load PDF	
5	27/05/19 08:42	COLOURED SURVEY PHOTOS2	 Load PDF	
6	27/05/19 08:42	COLOURED SURVEY PHOTOS3	 Load PDF	
7	27/05/19 08:42	COLOURED SURVEY PHOTOS4	 Load PDF	
8	27/05/19 08:42	COLOURED SURVEY PHOTOS5	 Load PDF	
9	27/05/19 08:42	COLOURED SURVEY PHOTOS6	 Load PDF	
10	27/05/19 08:42	COLOURED SURVEY PHOTOS7	 Load PDF	
11	27/05/19 08:50	REPAIR BILL, SURVEY BILL, SURVEY REPORT	 Load PDF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail Print
1	02/05/19 14:25	Email - Outsource		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	30/05/19 12:44	Colour Photo		Load PDF
2	30/05/19 12:45	PRS Invoice		Load PDF

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div> <div></div> <div> ^ v </div> </div> </div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19007705/UQD3E2-1

Date: 30/05/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B29077585TMV

Claimant Vehicle No: GBC8186E

Insured Vehicle No: WD2068Z

Date of Loss: 29/04/2019

Nature of Claim: TP

Claim No: 592101

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GBC8186E

Make &amp; Model: NISSAN NV350, 2.5 5MT 5DR EURO V (A)

Engine No: YD25337502A

Reg. Date: 25/11/2013 (Man. Year: 2013)

Chassis No: JN1MC2E26Z0001395

Colour: White

Odometer: 203526 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,403.76	4,039.72	1,364.04	25.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	1,180.00	970.00	45.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,553.76</b>	<b>5,219.72</b>	<b>2,334.04</b>	<b>30.90</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,150.00</b>		
<b>(S\$)</b>	<b>7,553.76</b>	<b>4,150.00</b>	<b>3,403.76</b>	<b>45.06</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>528.76</b>	<b>290.50</b>	<b>238.26</b>	<b>45.06</b>
<b>Nett Amount (S\$)</b>	<b>8,082.52</b>	<b>4,440.50</b>	<b>3,642.02</b>	<b>45.06</b>

## INSPECTION

Date of Assignment: 02/05/2019

Date Inspected: 03/05/2019 Inspected At:

 Bluwel Automotive Service Pte Ltd (HQ)  
 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56  
 Autobay@Kaki Bukit  
 Singapore 417883

Estimated Period of Repair: 4.0 days



---

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 30 May 2019)	
<b>Parts:</b>	N/A	NISSAN NV350 2.5 5MT 5DR EURO V (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBC8186E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Cracked	528.50 FL	*528.50 FL
2	1		*FRONT BUMPER O/S SIDE BRACKET	Cracked	91.70 FL	*91.70 FL
3	1		*FRONT BUMPER	Distorted	892.70 FN	*514.70 FN
4	1		*FRONT O/S CORNER PANEL	Dented	437.10 FN	*437.10 FN
5	1		*FRONT O/S HEADLAMP	Cracked	412.60 FN	*412.60 FN
6	1		*FRONT GRILLE LOGO	Not Necessary	42.80 FN	*- FN
7	1		*FRONT O/S DOOR STEP GARNISH	Cut	142.60 FN	*142.60 FN
8	1		*FRONT BUMPER O/S FOG LAMP	Cracked	311.80 FN	*311.80 FN
9	1		*FRONT BUMPER O/S FOG LAMP COVER	Torn	107.80 FN	*65.80 FN
10	1		*AIR CON CONDENSER (NOT NECESSARY)	Not Consistent With The Impact	1,052.80 FN	*- FN
11	1		*TURBO COOLER	Punctured	2,121.60 FN	*2,121.60 FN
					<b>Sub Total (S\$)</b>	<b>6,142.00 4,626.40</b>
					- List Item Discount on L Items 30.00/30.00% (S\$)	186.06 186.06
					- Nett Item Discount on N Items 10.00/10.00% (S\$)	552.18 400.62
					<b>Total Parts (S\$)</b>	<b>5,403.76 4,039.72</b>

F=Franchise part. L=ListItemDisc. N=NettItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS	New	50.00	20.00
2	TO REMOVE AND REPLACE AIR-CON SYSTEM, REFILL GAS AND TEST FOR LEAKAGES	New	200.00	0.00
3	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	900.00	500.00
4	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	900.00	660.00
5	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	100.00	0.00
Gross Labour Cost (S\$)			2,150.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >