

ASS. REC. BY:

REF:

CS/FCI19009393/JV d3

n2

Special Instruction:

Survey:

Amie file

## ASSIGNMENT (Office)

From (Person):

Henny Koro

of

FCI

Date/Time:

12:40pm @ 28/5/19

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC 5748M

Insured:

SHA 9097L

at Workshop m/s

Crown Asia

Tel:

89969995

of

44 Sungai Rendut Ave

Policy No:

Claim No:

D19003451MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

23/5/2019

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

12:57pm @ 28/5/19

Person Contacted:

Jyden

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	PC 5748M - CS / ASM1801A 1962 / R1 x d 302	Do A: 11/08/2018
	SHA 9097L - CS / FCI 15012560 / Av. by 2	Do A: 24/7/2015
7/6/19	Email preli revised to FCI	

(08/11/13)

ASS. REC. BY: Hue JieREF PC1**ASSIGNMENT**

From: \_\_\_\_\_

Date: 4.6.2019

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: PC 5748Mat Workshop m/s Crown Asia Busof NO 44 Sungai Kadut Street 1

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: 10.00am - 12.00 p.m

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS rep

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: PC 5748MYr Regn: 18 Apr 2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Isuzu LT434PC.C. 1790Colour: Multi Colour

A/C: Insured / Std / NI / NA

Sp. Reading: 115211

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JALLT434PH7000006Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 295/80R22.5

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. 7 mmR/Bal. 7/7 mmL/Bal. 7 mmL/Bal. 7/7 mmD.O.A. 23/5/19D.O.I. 4/6/19

Survey held at

Crown AsiaDes. of Damages: Fr / Rear / DIS / N/S / U/C / Rooftop orfront ok

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Called a few times to go thru estimate for finalization  
but Jayden on leave.

5/7/19 Confirmed L/S \$3100/- 4 days of repair. (Red 1562, 349)

RECEIVED 05 JUL 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

5/7 - typistReport Format: CWSLump Sum / I.B.I.: (\$) 3100/2Days Of Repair: 4Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

135505016251



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19003451MFSH

Our ref: CS/FCI19009393/Jvd3

Date: 7/6/2019

The Motor Claims Department  
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam

**PRELIMINARY ADVICE OF VEHICLE NO. PC 5748M**


We thank for your instruction on 28/5/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle  
on 4/6/2019 at the premises of M/s CROWN ASIA BUS BUILDER PTE LTD  
and have the following to report:-

Workshop Estimate Amount	: S\$4,662.00
Revised Estimate Amount	: S\$3,712.00
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

**Description of Damage:**

The vehicle sustained damages at the  
front o/s portion



Comments/Present Status:  
Damages Consistent

Yours faithfully,

**ONG HWEE JIE**  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

Date	27-05-2019	Our Ref No. D19003451MFSH
Accident Date	23-05-2019	Claim Type. Third Party
Insured Vehicle	SHA9097L	Third Party Vehicle. PC5748M
Survey Location	44 Sungei Kadut Ave	
Contact Person.	JAYDEN	
Contact No.	69669995/ 69969995	Fax No. 64694319
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	CROWN ASIA BUS BUILDER PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Veron Chen (LKKAUTO)

---

**From:** Hwee Jie (LKK Auto)  
**Sent:** Friday, 5 July 2019 2:01 PM  
**To:** Claims  
**Cc:** Veron Chen (LKKAUTO)  
**Subject:** RE: AFTER REPAIR OF PC5748M

Hi,

Finalized L/S \$3,100/- 4days of repair.

Best Regards,

*Hwee Jie* | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 9180 3151 | Email: [Hweejie@lkkauto.com](mailto:Hweejie@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claims [<mailto:claims@crownasia.com.sg>]  
**Sent:** Thursday, 20 June, 2019 1:55 PM  
**To:** Hwee Jie (LKK Auto)  
**Subject:** AFTER REPAIR OF PC5748M

Dear Hwee Jie,

Please find the attached after repair photo for PC5748M.

I calculate for a L/S of \$3200.00 with repair for 3 days as the labour marking as we include the repair of luggage compartment rather than change a new one  
Please let me know whether our offer is acceptable

Thanks and Best Regards,  
Jayden



CROWN Asia Bus Builder Pte Ltd

Tel: 6966 9995 / 6996 9995 Fax: 6469 4319

Email: [jayden@crownasia.com.sg](mailto:jayden@crownasia.com.sg)

44 Sungei Kadut Ave, Singapore 729667

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Friday, 7 June 2019 2:08 PM  
**To:** 'CWS Motor Claims'  
**Cc:** 'Henry Kao Cai Jie'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D19003451MFSH/1, PC 5748M  
**Attachments:** PC 5748M PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle PC 5748M  
Date of survey: 4/6/2019  
Number of days : 4 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 28 May 2019 2:52 PM  
**To:** 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D19003451MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Tuesday, 28 May 2019 12:40 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Henry Kao Cai Jie

<HenryKao@msfirstcapital.com.sg>

**Subject:** PRI: SURVEY ASSESSMENT - D19003451MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	7049C
<b>Vehicle Details</b>	
Vehicle No.:	PC5748M
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jun 2019
Vehicle Make:	ISUZU
Vehicle Model:	LT434P 7.8 SMT
Primary Colour:	Multi-Colour
Manufacturing Year:	2016
Engine No.:	6HK1692281
Chassis No.:	JALLT434PH7000006
Maximum Power Output:	-
Open Market Value:	\$104,621.00
Original Registration Date:	18 Apr 2017
First Registration Date:	18 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$5,232.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	17 Apr 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$32,297.00
COE Rebate Amount:	\$25,389.00
Total Rebate Amount:	\$25,389.00

The information contained herein is correct as at 07 Jun 2019

OK



**CROWN ASIA BUS BUILDER PTE. LTD.** (UEN:201023449R)

44 Sungei Kadut Avenue Singapore 729667

Tel: (65) 6469 3319, Fax: (65) 6902 6758

GST ID No : 201023449R

**Repair Estimate****No. : QT-000047**

MS FIRST CAPITAL INSURANCE LIMITED

C/O LKK AUTO CONSULTANTS PTE LTD

3 ANSON ROAD,

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

TEL :

FAX :

Your Ref. :

Our D/O No. :

Terms : C.O.D.

Date : 03-06-2019

Page : 1 of 2

Item	Tax Code	Description	Qty	UOM	U/ Price S\$	Disc.	Total S\$
------	----------	-------------	-----	-----	-----------------	-------	--------------

ZR

Traffic accident on 23/05/2019 involving PC5748M  
and SHA9097L along Central Boulevard towards  
Sheaves Ave

**Parts Required:**

1.	SR	FRONT BUMPER	CUT ✓	1.00	2,600.00		2,600.00
2.	SR	COMPARTMENT LOCK	SLR ✓	1.00	80.00		80.00
		SubTotal					2,680.00
3.	SR	LESS 10% TRADE DISCOUNT		1.00	-268.00		-268.00
4.	ZR	LABOUR CHARGES		1.00	950.00		950.00
		1. TO PUTTY AND SPRAY ON FRONT RIGHT BUMPER AND COMPARTMENT AREA					500 600
5.	ZR	LABOUR CHARGES		1.00	1,300.00		1,300.00
		3. TO KNOCK AND STRAIGHTEN ALL NECESSARY PARTS					800
		- FRONT RIGHT BUMPER AND COMPARTMENT					900
		- SPRAY FOAM FOR FRONT BUMPER					

NOTE: THIS ESTIMATE IS BASED ON VISIBLE  
DAMAGE ONLY. SHOULD ANY HIDDEN PARTS  
AND/OR LABOUR CHARGES REQUIRED  
DURING WORKS IN PROGRESS, IT WILL BE  
NOTIFIED ACCORDINGLY.

PRICE QUOTED IS INCLUDED TO 7% GST

**CROWN ASIA BUS BUILDER PTE. LTD.** (UEN:201023449R)

44 Sungei Kadut Avenue Singapore 729667

Tel: (65) 6469 3319, Fax: (65) 6902 6758

GST ID No : 201023449R

**Repair Estimate****No. : QT-000047**

MS FIRST CAPITAL INSURANCE LIMITED

C/O LKK AUTO CONSULTANTS PTE LTD

3 ANSON ROAD,

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

TEL :

FAX :

Your Ref. :

Our D/O No. :

Terms : C.O.D.

Date : 03-06-2019

Page : 2 of 2

Item	Tax Code	Description	Qty	UOM	U/ Price S\$	Disc.	Total S\$
------	-------------	-------------	-----	-----	-----------------	-------	--------------

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE DOLLAR FOUR THOUSAND EIGHT HUNDRED THIRTY  
AND CENTS EIGHTY FOUR ONLY

**Sub Total (Excluding GST) 4,662.00****GST payable @ 7% on 2,412.00 168.84****Total (Inclusive of GST) 4,830.84****Notes :**

1. All cheques should be crossed and made payable to  
CROWN ASIA BUS BUILDER PTE. LTD.
2. Goods sold are neither returnable nor refundable. Otherwise  
a cancellation fee of 20% on purchase price will be imposed.

**GST Summary****Amount(S\$)****Tax(S\$)**

\$3100/-

Hwee Jie - Lkk

4/6/19

L/s 4 days

**Authorised Signature**




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19009393/Jvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-07-2019	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 9097L	Veh. Inspected	PC 5748M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003451MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	28/05/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	ISUZU LT434P	c.c	7790	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JALLT434PH7000006	Colour	MULTI	
Odometer	115211	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	MICHELIN	7 mm	
L/H Front Tyre	295/80 R22.5	MICHELIN	7 mm	
R/H Rear Tyre	295/80 R22.5 (D)	MICHELIN	7/7 mm	
L/H Rear Tyre	295/80 R22.5 (D)	MICHELIN	7/7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	23/05/2019	Inspection Date	04/06/2019	
Survey held at	CROWN ASIA BUS BUILDER PTE LTD NO. 44 SUNGEI KADUT STREET 1 SINGAPORE 729349			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 5748M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	FRONT BUMPER	CUT	2,600.00	2,600.00
1	COMPARTMENT LOCK	SCRATCHED	80.00	80.00
	LESS 10% DISCOUNT		-268.00	-268.00
			2,412.00	2,412.00
	<b>LABOUR</b>			
	TO PUTTY AND SPRAY ON FRONT RIGHT BUMPER AND COMPARTMENT AREA.		950.00	600.00
	TO KNOCK AND STRAIGHTEN ALL NECESSARY PARTS -FRONT RIGHT BUMPER AND COMPARTMENT. -SPRAY FOAM FOR FRONT BUMPER.		1,300.00	900.00
			2,250.00	1,500.00
	<b>GRAND TOTAL</b>		<b>4,662.00</b>	<b>3,912.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,100.00</b>

Report Ref No. CS/FCI19009393/Jvd3n2

ONG HWEЕ JIE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.