

ASS. REC. BY:

REF: 02/CTI19009404/ED3

n2

Special Instruction:

Surveyor: Stvl

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI Date/Time: 27/5/19 @ 5:17pm

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLU 7059 H Insured: GX7861B

at Workshop m/s: Mova Automotive Tel: 02723892 Jacelyn
of Blk 128, Bkt March Lane 3 #01-04

Policy No: Claim No: SNM19 D202336

Sum Insured: Excess:

Make of Veh: D.O.A. 22/5/19
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:40am @ 27/5/19 Person Contacted: Nithya Vehicle: IN / OUT

Date/Time	Action/Instruction	Estimate	✓
	SLU 7059 H - X		
	GX 7861 B - X		

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MY
 To Inspect Vehicle No: _____
 at Workshop n/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLU 7059H In Regn. 12/12/17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota wish G.C. 1798
 Colour: Grey A/C Insured / Std / NI / N
 Sp. Reading: 48587 T/Rxlin: Insured / Std / NI / N.
 Eng/No: _____
 C/No: JTDG620w 60J 008530
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/452R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or NEXEN
 Front: _____ Rear: _____
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 22/5/19 D.O.I. 10/6/19
 Survey held at Mora, Bukit Merah
 Des. of Damages: Frl / Rear / O/S / N/S / UIC / Rooftop or
Rear RH
 The UIC / Chassis frame / Body Structure affected due to collision:

Date / Time : _____ Action / Instruction

4/7/19 Final SSK 1139.50, 33.90
Final Cons 12300, 7 repair days. (Real)

RECEIVED 05 JUL 2019

Date/Time. File Pass to? ☐ : Procl. Report

☐ : Final Report

Date/Time. File Return to?

5/7- typist

Report Format: menimen

Lump Sum / I.B.F. 2300p

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Wee-end (\$

Survey Fee:

Transportation

☐ : S + R. (\$

☐ : Photos

☐ : Labels

220

Veron Chen (LKKAuto)

From: Jacelyn <jacelyn@movas.com.sg>
Sent: Thursday, 4 July 2019 6:36 PM
To: Steve Chen (LKK Auto)
Cc: SUR
Subject: FINALIZATION: SLU7059H - TP/CHINA TAIPING - TOYOTA WISH 1.8 (DOA 22.05.2019)
Attachments: FINALIZE.PDF; IMG_20190621_114902.jpg; IMG_20190621_114852.jpg; IMG_20190621_114856.jpg

Hi Steve,

Please find the attached 'Marking Estimate' & After-Paint' photographs for your reference.

We propose the finalize amount at Lumpsum \$ 2,300.00 with 7 working days. Kindly revert.

Best Regards,
Jacelyn Ooi
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 27 May 2019 5:17 PM
To: Nitha
Cc: assignments
Subject: RE: TP CLAIMS - SLU7059H AGAINST GX7861B DOA 22/05/2019 AT BLK 18 PASIR PANJANG WHOLE SALE CENTRE / OUR REF: SNM19D202336

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Nitha [mailto:nitha@moval.com.sg]

Sent: Monday, 27 May, 2019 5:18 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: RE: TP CLAIMS - SLU7059H AGAINST GX7861B DOA 22/05/2019 AT BLK 18 PASIR PANJANG WHOLE SALE CENTRE / OUR REF: SNM19D202336

Dear Boon Sen,

Please arrange LKK.

Thank you.

Best Regards,

Nitha

Claims Officer
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

Sent: Monday, 27 May 2019 12:00 PM

To: nitha@nova.com.sg

Subject: RE: TP CLAIMS - SLU7059H AGAINST GX7861B DOA 22/05/2019 AT BLK 18 PASIR PANJANG WHOLE SALE CENTRE / OUR REF: SNM19D202336

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Monday, 27 May, 2019 11:57 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; nitha@movva.com.sg

Cc: Angie Foo <angie.foo@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: FW: TP CLAIMS - SLU7059H AGAINST GX7861B DOA 22/05/2019 AT BLK 18 PASIR PANJANG WHOLE SALE CENTRE

Dear Boon Sen,

Please conduct PRS – TP: SLU7059H (SNM19D202336) soonest possible.

File with OIC – Boon Sen - 63896171

From: Nitha [<mailto:nitha@movva.com.sg>]

Sent: Monday, 27 May 2019 11:45 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: 'Jacelyn Ooi (Mova)' <jacelyn@movva.com.sg>; 'Suanne Chiu (Mova)' <suann@movva.com.sg>

Subject: TP CLAIMS - SLU7059H AGAINST GX7861B DOA 22/05/2019 AT BLK 18 PASIR PANJANG WHOLE SALE CENTRE

Dear Sir/Madam,

Good day

REF : GX7861B

Kindly assist revert officer in charge and liability and arrange survey for the above mention case.

Thank you,

Best Regards,

Nitha

Claims Officer

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314



This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6324A
Vehicle Details	
Vehicle No.:	SLU7059H
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	2ZR0A34846
Chassis No.:	JTDGG20W60J008530
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$19,955.00
Original Registration Date:	12 Dec 2017
First Registration Date:	12 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$19,955.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Dec 2027
PARF Rebate Amount:	\$14,966.00
Intended COE Rebate Details	
COE Expiry Date:	11 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,390.00
COE Rebate Amount:	\$48,796.00
Total Rebate Amount:	\$63,762.00

The information contained herein is correct as at 10 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/05/2019 16:09
Date Of Accident	22/05/2019 14:00
Exact Location Of Accident	BLK 18 PASIR PANJANG WHOLE SALE CENTRE #01-127
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU7059H
Insured/Policyholder	
Name Of Registered Owner	LOW YEUN CHING
NRIC No	S1676324A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96394700
Alternative Phone No	OFFICE-96394700

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800125603
Cover Note Number	

Driver

Name of Driver	CHIU KA WAI
NRIC No	S2579752C
Date Of Birth	29/07/1951
Occupation	INDOOR
Date Of Driving Pass	08/12/1989
Driving Experience	29 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96394700
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	30 JALAN KEMAMAN #11-02
Postcode	329341
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX7861B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



LICENSE PLATE:	SLU 7059 H	ACCIDENT DATE & TIME:	2019年 5月 22号. 2PM.
CONTACT NUMBER:	96394700	E-MAIL ADDRESS:	
LOCATION:	BLK 18 PASIR PANJANG WHOLE SALE CENTRE #01-127		
<p>My vehicle SLU 7059 H was parked along Blk 18 Pasir Panjang whole sale centre #01-127. A lorry GX 7861 B has reversing accidentally hit onto my vehicle rear right portions. The driver ask me to claim his insurance.</p>			
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION			
Please state:			
<input type="checkbox"/> Claim Own Policy <input checked="" type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only			

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Estimate

27/05/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Page # :- 1

Veh # :- SLU7059H

Veh Model :- TOYOTA WISH

Estimate# :- CK419207

Claim # :- TP/CK135036

ACC. Date :- 22/05/19

Terms :- C.O.D Days

Remarks :- MFG 12 DEC 2017 (2017)

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	TAILLAMP RH <i>BR</i>	1 PC	295.00	295.00
2.	TAILLAMP PANEL RH <i>X R</i>	1 PC	89.00	89.00
3.	TAILLAMP LOWER BRACKET RH <i>BR</i>	1 PC	91.00	91.00
4.	REAR BUMPER <i>BR</i>	1 PC	574.00	574.00
5.	REAR BUMPER SIDE RETAINER RH <i>BR</i>	1 PC	93.00	93.00
6.	REAR BUMPER REFLECTOR RH <i>? X MM</i>	1 PC	82.00	82.00
7.	REAR BUMPER CLIPS <i>MC</i>	10 PC	5.00	50.00
8.	REAR FENDER RH <i>BR</i>	1 PC	1,032.00	1,032.00
LIST TOTAL S\$				2,306.00
25% DISCOUNT S\$				-576.50
				1,729.50
SPECIAL NET ITEMS :				
1.	SEALANT <i>new</i>	1 PC	40.00	40.00
SPECIAL NET TOTAL S\$				40.00
LABOUR :				
TO REMOVE & REFIT REAR QTR GLASS RH				50 80.00
TO REMOVE & TRANSFER PARKING SENSOR & CHECK WIRING				30 80.00
TO CUT OFF REAR FENDER RH. TO REPLACE DAMAGED ITEMS. REALIGN CONNECTION				600.00 ✓
TO REMOVE & REFIT REAR FENDER INNER COMPARTMENT, TRIM, SEAT & ETC				30 150.00
TO APPLY BODY JOINT SEALANT				30 80.00
TO RUST PROOF ON REPAIRED AREAS				30 80.00
TO SPRAY PAINT ON REPAIRED AREAS				50.0 600.00
LABOUR TOTAL S\$				1,670.00

Steve (LKK)

12/6/19, 2:31 pm

L/S

Ry AL spj

Estimate

27/05/2019

CHINA TAIPING INSURANCE (S) PTE LTD
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909.

Page # :- 1 135036
 Veh # :- SLU7059H
 Veh Model :- TOYOTA WISH
 Estimate# :- CK419207
 Claim # :-
 ACC. Date :- 22/05/19
 Terms :- C.O.D Days
 Remarks :-

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel : (65) 6476 3333
 Fax : (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722
 Tel : (65) 6272 3892
 Fax : (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S	
AMOUNT S\$	3,439.50
GST @ 7 %	240.77
AMOUNT DUE S\$	3,680.27

Customer's Signature/Co. Stamp

MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

27/05/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- SLU7059H

Veh Model :- TOYOTA WISH

Estimate# :- CK419207

Claim # :- TP / CK135036

ACC. Date :- 22/05/19

Terms :- C.O.D Days

Remarks :- MFG 12 DEC 2017 (>017)

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	TAILLAMP RH <i>BR</i>	1 PC	295.00	295.00 ✓
2.	TAILLAMP PANEL RH <i>X R</i>	1 PC	89.00	89.00 ✓
3.	TAILLAMP LOWER BRACKET RH <i>BR</i>	1 PC	91.00	91.00 ✓
4.	REAR BUMPER <i>BR</i>	1 PC	574.00	574.00 ✓
5.	REAR BUMPER SIDE RETAINER RH <i>BR</i>	1 PC	93.00	93.00 ✓
6.	REAR BUMPER REFLECTOR RH <i>?</i>	1 PC	82.00	82.00 ✓
7.	REAR BUMPER CLIPS <i>MC</i>	10 PC	5.00	50.00 ✓
8.	REAR FENDER RH <i>OP</i>	1 PC	1,032.00	1,032.00 ✓
LIST TOTAL S\$			2115.00	2,308.00
25% DISCOUNT S\$			- 576.50	
			1586.25	1,729.50
SPECIAL NET ITEMS :				
1.	SEALANT	1 PC	40.00	40.00
SPECIAL NET TOTAL S\$			30.00	40.00
LABOUR :				
TO REMOVE & REFIT REAR QTR GLASS RH			50	80.00
TO REMOVE & TRANSFER PARKING SENSOR & CHECK WIRING			90	80.00
TO CUT OFF REAR FENDER RH. TO REPLACE DAMAGED ITEMS. REALIGN CONNECTION			600.00	✓
TO REMOVE & REFIT REAR FENDER INNER COMPARTMENT, TRIM, SEAT & ETC			150.00	
TO APPLY BODY JOINT SEALANT			80.00	
TO RUST PROOF ON REPAIRED AREAS			80.00	
TO SPRAY PAINT ON REPAIRED AREAS			600.00	
LABOUR TOTAL S\$			1,260.00	1,670.00

P = 1586.25

SV = 30.00

L = 1260.00

2876.25

LS -20%

2301.00

Lumpsum : \$ 2300.00

STAVE (LKK)

W. Minda
7 obj

10/6/19, 2.30 pm

L/S

Ry AL spg

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

27/05/2019

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 135036

Veh # :- SLU7059H

Veh Model :- TOYOTA WISH

Estimate# :- CK419207

Claim # :-

ACC. Date :- 22/05/19

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 3,439.50

GST @ 7 % 240.77

AMOUNT DUE S\$ 3,680.27

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**
Jacelyn

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19009404/EVD3N2

Date: 10/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN011250181414	
Claimant Vehicle No :	SLU7059H	Insured Vehicle No :	GX7861B	
Date of Loss:	22/05/2019	Nature of Claim:	TP	Claim No: SNM19D202336C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU7059H	Engine No:	2ZR0A34846
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20W60J008530
Reg. Date:	12/12/2017 (Man. Year: 2017)	Odometer:	48587 km
Colour:	Grey		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45ZR17	Rear Tyre Size:	215/45ZR17
Front Left Side:	Nexen 7 mm	Rear Left Side:	Nexen 7 mm
Front Right Side:	Nexen 7 mm	Rear Right Side:	Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,769.50	1,616.25	153.25	8.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,670.00	1,260.00	410.00	24.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,439.50	2,876.25	563.25	16.38
Approved Total (Overridden) (S\$)		2,300.00		
(S\$)	3,439.50	2,300.00	1,139.50	33.13
+ GST 7.00/7.00% (S\$)	240.77	161.00	79.77	33.13
Nett Amount (S\$)	3,680.27	2,461.00	1,219.27	33.13

INSPECTION

Date of Assignment:	05/07/2019	
Date Inspected:	10/06/2019 Inspected At:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722
Estimated Period of Repair:	7.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2019)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU7059H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMP RH	Broken	295.00 FL	*295.00 FL
2	1		*TAILLAMP PANEL RH	Repair	89.00 FL	*- FL
3	1		*TAILLAMP LOWER BRACKET RH	Broken	91.00 FL	*91.00 FL
4	1		*REAR BUMPER	Broken	574.00 FL	*574.00 FL
5	1		*REAR BUMPER SIDE RETAINER RH	Broken	93.00 FL	*93.00 FL
6	1		*REAR BUMPER REFLECTOR RH	Not Necessary	82.00 FL	*- FL
7	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
8	1		*REAR FENDER RH	Dented	1,032.00 FL	*1,032.00 FL
9	1		*SEALANT	Necessary	40.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,346.00	2,145.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	576.50	528.75

Total Parts (\$\$)	1,769.50	1,616.25
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT REAR QTR GLASS RH	New	80.00	50.00
2	TO REMOVE & TRANSFER PARKING SENSOR & CHECK WIRING	New	80.00	20.00
3	TO CUT OFF REAR FENDER RH.TO REPLACE DAMAGED ITEMS.REALIGN CONNECTION	New	600.00	600.00
4	TO REMOVE & REFIT REAR FENDER INNER COMPARTMENT,TRIM SEAT & ETC	New	150.00	30.00
5	TO APPLY BODY JOINT SEALANT	New	80.00	30.00
6	TO RUST PROOF ON REPAIRED AREAS	New	80.00	30.00
7	TO SPRAY PAINT ON REPAIRED AREAS	New	600.00	500.00
Gross Labour Cost (S\$)			1,670.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >