

27/03/2019

ASS. REC. BY:

Surveyor:

Cano Diany

REF: CS3/ASM19009411/Gcd3er

Special Instruction:

ASSIGNMENT (Office)

From (Person): Motorsurvey of ASM(CAXA) Date/Time: 27/5/2019

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLA 330A Insured: SKM 9568X

at Workshop m/s Teamwork Garage Tel: 6444 2475

of 53 ubi Ave 1 #01-25

Policy No: Claim No: 39M010EL

Sum Insured: Excess:

Make of Veh: D.O.A. 22/5/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 27/8/2019 Person Contacted: Darren Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	SLA 330A-X	
	SKM 9568X-X	
30/5/19-	Damen call and say car just in today.	
	Dismantle: 31/5/2019	

ASS. REC. BY:

GL.

REF:

ASM (AXA)

PRS

ASSIGNMENT

From:

Date:

30/5/2019

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLA 330A

at Workshop m/s

Teamwork

of

53 ubi Ave 1 # 01-25

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$168k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLA 330A

Yr Regn:

06 Dec 2012

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW M5 4.4 c.c 4395

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

63607

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WB SFV 920 40 DX 95973

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 265 / 35 8R 20

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC ☒ OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

30-05-19

Survey held at

w/s

5:15 pm

Des. of Damages: Frt / Rear ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$2000 - \$3000

3/5/2019

RECEIVED 19 JUN 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

100

Transportation:

S + RS, SI

Photos

Others

TOTAL

100

Report Format:

PRS.

Lump Sum / L&B (\$



Service Request Details

Claim

S9M01OEL

Reference

CS3/ASM19009411/T1cd3 

Loss Date

May 22, 2019

Report Date

May 27, 2019 10:20:00 AM

Request Date

May 30, 2019

Due Date

May 27, 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work

More ▾

Vehicle Information

Incident Vehicle Registration #

SLA330A

Model
M5

Service Address

...

Primary Contact/Insured

TEO JANSEN
12 KITCHENER LINK, #11-25, 207224, Singapore

OETNESNAJ@GMAIL.COM

Claim Handler

KHOR Saw Theng
6568804754
sawtheng.khor@axa.com.sg

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

New Message

TYPE?

SENT5/28/19 11:22 AM

FROMLKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECTRE: DS

BODYHi Kc. wksp is not agreed with DS. Thanks. Mkwan

↩

TYPE?

SENT5/28/19 10:33 AM

SUBJECT

DS

BODY

PLS PROCEED DS WITH QUANTUM TO BE AGREED



Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Monday, 27 May 2019 11:43 AM
To: assignments
Subject: FW: OUR REF : 1905-75 // YOUR REF : SKM9568X ACCIDENT INVOLVING SKM9568X AND SLA330A
Attachments: 2019_05_27_09_41_26.pdf

Hi

TP smart. No DS.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: TEAMWORK <claims@teamworkgarage.com>
Sent: Monday, 27 May, 2019 9:44 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Cc: TEAMWORK <claims@teamworkgarage.com>
Subject: OUR REF : 1905-75 // YOUR REF : SKM9568X ACCIDENT INVOLVING SKM9568X AND SLA330A

WITHOUT PREJUDICE

OUR REF : 1905-75
YOUR REF : SKM9568X

Dear Sir / Madam,
PRE-REPAIR INSPECTION FOR SLA330A
ACCIDENT INVOLVING SKM9568X AND SLA330A ON 22.05.2019.

We refer to the above matter and enclosed herewith our client's GIA report and notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction-Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention.

Regards,

Shu Shan

Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 2475
Fax: 6844 2474



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62563562

Immediate Advice

Date: 17/06/2019

To : AXA Insurance Pte Ltd

Survey details

Date of loss	22-May-19
Date of appointment	27-May-19
Date of survey	30-May-19
Location of survey	TEAMWORK GARAGE

Vehicle Details:

Claim Type:	Third Party
Vehicle number	SLA 330A
Make and Model	B.M.W. M5 4.4 A
Date of registration	6-Dec-12
Excess	
Market Value	\$186,000
Parf Rebate	\$94,137
Nett Loss	\$91,863

Repair details

Initial Estimate	
------------------	--

Proposed/Revised repair cost:

Parts	
Check item	
Labour	
Total	
Lump Sum(if applicable)	

Number of days of repair	3
--------------------------	---

Remarks:

The estimated repair cost of the damaged vehicle is in the region of \$2,000.00 - \$3,000.00

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5049F
Vehicle Details	
Vehicle No.:	SLA330A
Vehicle to be Exported:	No
Intended Deregistration Date:	30 May 2019
Vehicle Make:	B.M.W.
Vehicle Model:	M5 4.4 A
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	21810312S63B44B
Chassis No.:	WBSFV92040DX95973
Maximum Power Output:	412.0 kW (552 bhp)
Open Market Value:	\$100,349.00
Original Registration Date:	06 Dec 2012
First Registration Date:	06 Dec 2012
Transfer Count:	2
Actual ARF Paid:	\$100,349.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Dec 2022
PARF Rebate Amount:	\$65,226.00
Intended COE Rebate Details	
COE Expiry Date:	05 Dec 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$82,289.00
COE Rebate Amount:	\$28,911.00
Total Rebate Amount:	\$94,137.00

The information contained herein is correct as at 30 May 2019

OK

▶ bmw m5 Used Vehicle List (2 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
BMW M Series M5	\$152,888	\$29,150 /yr	23-Nov-2012	4,395 cc	-		Availal

Sleeping Beauty With An Aggressive Exhaust Note. Free 1 Year Engine And Gearbox Warranty. Please Call In For Viewing. No Dealers/Consignments Please.

Office No. - -

Ben - 97801308

BMW M Series M5	\$168,000	\$32,710 /yr	11-Dec-2012	4,395 cc	36,000 km	Wheels Singapore Pte Ltd	Availal
------------------------	------------------	--------------	-------------	----------	-----------	--------------------------	---------

Expat Owner. Fussy Owner, Protective Film On Front Bonnet, Bumper, Side Mirrors And Headlights. Seldom Driven, Full Servicing Records Fr Munich. Low Mileage. Sheltered Carpark. Very Well Maintained ...

Office No. - 66815662

Benjamin - 83237600 | Mr Ng - 86857799

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/05/2019 15:35
Date Of Accident	22/05/2019 12:50
Exact Location Of Accident	46 LORONG 33 GEYLANG TWDS SIMS AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA330A
Insured/Policyholder	
Name Of Registered Owner	LOH TECK SENG
NRIC No	S8005049F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96334403
Alternative Phone No	OFFICE-96334403

Vehicle Particulars

Manufacturer	BMW
Model	M5
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10904894
Cover Note Number	

Driver

Name of Driver	CYNTHIA CHA CHIN CHIN
NRIC No	S7605449E
Date Of Birth	24/02/1976
Occupation	INDOOR
Date Of Driving Pass	03/08/1994
Driving Experience	24 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92966966
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 60 LENGKONG TIGA #08-01
 Postcode 417454
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured FRIEND
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1 NAME: : MICHELLE LIM
 GENDER: : FEMALE
 Passenger 2 NAME: : CHOO CHOON LENG
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG 46 LORONG 33 GEYLANG TOWARDS SIMS AVE. WHEN I WAS CHECKING THE MAIN ROAD IS CLEAR BEFORE TURNING INTO SIMS AVE. SUDDENLY, I FELT AN IMPACT FROM MY REAR. WHEN I GOT DOWN FROM MY VEHICLE, I REALISED THAT VEHICLE B COLLIDED ONTO MY VEHICLE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKM9568X
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A: SLA 330 A

R: SKM 9568 X





**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS3/ASM19009411/Gcd3e2		
8 SHENTON WAY #24-01		Date: 20-06-2019		
AXA TOWERSINGAPORE 068811				
ATTN : KHOR SAW THENG		Code: ASM		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SKM 9568X	Veh. Inspected	SLA 330A	
Policy No.		Coverage (\$)	0.00	
Claim No.	S9M01OEL	Excess (\$)	0.00	
Assign From	KHOR SAW THENG	Assign Date	27/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. M5 4.4	c.c	4395	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WBSFV92040DX95973	Colour	BLACK	
Odometer	63607 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	265/35Z R20	MICHELIN	6 mm	
L/H Front Tyre	265/35Z R20	MICHELIN	6 mm	
R/H Rear Tyre	265/35Z R20	MICHELIN	6 mm	
L/H Rear Tyre	265/35Z R20	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	22/05/2019	Inspect Date / Time	30/05/2019 (05:15 PM)	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

Report Ref No. CS3/ASM19009411/Gcd3e2

Inspected By



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEE,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.