

22/03/2019

ASS. REC. BY:

REF:

CS3/PCS/9009416/Ed30

Special Instruction:

Surveyor: Steve

Murphy

ASSIGNMENT (Office)

From (Person): Desmond Lee of FES

Date/Time: 28/5/2019 @ 2pm

Estimated Cost: Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLV437R Insured: SKQ3208D

at Workshop m/s Jun Xing Motor Tel: 6858 1074

of Blk 5034 Amk Ind. Park 2 # 01-321

Policy No: Claim No: DMPC19001384/DL

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 27/5/2019

CA / REV / REP. / REV 24 HRS Cup

H.O.D. Endorsement:

Date/Time: 4:36pm @ 28/5/19 Person Contacted: Victoria Vehicle IN (OUT)

Date/Time	Action/Instruction	Estimate	(X)
	SKQ 3208D - X		
	SLV437R - X		
	Dismantle: 31/5/2019		
	After repair: 3/6/2019		

Steve

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/b: _____

of: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S

Veh No: SLV 437R Vt Rego: 23/7/10

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mazda 3 cc: 1598

Colour: Red A/C: Insured / Std / NI

Sp. Reading: 152878 T/Radio: Insured / Std / NI

Eng/No: _____

Ci/No: JM6BL10Z1A0115498

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 7 mm R/Bal. 7

L/Bal. 7 mm L/Bal. 7

D.O.A. 27/5/19 D.O.A. 30/5/19

Survey held at Jun Xing

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to:

Date / Time / Action / Instruction

MV - 20000
 PV - 15293
 NV - 4707

repair days - 3
 repair charge - 12K - 2K

[Signature]
 2/6/2019

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: 3
 Resurvey No. of Trip: 3

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	100
Transportation	100
3. R.C. CI	100
Photos	
Labels	11
	311

Report Format: PRG

Lump Sum / I.B. I: (\$)

Nivitha (LKK Auto)

From: Desmond Lee Ker Wen (ECICS, Claims) <Desmond_Lee@ecics.com.sg>
Sent: Tuesday, 28 May 2019 2:00 PM
To: Accident@kscgp.com; Surinda B (IFST); assignments@lkkauto.com;
sur@lkkauto.com
Cc: jiapei@kscgp.com
Subject: RE: Notice to conduct pre-repair survey (Our Ref:DMPC1900138H/DL - SKQ3208D
// Your Ref: SLV 437R/JX/jp/ws)
Attachments: 2nd PRS 190528.pdf

Dear Wan Sim

We are not agreeable to your list of appointed surveyors.

We are appointing LKK for the PRI.

Hi LKK

Kindy assist in the PRI

Best regards

Desmond Lee

Senior Associate | Claims



DID (65) 6303 0167

Tel (65) 6337 4779

Email Desmond_Lee@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Accident@kscgp.com [mailto:Accident@kscgp.com]
Sent: Tuesday, 28 May 2019 11:39 AM
To: Desmond Lee Ker Wen (ECICS, Claims)
Cc: jiapei@kscgp.com
Subject: RE: Notice to conduct pre-repair survey (Our Ref:DMPC1900138H/DL - SKQ3208D // Your Ref: SLV 437R/JX/jp/ws)

Dear Desmond,

We enclose herewith our 2nd Notice to conduct pre-repair survey. Our client is not agreeable to your proposed surveyors.

The workshop's details are as follows:

Jun Xing Motor Services Pte Ltd
Block 5034 Ang Mo Kio Industrial Park 2 #01-321
Singapore 569537

Contact: Ms. Victoria Yong / Tel: 6858 1074 / Fax: 6481 5486

Thank you.

Regards,
Wan Sim
for and on behalf of Mr Gurdeep Singh Sekhon
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: Desmond Lee Ker Wen (ECICS, Claims) [mailto:Desmond_Lee@ecics.com.sg]
To: Accident@kscgp.com
Sent: Tue, 28 May 2019 01:45:04 +0000
Subject:

Without prejudice

Dear Wan Sim

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop.

We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Best regards

Desmond Lee

Senior Associate | Claims



DID (65) 6303 0167

Tel (65) 6337 4779

Email Desmond.Lee@ecics.com.sg

Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: ECICS Claims

Sent: Tuesday, 28 May 2019 8:54 AM

To: Desmond Lee Ker Wen (ECICS, Claims)

Cc: ECICS Claims

Subject: FW: Notice to conduct pre-repair survey (Your Ref: SKQ 3208D; Our Ref: SLV 437R/JX/jp/ws)

Hi Desmond

Please assist.

Thank you.

Best regards

Janice Goh

Senior Associate | Claims



DID (65) 6303 0182

Tel (65) 6337 4779

Email janice_goh@ecics.com.sg

Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Accident@kscgp.com [mailto:Accident@kscgp.com]

Sent: Monday, 27 May 2019 6:29 PM

To: ECICS Claims

Cc: jiapei@kscgp.com

Subject: Notice to conduct pre-repair survey (Your Ref: SKQ 3208D; Our Ref: SLV 437R/JX/jp/ws)

Dear Sirs,

We enclose herewith our 1st Notice to conduct pre-repair survey for your necessary action.

Thank you.

Regards,

Wan Sim

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

This email has been scanned by the MxScan Email Security System.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Your Ref : DMPC1900138H/DL

Our Ref : SLV 437R/JX/jp/ws

Date : 28 May 2019

Fax : 6538 3708

Tel : 3152 0989

Email : accident@kscgp.com

ECICS Ltd

BY EMAIL ONLY

DATE OF ACCIDENT: 27 May 2019

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email of even date.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/no.	Name of Surveyor
1	Ho Joo Loong, Danny
2	Lee Kok Weng
3	Seah Kwang Boon

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Jun Xing Motor Services Pte Ltd
Block 5034 Ang Mo Kio Industrial Park 2 #01-321,
Singapore 569537

Contact Person/Tel : Ms. Victoria Yong / Tel: 6858 1074 / Fax: 6481 5486

Yours faithfully,

WS

Your Ref : DMPC1900138H/DL

Our Ref : SLV 437R/JX/jp/ws

Date : 28 May 2019

Acknowledgement

This is to confirm that I _____ *[Full Name of Surveyor]* of
_____ *[Surveyor's Company]* have completed as follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (part by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post – Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4682B
Vehicle Details	
Vehicle No.:	SLV437R
Vehicle to be Exported:	No
Intended Deregistration Date:	30 May 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 1.6L SDN LUX
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	Z6810778
Chassis No.:	JM6BL10Z1A0115498
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$21,679.00
Original Registration Date:	23 Jul 2010
First Registration Date:	23 Jul 2010
Transfer Count:	2
Actual ARF Paid:	\$21,679.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jul 2020
PARF Rebate Amount:	\$11,923.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jul 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$29,501.00
COE Rebate Amount:	\$3,370.00
Total Rebate Amount:	\$15,293.00

The information contained herein is correct as at 30 May 2019

OK

THE DBS MULTIPLIER ACCOUNT

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 10 Years Coe Renewal Toyota Wish 1.8A



2.98%p.a \$0 Admin Fees@Gv
Finance.2 Years Warranty.
Monthly From \$788.
GV Credit Pte Ltd StarAd

HIN LUNG AUTO
Ho Bee Group **30 years of car sale**
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

Browse by Category

Sort by Date Posted 20 results/page

5 vehicles

Mazda 3

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mazda 3		Any	Any	2010	Any	Any	Any	Availabl
	Mazda 3	Mazda 3 1.6A (New 5-yr COE)	\$32,800	\$6,550 /yr	29-Mar-2010	1,598 cc	137,730 km	Sedan	Availabl
Short Term Use, Better Than Rental, Tip Top Condition, New Paint And New 5 Year COE, 17" Sports Rims, When COE Expiring Body Value \$1000, Road Tax Till 28/9/2019. Minimum Parf \$10300.									
Posted: 29-May-2019 Tags: 2010 Mazda 3, 2010 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda 3	Mazda 3 1.6A Luxury	\$16,800	\$7,180 /yr	29-Mar-2010	1,598 cc	124,600 km	Sedan	Availabl
100% Loan Available, Full Loan Available, New Arrival, Very Well Kept. Super Spacious, Original Paint Work ACT Now Test Drive Today!									
1axis Posted: 16-May-2019 Tags: 2010 Mazda 3, 2010 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda 3	Mazda 3 1.6A Luxury	\$19,800	\$9,330 /yr	29-Jun-2010	1,598 cc	-	Sedan	Availabl
Low Depreciation, Best For Pte Hire. Well Maintained No Repair Needed. High Bank Loan/In House Loan, Trade In Welcome.									
Posted: 16-May-2019 Tags: 2010 Mazda 3, 2010 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda 3	Mazda 3 1.6A Luxury	\$22,688	\$8,870 /yr	22-Sep-2010	1,598 cc	-	Sedan	Availabl
Loan Available, Trade In Welcome, Price Negotiable, Call Or Visit Our Showroom For Viewing Now! Please Call For Viewing And Test Drive. Flexible Loan Available.									
Posted: 10-May-2019 Tags: 2010 Mazda 3, 2010 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.

	Mazda 3	Mazda 3 1.6A Luxury	\$19,700	\$9,640 /yr	11-May-2010	1,598 cc	164,000 km	Sedan	Availabl
Well Maintained, Mint Condition. Ideal For Short Term Usage With Low Depreciation.									
Posted: 10-May-2019 Tags: 2010 Mazda 3, 2010 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									

Save this search criteria, to get email alerts whenever a match is found.

Compare Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/05/2019 16:19
Date Of Accident	27/05/2019 07:30
Exact Location Of Accident	PIE (TUAS)18.5 NEAR CJC
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV437R
Insured/Policyholder	
Name Of Registered Owner	FONG HUI XIAN PEBBLE
NRIC No	S9034682B
Email Address	PEBBLEFONG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96179025
Alternative Phone No	OFFICE-96179025
Vehicle Particulars	
Manufacturer	MAZDA
Model	3-1.6 SP LUX (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA410953/1
Cover Note Number	
Driver	
Name of Driver	FONG HUI XIAN PEBBLE
NRIC No	S9034682B
Date Of Birth	23/09/1990
Occupation	INDOOR
Date Of Driving Pass	09/09/2011
Driving Experience	7 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96179025
Fax Number	
Contact Number	OFFICE-96179025
EEmail Address	PEBBLEFONG@GMAIL.COM

USS	BLK 348 UBI AVE 1 #09-1047
code	400348
as driver an employee of the Insured's Company	NO
No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	JJT8144 (MOTORCYCLE)
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PASSENGER 1
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	NANYANG N.P.C
Police Station Address	ROAD: 2 JURONG WEST AVE 5 , POSTCODE: 649482 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7929999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKQ3208D
Vehicle Make/Model/Colour	CAR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WU MIN SHI
NRIC/Passport Number	
Contact Number	97621401

ss
ode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number JJT8144
Vehicle Make/Model/Colour MOTORBIKE
Details Of Properties
Vehicle Category MOTORCYCLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name UNKNOWN
Approximate Age
Injuries Sustain
Injured person in which vehicle? JJT8144
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 27/5/19 1600H

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 27/5/19 at around 0930H, I was driving my car bearing registration no. SLV4372 on the second lane along PIE TMS (18-51km) after EXIT 18 & noticed an accident had happened ahead of me. I managed to stop my vehicle in time, however, out of a sudden, one vehicle bearing registration no. SKQ3208D had collided into the rear of my car.

I got out from my car & realised a chain accident had happened. The Traffic Police was at the scene to assist & had advised me to lodge a police report.


SKQ3208D Subaru Forester XT (MR WM MIN SHI : 97621401)

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 27/5/19 1600H

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 27/5/19
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

Midnight Accident

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jun 2019 08:24 Edit Reg		28 May 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	-, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM								
Main Claimant:	-								
Vehicle Reg. No.:	SLV437R	Date of Loss:	27/05/2019 00:00 - :59 [106 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / DMPC1900138H/DL		Policy/Cover Note No.:						
Vehicle Reg. No. (Insured):	SKQ3208D	Policy No. (Claimant):							
		Excess:							
Repairer:	Jun Xing Motor Service (HQ) Blk 5034 #01-321 Ang Mo Kio Industrial Park 2, 569537 Ang Mo Kio - Tel:								
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Desmond Lee - 6303 0167]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 07/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLV437R (DMPC1900138H/DL)
[SKQ3208D]

TP

-
May 27 2019 12:00AM

[-]

Jun Xing Motor Service

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			View <input type="button" value="View in Browser"/>
Photos/Images			3 per page <input type="button" value="v"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="button" value="Print"/>
1	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
2	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
3	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
4	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
5	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
6	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
7	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
8	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
9	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
10	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
11	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
12	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
13	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
14	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
15	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
16	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
17	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
18	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
19	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
20	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
21	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
22	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
23	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
24	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
25	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
26	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
27	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
28	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
29	14/06/19 09:44	General View	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
30	14/06/19 09:45	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
31	14/06/19 09:45	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
32	14/06/19 09:45	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
33	14/06/19 09:45	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
34	14/06/19 09:45	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
35	14/06/19 09:45	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
36	14/06/19 09:45	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>
37	14/06/19 09:45	Photographs of Damaged Parts	<input type="button" value="i"/> Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
38	14/06/19 09:45	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
39	14/06/19 09:45	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
40	14/06/19 09:45	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
41	14/06/19 09:45	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
42	14/06/19 09:45	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
43	14/06/19 09:45	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
44	14/06/19 09:45	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
45	14/06/19 09:47	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
46	14/06/19 09:47	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
47	14/06/19 09:47	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
48	14/06/19 09:47	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
49	14/06/19 09:47	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
50	14/06/19 09:47	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
51	14/06/19 09:47	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
52	14/06/19 09:47	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
53	14/06/19 09:47	Photo After Spray		Load JPG <input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/ICS19009416/ECD3E2**Date:** 24/06/2019REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No : SLV437R**Insured Vehicle No :** SKQ3208D

Date of Loss: 27/05/2019

Nature of Claim: TP

Claim No: DMPC1900138H/DL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLV437R**

Make & Model: MAZDA 3, 1.6 SP Lux (A)

Engine No: Z6810778

Reg. Date: 23/07/2010 (Man. Year: 2009)

Chassis No: JM6BL10Z1A0115498

Colour: Red

Odometer: 152878 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 7 mm

Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/05/2019

Date Inspected: 30/05/2019 Inspected At:

Jun Xing Motor Service (HQ)
Blk 5034 #01-321 Ang Mo Kio Industrial
Park 2
Singapore 569537

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,200.00 -\$2,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Jun 2019)
Parts: 143	MAZDA 3 1.6 SP Lux (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV437R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >