

22/03/2002

ASS. REC. BY:

REF:

CS3/III19009417/Gcd3h

Special Instruction:

Surveyor: Gubriel Wice
in Wice

ASSIGNMENT (Office)

From (Person): Gubriel Wice

of

III

Date/Time:

28/5/2019 @ 2:35pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 4296J

Insured:

SHA 1164D

at Workshop m/s

Neo Automotive

Tel:

90914853

of

53 ubi Ave L #05-44 puyubon Ind. Park

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/5/2019

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

3:23pm 28/5/19

Person Contacted:

Mrs. NEOVehicle IN OUT

Date/Time	Action/Instruction	Estimate (X)
	<u>SLB 4296J - NA/INC19009269/h4</u>	<u>20A 28/5/2019</u>
	<u>SHA 1164D - NA/INC19009269/h4</u>	<u>20A 28/5/2019</u>
	<u>Dismantle: 29/5/2019 0526pm</u>	
	<u>After repair: 31/5/2019 0519pm</u>	

ASS. REC. BY:

PRS
622.

REF:

III

ASSIGNMENT

From:

Date:

28/5/2019

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLB 4296J

at Workshop m/s

Neo Automotive

of

53 ubi Ave 1 # 05-44

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
	<input checked="" type="radio"/>

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

- 3

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

1up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLB 4296J

Yr Regn:

- /

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota AX10 1.5X C.C 1496

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

249373

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NRE 1610011364

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ M / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ FIRENZA / SUMI /

TOYO / YOKO or

FIRENZA

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

28-05-19

Survey held at

IDAC UBI NAC 0515pm

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$ 2000 - \$ 3000

RECEIVED 07 JUN 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS \$1

Photos

Other:

TOTAL

Report Format:

PRS

Lump Sum / L.B.J. (\$)

120

11

131

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRT

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	(Not Notified) Edit Reg		28 May 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:									
Main Claimant: NEO AUTO LEASING PTE LTD, Co. Reg. No.: 201814915N									
Vehicle Reg. No.: SLB4296J		Date of Loss: 26/05/2019 14:00 - :59							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SHA1164D		Policy No. (Claimant):							
		Excess:							
Repairer: Neo Automotive (HQ) 53 UBI AVE 1 #05-44 PAYA UBI INDUSTRIAL PARK SINGAPORE, 408934 Ubi - Tel:									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pooi Chin Han Daniel]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 07/06/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 28 May 2019 2:35 PM
To: Helen; 'sur@lkkauto.com'; admin-d@lkkauto.com
Cc: Pooi Chin Han Daniel
Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLB4296J(Accident involving SLB4296J and SHA1164D on 26.05.2019)
Attachments: sha1164d_20190528142618.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SLB4296J
III INSURED VEHICLE NO. : SHA1164D
DATE OF LOSS : 26.05.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Daniel**.

Please let us have your client's **accident report and repair estimate** for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



883 North Bridge Road
#11-03 Southbank
Singapore 198785
T: 6292 5838
F: 6292 5938
(UEN No. 201333127N)
(GST Reg No. 201333127N)

Our Ref : CY.SLB4296J.19.NA.wp(PT)

Your Ref : Your Insured vehicle SHA 1164D

28 May 2019

Comfort Transportation Pte Ltd
c/o India International Insurance Pte Ltd
(Motor Claims Department)
64 Cecil Street #04/#05 IOB Building
Singapore 049711



BY Fax No: 6224 4174

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES
ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SLB 4296J & SHA 1164D ON
26.05.2019 @ 14:35HRS AT CLAYMORE RD (PALAIS RENAISSANCE DROP OFF POINT)**

We are instructed by Neo Auto Leasing Pte Ltd to notify you of a road traffic accident on 26.05.2019 at about 14:35hrs along Claymore Rd (Palais Renaissance Drop Off Point) involving our client's customer's vehicle registration number SLB 4296J and vehicle registration number SHA 1164D driven by you at the material time. A copy of the Singapore accident statement report is enclosed.

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

At the same time, our proposed list of surveyors is appended as below:-

1. Lee Kok Weng
2. Seah Kwang Boon
3. Amas Ong Poh Meng
4. Louis Ng

Yours faithfully,


C. Yogarajah LLC
Enc

Cc: M/s. Neo Automotive Pte Ltd
53 Ubi Ave 1
#05 - 44 Paya Ubi Industrial Park
Singapore (408934)
Mrs. Neo (9091 4853)
Fax no : 6385 8262

Confidentiality & Privilege: This message is intended for the recipient to whom it is addressed. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. Disclaimer: Mail/Fax/Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has been securely transmitted and not been tampered with, C. Yogarajah LLC cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this communication for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the firm shall be understood as neither given nor endorsed by C. Yogarajah LLC Advocates & Solicitors. Thank you.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4915N
Vehicle Details	
Vehicle No.:	SLB4296J
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X CVT ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	2NR8526846
Chassis No.:	NRE1610011364
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$14,472.00
Original Registration Date:	07 Apr 2016
First Registration Date:	07 Apr 2016
Transfer Count:	2
Actual ARF Paid:	\$9,472.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Apr 2026
PARF Rebate Amount:	\$7,104.00
Intended COE Rebate Details	
COE Expiry Date:	06 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,000.00
COE Rebate Amount:	\$30,740.00
Total Rebate Amount:	\$37,844.00

The information contained herein is correct as at 07 Jun 2019

OK

27/05/2019 17:06 63858262

PAGE 01/06

MNA11006638 / National Assessment Centre Services - Ubi
ENTRY DATE & TIME: 27/05/2019 14:08
SUBMITTED BY: Liew Shun Hui

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 27/05/2019 14:08
Date Of Accident 26/05/2019 14:35
Exact Location Of Accident CLAYMORE DR (PALAIS RENAISSANCE DROP OFF POINT)
Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLB4296J
Name Of Registered Owner NEO AUTO LEASING PTE LTD
Co Reg No 201814915N
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-91449265

Vehicle Particulars
Manufacturer TOYOTA
Model AXIO
Exact Purpose for which vehicle was being used at time of accident COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE HIRE

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy NO
Policy Number 6103424803
Cover Note Number

Driver
Name of Driver TENG HEONG CHEONG
NRIC No S1398313E
Date Of Birth 13/11/1959
Occupation OUTDOOR
Date Of Driving Pass 11/10/1978
Driving Experience 40 YEARS AND 7 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-90286198
Fax Number
Contact Number
Email Address NOEMAIL

27/05/2019 17:06 63858262

PAGE 02/06

Address BLK 636 BEDOK RESERVOIR RD #13-27
 Postcode 410636
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : UNKNOWN
 GENDER: : FEMALE

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

I WENT TO THE CLAYMORE DR TO PICKING UP MY PASSENGER, THERE WAS ROAD END INFRONT OF THE PALAIS RENAISSANCE, I INTEND MAKE A U TURN, WHILE MAKING THE U TURN, THERE WAS ANOTHER STATIONARY INFRONT OF ME, I HAVE TO REVERSE MY VEH TO MOVING OFF, WHEN I CHECK TRAFFIC BEHIND WAS CLEAR, I ENGAGED MY REVERSED GEAR PREPARE TO REVERSE, BEFORE REVERSING MY VEH, SUDDENLY I FELT AN IMPACT FROM BEHIND, AFTER THE INCIDENT, I ALIGHTED FROM MY VEH AND REALIZED VEH B FROM BEHIND COLLIDED ONTO MY VEH REAR PORTION.

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA1164D
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category TAXI
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident as speed up the claim's process.
2. This form must be completed by the Policyholder and/or the Authorized Officer.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to cancel the policy/claim.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false information may be referred to the Police for investigation.
6. The report will be forwarded by the Insurance of the CMA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will have to be made available upon application by interested parties.
7. By the completion of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available as stated.
8. Consents under the Personal Data Protection Act (PDPA)
(understand, acknowledge, agree and consent that:
(a) my Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form) and any other personal information provided by me or processed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurers who have insured vehicles involved in this accident (all Insurers who have insured vehicles involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claim and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instruction or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the evidence I provide in documents/notes/packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
(b) all Insurers who have insured vehicles involved in this accident and the Insurers' lawyers/firm may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party all vice provided be permitted (including their lawyers/firm), which may be used outside of Singapore, for one or more of the above Purposes;
(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management of present and all future claims;
(e) the information as contained under (d) above may be shared / disclosed:
(i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulatory, law enforcement and government agencies as reasonably required for the purposes stated; or
(ii) for complying with requirements under any regulatory, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Officer's Signature
Name:
NIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

Sketch Plan area with grid lines and handwritten notes. The notes include "A = 528 5393" and "B = 518 104D". There are also some symbols and a small diagram of a vehicle or structure.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Large rectangular area for describing the circumstances of the accident. It contains a diagonal line drawn across it, and the word "Please" is written at the top left.

DECLARATION

I/We declare the foregoing particulars are true to the best of my/our knowledge.

Portyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Officer/Personnel's Signature
Name
NRIC/PPN No.

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jun 2019 11:58 Edit Reg		28 May 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case





















Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	NEO AUTO LEASING PTE LTD, Co. Reg. No.: 201814915N								
Vehicle Reg. No.:	SLB4296J	Date of Loss:	26/05/2019 14:00 - :59 [37 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SHA1164D	Policy No. (Claimant):							
		Excess:							
Repairer:	Neo Automotive (HQ) 53 UBI AVE 1 #05-44 PAYA UBI INDUSTRIAL PARK SINGAPORE, 408934 Ubi - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pooi Chin Han Daniel]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 07/06/2019]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLB4296J
[SHA1164D]
TP
NEO AUTO LEASING PTE LTD
May 26 2019 2:00PM
[-]
Neo Automotive

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
2	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
3	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
4	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
5	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
6	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
7	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
8	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
9	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
10	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
11	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
12	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
13	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
14	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
15	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
16	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
17	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
18	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
19	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
20	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
21	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
22	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
23	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
24	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
25	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
26	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
27	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
28	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
29	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
30	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
31	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
32	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
33	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
34	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
35	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
36	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					
37	07/06/19 12:59	General View		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	07/06/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	07/06/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	07/06/19 13:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	07/06/19 13:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	07/06/19 13:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	07/06/19 13:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	07/06/19 13:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	07/06/19 13:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	07/06/19 13:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	07/06/19 13:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	07/06/19 13:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	07/06/19 13:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	07/06/19 13:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	07/06/19 13:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	07/06/19 13:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	07/06/19 13:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	07/06/19 13:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	07/06/19 13:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	29/05/19 08:46	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19009417/GCD3E2

Date: 10/06/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SLB4296J

Insured Vehicle No : SHA1164D

Date of Loss: 26/05/2019

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB4296J

Make & Model: TOYOTA AXIO, 1.5 (A)

Reg. Date: 07/04/2016 (Man. Year: 2015)

Colour: Silver

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

Engine No: 2NR8526846

Chassis No: NRE1610011364

Odometer: 249373 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size:

185/60 R15

Front Left Side: Firenza 6 mm

Rear Left Side:

Firenza 6 mm

Front Right Side: Firenza 6 mm

Rear Right Side:

Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/05/2019

Date Inspected: 28/05/2019 Inspected At:

Neo Automotive (HQ)

53 UBI AVE 1 #05-44 PAYA UBI
INDUSTRIAL PARK SINGAPORE
Singapore 408934

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Jun 2019)
Parts: 143	TOYOTA AXIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLB4296J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >