



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19009429/Kpa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 17-08-2020



ATTN:KIAN CHUAN

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SCQ 809J	Veh. Inspected	SJL 9498G
Policy No.	VA1/GA172478	Coverage (\$)	0.00
Claim No.	S9M01OOK	Excess (\$)	0.00
Assign From		Assign Date	28/05/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053ZEE106121892	Colour	METALLIC GREEN
Odometer	128705	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	HIFLY	8 mm
L/H Front Tyre	205/55 R16	HIFLY	8 mm
R/H Rear Tyre	205/55 R16	HANKOOK	3 mm
L/H Rear Tyre	205/55 R16	HANKOOK	3 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	26/05/2019	Inspection Date	29/05/2019
Survey held at	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	-----------------------