

ASS. REC. BY: Steve

REF: EQP

9438 (E H)

ASSIGNMENT

From: \_\_\_\_\_ Date: 31/5/2019

Estimated Cost: \_\_\_\_\_

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLV 6206 B

at Workshop m/s: Borneo Motor

of: Spandan Crescent

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: 10am-11am Raymond

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLV 6206 B Yr Regn: 8/01/18

Type: (M) Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toyota Airtis c.c. 1598

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 15423 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MRO53 REH 604576793

Gen. Cond: (Good) / Fair / Poor / Burnt

Steering: (In) order / Jammed / Leaked / Burnt or

Brake: (In) order / Jammed / Leaked / Burnt or

Modi: Nil / (S) Rim / STD A/Rim or

Tyre Size: F: 205/55R16 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / (Y) OKO or

Front R/Bal. 7 mm Rear R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 23/5/19 D.O.I. 31/5/19

Survey held at Borneo Motor

Des. of Damages: (Frt) Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV - 85k

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / L.B.I. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_ \$ + RS, \_\_\_ \$

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL \_\_\_\_\_

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9892H
Vehicle Details	
Vehicle No.:	SLV6206B
Vehicle to be Exported:	No
Intended Deregistration Date:	31 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS STANDARD AUTO
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	1ZR0A56906
Chassis No.:	MR053REH604576793
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,741.00
Original Registration Date:	08 Jan 2018
First Registration Date:	08 Jan 2018
Transfer Count:	0
Actual ARF Paid:	\$19,741.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Jan 2028
PARF Rebate Amount:	\$14,805.00
Intended COE Rebate Details	
COE Expiry Date:	07 Jan 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,200.00
COE Rebate Amount:	\$32,860.00
<b>Total Rebate Amount:</b>	<b>\$47,665.00</b>

The information contained herein is correct as at 31 May 2019

OK