

22/03/2012

ASS. REC. BY:

REF: CS/CT19009443/4d302

Special Instruction:

Surveyor: MARTASASSIGNMENT (Office)From (Person): ong chin kiatof CT1Date/Time: 22.5.19 18.40p.m

Estimated Cost:

Bill to:

OD-TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: PBJ 5377DInsured: GZ 2003Jat Workshop m/s Dirt Wheel MotorTel: 96676280of BK: 9004 Tampinase Strut 93, # 01-100Policy No: D MCVSN 30016319000Claim No: SNM19020177302

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 21.4.2019

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 29.5.19 9.09a.m

Person Contacted:

mikeVehicle IN/OUT

Date/Time

Action/Instruction

Estimate (✓)

PBJ 5377D-X

GZ 2003J-X

(08/11/13)

REF CT1

ASS. REC. BY:

## ASSIGNMENT

From:

Date:

29.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBJ 5377 D

at Workshop m/s

Dist Wheel / Moto

of B1K 9004 Tampines Street 93, #01-100

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

7k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

mvp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBJ 5377 D

Yr Regn:

7, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KTM 200 Duke

C.C.

200

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

Batter Key

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VBKJU C407E. 009982

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110-70R17

R:

160/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

21/4/19

D.O.I.

29/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S, N/S Body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/6/19 11A 1879 hrs.  
Confused L/S & 2700 with muke. (Red: 1887, 41%)

RECEIVED 27 JUN 2019

Date/Time, File Pass to?



Preli. Report



Final Report

1) 26/6 Typist

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

220

Transportation:

S + RS, SI

Photos

Others

TOTAL

220

Report Format:

TP

Lump Sum / I.B.I. (\$

2700)

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2019		28 May 2019 18:40 Assign				<b>New Assignment</b> Cancel Case

Main

Reference

Claim Details

Documents

Show All

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HAI LEE SEAFOOD TRADING COMPANY, Co. Reg. No.: 22115000E		
Main Claimant:	GABRIEL CHEN HONG, ID: S9842878Z		
Vehicle Reg. No.:	FBJ5377D	Date of Loss:	21/04/2019 11:00 - :59 [57 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D201773C02	Policy/Cover Note No.:	DMCVSN30016319000 (Comprehensive)
Vehicle Reg. No. (Insured):	GZ2003J	Policy No. (Claimant):	5105840216
		Excess:	S\$0.00
Repairer:	Dirt Wheel Motor Trading (HQ) Blk 9004 Tampines Street 93, #01-100, 528838 Tampines - Tel: 67833063		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/06/2019]		
Driver/Custodian (Insured):	LI SHICHENG (29 / Male), NRIC: G8598873K Email:		
Adj Asg. Remarks:	to assign Mr Marcus Chua for SJE. please contact Mr Mike at 9667 6280 / 6783 3063 to arrange for survey. thank you.		

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	2878Z
<b>Vehicle Details</b>	
Vehicle No.:	FBJ5377D
Vehicle to be Exported:	No
Intended Deregistration Date:	30 May 2019
Vehicle Make:	K.T.M.
Vehicle Model:	200 DUKE
Primary Colour:	White
Secondary Colour:	Orange
Manufacturing Year:	2014
Engine No.:	0490641646
Chassis No.:	VBKJUC407EC009982
Maximum Power Output:	-
Open Market Value:	\$3,923.00
Original Registration Date:	03 Jul 2014
First Registration Date:	03 Jul 2014
Transfer Count:	2
Actual ARF Paid:	\$589.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	02 Jul 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,890.00
COE Rebate Amount:	\$1,979.00
<b>Total Rebate Amount:</b>	<b>\$1,979.00</b>

The information contained herein is correct as at 30 May 2019

OK

Bike model  
KTM 200 Duke


Type  
Any

Price From  
Any

Price To  
Any

Class  
Any

MORE SEARCH OPTIONS ▼

Q SEARCH  VIEW ALL (/LISTING/USEDBIKES/LISTING/)

Q SEARCH ▼

KTM 200 Duke (/listing/usedbike/ktm-ktm-200-duke/12450/)



(/listing/usedbike/ktm-ktm-200-duke/12450/)

**SGD\$11000**

Reg : 31/03/2016

Type: Street Bikes

200cc

-

KTM 200 Duke on sale. Interested parties are welcome to Neg. Trade/Loan available. Do visit us at Wing Fuat @ Sims Place. No Early Settlement Fee.

Posted on : 26/05/2019

★ PAID AD    ★ DEALER AD

 COMPARE    DETAILS > (/LISTING/USEDBIKE/KTM-KTM-200-DUKE/12450/)

KTM 200 Duke (/listing/usedbike/ktm-ktm-200-duke/9087/)



(/listing/usedbike/ktm-ktm-200-duke/9087/)

**SGD\$9800**

Reg : 11/07/2015

Type: Street Bikes

200cc

KTM Duke 200 COE expire july 2025. Low weight and easy handling. Stock condition. Loan available, welcome trade in. Come visit us at Sin Boon Motor. Interested buyers are welcome to negotiate.

Posted on : 12/05/2019

★ PAID AD    ★ DEALER AD

■ COMPARE    DETAILS > (/LISTING/USEDBIKE/KTM-KTM-200-DUKE/9087/)

KTM 200 Duke (/listing/usedbike/ktm-ktm-200-duke/12638/)



(/listing/usedbike/ktm-ktm-200-duke/12638/)

**SGD\$9500**

Reg : 07/03/2016

Type: Street Bikes

200cc

9310km

Color Original but Sticker is Faded on right side (photo). Lady Rider seldom Ride, Low mileage. Condition good. Plat no 3 digit. Service only at KTM. Insurance & Road Tax Mar 2020. To view the bike...

Posted on : 11/05/2019

★ PAID AD    ★ DIRECT SELLER

■ COMPARE    DETAILS > (/LISTING/USEDBIKE/KTM-KTM-200-DUKE/12638/)

KTM 200 Duke (/listing/usedbike/ktm-ktm-200-duke/12856/)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	17/05/2019 12:37
Date Of Accident	21/04/2019 11:00
Exact Location Of Accident	LOYANG AVENUE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FBJ5377D
Insured/Policyholder	
Name Of Registered Owner	GABRIEL CHEN HONG
NRIC No	S9842878Z
Email Address	CRATEZ9245@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81216403
Alternative Phone No	OTHERS-81216403
Vehicle Particulars	
Manufacturer	KTM
Model	200 DUKE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5105840216
Cover Note Number	
Driver	
Name of Driver	GABRIEL CHEN HONG
NRIC No	S9842878Z
Date Of Birth	24/12/1998
Occupation	INDOOR
Date Of Driving Pass	15/11/2018
Driving Experience	0 YEAR AND 5 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81216403
Fax Number	
Contact Number	OTHERS-81216403
Email Address	CRATEZ9245@GMAIL.COM

Address	BLK 184 #07-54 PASIR RIS STREET 11
Postcode	510184
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

AS PER POLICE REPORT No.T/20190427/7030;

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### Details of Witness 1

Name	TAN JUN LONG, JASON
Phone Number	98809808
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ2003J
Vehicle Make/Model/Colour	TOYOTA DYNA 150 D
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	



Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1	
Name	GABRIEL CHEN HONG
Approximate Age	20
Injuries Sustain	
Injured person in which vehicle?	FBJ5377D
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 184 #07-54 PASIR RIS STREET 11
Postcode	510184

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

17 MAY 2019


Policyholder's Signature

Date & Time: 17/05/19

Driver's Signature

(If driver is not the policyholder)

Date & Time:

**IDAC KAKI BUKIT (VAC)**


Reporting Centre 23 Kaki Bukit Ave 4

Name: Singapore 415933

NRIC/TEL: 67416697 Fax: 67492305

Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer  
To Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*  
Policyholder's Signature  
Date & Time: 17/05/19

*[Signature]*  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

17 MAY 2019

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Reporting Centre Personnel's Signature  
Name: Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

# Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190427/7030

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20190427/7030

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/04/2019 23:58		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: GABRIEL CHEN HONG			Address: APT BLK 184 PASIR RIS STREET 11 #07-54 SINGAPORE 510184		
ID Type / ID No.: NRIC NO / S9842878Z			Contact No.: Home/Office: Mobile: 81216403		
Nationality: SINGAPORE CITIZEN			Email: cratez9245@gmail.com		
Sex: Male	Age: 20	Date of Birth: 24/12/1998	Type of Informant: Rider		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Student			Driving Licence Information: Class: 2B Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 21/04/2019 10:45	Type of Location: T-Junction
Location:  PASIR RIS DRIVE 1				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBJ5377D	Motorcycle	KTM	200 DUKE	White		0
GZ2003J	Lorry			White		0

<b>Details of Vehicle Insurance</b>				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBJ5377D	NTUC Income Insurance Co-Operative Limited	5105840216	29/11/2018	28/11/2019

# Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190427/7030

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20190427/7030

## CONTINUATION OF REPORT

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Rider</b>			
Name	GABRIEL CHEN HONG	ID No.	S9842878Z
Related Vehicle	FBJ5377D (Motorcycle)	Contact No.	81216403
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	21/04/2019	Date Discharge	26/04/2019
No. of Days granted Medical Leave	36	Degree of Injury	Serious
<b>Driver</b>			
Name	LI SHICHENG	ID No.	0 77751157
Related Vehicle	GZ2003J (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: 17/04/2023
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

### Brief Details.

I was hit by a lorry/van with number plate GZ2003J at a T junction on Pasir Ris Drive 1/Loyang Avenue who beat the red light. I flew off my motorcycle several meters away and landed at the other side of the road. There were several eye witnesses that I am in contact with and have several photos of the accident that the eye witness help me take after I was hit.  
The accident happened at the T junction along a stretch of 3 story terrace houses.



**SINGAPORE  
POLICE FORCE**



T/20190427/7030

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20190427/7030

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPIB /  
RAZIZ BIN TAHAR  
Contact No.: 65476200

Authentication Stamp  
NP168

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
27/04/2019 23:58

Classification Of Case:

# Accident Sketch Plan Pg. 1



TRAFFIC INVESTIGATION  
TRAFFIC POLICE  
10 UBI AVENUE 3  
SINGAPORE 408865  
Fax: 65474749

## CASE CARD

REPORT NO.:

G/20190421/0102

Traffic Accident along

LOYANG AVE

involving vehicles:

lorry and motorcycle

on 21/04/19

at about am/pm.

With reference to the above, you are advised to lodge an accident report online via the SPF Electronic Police Centre website (<http://www.police.gov.sg/epc>) within 24 hours.

9682



T/20190421/2025

1 of 3

Report No. T/20190421/2025

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/04/2019 12:36		Vide Report No.: G/20190421/0102		Station Diary No.: 37	
<b>Informant's Particulars</b>					
Name of Informant: TAN JUN LONG, JASON			Address: APT BLK 6 FLORA DRIVE #03-75 SINGAPORE 507027		
ID Type / ID No.: NRIC NO / S9213296Z			Contact No.: Home/Office: Mobile: 98809808		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 27	Date of Birth: 07/04/1992	Type of Informant: Witness		
Race: Chinese			Language:		Institution / School Name:
Occupation: EXECUTIVE			Driving Licence Information: Class:		Date of Expiry:

## General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 21/04/2019 11:00	Type of Location: T-Junction
Location: Along Road 1 LOYANG AVENUE				
Along the junction of LOYANG AVENUE and Pasir Ris drive 1				
Weather: Clear	Road Surface: Dry		Road Speed Limit:	
Traffic Flow: Two Way	Traffic Control: Traffic Light - Working		Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: Yes	

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBJ5377D	Motorcycle				Seriously Damaged	0
GZ2003J	Lorry				Seriously Damaged	0



**SINGAPORE  
POLICE FORCE**



T/20190421/2025

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

2 of 3

Report No. T/20190421/2025

**CONTINUATION OF REPORT**

**Brief Details.**

On the above mentioned date,time and said location, I and my girlfriend was a pedestrian standing at the pavement of Pasir Ris Drive 1 when both of us witness an accident happened at the junction of Pasir Ris Drive 1 and Loyang Ave. I wish to state both of use saw the lorry, GZ2003J beat the red light along Loyang Ave and the front portion of the lorry collided onto the right side of one motorcycle FBJ5377D while the motorcycle was turning from Pasir Ris Drive 1 to Loyang Ave. Due to the impact the motorist fell onto the ground and was seen lying down. I wish to state the motorist was conscious at that point of time and shortly after around 10 min, ambulance and police came. The motorist was then conveyed to Changi General Hospital. The Police also took down my particular and inform us to lodge a Traffic accident report as a witness.



Report No. T/20190421/2025

2 of 3

T/20190421/2025



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999



T/20190421/2025

3 of 3

Report No. T/20190421/2025

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
G /  
Staff Sgt TAN YI KUN

*[Signature]*

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / GIT /  
Sr Staff Sgt RAZIZ BIN TAHAR  
Contact No.: 65476200

Signature Of Informant:

*[Signature]*

Date/Time:  
21/04/2019 12:36

Classification Of Case:

Authentication Stamp  
NP168



**SINGAPORE  
POLICE FORCE**

SIGNATURE

# Accident Sketch Plan Pg. 1



ORIGINAL

MEDICAL CERTIFICATE

SUR201981807

Name GABRIEL CHEN HONG		NRIC No. S9842878Z
This is to certify that the above-named is unfit for duty for a period of <u>36</u> days from <u>21-Apr-2019</u> to <u>26-May-2019</u>		
Type of medical leave granted :		
<input checked="" type="checkbox"/> Hospitalization Leave	<input type="checkbox"/> Outpatient Sick Leave	
Admitted on : <u>21-Apr-2019</u>	<input type="checkbox"/> Maternity Leave,	Delivered on : _____
Discharged on : <u>26-Apr-2019</u>	<input type="checkbox"/> Sterilization Leave,	Operated on : _____
This certificate is not valid for absence from court attendance.		
Diagnosis	Surgical Operation (if applicable)	
Fit for light duty from <u>N.A.</u> to <u>N.A.</u>		
Comments :		
The above-named patient attended my clinic at <u>N.A.</u> and left at <u>N.A.</u> No medical leave is necessary.		
Hospital/Clinic General Surgery Changi General Hospital	Ward No. CGH-W37 Date 26-Apr-2019	Signature, Name (in BLOCK LETTERS) and Designation/MCR No.  VANESSA SHEN CIMIN, P1158I

WARD 37  
Changi General Hospital  
Simei Street 3  
Singapore 529889  
Tel No. 6788 8833

# Dirt Wheel Motor Trading

Blk 9004 Tampines ST 93 # 01-100 Singapore 528838

Tel (65) 67833063 Fax (65) 67881202



(1/2)

Name : Gabriel  
Contact : 91216403

KtM Model : Duke 200.  
Year : 2014 ABS-White

Frame no : VBK JUC 407 EC 009982

FBJ5377D

No.	Parts Number	Description	Qty	\$\$\$	States / Remark
1	90202001000	Handle Bar.		\$150	✓ Side Set ✓
2	90101039010	Handle Bar Support.		\$124	R/L Set ✓
3	90102039000	Grip Left		\$12	R Hand T/m ✓
4	90102031200	Clutch lever set.		\$62	R side Set ✓
5	9011070000	Headlight switch		\$52	R/L Cn ✓
6	Mirror set.	Mirror Set		\$48	Set ✓
7	90114169100	Meter		\$523	T/Bottom Cn ✓
8	90114060000	Meter holder.		\$16	R/L Cn ✓
9	90109945000	wheel slider / front.		\$92	S 2nd. Cn ✓
10	Frame Slider	Frame Slider.		\$200.	Cn ✓
11	90108049000/20	Cank Cover / White		\$163	102/Wall Cn ✓
12	90108050000/42	Cank Cover / Matt Black (L)		\$115	S/Top Cn ✓
13	90108051000/47	Cank Cover / Matt Black (R)		\$115	S/Top Cn ✓
14	90114001100	Head lamp		\$141	102/Wall Set X
15	90114062000	Head lamp holder.		\$44	S/Top Cn ✓
16	90108042000/47.	Side Cover / Top / (R)		\$82	S/Top Cn ✓
17	90108041000/47	Side Cover / Top / (L)		\$82	S/Top Cn ✓
18	90114125000	Signal light / Rear / (L)		\$62	R Rade. Cn ✓
19	90114126000	Signal light / Rear / (R)		\$62	R Rade. Cn ✓
20	90134031133	Gear shifter		\$51	R Rade. Set ✓
21	90103039000	Footrest Bracket / Front / (R)		\$62	R Rade. Set ✓
22	90103041033	Footrest / Front / (R)		\$34	R Rade. Set ✓
23	90504030044	Swing Arm		\$445	102 B&C Set ✓
24	90110084000	Chain Adjuster screw		\$11	R/L Cn ✓
25	90210086000	Axle Nut / Rear		\$7	✓/10 Cn ✓
26	90113080000	Brake capiter / Rear		\$260	R/Bottom Cn ✓
27	90210001044/30.	Rim / Rear		\$546	102/Wall R X
28	90110060000	Brake Dis / Rear		107	T/3rd Wepd ✓
29					
30					

not Authorized  
hkh  
marcus

take up. Hkh. ag  
1/1 2700

HP 90096608

July. 28/5/19

# Dirt Wheel Motor Trading

Blk 9004 Tampines ST 93 # 01-100 Singapore 528838

Tel (65) 67833063 Fax (65) 67881202



Name : Gabriel  
Contact : 81216403

KtM Model : Duke 200  
Year : 2007

Frame no : VBK JUC 407 EC 009982

FRJ 5377D

No:	Parts Number	Description	Qty	\$\$\$	States / Remark
1	901 03049 000	Footrest Bracket / Rear / (R)		\$54	R Rack cur /
2	901 03051 033	Footrest / Rear / (R)		\$34	R Rack. cur /
3	901 03044 000	Footrest pin x2		\$6	R 2 cur /
4	J094018350	Footrest lock pin x2		\$3	R 2 cur /
5	901 03053 000	Footrest engagement plate Top x2	2	\$6 x2	R 2 cur / 12
6	901 03052 000	Footrest engagement plate Bottom x2	2	\$6 x2	R 2 cur / 12
7	901 03048 000	Footrest Bracket Rear / (L)		\$54	R Rack cur /
8	901 03050 033	Footrest / Rear / (L) LH		\$34	R Rack. cur /
9	901 10945 000	Wheel slider / Rear RH		\$92	B / 2nd. cur /
10	901 12008 033	Rear Grip / (L) LH		\$21	R / Bottom cur /
11	901 12009 033	Rear Grip / (R) RH		\$21	R / Bottom cur /
12					
13					
14		Towing charge	x2	\$100	50
15					
16		Labour		\$380.	300
17					
18					
19					
20					
21					
22					3330
23					3347
24					
25					
26					
27					
28					
29					
30					

4582

### ...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2019		28 May 2019 18:40 <a href="#">Edit Adj Rpt</a>	<b>S\$2,700.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,700.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>HAI LEE SEAFOOD TRADING COMPANY</b> , Co. Reg. No.: 22115000E								
Main Claimant:	<b>GABRIEL CHEN HONG</b> , ID: S9842878Z								
Vehicle Reg. No.:	<b>FBJ5377D</b>	Date of Loss:	21/04/2019 11:00 - :59 [57 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D201773C02</b>	Policy/Cover Note No.:	DMCVSN30016319000 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>GZ2003J</b>	Policy No. (Claimant):	5105840216						
		Excess:	S\$0.00						
Repairer:	<b>Dirt Wheel Motor Trading (HQ)</b> Blk 9004 Tampines Street 93, #01-100, 528838 Tampines - Tel: 67833063								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Ong Chin Kiat</b> ]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 07/06/2019]								
Driver/Custodian (Insured):	LI SHICHENG (29 / Male) , NRIC: G8598873K Email:								
Adj Asg. Remarks:	to assign Mr Marcus Chua for SJE. please contact Mr Mike at 9667 6280 / 6783 3063 to arrange for survey. thank you.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



































## Claim Documents

\*FBJ5377D (SNM19D201773C02)  
[GZ2003J]  
TP  
GABRIEL CHEN HONG  
Apr 21 2019 11:00AM  
[HAI LEE SEAFOOD TRADING COMPANY]  
Dirt Wheel Motor Trading







Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	VAC (Kaki Bukit)								Thumbnail	Print			
1	17/05/19 13:23	Accident Statement								Load HTM				
2	21/05/19 13:48	Addendum Sheet								Load TIF				
3	21/05/19 13:48	Accident Statement Addm. #1								Load HTM				
Photos/Images									3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
2	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
3	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
4	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
5	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
6	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
7	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
8	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
9	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
10	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
11	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
12	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
13	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
14	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
15	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
16	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
17	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
18	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
19	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
20	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
21	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
22	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
23	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
24	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
25	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
26	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
27	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
28	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
29	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
30	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
31	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			
32	26/06/19 16:42	General View								Load JPG	<input checked="" type="checkbox"/>			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
33	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
34	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
35	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
36	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
37	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
38	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
39	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
40	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
41	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
42	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
43	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
44	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
45	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
46	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
47	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
48	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
49	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
50	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
51	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
52	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
53	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
54	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
55	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
56	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
57	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
58	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
59	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
60	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
61	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
62	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
63	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
64	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
65	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
66	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
67	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
68	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
69	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
70	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
71	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
72	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
73	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
74	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
75	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
76	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
77	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
78	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
79	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
80	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
81	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
82	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
83	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
84	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
85	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
86	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
87	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
88	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
89	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
90	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
91	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
92	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
93	26/06/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
94	26/06/19 16:43	General View	 Load JPG	<input checked="" type="checkbox"/>
95	26/06/19 16:43	General View	 Load JPG	<input checked="" type="checkbox"/>
96	26/06/19 16:43	General View	 Load JPG	<input checked="" type="checkbox"/>
97	26/06/19 16:43	General View	 Load JPG	<input checked="" type="checkbox"/>
98	26/06/19 16:43	General View	 Load JPG	<input checked="" type="checkbox"/>
99	26/06/19 16:43	General View	 Load JPG	<input checked="" type="checkbox"/>
100	26/06/19 16:43	General View	 Load JPG	<input checked="" type="checkbox"/>
101	26/06/19 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	26/06/19 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	26/06/19 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	26/06/19 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	26/06/19 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	26/06/19 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	26/06/19 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	26/06/19 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	26/06/19 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	26/06/19 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	26/06/19 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	26/06/19 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	26/06/19 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	26/06/19 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	26/06/19 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/05/19 18:40	INSD GZ2003J GIA REPORT	 Load PDF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	17/05/19 13:23	Accident Statement	 Load HTM	
2	21/05/19 13:48	Addendum Sheet	 Load TIF	
3	21/05/19 13:48	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	17/05/19 12:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	17/05/19 12:42	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	17/05/19 12:42	Accident Photo	 Load JPG	



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
				<input checked="" type="checkbox"/>
4	17/05/19 12:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	17/05/19 12:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	17/05/19 12:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	17/05/19 12:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	17/05/19 12:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	17/05/19 12:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	17/05/19 12:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	17/05/19 12:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	17/05/19 12:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	17/05/19 12:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	17/05/19 12:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	17/05/19 12:42	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	17/05/19 13:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
17	17/05/19 13:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
18	17/05/19 13:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
19	17/05/19 13:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
20	17/05/19 13:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	17/05/19 12:43	Accident Sketch Plan	Load TIF	
2	17/05/19 12:43	Accident Sketch Plan	Load TIF	
3	17/05/19 12:43	Accident Sketch Plan	Load TIF	
4	17/05/19 12:43	Accident Sketch Plan	Load TIF	
5	17/05/19 12:43	Accident Sketch Plan	Load TIF	
6	17/05/19 12:43	Accident Sketch Plan	Load TIF	
7	17/05/19 12:43	Accident Sketch Plan	Load TIF	
8	17/05/19 12:43	Accident Sketch Plan	Load TIF	
9	17/05/19 12:43	Accident Sketch Plan	Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119009443/UTD3E2

Date: 10/07/2019

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN30016319000

Claimant Vehicle  
No: FBJ5377DInsured Vehicle  
No: GZ2003J

Date of Loss: 21/04/2019

Nature of Claim: TP

Claim  
No: SNM19D201773C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBJ5377D

Make &amp; Model: KTM 200 DUKE, 200cc

Engine No: 0490641646

Reg. Date: 03/07/2014 (Man. Year: 2014)

Chassis No: VBKJUC407EC009982

Colour: White

Odometer: 0 km

Engine Capacity: 200 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	160/60 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,107.00	2,997.00	1,110.00	27.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	480.00	350.00	130.00	27.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,587.00</b>	<b>3,347.00</b>	<b>1,240.00</b>	<b>27.03</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,587.00</b>	<b>2,700.00</b>	<b>1,887.00</b>	<b>41.14</b>

### INSPECTION

Date of Assignment: 28/05/2019

Date Inspected: 29/05/2019 Inspected At:

Dirt Wheel Motor Trading (HQ)  
Blk 9004 Tampines Street 93, #01-100  
Singapore 528838

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 10 Jul 2019)	
<b>Parts:</b>	N/A	KTM 200 DUKE 200cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBJ5377D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	156.00 F	*156.00 FL
2	1		*HANDLE BAR SUPPORT	Bent	124.00 F	*124.00 FL
3	1		*GRIP LEFT	Torn	12.00 F	*12.00 FL
4	1		*SET CLUTCH LEVER	Bent	62.00 F	*62.00 FL
5	1		*HEADLIGHT SWITCH	Cracked	52.00 F	*52.00 FL
6	1		*SET MIRROR	Broken	48.00 F	*48.00 FL
7	1		*METER	Cracked	523.00 F	*523.00 FL
8	1		*METER HOLDER	Cracked	16.00 F	*16.00 FL
9	1		*WHEEL SLIDER / FRONT	Cut	92.00 F	*92.00 FL
10	1		*FRAME SLIDER	Cut	200.00 F	*200.00 FL
11	1		*TANK COVER / WHITE	Cut	163.00 F	*163.00 FL
12	1		*HEAD LAMP	Serviceable	181.00 F	*- FL
13	1		*HEAD LAMP HOLDER	Cracked	44.00 F	*44.00 FL
14	1		*SIDE COVER / TOP (R)	Cracked	82.00 F	*82.00 FL
15	1		*SIDE COVER / TOP (L)	Cracked	82.00 F	*82.00 FL
16	1		*SIGNAL LIGHT / REAR (L)	Damaged	62.00 F	*62.00 FL
17	1		*SIGNAL LIGHT / REAR (R)	Broken	62.00 F	*62.00 FL
18	1		*GEAR SHIFTER	Bent	51.00 F	*51.00 FL
19	1		*FOOTREST BRACKET / FRONT (R)	Bent	62.00 F	*62.00 FL
20	1		*FOOTREST / FRONT (R)	Broken	34.00 F	*34.00 FL
21	1		*SWING ARM	Bent	445.00 F	*445.00 FL
22	1		*CHAIN ADJUSTER SCREW	Cut	11.00 F	*11.00 FL
23	1		*AXLE NUT REAR	Cut	7.00 F	*7.00 FL
24	1		*BRAKE CALIPER / REAR	Cracked	260.00 F	*260.00 FL
25	1		*RIM / REAR	Repair	596.00 F	*- FL
26	1		*BRAKE DIS / REAR	Warped	107.00 F	*107.00 FL
27	1		*FOOTREST BRACKET / REAR (R)	Cut	54.00 F	*54.00 FL
28	1		*FOOTREST / REAR (R)	Cut	34.00 F	*34.00 FL
29	2		*FOOTREST PIN	Necessary	6.00 F	*6.00 FL
30	2		*FOOTREST LOCK PIN	Necessary	3.00 F	*3.00 FL
31	2		*FOOTREST ENGAGEMENT PLATE TOP	Necessary	12.00 F	*12.00 FL
32	2		*FOOTREST ENGAGEMENT PLATE BOTTOM	Necessary	12.00 F	*12.00 FL
33	1		*FOOTREST BRACKET REAR / (L)	Cracked	54.00 F	*54.00 FL
34	1		*FOOTREST / REAR / (L) LH	Cracked	34.00 F	*34.00 FL
35	1		*WHEEL SLIDER REAR RH	Missing	92.00 F	*92.00 FL
36	1		*REAR GRIP LH	Missing	21.00 F	*21.00 FL
37	1		*REAR GRIP RH	Missing	21.00 F	*21.00 FL
38	1		*TANK COVER / MATT BLACK (L)	Cut	115.00 F	*115.00 FL
39	1		*TANK COVER / MATT BLACK (R)	Cut	115.00 F	*115.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. L=ListItemDisc.						
				Sub Total (S\$)	4,107.00	3,330.00
			- List Item Discount on L Items 0.00/10.00% (S\$)		0.00	333.00
				Total Parts (S\$)	4,107.00	2,997.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TOWING CHARGE	New	100.00	50.00
2	LABOUR	New	380.00	300.00
Gross Labour Cost (S\$)			<b>480.00</b>	<b>350.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >