

ASS. REC. BY:

REF: CS/CTI 19009444/B7C/302

Special Instruction:

Survivor: Lim

ASSIGNMENT (Office)

From (Person): Irene Tay Hu Ping

of CTI

Date/Time: 27.5.19 16.55pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: EX 7557D

Insured: SMF 7557D

at Workshop m/s Team Autoprio

Tel: 62581955

of 385 sin ming Drive, # 01-02

Policy No: DMP/CSA 17661118011

Claim No: SNM19D 20 22 2302

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 16.5.2019

CA / REV / REP. / REV 24 HRS

"rup"

H.O.D. Endorsement:

Date/Time: 27.5.19 5.25pm

Person Contacted: Adel

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	EX 7557D - X
	SMF 7557D - NBA/CTI 19008782/4
	RUA - 16/05/2019

Bumput

ASSIGNMENT

From: _____ Date: 28.5.2019

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: Ex 7557D

at Workshop m/s Team Autopro

of 385 sin ming Drive # 01-02

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: Ex 7557D Yr Regn: 23/3/2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: AD Aranta 1.6 GLS c.c 1591

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 1526 T/Radio: Insured / Std / NI / NA

Eng/No: G4FGKU113589

C/No: KMHD8A1CMKU881710

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65/15

R: 195/65/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or NEXEN

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 17/5/19 D.O.I. 28/5/19

Survey held at Team Autopro

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range 1000/2 - 1500/2
	confirm p/p
	offer 415/2 (Red: 5484.56; 92%)
	30amp
	MV 75,000/2
	PV 34,618/2
	NV 40,382/2
	RECEIVED 16 JUL 2019
	28/6/19
	TERMIN LIM
	29/5/19

Date/Time, File Pass to?

☐ : Preli. Report

1) 15A typist

☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: 220

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

220

Report Format: TP

Lump Sum / U.I. (\$) 415

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 May 2019		27 May 2019 16:55 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SEAH MIN FERN, ID: S7636511C		
Main Claimant:	SEAH CHEE WAH, ID: S0188306B		
Vehicle Reg. No.:	EX7557D	Date of Loss:	16/05/2019 10:00 - :59 [1 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D202223C02	Policy/Cover Note No.:	DMPCSN17601118011 (Comprehensive)
Vehicle Reg. No. (Insured):	SMF7557D	Policy No. (Claimant):	VPA/P2280433
		Excess:	S\$0.00
Repairer:	Team Autopro Pte Ltd (Sin Ming) 385 Sin Ming Drive, #01-02 Vicom Inspection Centre, 575718 Sin Ming - Tel: 62581955		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/06/2019]		
Driver/Custodian (Insured):	SEAH MIN FERN (42 / Female), NRIC: S7636511C Email:		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	17/05/2019 17:29
Date Of Accident	16/05/2019 10:10
Exact Location Of Accident	FRONTAGE OF 33 SIN MING DR #01-361
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	EX7557D
Insured/Policyholder	
Name Of Registered Owner	SEAH CHEE WAH
NRIC No	S0188306B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88667557
Alternative Phone No	OFFICE-88667557
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	AVANTE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P2280433
Cover Note Number	
Driver	
Name of Driver	SEAH CHEE WAH
NRIC No	S0188306B
Date Of Birth	29/05/1953
Occupation	INDOOR
Date Of Driving Pass	29/09/1995
Driving Experience	23 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88667557
Fax Number	
Contact Number	OFFICE-88667557
EMail Address	NOEMAIL

Address	APT BLK 408A FERNVALE ROAD #24-34
Postcode	791408
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMF7557D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	PC5353T
-----------------------------	---------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

BUS

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


AT THE STATED DATE, TIME & PLACE. I WAS INSIDE
my SHOP. SUDDENLY I HEARD AN VERY LOUD BANG.
I CAME OUT AND UNDERSTAND THAT A BUS HIT ONTO
VEH B AND FORCE IT TO PUSH FORWARD AND HIT
ONTO MY CAR. I WISH TO STATE THAT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SJE :	_____	Vehicle Nos :	EX 7557 D
Date of Survey :	_____	Model :	Elantra
Date of ReSurvey:	After-Paint: _____	Year :	_____
Contacts :	_____	Chassis No :	_____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear bumper	1	\$ 867.00	\$ -867.00
2	Rear bumper retainer	2	\$ 94.60	\$? 189.20
3	Rear bumper reflector	2	\$ 85.00	\$? 170.00
4	Rear bumper reinforcement	1	\$ 320.00	\$? 320.00
5	Rear bumper inner sponge	1	\$ 182.50	\$? 182.50
6	Tail lamp	2	\$ 476.00	\$? 952.00
Parts Sub Total :				\$ 2,680.70
20% Discount				\$ 536.14
PARTS TOTAL :				\$ 2,144.56

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 60.00	\$ 60.00
2	No plate with garnish	1	\$ 115.00	\$ 115.00
5	Reverse sensor	2	\$ 400.00	\$ 800.00
6	Rear bumper clips	1	\$ 50.00	\$ 50.00
7	Tail lamp clips	2	\$ 50.00	\$ 100.00
8	Tail lamp seal	2	\$ 60.00	\$ 120.00
SPECIAL NETT TOTAL :				\$ 1,245.00

Nos.	LABOUR	S\$
2	R&R reverse camera and sensor and check function	\$ 100.00
3	Panel beat	\$ 1,200.00
4	Rust proofing	\$ 150.00
5	Spray painting	\$ 1,000.00
6	Check wiring	\$ 60.00
LABOUR TOTAL :		\$ 2,510.00

PARTS TOTAL : \$ 2,144.56
 SPECIAL NETT TOTAL : \$ 1,245.00
 LABOUR TOTAL : \$ 2,510.00
GRAND TOTAL : \$ 5,899.56

LKA Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

30/5/19

? Photo
 Lump sum
 repair
 item
 in
 28/5/19

Resurvey 29/5/19
 @ 1230 hrs

Repair days 3

Parts 0.00
 SN 115.00
 Labour 300.00
 415.00

L/S 300/2

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8306B
Vehicle Details	
Vehicle No.:	EX7557D
Vehicle to be Exported:	No
Intended Deregistration Date:	29 May 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	AD AVANTE 1.6 GLS (A)
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	G4FGKU113589
Chassis No.:	KMHD841CMKU881710
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$12,561.00
Original Registration Date:	23 Mar 2019
First Registration Date:	23 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$12,561.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Mar 2029
PARF Rebate Amount:	\$9,420.00
Intended COE Rebate Details	
COE Expiry Date:	22 Mar 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,689.00
COE Rebate Amount:	\$25,198.00
Total Rebate Amount:	\$34,618.00

The information contained herein is correct as at 29 May 2019

OK

Dep 7120/yr

593/mth

MV 75,000/2

PV 34,618/2

NV 40,382/2

TCU m hui
29/5/19

CHEAPEST CAR INSURANCE RENEWAL



Compare
10+ Insurers

GET A CHEAPER QUOTE NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Volvo S60 T4.



1 Owner Car. Service And Repair
Record Are Kept In A File.
Direct Owner StarAd

KA-HUP

**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

HOTLINE: 6741 9997 [view our cars](#)

Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

2 vehicles

Hyundai Avante

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Hyundai Avante		Any	Any	2019	Any	Any	Any	All



Hyundai Avante 1.6A GLS

\$75,000

\$7,120 /yr

30-Jan-2019

1,591 cc

10,196 km

Sedan

Available

Like New. Tip Top Condition. New 7 Years Free Service (Premier Customer Package) With Komoco Motors.

Posted: 29-May-2019

Tags: 2019 Hyundai Avante, 2019 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai

DIRECT OWNER



Hyundai Avante 1.6A GLS (OPC)

\$59,800

\$5,430 /yr

08-Apr-2019

1,591 cc

450 km

Sedan

Available

1 And Only New Facelift Avante In The Market! Practically Brand New, 1 Month Old. Mileage Clocked At Barely 500km! New And Improved Engine, Gearbox And Chassis. This Facelift Has A Sporty, Sleek New B...

Bavarian Marques Pte Ltd

Posted: 24-May-2019

Tags: 2019 Hyundai Avante, 2019 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai

PREMIUM AD

Save this search criteria, to get email alerts whenever a match is found.

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
--	------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view [Expired ads](#)

20 ▼ results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Hyundai, Hyundai Singapore, used Hyundai Singapore, used Hyundai, used vehicles Singapore or even buy used Hyundai Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 May 2019		27 May 2019 16:55 Edit Adj Rpt	\$415.00 Edit Estimates	\$415.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SEAH MIN FERN , ID: S7636511C								
Main Claimant:	SEAH CHEE WAH , ID: S0188306B								
Vehicle Reg. No.:	EX7557D	Date of Loss:	16/05/2019 10:00 - :59 [1 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202223C02	Policy/Cover Note No.:	DMPCSN17601118011 (Comprehensive)						
Vehicle Reg. No. (Insured):	SMF7557D	Policy No. (Claimant):	VPA/P2280433						
		Excess:	S\$0.00						
Repairer:	Team Autopro Pte Ltd (Sin Ming) 385 Sin Ming Drive, #01-02 Vicom Inspection Centre, 575718 Sin Ming - Tel: 62581955								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 06/06/2019]								
Driver/Custodian (Insured):	SEAH MIN FERN (42 / Female) , NRIC: S7636511C Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*EX7557D (SNM19D202223C02)
[SMF7557D]
TP
SEAH CHEE WAH
May 16 2019 10:00AM
[SEAH MIN FERN]
Team Autopro Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	17/05/19 17:32	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
2	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
3	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
4	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
5	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
6	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
7	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
8	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
9	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
10	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
11	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
12	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
13	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
14	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
15	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
16	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
17	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
18	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
19	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
20	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
21	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
22	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
23	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
24	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
25	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
26	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
27	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
28	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
29	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
30	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
31	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>
32	15/07/19 09:59	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
---------------	--	--	------------	-------------------------------------

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)		Thumbnail	Print
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	27/05/19 16:55	INSD SMF7557D GIA REPORT		Load PDF	
2	27/05/19 16:55	PRI		Load PDF	
3	27/05/19 16:55	TP PC5353T GIA REPORT (3/3)		Load PDF	

Linked Accident Report Documents

Assessment Reports				View	View in Browser	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)		Thumbnail	Print	
1	17/05/19 17:32	Accident Statement		Load HTM		
Photos/Images				3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)		Thumbnail	Print	
1	17/05/19 17:32	Accident Photo		Load JPG	<input checked="" type="checkbox"/>	
2	17/05/19 17:32	Accident Photo		Load JPG	<input checked="" type="checkbox"/>	
3	17/05/19 17:32	Accident Photo		Load JPG	<input checked="" type="checkbox"/>	
4	17/05/19 17:32	Accident Photo		Load JPG	<input checked="" type="checkbox"/>	
5	17/05/19 17:32	Accident Photo		Load JPG	<input checked="" type="checkbox"/>	
6	17/05/19 17:32	Accident Photo		Load JPG	<input checked="" type="checkbox"/>	
7	17/05/19 17:32	Accident Photo		Load JPG	<input checked="" type="checkbox"/>	
Documentation				1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)		Thumbnail	Print	
1	17/05/19 17:32	Sketch Plan		Load TIF		
2	17/05/19 17:32	Sketch Plan #2		Load TIF		

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19009444/BTD3E2

Date: 19/07/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN17601118011

Claimant Vehicle
No : EX7557DInsured Vehicle
No : SMF7557D

Date of Loss: 16/05/2019

Nature of Claim: TP

Claim
No: SNM19D202223C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: EX7557D

Make & Model: HYUNDAI AVANTE, 1.6 (A)

Engine No: G4FGKU113589

Reg. Date: 23/03/2019 (Man. Year: 2019)

Chassis No: KMHD841CMKU881710

Colour: Silver

Odometer: 1526 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 7 mm	Rear Left Side:	Nexen 7 mm
Front Right Side:	Nexen 7 mm	Rear Right Side:	Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,389.56	115.00	3,274.56	96.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,510.00	300.00	2,210.00	88.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,899.56	415.00	5,484.56	92.97

INSPECTION

Date of Assignment: 27/05/2019

Date Inspected: 28/05/2019 Inspected At:

Team Autopro Pte Ltd (Sin Ming)
385 Sin Ming Drive, #01-02 Vicom
Inspection Centre
Singapore 575718

Estimated Period of Repair: 3.0 days

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Jul 2019)
Parts: 143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for EX7557D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	867.00 FL	*- FL
2	2		*REAR BUMPER RETAINER	Not Necessary	189.20 FL	*- FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	170.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	320.00 FL	*- FL
5	1		*REAR BUMPER INNER SPONGE	Not Necessary	182.50 FL	*- FL
6	2		*TAIL LAMP	Not Necessary	952.00 FL	*- FL
7	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
8	1		*NO PLATE WITH GARNISH	Cut	115.00 FS	*115.00 FS
9	2		*REVERSE SENSOR	Not Necessary	800.00 FS	*- FS
10	1		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
11	2		*TAIL LAMP CLIPS	Not Necessary	100.00 FS	*- FS
12	2		*TAIL LAMP SEAL	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,925.70	115.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	536.14	0.00
Total Parts (\$\$)	3,389.56	115.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R REVERSE CAMERA AND SENSOR AND CHECK FUNCTION.	New	100.00	0.00
2	PANEL BEAT.	New	1,200.00	0.00
3	RUST PROOFING.	New	150.00	0.00
4	SPRAY PAINTING.	New	1,000.00	300.00
5	CHECK WIRING.	New	60.00	0.00
Gross Labour Cost (\$\$)			2,510.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >