



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19009481/Upa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 14-09-2020



ATTN:VALE OH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLX 9849R	Veh. Inspected	SLR 625K
Policy No.	CN887481	Coverage (\$)	0.00
Claim No.	S9M01OY0	Excess (\$)	0.00
Assign From		Assign Date	29/05/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN PULSAR (A)	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VSKDDAC13U0106968	Colour	BLUE
Odometer	26108	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R17	CONTINENTAL	6 mm
L/H Front Tyre	205/50 R17	CONTINENTAL	6 mm
R/H Rear Tyre	205/50 R17	CONTINENTAL	6 mm
L/H Rear Tyre	205/50 R17	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	28/05/2019	Inspection Date	29/05/2019
Survey held at	KIM CHWEE AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------