



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE ANG			Ref: CC4/ASM19009482/Ggs3q2 Date: 18/11/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFQ 57B	Veh. Inspected	SJN 3033T	
Policy No.	P1718754	Coverage (\$)	0.00	
Claim No.	S9M01O4P	Excess (\$)	0.00	
Assign From		Assign Date	29/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6BM42A8G0335890	Colour	GREY	
Odometer	37225 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	YOKOHAMA	5 mm	
L/H Front Tyre	205/60 R16	YOKOHAMA	5 mm	
R/H Rear Tyre	205/60 R16	YOKOHAMA	5 mm	
L/H Rear Tyre	205/60 R16	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/05/2019	Inspection Date	29/05/2019	
Survey held at	MENG WHEE BROS MOTOR SERVICE BLK 10 ANG MO KIO IND PARK 2A #05-25 SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	