

Surveyor:

WAPKINS

DOI:

ASSIGNMENT

29/5/19

Date / Time:

29/5/19

Registered in Merimen:

29/5/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLK 5756B

Name of Insured:

Wm Chye Hoe

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

28/5/2019

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SLL1634J



INSRS:

WSP:

Tel:

Liability:

RMKS:

Choo Motor

82921



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SLL1634J. x; SLK5756B. x

STAGE

DATE / PIC

7/6/19

seek liability via merimen  
DAD collided onto parked TP

10/6/19

mandate approve via merimen.

27/6/19

File pass to typist type report

4/7/19

Seek mandate via merimen

10/7/19

Mandate approve via merimen

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

-

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

NIL.

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

5300.00

Loss of Rental (LOR):

S\$

(

-

days)

Loss of Use (LOU):

S\$

180.00

(\$60 x 3

days)

Loss of Income (LOI):

S\$

(\$ x

days)

LOR only ☐ LOU only ☐

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

S\$

-

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

5480.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

5480.00

Name 1:

Choo Motor Spray Painter

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASS. REC. BY: Marcus

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

10/6/19 4/5 85300 confirmed with Alan.

(Red = \$8278.02  
61.1)

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$ )

Add Fee:

☐

Site Insp (\$ )

☐

Interview (\$ )

☐

Tech. Invs (\$ )

☐

Weekend (\$ )

CHOO MOTOR SPRAY PAINTER  
BLK1 KAKI BUKIT AVE 6  
#01-39 AUTOBAY  
SINGAPORE 417883

not Addressed  
Hale  
4/5 \$5300  
3dy 28/5/19

VEHICLE NO: SLL 1634Y

| QTY   | PARTICULAR                                |
|-------|---|
| 1 PCS | FRONT BUMPER 1534.30                      |
| 1 SET | FRONT BUMPER CLIPS                        |
| 1 PCS | FRONT BUMPER REINFORCEMENT                |
| 1 PCS | FRONT BUMPER LOWER CHROME MOULDING 28F.43 |
| 1 PCS | FRONT BUMPER PDC SENSOR O/S               |
| 1 PCS | FRONT BUMPER SPONGE                       |
| 1 PCS | HEADLAMP ASSY O/S 3126.48                 |
| 1 PCS | FRONT SUPPORT PANEL 805.30                |
| 1 PCS | FRONT FENDER O/S                          |
| 1 PCS | FRONT SPORT RIM O/S                       |

|        |             |   |
|--------|-------------|---|
| deputy | \$1,866.02  | / |
| nu     | \$60.00     | / |
| 11     | \$715.00    | X |
| nu     | \$311.00    | / |
| 11     | \$265.00    | X |
| to. n  | \$199.00    | / |
| cu     | \$4,850.00  | / |
| one    | \$1,016.00  | / |
| n      | \$1,266.00  | X |
| n      | \$1,200.00  | X |
|        | \$11,748.02 |   |

(102)

LABOUR CHARGES:

|  |
|--|
| TO CHECK WIRING                            |
| TO DISMANTLE & REFIX FRONT PDC SENSOR      |
| TO REFILL AIR CON GAS                      |
| TO CONDUCT WHEEL ALIGNMENT                 |
| TO SPRAY RUST PROOFING                     |
| LABOUR FOR PANEL BEATING & REPLACING PARTS |
| TO PUTTY & SPRAY PAINTING                  |

|          |             |
|----------|-------------|
| \$80.00  | 20          |
| \$80.00  | 50          |
| \$120.00 | 100         |
| \$120.00 | 60          |
| \$50.00  | X           |
| \$580.00 | 520         |
| \$800.00 | 500         |
| TOTAL    | \$13,578.02 |

- AKK 2. To Contractors liability  
the Repairer at the following:
- To repair or replace the spray painting
  - To replace damaged part(s) during recovery
  - Parts prices are subject to confirmation
  - This policy covers up to a "Without Prejudice" basis
  - No claim shall be made against the
  - Supplier's liability shall be covered and is subject to the approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6013.28  
5411.95  
6661.55  
5321

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 8292I

Vehicle Details

Vehicle No.: SLL1634J  
Vehicle to be Exported: No  
Intended Deregistration Date: 29 May 2019  
Vehicle Make: MERCEDES BENZ  
Vehicle Model: CLA180 COUPE URBAN (R18 LED)  
Primary Colour: Grey  
Manufacturing Year: 2016  
Engine No.: 27091031137639  
Chassis No.: WDD1173422N445604  
Maximum Power Output: 90.0 kW (120 bhp)  
Open Market Value: \$28,839.00  
Original Registration Date: 16 Feb 2017  
First Registration Date: 16 Feb 2017  
Transfer Count: 0  
Actual ARF Paid: \$27,375.00

Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 15 Feb 2027  
PARF Rebate Amount: \$20,531.00

Intended COE Rebate Details

COE Expiry Date: 15 Feb 2027  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$50,889.00  
COE Rebate Amount: \$39,269.00  
Total Rebate Amount: \$59,800.00

The information contained herein is correct as at 29 May 2019

OK

SGCARMART.COM

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Login

Sign up

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

As Good As New CLS450 AMG Line 4MATIC For Sale!

New Generation CLS450 AMG

With EQ Boost, 3 Years

Warranty By Cycle And Cancellation!

Seng Hup Auto StarAd

HIN LUNG AUTO

No Bee Group

One Stop Car Hub

Finance, Insurance, Workshop

New and Used Cars

30 years

of car sale

Browse by Category

▼

49 vehicles

cla 180

◀ Back ( 1 2 3 ) Next ▶

Sort by Date Posted

▼

20 results/page

▼

Advanced Search

Submit

|  | Make                       | Model        | Price     | Depreciation | Reg Date    | Eng Cap  | Mileage   | Veh Type  | Status    |
|--|----------------------------|--------------|-----------|--------------|-------------|----------|-----------|-----------|-----------|
| Search Selection   | cla 180                    |              | Any       | Any          | 2017        | Any      | Any       | Any       | Available |
|  | Mercedes-Benz CLA-Class    | CLA180 Urban | \$120,500 | \$12,920 /yr | 18-Sep-2017 | 1,595 cc | 14,000 km | Luxury    | Available |
| <div><div>New Arrival! Most Valued Buy! Beautiful White Unit With Pristine Condition! Peace Of Mind! Fully Serviced By Agent And Still Under 3 Years Warranty! Accident Free! Lowest Genuine Mileage At Only 14000...</div><div><div>Posted: 29-May-2019</div><div>Tags: 2017 Mercedes-Benz CLA180, 2017 mercedes-benz cla180, Mercedes-Benz CLA180, mercedes-benz cla180, Mercedes-Benz, CLA180, cla180, Used Mercedes-Benz</div></div></div>                                     |                            |              |           |              |             |          |           |           |           |
|  | Mercedes-Benz C-Class C180 | Avantgarde   | \$146,800 | \$15,030 /yr | 14-Sep-2017 | 1,595 cc | 26,000 km | Luxury    | Available |
| <div><div>1 Owner, Full C&amp;C Agent History, Beautiful Diamond Silver With Gorgeous Black Interior, Immaculate Condition, Warranty Till Oct 2020, Call Our Sales Consultants Or Drop By Showroom To View This Pristi...</div><div><div>Orchard Credit Pte Ltd</div><div><div>Posted: 29-May-2019</div><div>Tags: 2017 Mercedes-Benz C180, 2017 mercedes-benz c180, Mercedes-Benz C180, mercedes-benz c180, Mercedes-Benz, C180, c180, Used Mercedes-Benz</div></div></div></div> |                            |              |           |              |             |          |           |           |           |
|  | Mercedes-Benz B-Class B180 | Style        | \$103,000 | \$11,780 /yr | 28-Feb-2017 | 1,595 cc | 14,805 km | Hatchback | Available |
| <div><div>Agent Warranty Till Feb 2020. 160-Point Quality Assurance Check Done. Beautiful Paintwork.</div><div><div>Inchcape Pre-Owned</div><div><div>Posted: 29-May-2019</div><div>Tags: 2017 Mercedes-Benz B180, 2017 mercedes-benz b180, Mercedes-Benz B180, mercedes-benz b180, Mercedes-Benz, B180, b180, Used Mercedes-Benz</div></div></div></div>  |                            |              |           |              |             |          |           |           |           |
|  | Mercedes-Benz C-Class C180 | Avantgarde   | \$135,500 | \$14,620 /yr | 02-May-2017 | 1,595 cc | 36,761 km | Luxury    | Available |
| <div><div>1 Owner, Full Servicing By C&amp;C, Warranty Under C&amp;C, Brand New Condition.</div><div><div><div>Posted: 29-May-2019</div><div>Tags: 2017 Mercedes-Benz C180, 2017 mercedes-benz c180, Mercedes-Benz C180, mercedes-benz c180, Mercedes-Benz, C180, c180, Used Mercedes-Benz</div></div></div></div>   |                            |              |           |              |             |          |           |           |           |
| <div><div>Car Buying</div><div>Car Selling</div><div>Car Ownership</div></div> <div><div>Car Aftermarket</div><div>On The Move</div><div>Lifestyle</div></div> <div><div>Buy Tyres Online!</div><div>Latest Special Offers from Tyresport</div></div>  |                            |              |           |              |             |          |           |           |           |

Mercedes-Benz A-Class A180

Style

\$98,800

\$11,540 /yr

20-Feb-2017

1,595 cc

31,000 km

Hatchback

Available

Best Price With 2.28% Interest Rate, Full Maintained And Warranty By C&C, Service Just Done, Next Service Due Feb-2020! As Good As New Car Condition, But Save You Lots Of Money And Waiting Time! New N...

Auto Zoom Enterprise Pte Ltd

Posted: 29-May-2019

Tags: 2017 Mercedes-Benz A180, 2017 mercedes-benz a180, Mercedes-Benz A180, mercedes-benz a180, Mercedes-Benz, A180, a180, Used Mercedes-Benz

|  | Mercedes-Benz C-Class C180 | Avantgarde | \$143,800 | \$14,920 /yr | 10-Aug-2017 | 1,595 cc | 19,000 km | Luxury | Available |
| 100% Loan Approval To Drive Away! SLS3000 Nice Number Plate Tag Along On This Beautiful Black On White Beast! Best Selling Mercedes Model! Optional Accessories Upgrades Available! Test Drive Welcome! ...  Don Motoring | | | | | | | | | |

https://www.sgcarmart.com/used\_cars/listing.php?RGD=2017&MOD=cla 180&RPG=20&VEH=0&A... 29-May-19

## View Received Message

This mail is associated with :

**\*SLL1634J (MPC2019D0000566)**  
**[SLK5156B]**

TP  
CHUA CHEE YON, ALVIN  
May 28 2019 12:00AM  
[-]  
Choo Motor Spray Painter

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on **04/07/2019 17:01 PM**.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$5480.00) - SLL1634J - Claim Handler: Lalitha Krishnan

Approved:5480.00.

### DOCUMENTS SUMMARY

There are no documents.

## CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Co. Reg No: 22736900M

Tel No: 67452063 / 67467158 Fax No: 67458520

Date 24.06.2019

India International Insurance Pte Ltd

64 Cecil Street

#04-05 IOB Building

Singapore 049711

Attn: Motor Claims Department

Dear Sirs,

### ACCIDENT INVOLVING VEHICLE: SLL 1634J AND SHC 8361U ON 14.05.2019

We are the authorized repair workshop for the owner of motor vehicle no: **SLL1634J**, which was involved in the captioned accident with your insured vehicle: **SHC8361U**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

|                                 |           |                 |
|---------------------------------|-----------|-----------------|
| 01) Cost of Repair              | \$        | 5,300.00        |
| 02) Loss Of Use (3 day x \$120) | \$        | 360.00          |
|                                 | <u>\$</u> | <u>5,660.00</u> |

We enclosed herewith the following documents to support the claims:-


- |                                    |                                  |
|------------------------------------|----------------------------------|
| a) Final Repair Bill               | b) Vehicle Registration Log Card |
| c) GIA Report                      | d) I/C & Driving Licence         |
| e) Insurance Certificate           |                                  |
| g) Letter of Authorisation, etc... |                                  |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

**Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.**

Thank you.

Yours faithfully,

  
For Choo Motor Spray Painter  
Jason Tang

DATE : 24th June 2019

TO : India International Insurance Pte Ltd

RE : ACCIDENT INVOLVING VEHICLE NO. SLL16343 & SLK51568

ALONG Loyang Port Carpark

ON 28/5/2019

I/We, Chua Chee Yon, Alvin

of (NRIC No./ROC No.) S7838295I

of 89 Yishun Street 81 #06-10 S768449

owner of vehicle no. SLL16343 in consideration of M/s CHOO MOTOR SPRAY PAINTER repairing my/our vehicle SLL16343 at my/our instruction and hereby authorise M/s CHOO MOTOR SPRAY PAINTER to demand claim settlement whatever amount settled/payable by the Insurance Company and/or third party or to commence legal proceedings, if necessary, under my name, for the cost of repairs, car rental and/or loss of use, etc. and to their appointing solicitor to act for me/us in respect of the said accident/claim and all claimed and/or settled shall belong to them absolutely.

I/We further agree and undertake to indemnify them against the above-mentioned claim cost which may arise therewith.

Signature of Owner :



Name of Owner :

CHUA CHEE YON, ALVIN



## EXPRESS SETTLEMENT

### DISCHARGE VOUCHER

#### III- Direct Settlement (PODS)

India Ref:

Claimant Ref:

mpc20190000566  
SLL 1634J

We/I, Choo Motor Spray Painter ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 5,300.00 (repair cost), S\$ 180.00 (loss of use/rental), S\$ NIL (search fee), vehicle no. SLL 1634J that was damaged pursuant to the accident which occurred on 28/05/2019 (date) at LOYANG POINT CAR PARK (location) involving vehicle no. SLK 5156B (insured vehicle). This is pursuant to the inspection conducted on 29/05/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CHUA CHEE YON, ALVIN ("the third party claimant") of vehicle no. SLL 1634J to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLL 1634J (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 5,480.00 to Choo Motor Spray Painter

Dated this 12 day of 7 2019

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

TANG JUN ZHONG  
S8704986H

NRIC:

Address:

4 Kaki Bukit Avenue 6, #01-46/48/50  
AutoBay, Singapore 417883  
Tel: 6746 5405 / 6745 2063 Fax: 6745 8520

Nationality:

Email: general@fastechauto.com.sg

Occupation:

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

NRIC:

Address:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Nationality:

Occupation:



## TAX INVOICE

### CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Co. Reg No: 22736900M

Tel No: 67452063 / 67467158 Fax No: 67458520

India International Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

Attn : Motor Claim Department

Invoice : 21121

Date: 24.06.2019  
Vehicle No: SLL1634J  
Make/Model: MERCEDES BENZ  
Chassis/Eng# :  
Accident Date: 28.05.2019  
Claim No : 0519-21121  
Reference :  
Policy No :

---

|                               | Amount       |
|-------------------------------|--------------|
| To proceed on lump sum repair | S\$ 5,300.00 |

---

E. & O. E.

Total : S\$ 5,300.00

Amount Due : S\$ 5,300.00



---

CHOO MOTOR SPRAY PAINTER

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

## CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt  | Adj Submitted                                  | Ins Auth'd | Status  |
|------|---|---------------|---|--|--|------------|---|
| Main | 29 May 2019<br><a href="#">Edit Reg</a> |               | 29 May 2019 00:00<br><a href="#">Edit Adj Rpt</a> | <b>\$55,300.00</b><br><a href="#">Edit Estimates</a> | <b>\$55,300.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main   | Reference   | Claim Details          | Documents  | Show All |         |             |              |            |       |
|--|---|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>  |   |                        |  |          |         |             |              |            |       |
| Insured:   | LOW CHYE HOE, ID: S1556431H   |                        |  |          |         |             |              |            |       |
| Main Claimant:   | CHUA CHEE YON, ALVIN, ID: S7838292I   |                        |  |          |         |             |              |            |       |
| Vehicle Reg. No.:  | SLL1634J  | Date of Loss:          | 28/05/2019 00:00 - :59<br>[27 Months and 12 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:  | TP / MPC2019D0000566  | Policy/Cover Note No.: | D19MPC0000488 (Comprehensive)  |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):  | SLK5156B  | Policy No. (Claimant): | MT/00586340  |          |         |             |              |            |       |
|  |   | Excess:                | S\$1,000.00  |          |         |             |              |            |       |
| Repairer:  | Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 67453897 |                        |  |          |         |             |              |            |       |
| Handling Insurer:  | India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Lalitha Krishnan - 6347 6139]            |                        |  |          |         |             |              |            |       |
| Claimant's Insurer:  | Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888  |                        |  |          |         |             |              |            |       |
| Adjuster:  | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 10/06/2019]      |                        |  |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>  |   |                        |  |          |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>III_SG (04/07/2019): Alert - Adj Mandate Approved (\$5480.00) - SLL1634J - Claim Handler: Lalitha Kri...</li> <li>III_SG (10/06/2019): Alert - Adj Mandate Approved (\$0.00) - SLL1634J - Claim Handler: Lalitha Krishn...</li> </ul> |   |                        |  |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>  |   |                        |  |          |         |             |              |            |       |
| Due Date   | Priority  | Type                   | Task Group   | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.  |   |                        |  |          |         |             |              |            |       |

## Claim Documents

\*SLL1634J (MPC2019D0000566)  
[SLK5156B]






































TP



CHUA CHEE YON, ALVIN

May 28 2019 12:00AM

[LOW CHYE HOE]

Choo Motor Spray Painter

| Upload Documents   Upload Photos   Compose New Letter |                 |                                   | View <span>View in Browser</span>  |                                     |
|---|-----------------|-----------------------------------|--|-------------------------------------|
| Photos/Images   |                 |                                   | 3 per page   | <input checked="" type="checkbox"/> |
| No  | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1   | 04/07/19 16:10  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 2   | 04/07/19 16:10  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 3   | 04/07/19 16:10  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 4   | 04/07/19 16:10  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 5   | 04/07/19 16:10  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 6   | 04/07/19 16:10  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 7   | 04/07/19 16:10  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 8   | 04/07/19 16:10  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 9   | 04/07/19 16:10  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 10  | 04/07/19 16:10  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 11  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 12  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 13  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 14  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 15  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 16  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 17  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 18  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 19  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 20  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 21  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 22  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 23  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 24  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 25  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 26  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 27  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 28  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 29  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 30  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 31  | 04/07/19 16:10  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 32  | 04/07/19 16:10  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 33  | 04/07/19 16:10  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 34  | 04/07/19 16:10  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 35  | 04/07/19 16:10  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 36  | 04/07/19 16:10  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 37  | 04/07/19 16:10  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images |                 |  | 3 per page  | <input checked="" type="checkbox"/> |
|---------------|-----------------|--|---|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)          | Thumbnail   | Print                               |
| 38            | 04/07/19 16:10  | Reinspection Photo                         |  Load JPG  | <input checked="" type="checkbox"/> |
| 39            | 04/07/19 16:10  | Reinspection Photo                         |  Load JPG  | <input checked="" type="checkbox"/> |
| 40            | 04/07/19 16:10  | Reinspection Photo                         |  Load JPG  | <input checked="" type="checkbox"/> |
| 41            | 04/07/19 16:10  | Reinspection Photo                         |  Load JPG  | <input checked="" type="checkbox"/> |
| 42            | 04/07/19 16:10  | Reinspection Photo                         |  Load JPG  | <input checked="" type="checkbox"/> |
| 43            | 04/07/19 16:10  | Reinspection Photo                         |  Load JPG  | <input checked="" type="checkbox"/> |
| 44            | 04/07/19 16:10  | Reinspection Photo                         |  Load JPG  | <input checked="" type="checkbox"/> |
| 45            | 04/07/19 16:10  | Reinspection Photo                         |  Load JPG  | <input checked="" type="checkbox"/> |
| 46            | 04/07/19 16:10  | Reinspection Photo                         |  Load JPG  | <input checked="" type="checkbox"/> |
| 47            | 04/07/19 16:10  | Reinspection Photo                         |  Load JPG  | <input checked="" type="checkbox"/> |
| 48            | 04/07/19 16:10  | Reinspection Photo                         |  Load JPG  | <input checked="" type="checkbox"/> |
| 49            | 04/07/19 16:10  | Reinspection Photo                         |  Load JPG  | <input checked="" type="checkbox"/> |
| 50            | 04/07/19 16:10  | Reinspection Photo                         |  Load JPG  | <input checked="" type="checkbox"/> |
| 51            | 04/07/19 16:10  | Reinspection Photo                         |  Load JPG  | <input checked="" type="checkbox"/> |
| 52            | 04/07/19 16:10  | Reinspection Photo                         |  Load JPG  | <input checked="" type="checkbox"/> |
| Documentation |                 |  | 1 per page  | <input checked="" type="checkbox"/> |
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)          | Thumbnail   | Print                               |
| 1             | 31/05/19 09:07  | TP GIA REPORT                              |  Load PDF  |                                     |
| 2             | 28/06/19 12:24  | WORKSHOP INVOICE                           |  Load PDF  |                                     |
| 3             | 28/06/19 12:24  | LOD  |  Load PDF  |                                     |
| 4             | 17/07/19 12:01  | AUTHORISATION TO ACT FORM                  |  Load PDF  |                                     |
| 5             | 17/07/19 12:01  | DISCHARGE VOUCHER                          |  Load PDF  |                                     |
| No            | Finalized On    | India International Insurance Pte Ltd (HQ) | Thumbnail   | Print                               |
| 1             | 30/05/19 08:42  | Singapore Accident Statement               |  Load PDF |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST  |  | Reset | Save | Print |
|--|--|-------|------|-------|
| There are no document checklists configured.   |  |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>       |  |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |  |       |      |       |

## LKK Auto Consultants Pte Ltd (Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19009487/UWA3Q2

Date: 17/07/2019

## REFERENCE

|                       |                                       |                      |                 |
|-----------------------|---------------------------------------|----------------------|-----------------|
| Handling Insurer:     | India International Insurance Pte Ltd | Policy No:           | D19MPC0000488   |
| Claimant Vehicle No : | SLL1634J                              | Insured Vehicle No : | SLK5156B        |
| Date of Loss:         | 28/05/2019                            | Nature of Claim:     | TP              |
|                       |                                       | Claim No:            | MPC2019D0000566 |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SLL1634J                     | Engine No:  | 27091031137639    |
| Make & Model:               | MERCEDES-BENZ C180, 1.6 (A)  | Chassis No: | WDD1173422N445604 |
| Reg. Date:                  | 16/02/2017 (Man. Year: 2016) | Odometer:   | 43921 km          |
| Colour:                     | Grey                         |             |                   |
| Engine Capacity:            | 1595 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |                   |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 225/40 R18       | Rear Tyre Size:  | 225/40 R18       |
| Front Left Side:  | Bridgestone 6 mm | Rear Left Side:  | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                                  | Repairer's       | Adjuster's      | Difference      | Diff %       |
|---|------------------|-----------------|-----------------|--------------|
| Parts   | 11,748.02        | 5,411.95        | 6,336.07        | 53.93        |
| Miscellaneous Items                             | 0.00             | 0.00            | 0.00            |              |
| Labour  | 1,830.00         | 1,250.00        | 580.00          | 31.69        |
| Paintwork Labour                                | 0.00             | 0.00            | 0.00            |              |
| Towing  | 0.00             | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>             | <b>13,578.02</b> | <b>6,661.95</b> | <b>6,916.07</b> | <b>50.94</b> |
| <b>Approved Total (Overridden) (S\$)</b>        |                  | <b>5,300.00</b> |                 |              |
| <b>Nett Amount (S\$)</b>                        | <b>13,578.02</b> | <b>5,300.00</b> | <b>8,278.02</b> | <b>60.97</b> |
| <b>+ Loss of Use (3.0 x S\$60.00/day) (S\$)</b> |                  | 180.00          |                 |              |
| <b>Nett Liability (S\$)</b>                     |                  | <b>5,480.00</b> |                 |              |

## INSPECTION

|                             |                          |  |
|-----------------------------|--------------------------|--|
| Date of Assignment:         | 29/05/2019               |  |
| Date Inspected:             | 29/05/2019 Inspected At: | Choo Motor Spray Painter (HQ)<br>1 Kaki Bukit Avenue 6, #01-39 AutoBay @<br>Kaki Bukit<br>Singapore 417883 |
| Estimated Period of Repair: | 3.0 days                 |  |

---

**Adjuster:** MARCUS CHUA**Manager:** VIVIAN LAU PEI FENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

|                      |  |  |
|----------------------|--|--|
| <b>Part Source:</b>  | MRM-SG   | Version: 1.0 (Last Synchronised: 28 Jun 2019)                |
| <b>Parts:</b>        | M1-COUPE   | MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                            |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLL1634J)  |  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

## Recommended Parts

| No. | Qty | Part No. | Particulars                         | Condition     | Repairer's | Amount       |
|-----|-----|----------|-------------------------------------|---------------|------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                       | Deep Cut      | 1,866.02 F | *1,534.30 FL |
| 2   | 1   |          | *SET FRONT BUMPER CLIPS             | Necessary     | 60.00 F    | *60.00 FL    |
| 3   | 1   |          | *FRONT BUMPER REINFORCEMENT         | Not Necessary | 715.00 F   | *- FL        |
| 4   | 1   |          | *FRONT BUMPER LOWER CHROME MOULDING | Necessary     | 311.00 F   | *288.43 FL   |
| 5   | 1   |          | *FRONT BUMPER PDC SENSOR O/S        | Not Necessary | 265.00 F   | *- FL        |
| 6   | 1   |          | *FRONT BUMPER SPONGE                | Torn          | 199.00 F   | *199.00 FL   |
| 7   | 1   |          | *HEADLAMP ASSY O/S                  | Cut           | 4,850.00 F | *3,126.25 FL |
| 8   | 1   |          | *FRONT SUPPORT PANEL                | Cracked       | 1,016.00 F | *805.30 FL   |
| 9   | 1   |          | *FRONT FENDER O/S                   | Repair        | 1,266.00 F | *- FL        |
| 10  | 1   |          | *FRONT SPORT RIM O/S                | Repair        | 1,200.00 F | *- FL        |

F=Franchise part. L=ListItemDisc.

**Sub Total (S\$)**    **11,748.02**    **6,013.28**

- List Item Discount on L Items 0.00/10.00% (S\$)    0.00    601.33

**Total Parts (S\$)**    **11,748.02**    **5,411.95**

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                                | Lab.Type | Repairer's | Amount   |
|-------------------------|--|----------|------------|----------|
| <b>Labour Items</b>     |  |          |            |          |
| 1                       | TO CHECK WIRING                            | New      | 80.00      | 20.00    |
| 2                       | TO DISMANTLE & REFIX FRONT PDC SENSOR      | New      | 80.00      | 50.00    |
| 3                       | TO REFILL AIR CON GAS                      | New      | 120.00     | 100.00   |
| 4                       | TO CONDUCT WHEEL ALIGNMENT                 | New      | 120.00     | 60.00    |
| 5                       | TO SPRAY RUST PROOFING                     | New      | 50.00      | 0.00     |
| 6                       | LABOUR FOR PANEL BEATING & REPLACING PARTS | New      | 580.00     | 520.00   |
| 7                       | TO PUTTY & SPRAY PAINTING                  | New      | 800.00     | 500.00   |
| Gross Labour Cost (S\$) |  |          | 1,830.00   | 1,250.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >